

FORGELINE / QUALITY OPERATIONS

Dimensional Inspection SOP

Effective date: 2026-08-11 | Reference: NCR-026 | Controlled synthetic record

Applies to	Product Alpha and Product Beta
Dimensional acceptance	+/- 0.18 mm
Record owner	Quality Engineering

Purpose

This ForgeLine procedure establishes a consistent method for dimensional inspection at the +/- 0.18 mm acceptance boundary. It preserves a direct link between the recorded decision, Product Alpha or Product Beta evidence, and the NCR-026 corrective-action trail.

Required controls

- 1. Confirm the gage is identified and status-checked before use.
- 2. Record nominal, actual result, and acceptance decision for every required feature.
- 3. Hold and escalate any result outside the accepted boundary through NCR-026.

Acceptance and escalation

A result outside +/- 0.18 mm, a missing record, or a recurring adverse trend requires containment and documented escalation. The quality engineer records the disposition, responsible role, and the verification needed before release.

Records, review, and approval

Controlled evidence includes the completed inspection or supplier record, measured values where applicable, reviewer decision, and NCR-026 linkage. Retain only approved revisions in the quality system.

Review checklist

Check	Acceptance criterion
Identity	Product and lot/reference are unambiguous
Method	Current approved method is used
Decision	Acceptance or disposition is explicit
Traceability	NCR-026 linkage is present when escalation occurs

Approval statement

This synthetic SOP is approved for the ForgeLine training corpus. It does not describe a real facility, supplier, or quality record.