

NCR-026 Containment Workflow

ForgeLine | Product Alpha dimensional variance response | effective 2026-08-11

Document	FL-QWI-018
Effective	2026-08-11
Reference	NCR-026
Critical tolerance	±0.18 mm

Trigger

Start this workflow when a Product Alpha measurement falls outside the defined nominal ±0.18 mm acceptance band or when gage confidence is uncertain.

Containment objective

Prevent unverified material from moving forward while the quality team confirms the condition, measurement method, and affected sample range.

Release criteria

Only the quality lead may release contained material after documented re-measurement and a recorded NCR-026 disposition.

Execution sequence

#	Action	Record
1	Stop handling the affected sample and place it in the designated contained area.	Containment label applied
2	Record inspection point, observed value, gage status, and sample alias.	NCR-026 entry complete
3	Screen comparable samples using the same controlled method.	Screening record attached
4	Obtain quality disposition before any release.	Disposition recorded