



Security & Operations Inspection

Kwasa Damansara · Mechanical & Electrical — generic sample, not a real site

Inspector: Tuan Dev Site: Kwasa Damansara Duration: Aug 2026 SLA: 96.1%

INSPECTIONS

142

▲ +9.8% MoM

SLA HIT RATE

96.1%

▲ +1.4 pts

FINDINGS

214

▲ +6.0%

ESCALATIONS

17

▼ -18.5%

FINDING PROGRESS BY AREA

AREA	OWNER	PROGRESS	RISK	STATUS
Electrical Distribution	N. Mehta		Low	On Track
Cable Routing	D. Chen		Low	On Track
Access Control	R. Walker		High	At Risk
Lighting & Safety	M. Roy		Medium	On Track

Findings resolved by week

Resolved workload distribution across inspection areas

Electrical		91%
Cable Routing		85%
Lighting & Safety		77%
Access Control		66%

HIGHLIGHTS

- SLA improved after rebalancing inspection routing and incident triage.
- Access-control queue grew this month; remediation plan has budget and sponsorship.
- No critical safety findings. Two minor housekeeping observations remain open.
- This document is a generic portfolio sample — no client, site, or operational data represented.