

A02
installation
locating point
A03
assembly orienting
line