

SYNTHETIC EXAMPLE - NOT A CLIENT CLAIM

Feasible tile repair with a documented underlayment rate question

BASELINE v1 | 2026-09-21 | direct pre-tax USD

Item	Qty	Unit	Rate	Total
Tile lift and reset	18	SQ	200	3600.00
Compatible replacement tile	10	EA	30	300.00
Underlayment installation	18	SQ	150	2700.00

Direct subtotal: 6600.00

All quantities, observations and rates are fictional test assumptions.
Taxes, general overhead/profit, coverage and payment are not determined.