ETSITS 134 108 V11.15.0 (2016-01)



Universal Mobile Telecommunications System (UMTS);
LTE;
Common test environments for User Equipment (UE);
Conformance testing
(3GPP TS 34.108 version 11.15.0 Release 11)



Reference RTS/TSGR-0534108vbf0 Keywords LTE,UMTS

ETSI

650 Route des Lucioles F-06921 Sophia Antipolis Cedex - FRANCE

Tel.: +33 4 92 94 42 00 Fax: +33 4 93 65 47 16

Siret N° 348 623 562 00017 - NAF 742 C Association à but non lucratif enregistrée à la Sous-Préfecture de Grasse (06) N° 7803/88

Important notice

The present document can be downloaded from: http://www.etsi.org/standards-search

The present document may be made available in electronic versions and/or in print. The content of any electronic and/or print versions of the present document shall not be modified without the prior written authorization of ETSI. In case of any existing or perceived difference in contents between such versions and/or in print, the only prevailing document is the print of the Portable Document Format (PDF) version kept on a specific network drive within ETSI Secretariat.

Users of the present document should be aware that the document may be subject to revision or change of status.

Information on the current status of this and other ETSI documents is available at

http://portal.etsi.org/tb/status/status.asp

If you find errors in the present document, please send your comment to one of the following services: https://portal.etsi.org/People/CommiteeSupportStaff.aspx

Copyright Notification

No part may be reproduced or utilized in any form or by any means, electronic or mechanical, including photocopying and microfilm except as authorized by written permission of ETSI.

The content of the PDF version shall not be modified without the written authorization of ETSI.

The copyright and the foregoing restriction extend to reproduction in all media.

© European Telecommunications Standards Institute 2016.
All rights reserved.

DECTTM, **PLUGTESTS**TM, **UMTS**TM and the ETSI logo are Trade Marks of ETSI registered for the benefit of its Members. **3GPP**TM and **LTE**TM are Trade Marks of ETSI registered for the benefit of its Members and of the 3GPP Organizational Partners.

GSM® and the GSM logo are Trade Marks registered and owned by the GSM Association.

Intellectual Property Rights

IPRs essential or potentially essential to the present document may have been declared to ETSI. The information pertaining to these essential IPRs, if any, is publicly available for **ETSI members and non-members**, and can be found in ETSI SR 000 314: "Intellectual Property Rights (IPRs); Essential, or potentially Essential, IPRs notified to ETSI in respect of ETSI standards", which is available from the ETSI Secretariat. Latest updates are available on the ETSI Web server (https://ipr.etsi.org).

Pursuant to the ETSI IPR Policy, no investigation, including IPR searches, has been carried out by ETSI. No guarantee can be given as to the existence of other IPRs not referenced in ETSI SR 000 314 (or the updates on the ETSI Web server) which are, or may be, or may become, essential to the present document.

Foreword

This Technical Specification (TS) has been produced by the ETSI 3rd Generation Partnership Project (3GPP).

The present document may refer to technical specifications or reports using their 3GPP identities, UMTS identities or GSM identities. These should be interpreted as being references to the corresponding ETSI deliverables.

The cross reference between GSM, UMTS, 3GPP and ETSI identities can be found under http://webapp.etsi.org/key/queryform.asp.

Modal verbs terminology

In the present document "shall", "shall not", "should", "should not", "may", "need not", "will", "will not", "can" and "cannot" are to be interpreted as described in clause 3.2 of the <u>ETSI Drafting Rules</u> (Verbal forms for the expression of provisions).

"must" and "must not" are NOT allowed in ETSI deliverables except when used in direct citation.

Content

Intell	ectual Property Rights	2
Forev	vord	2
Moda	l verbs terminology	2
Forev	vord	4
Moda	l verbs terminology	4
	luction	
1	Scope	
2	References	
3	Definitions, abbreviations and symbols	
4	Common requirements of test equipment	
	1 Void	
	x A to C (informative): Void	
Anne	x D (informative): Change history	7
Histo	rV	29

Foreword

This Technical Specification (TS) has been produced by ETSI 3rd Generation Partnership Project (3GPP).

The present document may refer to technical specifications or reports using their 3GPP identities, UMTS identities or GSM identities. These should be interpreted as being references to the corresponding ETSI deliverables.

The cross reference between GSM, UMTS, 3GPP and ETSI identities can be found under http://webapp.etsi.org/key/queryform.asp.

Modal verbs terminology

In the present document "shall", "shall not", "should", "should not", "may", "need not", "will", "will not", "can" and "cannot" are to be interpreted as described in clause 3.2 of the <u>ETSI Drafting Rules</u> (Verbal forms for the expression of provisions).

"must" and "must not" are NOT allowed in ETSI deliverables except when used in direct citation.

The contents of the present document are subject to continuing work within the TSG and may change following formal TSG approval. Should the TSG modify the contents of the present document, it will be re-released by the TSG with an identifying change of release date and an increase in version number as follows:

Version x.y.z

where:

- x the first digit:
 - 1 presented to TSG for information;
 - 2 presented to TSG for approval;
 - 3 or greater indicates TSG approved document under change control.
- y the second digit is incremented for all changes of substance, i.e. technical enhancements, corrections, updates, etc.
- z the third digit is incremented when editorial only changes have been incorporated in the document.

Introduction

The definition of the Conformance Tests for UE in 3G will be a complex task as the complete test suite covers RF, EMC and Protocol aspects of the UE.

Each test requires a Test Environment to be defined in which the UE has to operate to defined standards, constraints and performance. The overall task can be simplified if there are a number of well defined and agreed Common Test Environments where every one can be used for a number of tests. Hence the present document defines testing conditions that are common to several tests avoiding the need to duplicate the same information for every single test.

The present document defines default values for a variety of common areas. Where values are not specified in test cases, the defaults in the present document will apply. If specified, the test case values will take precedence.

The present document addresses the FDD mode as well as the TDD mode.

1 Scope

The present document contains definitions of reference conditions and test signals, default parameters, reference radio bearer configurations used in radio bearer interoperability testing, common radio bearer configurations for other test purposes, common requirements for test equipment and generic set-up procedures for use in UE conformance tests.

2 References

The following documents contain provisions which, through reference in this text, constitute provisions of the present document.

- References are either specific (identified by date of publication, edition number, version number, etc.) or non-specific.
- For a specific reference, subsequent revisions do not apply.
- For a non-specific reference, the latest version applies. In the case of a reference to a 3GPP document (including a GSM document), a non-specific reference implicitly refers to the latest version of that document *in the same Release as the present document*.

[1] to [48] (void)

[49] 3GPP TS 34.108 Release 12: "Common test environments for User Equipment (UE);

Conformance testing"

3 Definitions, abbreviations and symbols

Void

4 Common requirements of test equipment

The requirements of the present document are provided in 3GPP TS 34.108 Release 12 [49].

5 to 11 Void

Annex A to C (informative): Void

Annex D (informative): Change history

Meetin g-1st- Level	Doc-1st-Level	CR	Rev	Subject	Cat	Version -Current	Version -New	Doc-2nd- Level
TP-08				Approval of the specification		2.0.0	3.0.0	
TP-09	TP-000131	001		RRC Message Contents: RLCSize	С	3.0.1	3.1.0	T1-000190
TP-09	TP-000131	002		RRC Message Contents: RLCParam	С	3.0.1	3.1.0	T1-000191
TP-09	TP-000131	003		RRC Message Contents: PCPreamble	С	3.0.1	3.1.0	T1-000192
TP-09	TP-000131	004		RRC Message Contents: RBIdentity	С	3.0.1	3.1.0	T1-000193
TP-09	TP-000131	005		RRC Message Contents: TrCHParam	С	3.0.1	3.1.0	T1-000194
TP-09	TP-000131 TP-000131	006 007		RRC Message Contents: UECapability RRC Message Contents: RBMapping	C C	3.0.1	3.1.0 3.1.0	T1-000195 T1-000196
TP-09	TP-000131	007		RRC Message Contents: PagingCause	С	3.0.1	3.1.0	T1-000196
TP-09	TP-000131	009		RRC Message Contents: CipheringAndIntegrity	С	3.0.1	3.1.0	T1-000197
TP-09	TP-000131	010		RRC Message Contents: RLCInfo	С	3.0.1	3.1.0	T1-000198
TP-09	TP-000131	011		RRC Message Contents: CompressedMode	С	3.0.1	3.1.0	T1-000200
TP-09	TP-000131	012		RRC Message Contents: SIB	С	3.0.1	3.1.0	T1-000201
TP-09	TP-000131	013		RRC Message Contents: PhyCH	D	3.0.1	3.1.0	T1-000202
TP-09	TP-000131	014		RRC Message Contents: Measurement	С	3.0.1	3.1.0	T1-000203
TP-09	TP-000131	015		RRC Message Contents: TFCS	C	3.0.1	3.1.0	T1-000204
TP-09	TP-000131	016		RRC Message Contents: DPCHFrameOffset	С	3.0.1	3.1.0	T1-000205
TP-09	TP-000131	017		Test USIM Parameters	F	3.0.1	3.1.0	T1-000215
TP-09	TP-000131	018		Correction to definition of the test algorithm for authentication (clause 8.1.2)	F	3.0.1	3.1.0	T1-000164
TP-09	TP-000131	019		Reference Radio Bearer Configurations	F	3.0.1	3.1.0	T1-000212
TP-09	TP-000131	020		TDD Single mode	F	3.0.1	3.1.0	T1-000220
TP-10	TP-000215	021		Common generic procedure for AS testing	В	3.1.0	3.2.0	T1-000294
TP-10	TP-000215	022		Requirements for the system simulator for support of Tcell parameter	F	3.1.0	3.2.0	T1-000303
TP-10	TP-000215	023		Minimum Performance Levels	F	3.1.0	3.2.0	T1-000306
TP-10	TP-000215	024		Downlink signal conditions and propagation conditions	D	3.1.0	3.2.0	T1-000307
TP-10	TP-000215	025		Updating 34.108 v3.1.0 to TDD single mode	F	3.1.0	3.2.0	T1-000281
TP-10	TP-000215	026		Application of integrity mode protection to signalling message by default	F	3.1.0	3.2.0	T1-000296
TP-10	TP-000215	027		Updates to the default message contents in clause 9	С	3.1.0	3.2.0	T1-000282
TP-10	TP-000215	028		Updates to System Information Block (SIB) and Master Information Block (MIB) messages	С	3.1.0	3.2.0	T1-000283
TP-10	TP-000215	029		Application of ciphering during conformance testing	С	3.1.0	3.2.0	T1-000285
TP-10	TP-000215	030		Addition for System Information parameters (34.108 clause 6.1)	F	3.1.0	3.2.0	T1-000304
TP-10	TP-000215	031		Correction for Generic Setup Procedures (34.108 clause 7.2)	F	3.1.0	3.2.0	T1-000305
TP-11	TP-010018	032		Default radio conditions for multi-cell environment	F	3.2.0	3.3.0	T1-010078
TP-11	TP-010018	033		Correction for Generic Setup Procedures (34.108 clause 7.2)	F	3.2.0	3.3.0	T1-010079
TP-11	TP-010018	034		Corrections for Test USIM Parameters(34.108 clause 8)	F	3.2.0	3.3.0	T1-010080
TP-11	TP-010018	035		Correction of clause number in TS 34.108.	D	3.2.0	3.3.0	T1-010081
	TP-010018	036		Update of authentication test algorithm	С	3.2.0	3.3.0	T1-010082
TP-11	TP-010018	037		Updates to clause 9 of TS 34.108 v3.2.0	F	3.2.0	3.3.0	T1-010084
TP-11	TP-010018	038		Updating to TDD single mode	F	3.2.0	3.3.0	T1-010088
TP-11	TP-010018	039		Simulated network environments for TDD mode (SIB)	F	3.2.0	3.3.0	T1-010089
TP-12	TP-010118	040		Corrections to clause 6.10 FDD parameters	F	3.3.0	3.4.0	T1-010205
TP-12 TP-12	TP-010118 TP-010118	041 042		Corrections to clause 6.10 TDD parameters Adding section for radio bearer configurations intended	F D	3.3.0 3.3.0	3.4.0 3.4.0	T1-010206 T1-010210
TD 40	TD 040440	042	-	for functional testing	<u> </u>	2 2 2	2.4.0	T4 040044
TP-12	TP-010118	043		Update of list of abbreviations	D	3.3.0	3.4.0	T1-010211
TP-12 TP-12	TP-010118	044 045	<u> </u>	Updates to clause 6.1 and 9	F F	3.3.0	3.4.0 3.4.0	T1-010212 T1-010213
TP-12	TP-010118 TP-010118	045		Updates to clause 7.4 clause 6.1: System Information Blocks for TDD Mode	F	3.3.0	3.4.0	T1-010213 T1-010214
TP-12	TP-010118	047		Editorial corrections and removal of a reference	F	3.3.0	3.4.0	T1-010214
TP-13	TP-010215	048		document Correction to reference	F	3.4.0	3.5.0	T1-010275
TP-13	TP-010215	048		Editorial modification for References	F	3.4.0	3.5.0	T1-010275
TP-13	TP-010215	050		Some corrections in clause 5	F	3.4.0	3.5.0	T1-010276
TP-13	TP-010215	050		Update to Scope Statement	F	3.4.0	3.5.0	T1-010277
TP-13	TP-010215	052		Clause 6.10 Definition of RB configurations, TDD	F	3.4.0	3.5.0	T1-010278
TP-13	TP-010215	053		parameters Updates to clause 6.1, clause 7.4 and clause 9	' F	3.4.0	3.5.0	T1-010279
11-13	115-010213	000	<u> </u>	Topuales to clause o. 1, clause 1.4 and clause 3	<u>Ir</u>	J.4.U	0.0.0	11-010200

Meetin g-1st-	Doc-1st-Level	CR	Rev	Subject	Cat	Version -Current	Version -New	Doc-2nd- Level
Level								
TP-13	TP-010215	054		Clause 6.1: Default radio conditions for Signalling tests	F	3.4.0	3.5.0	T1-010281
TP-13	TP-010215	055		Correction of Radio Bearer Configurations for FDD	F	3.4.0	3.5.0	T1-010282
				Mode				
TP-13	TP-010215	056		Correction of Radio Bearer Configurations for TDD	F	3.4.0	3.5.0	T1-010283
				Mode				
TP-13	TP-010215	057		Changes to Signalling Radio Bearer (SRB) numbering	F	3.4.0	3.5.0	T1-010284
TP-13	TP-010215	058		Missing bearers in tables 6.10.2.1.1 and 6.10.3.1.1	F	3.4.0	3.5.0	T1-010285
TP-13	TP-010215	059		Correction of system information block 5	F	3.4.0	3.5.0	T1-010286
TP-13	TP-010215	060		,	F	3.4.0	4.0.0	T1-010287
				6				
TP-13	TP-010215	061		Introduction of System Information Blocks for 1.28 Mcps TDD Mode	F	3.4.0	4.0.0	T1-010288
TP-13	TP-010215	062		Introduction of typical radio parameters for 1.28 McpsTDD	F	3.4.0	4.0.0	T1-010289
TP-13	TP-010215	063		Clause 6.11 RBs for RLC and PDCP testing	F	3.4.0	3.5.0	T1-010290
TP-14	TP-010285	065	1	Correction to 6.1 Contents of System Information Blocks	Α	4.0.0	4.1.0	T1-010475
TP-14	TP-010285	067	1	Corrections to clause 6.1, 7.4 and 9	Α	4.0.0	4.1.0	T1-010473
TP-14	TP-010258	069	 	Reference Radio Conditions	Α	4.0.0	4.1.0	T1-010461
	TP-010258	071		Modification of Test procedures for RF tests	A	4.0.0	4.1.0	T1-010461
			1					
TP-14	TP-010258	073	1	Default message contents for RF tests	A	4.0.0	4.1.0	T1-010465
TP-14	TP-010258	075	1	Correction to 6.10 Reference Radio Bearer	Α	4.0.0	4.1.0	T1-010467
TD 44	TD 040050	077		configurations		400	4.4.0	T4 040400
TP-14	TP-010258	077	<u> </u>	Definition of default value of rate matching attribute	A	4.0.0	4.1.0	T1-010469
	TP-010258	079		Update of clause 7.4 and 6.10	Α	4.0.0	4.1.0	T1-010471
	TP-010292	081		Correction on introduction of clause 6.10	Α	4.0.0	4.1.0	
TP-15	TP-020038	083		Replacement of Block STTD by Space Code Transmit Diversity (SCTD) (Rel-4)	Α	4.1.0	4.2.0	T1-020092
TP-15	TP-020038	085		Update of reference radio conditions (Rel-4)	Α	4.1.0	4.2.0	T1-020098
TP-15	TP-020038	087		Update of system reference configurations and default messages (Rel-4)	Α	4.1.0	4.2.0	T1-020100
TP-15	TP-020038	089		Corrections to 34108-410	Α	4.1.0	4.2.0	T1-020102
TP-15	TP-020038	091		Introduction of new Reference RABs (Rel-4)	Α	4.1.0	4.2.0	T1-020195
TP-15	TP-020038	094		Update of SIBs for TDD (both modes) in TS 34.108 (Rel4)	F	4.1.0	4.2.0	T1-020107
TP-15	TP-020038	095		Clarification of bit rate of Interactive/Background PS RAB function (Rel-4)	Α	4.1.0	4.2.0	T1-020184
				Correction of CR implementation errors in clauses: 6.10.2.2 and 6.10.2.4.1.58.2.1.1		4.2.0	4.2.1	
TP-16	TP-020141	108		Clause 7(reference) Update of generic setup procedures to use 13.6 kbps SRB in RRC connection establishment TDD (3.84 Mcps and 1.28 Mcps)	F	4.2.1	4.3.0	T1-020289
TP-16	TP-020141	109		Correction to clause 7.3.3.4 RADIO BEARER SETUP message	Α	4.2.1	4.3.0	T1-020291
TP-16	TP-020141	110		Change of RM attribute of DL:3.4 kbps SRBs for DCCH in for REL4	Α	4.2.1	4.3.0	T1-020292
TP-16	TP-020141	111		New additional RAB configuration (R1-020669) for REL4	Α	4.2.1	4.3.0	T1-020293
TP-16	TP-020141	112		Correction of Puncturing Limit for RABs for REL4	Α	4.2.1	4.3.0	T1-020294
TP-16	TP-020141	113		Test USIM	Α	4.2.1	4.3.0	T1-020295
TP-16	TP-020141	114		Clause 6.1 (SIBs) Rel-4 (3.84 Mcps and 1.28 Mcps	F	4.2.1	4.3.0	T1-020296
TP-16	TP-020141	115		TDD) Clause 6.10 References for TDD about Clarification of	A	4.2.1	4.3.0	T1-020297
	<u></u>	<u> </u>	<u>L</u>	bit rate of Interactive/Background PS RAB	L		<u></u>	<u></u> _
TP-16	TP-020141	116		Correction to default message in clause 9 for Rel4	Α	4.2.1	4.3.0	T1-020298
TP-16	TP-020141	117		Correction to clause 6.1 for Rel4	Α	4.2.1	4.3.0	T1-020299
TP-16	TP-020141	118		WCDMA1800 additions for Rel4	Α	4.2.1	4.3.0	T1-020300
TP-16	TP-020141	119		Clause 9.1 Default message contents for TDD (3.84 Mcps and 1.28 Mcps) R4	F	4.2.1	4.3.0	T1-020301
TP-16	TP-020141	121		Update of generic setup procedures to use 13.6 kbps SRB in RRC connection establishment	А	4.2.1	4.3.0	T1-020434
TP-17	TP-020184	123	-	Alignment of reference configurations on S-CCPCH with default system information messages	Α	4.3.0	4.4.0	T1-020503
TP-17	TP-020184	125	-	Addition of reference compressed mode pattern	Α	4.3.0	4.4.0	T1-020505
TP-17	TP-020184	127	-	Corrections to default message contents as T1S- 020347rev1	A	4.3.0	4.4.0	T1-020507
TP-17	TP-020184	129	<u> </u>	Additional default message contents for RF Testing	Α	4.3.0	4.4.0	T1-020509
TP-17	TP-020184	131	t	Corrections related to SIB11, SIB12 and to the	A	4.3.0	4.4.0	T1-020509
			<u> </u>	MEASUREMENT CONTROL message				
TP-17	TP-020184	133	-	Corrections to clause 6.1 (T1S-020349rev1)	Α	4.3.0	4.4.0	T1-020530
TP-17	TP-020184	135	1	Introduction of reference configurations on S-CCPCH	Α	4.3.0	4.4.0	T1-020539
				and PRACH with two interactive PS domain RABs		1		

g-1st- Level	Doc-1st-Level	CR	Rev	Subject	Cat	Version -Current		Doc-2nd- Level
	TP-020184	137	-	Removal of reference radio bearer configurations for unidirectional streaming CS RABa above 64 kbps	А	4.3.0	4.4.0	T1-020541
TP-17	TP-020184	140	-	Some corrections and updates in clause 6.1 for TDD mode	F	4.3.0	4.4.0	T1-020576
TP-17	TP-020184	142	-	Inclusion of default message contents for RF in clause 9.2 for TDD mode	F	4.3.0	4.4.0	T1-020578
TP-18	TP-020293	144	-	Correction to default messages in 9.1 and 9.2	Α	4.4.0	4.5.0	T1-020658
TP-18	TP-020293	146	-	Corrections in the TDD test frequencies according to core specs	Α	4.4.0	4.5.0	T1-020674
TP-18	TP-020293	148	-	Addition of alternative configuration using Turbo Coding for Interactive or background / UL:8 DL:8 kbps / PS RAB + UL:3.4 DL:3.4 kbps SRBs for DCCH	Α	4.4.0	4.5.0	T1-020694
TP-18	TP-020293	150	-	Correction to content of clause 6.10.2.	Α	4.4.0	4.5.0	T1-020709
TP-18	TP-020293	152	-	Correction to SIB 11/12 definition	Α	4.4.0	4.5.0	T1-020712
		154	-	Reference Measurement Channels	Α	4.4.0	4.5.0	T1-020768
TP-18	TP-020293	156	-	Transferring system information definition using ASN.1 description to PRD	Α	4.4.0	4.5.0	T1-020778
	TP-020293	158	-	Correction to RLC RAB TFCS	Α	4.4.0	4.5.0	T1-020780
TP-18	TP-020293	160	-	Default Message contents : Correction from CRs approved in RP17meeting	Α	4.4.0	4.5.0	T1-020783
		162	-	Corrections to SIB1 to SIB6	Α	4.4.0	4.5.0	T1-020799
		164	-	Correction to RAB configurations as revision of T1S020756	A	4.4.0	4.5.0	T1-020801
	TP-020293	166		Parameter addition for Reference RABs based on LS from RAN2	A	4.4.0	4.5.0	T1-020803
TP-18	TP-020293	168	ı	Addition to clause 7.4 for multi call as T1S-020577rev2 (revision to T1S020820)	Α	4.4.0	4.5.0	T1-020818
		169	-	RAB Combinations for IMS Services	F	4.4.0	4.5.0	T1-020819
TP-18	TP-020293	171		Correction to Contents of the Scheduling Block System Information in clause 6.1.3.	F	4.4.0	4.5.0	T1-020844
		173	-	RAB Removal from Rel-4 TS 34.108 as T1S030002rev1	Α	4.5.0	4.6.0	T1-030037
TP-19	TP-030044	175	-	Combine all Radio Bearer Setup messages into one table	Α	4.5.0	4.6.0	T1-030040
TP-19	TP-030044	177	ı	Corrections to SB and SIB configurations in clause 6.1 as T1S030046rev1	Α	4.5.0	4.6.0	T1-030042
		179	-	Correction to TS 34.108 Rel-4 ; PAGING TYPE1 message (Packet in PS)	A	4.5.0	4.6.0	T1-030044
	TP-030044	181	ı	Clarification of authentication test algorithm and GSM cipher key	Α	4.5.0	4.6.0	T1-030046
TP-19	TP-030044	183	1	Addition of simulated network environment for inter-RAT test cases	Α	4.5.0	4.6.0	T1-030048
-		185	-	and RAC in 51.010-1.	A	4.5.0	4.6.0	T1-030050
		187	-	Addition of default inter-RAT handover messages	Α		4.6.0	T1-030052
		189	-	Correction of activation time IEs in default messages	Α	4.5.0	4.6.0	T1-030054
	TP-030044	191	-	Correction to default SECURITY MODE COMMAND message	Α	4.5.0	4.6.0	T1-030056
	TP-030044	193	-	Addition of option for UL CM only in default reference CM patterns	A	4.5.0	4.6.0	T1-030058
	TP-030044	195		Introduction of a reference RB configuration for RMC for BTFD tests (Rel4)		4.5.0	4.6.0	T1-030060
	TP-030044	197	-	Update of the RRC connection request messages in 34.108 Rel4	Α	4.5.0	4.6.0	T1-030063
	TP-030043	198	-	Introduction of Conversational PS RABs in Rel-4 TS 34.108 as T1S030003rev1	F	4.5.0	4.6.0	T1-030107
TP-19	TP-030043	200	-	Update of default parameters for 1 to 8 cell environments (TDD), clause 6.1.4, Rel-4	A	4.5.0	4.6.0	T1-030208
TP-19	TP-030043	202	-	Update of Multi-cell environment for default radio conditions (TDD), clause 6.1.6 (Inclusion of cell 4), Rel-4	А	4.5.0	4.6.0	T1-030210
		204	-	Modification to Generic Registration Procedures	Α	4.5.0	4.6.0	T1-030222
		206	<u> </u>	Update of default configurations to enable testing of low end UE	Α	4.5.0	4.6.0	T1-030228
TP-20		208	-	Reinstate parameters for Interactive or background /UL:64 kbps / PS RAB	Α	4.6.0	4.7.0	T1-030437
		210	-	Correction to Figure 7.4.1.1 (Rel-4)	Α	4.6.0	4.7.0	T1-030483
		212	-	Update of SIB 11 and 12 in clause 6.1.0b in TS 34.108 (TDD)	Α	4.6.0	4.7.0	T1-030507
		214	-	Update of Default parameters for 1 to 8 cell environments in TS 34.108 (TDD)	Α	4.6.0	4.7.0	T1-030509
TP-20	TP-030098	216	-	Correction of default messages according to 25331 CR1823	А	4.6.0	4.7.0	T1-030632

g-1st-	Doc-1st-Level	CR	Rev	Subject	Cat	Version -Current		Doc-2nd- Level
TP-20	TP-030098	218	-	Clause 8.2: Definition of default values for	A	4.6.0	4.7.0	T1-030644
TP-20	TP-030098	219		authentication key K on test USIM	۸	4.6.0	470	T1-030692
TP-20	TP-030098	221	<u> </u>	Update of Reconfiguration messages Correction to RADIO BEARER RELEASE and RRC	A A	4.6.0	4.7.0 4.7.0	T1-030692
				CONNECTION SETUP messages (Revision of T1-030569)				
TP-20	TP-030140	226	-	Correction to default SIB5 (FDD)	Α	4.6.0.	4.7.0	T1-030745
TP-21	TP-030191	228	-	CR to 34.108, Rel-4, Clarification of seg_count in 6.1.0a.3	A	4.7.0	4.8.0	T1-030827
TP-21	TP-030191	230	-	General correction in clause 7.4 for Common generic procedures for AS testing	A	4.7.0	4.8.0	T1-030976
TP-21	TP-030191	233	-	Incorrect activation time in CELL_FACH state .	A	4.7.0	4.8.0	T1-031064
TP-21 TP-21	TP-030191 TP-030191	235 237	-	Incorrect Transport channel Parameters Corrections to TS 34.108 common procedures in clause	A A	4.7.0 4.7.0	4.8.0 4.8.0	T1-031066 T1-031095
			-	7.4 of Rel-4 of TS 34.108				
TP-21	TP-030191 TP-030191	239 242	-	Removal of RLC AM in the Default Message Content	A A	4.7.0 4.7.0	4.8.0 4.8.0	T1-031151
TP-21				CR 34.108 Rel-4: Manual attach in State 7 Registered Idle Mode on CS/PS				T1-031175
TP-21	TP-030191	244	_	URA Identity in Cell Update Confirm and URA Update Confirm	A	4.7.0	4.8.0	T1-031179
TP-21	TP-030191	246	-	CR to 34.108 R4; Correction to specification to reflect a change already approved in TTCN CR T1-030396	Α	4.7.0	4.8.0	T1-031241
TP-21	TP-030191	248	<u> </u>	CR to 34.108 REL-4; Correction to clause 7.3 Test procedures for RF test	Α	4.7.0	4.8.0	T1-031251
TP-21	TP-030191	240	-	RB configuration for the support of wideband AMR speech telephony services	F	4.7.0	4.8.0	T1-031154
TP-22	TP-030279	251	1	Addition of Default message contents for TDD	F	4.8.0	4.9.0	T1-031659
TP-22	TP-030279	252	1	Addition of Default message contents for TDD	F	4.8.0	4.9.0	T1-031660
TP-22	TP-030279	253	1	Addition of Default message contents for TDD	F	4.8.0	4.9.0	T1-031661
TP-22	TP-030279	254	1	Addition of Default message contents for TDD	F	4.8.0	4.9.0	T1-031662
TP-22	TP-030279	255	1	Addition of Default message contents for TDD	F	4.8.0	4.9.0	T1-031663
TP-22	TP-030279	256	1	Addition of Default message contents for TDD	F	4.8.0	4.9.0	T1-031664
TP-22	TP-030279	257	1	Addition of Default message contents for TDD	F	4.8.0	4.9.0	T1-031665
TP-22	TP-030279	258	1	Addition of Default message contents for TDD	F	4.8.0	4.9.0	T1-031666
TP-22	TP-030279	260	2	CR on PAGING TYPE 1, RRC CONNECTION REQUEST and RRC CONNECTION SETUP messages for MT RR Connection	Α	4.8.0	4.9.0	T1-031596
TP-22	TP-030279	262		CR 34.108 Rel-4: EFRPLMNACT (RPLMN Last used Access Technology) removed	Α	4.8.0	4.9.0	T1-031381
TP-22	TP-030279	264	1	Update of default messages for RRC CONNECTION SETUP and SECURITY MODE COMMAND	Α	4.8.0	4.9.0	T1-031547
TP-22	TP-030279	266	1	Description and corrections of channels for minimum performance levels, TDD mode.	F	4.8.0	4.9.0	T1-031645
TP-22	TP-030279	268	1	Test frequencies of UMTS800MHz band VI	Α	4.8.0	4.9.0	T1-031555
TP-22	TP-030279	269		CR 34.108 Rel-4: Addition of Bearer combination for Interactive/background UL 64 kbps DL 768 kbps for Rel-5	F	4.8.0	4.9.0	T1-031441
TP-22	TP-030279	271	1	Update of generic test procedure for TX, RX and Performance Requirement	Α	4.8.0	4.9.0	T1-031610
TP-22	TP-030279	273	1	Introduction of generic test procedure for RRM handover test cases	Α	4.8.0	4.9.0	T1-031608
TP-22	TP-030279	275	1	Correction of CM TGD parameter	Α	4.8.0	4.9.0	T1-031591
TP-22	TP-030279	277	1	Corrections to default message contents of Radio Bearer Release	F	4.8.0	4.9.0	T1-031594
TP-22	TP-030279	279	1	Modification to default DPCCH_Power_offset value	Α	4.8.0	4.9.0	T1-031598
TP-22	TP-030279	283		Correction of TFCS for radio bearer combination 6.10.2.4.1.51b	A	4.8.0	4.9.0	T1-031527
TP-23	TP-040037	284	-	New Radio Bearer Setup (FDD) message for RF (Revision of T1-040258)	F	4.9.0	4.10.0	T1-040417
TP-23	TP-040037	287	-	Corrections to default message contents of RRC Connection Setup message -> 2nd change not implemented (not implementable)	А	4.9.0	4.10.0	T1-040080
TP-23	TP-040037	289	-	Correction to Default parameters for Cells 1 to 8 in MultiPLMN cell environments - Rel-4	Α	4.9.0	4.10.0	T1-040095
TP-23	TP-040037	291	-	Corrections to TDD HCR RABs	Α	4.9.0	4.10.0	T1-040103
TP-23	TP-040037	296	-	LCR Corrections to TDD RABs merge of T1-040104,	F	4.9.0	4.10.0	T1-040299
TP-23	TP-040037	298	-	T1-040201 and T1-040203 Correction to handling of Entered Parameter IE in	Α	4.9.0	4.10.0	T1-040411
TP-23	TP-040037	300	_	default contents for Initial Direct Transfer The diverse operation in TDD mode updating according	Α	4.9.0	4.10.0	T1-040368
TP-23	TP-040037	302		to the core specification correction of measurement control default message	F	4.9.0	4.10.0	T1-040300
17-23	117-040037	JUZ	ı	correction of measurement control default message	ļr	4.3.0	4.10.0	11-040370

Meetin g-1st- Level	Doc-1st-Level	CR	Rev	Subject	Cat	Version -Current		Doc-2nd- Level
Love				contents for TDD -> Not implemented (not implementable)				
TP-23	TP-040037	303	-	correction of RADIO BEARER SETUP default message contents for 1.28 Mcps TDD	F	4.9.0	4.10.0	T1-040371
TP-23	TP-040037	304	-	Correction of RADIO BEARER RELEASE default message contents for TDD: AM or UM (1.28 Mcps TDD)	F	4.9.0	4.10.0	T1-040372
TP-23	TP-040037	305	=	Contents of RRC CONNECTION SETUP message: UM (Transition to CELL_DCH) (1.28 Mcps TDD) -> Not implemented (not implementable)	F	4.9.0	4.10.0	T1-040373
TP-23	TP-040037	292	-	New I/B UL:64 DL:768 kbps PS RAB misplaced	F	4.10.0	5.0.0	T1-040109
TP-23	TP-040037	294	-		F	4.10.0	5.0.0	T1-040271
TP-23	TP-040037	295	-	Baseline radio bearer combination for HSDPA support	В	4.10.0	5.0.0	T1-040273
TP-24	TP-040112	308	=	Correction to IEs "START" and "ul_CounterSynchronisationInfo".	F	5.0.0	5.1.0	T1-040512
TP-24	TP-040112	309	=	Correction to HSDPA reference radio bearer configurations	F	5.0.0	5.1.0	T1-040522
TP-24	TP-040112	310	-	Addition of test procedure for HSDPA RF testing	F	5.0.0	5.1.0	T1-040546
TP-24	TP-040112	315	=	Corrections to default RRC messages	F	5.0.0	5.1.0	T1-040593
TP-24	TP-040112	318	=	Change of default LAC/RAC for inter-RAT test cases	Α	5.0.0	5.1.0	T1-040656
TP-24	TP-040112	319	=	Contents of Physical channel Reconfiguration message modified to incorporate transition to URA_PCH or CELL_PCH	F	5.0.0	5.1.0	T1-040673
TP-24	TP-040112	320	-	Correction of reference test frequencies for UMTS800(band VI)	F	5.0.0	5.1.0	T1-040701
TP-24	TP-040112	325	-	Update of generic setup procedures in clauses 7.3.4 and 7.3.5.	Α	5.0.0	5.1.0	T1-040754
TP-24	TP-040112	326	=	Physical channel parameters for AM RLC 7 bit Length Indicator TestCases (Rel-5)	F	5.0.0	5.1.0	T1-040902
TP-24	TP-040112	327	=	Corrections to the default contents of Security Mode Command (Rel-5)	F	5.0.0	5.1.0	T1-040903
TP-24	TP-040112	330	-	Corrections to Contents of Scheduling Block 1 (FDD)	F	5.0.0	5.1.0	T1-040909
TP-24	TP-040112	331	-	Corrections to Contents of PHYSICAL CHANNEL RECONFIGURATION message: AM or UM	F	5.0.0	5.1.0	T1-040911
TP-24	TP-040112	332	-	Corrections to Contents of RRC CONNECTION SETUP message: UM	F	5.0.0	5.1.0	T1-040913
TP-24	TP-040112	333	-	RADIO BEARER SETUP message (FDD) for Test Loop Mode2.	F	5.0.0	5.1.0	T1-040917
TP-24	TP-040112	335	-	Changes to establish one version of 34.108 covering all releases	A	5.0.0	5.1.0	T1-040931
TP-24	TP-040112	338	-	Addition of generic test procedure for AS test cases using the test loop	A	5.0.0	5.1.0	T1-040934
TP-24	TP-040112	339	-	Corrections to LCR TDD RABs	F	5.0.0	5.1.0	T1-040935
TP-25	TP-040157	343	-	Correction to generic test procedure in clause 7.4.2.6a.	F	5.1.0	5.2.0	T1-041040
TP-25	TP-040157	344	-	Addition of default messages for Signalling (FDD)	F	5.1.0	5.2.0	T1-041044
TP-25	TP-040157	345	-	Minor change to terminology in SRB tables of clause 6.10	F	5.1.0	5.2.0	T1-041140
TP-25	TP-040157	346	-	Default Message Content for System Information Block type 5 (FDD) and type 6 (FDD)	F	5.1.0	5.2.0	T1-041154
TP-25	TP-040157	347	-	Corrections to DCCH Transport channel Parameters for HSDPA RAB	D	5.1.0	5.2.0	T1-041171
TP-25	TP-040157	348	_	Corrections to clause 9	F	5.1.0	5.2.0	T1-041223
TP-25	TP-040157	349	-	Corrections to HCR TDD RAB combinations	F	5.1.0	5.2.0	T1-041235
TP-25	TP-040157	350	-	Adding missing clause 6.10.2.4.1.62.1	F	5.1.0	5.2.0	T1-041252
TP-25	TP-040157	351	-	Modification of AICH power offset in SysInfo 5 and 6.	F	5.1.0	5.2.0	T1-041253
TP-25	TP-040157	352	-	Correction to Default Message Content for Radio Bearer Setup Message.		5.1.0	5.2.0	T1-041259
TP-25	TP-040157	353	-	Correction to Default Message Content for Radio Bearer Reconfiguration Message for Condition A6		5.1.0	5.2.0	T1-041266
TP-25	TP-040157	354	_	CR to 34.108: introduction of default RB SETUP message from cell_FACH state for HSDPA	F	5.1.0	5.2.0	T1-041298
TP-25	TP-040157	355	-	Corrections to Contents of RADIO BEARER SETUP message: BTFD RMC	F	5.1.0	5.2.0	T1-041317
TP-25	TP-040157	340	-	Resolution of downlink code conflict between OCNS DPCH and S-CCPCH	F	5.1.0	5.2.0	T1-041327
TP-25	TP-040157	361	-	Correction to test procedure for test cases using Cell_PCH or URA_PCH state	F	5.1.0	5.2.0	T1-041346
TP-25	TP-040157	362	1-	Removal of DCCH dummy transmission for RF testing	F	5.1.0	5.2.0	T1-041350
TP-25	TP-040157	341	-	Correct title to test procedure for test cases using Cell_PCH or URA_PCH state	F	5.1.0	5.2.0	T1-041354
TP-25	TP-040157	363	-	Addition of intra frequency cell to cell environments	F	5.1.0	5.2.0	T1-041356
TP-25	TP-040157	342	-	Correct primary scrambling code usage in default	F	5.1.0	5.2.0	T1-041365

Meetin g-1st- Level	Doc-1st-Level	CR	Rev	Subject	Cat	Version -Current	Version -New	Doc-2nd- Level
				message contents in clause 9.2.1				
	TP-040157	356	-	HSDPA downlink code allocation	F	5.1.0	5.2.0	T1-041374
TP-25	TP-040157	357	-	Correction to test procedure for test cases using CELL_FACH state	F	5.1.0	5.2.0	T1-041376
TP-25	TP-040157	358	-	Varying DPCH Power Offset according to data transmission rate	F	5.1.0	5.2.0	T1-041416
TP-25	TP-040157	359	-	Corrections to default message for RADIO BEARER SETUP message in clause 9.2.1 (HSDPA RF)	F	5.1.0	5.2.0	T1-041418
TP-25	TP-040157	360	-	Test SIB schedule for two S-CCPCH or two PRACH in 34.108	F	5.1.0	5.2.0	T1-041422
TP-25	TP-040157	364	-	Correction to Default Message Content for Radio Bearer Setup Message re: RM Attribute values	F	5.1.0	5.2.0	T1-041433
TP-26	TP-040233	365	-	CR to 34.108 Rel-5:Correction to default value of Qrxlevmin	F	5.2.0	5.3.0	T1-041532
TP-26	TP-040233	366	-	CR to 34.108 Rel-5: Corrections of the values in 6.11.5.4 for LCR TDD	F	5.2.0	5.3.0	T1-041573
TP-26	TP-040233	367	-	Alignment of Prose to TTCN for SCH power level	F	5.2.0	5.3.0	T1-041584
TP-26	TP-040233	368	-	Addition of new HSDPA RAB configurations with UL 64 kbps	F	5.2.0	5.3.0	T1-041651
TP-26	TP-040233	369	-	Correction to initial conditions and references in clause 7.3	F	5.2.0	5.3.0	T1-041654
TP-26	TP-040233	370	-	Introduction of reference radio bearer combination for PS streaming and downlink rate up to 128 kbps	F	5.2.0	5.3.0	T1-041685
TP-26	TP-040233	371	-	Correction of clause 6.1 (Simulated network environment)	F	5.2.0	5.3.0	T1-041686
TP-26	TP-040233	372	-	Correction to generic Call Setup procedure for mobile terminating circuit switched calls	F	5.2.0	5.3.0	T1-041699
TP-26	TP-040233	373	-	CR to 34.108 Rel-5; Corrections to the default RADIO BEARER SETUP message for HSDPA	F	5.2.0	5.3.0	T1-041754
TP-26	TP-040233	374	-	Physical layer multiplexing configuration in case of AMR and two PS RABs	F	5.2.0	5.3.0	T1-041801
TP-26	TP-040233	375	<u> </u>	Addition of new HSDPA RAB configurations	F	5.2.0	5.3.0	T1-041802
TP-26	TP-040233	376	-	Introduction of information for tests for Performance requirements for A-GPS.	В	5.2.0	5.3.0	T1-041850
TP-26	TP-040233	377	-	Introduction of UMTS-850 MHz band V	F	5.2.0	5.3.0	T1-041874
TP-26	TP-040233	378	-	CR to TS 34.108 Rel-5; Adding a new test condition for RADIO BEARER RELEASE Procedure (Revision of T1-041716).	F	5.2.0	5.3.0	T1-041933
TP-26	TP-040233	379	-	Update of Reference Radio Bearer for Conversational / speech / UL:5.9 DL:5.9 kbps / CS RAB for DL SF=256	F	5.2.0	5.3.0	T1-041942
TP-26	TP-040233	380	-	CR to 34.108: Correction to the maximum bit rate for HS-PDSCH	F	5.2.0	5.3.0	T1-041943
TP-26	TP-040233	381	-	Alignment of Prose to TTCN for RRC Connection Release (Cell DCH state) and RRC Connection Setup Message (Cell FACH State).	F	5.2.0	5.3.0	T1-041965
TP-27	TP-050032	382	-	Updates from core specification changes	F	5.3.0	5.4.0	T1-050095
TP-27	TP-050032	383	-	Correction to Hand over test procedure in CELL_DCH	F	5.3.0	5.4.0	T1-050350
TP-27	TP-050032	384	-	CR to 34.108: Changes to test frequencies for UMTS 850 Band	В	5.3.0	5.4.0	T1-050380
TP-27	TP-050032	385	<u> - </u>	Correction to default SIB configurations	F	5.3.0	5.4.0	T1-050019
TP-27	TP-050032	386	[-	Editorial corrections in HSDPA RAB configurations 6.10.2.4.5.2 and 6.10.2.4.5.4.	D	5.3.0	5.4.0	T1-050052
TP-27	TP-050032	387	-	CR to 34.108 Rel-5: Update to the contents of PHYSICAL CHANNEL RECONFIGURATION message for 1.28 Mcps TDD	F	5.3.0	5.4.0	T1-050064
TP-27	TP-050032	388	-	CR to 34.108 Rel-5: Update to the contents of TRANSPORT CHANNEL RECONFIGURATION message for 1.28 Mcps TDD	F	5.3.0	5.4.0	T1-050065
TP-27	TP-050032	389	-	CR to 34.108 Rel-5: Update to the contents of RRC CONNECTION REQUEST message for TDD	F	5.3.0	5.4.0	T1-050066
TP-27	TP-050032	390	-	Correction to the HSDPA RB Identity in Radio Bearer Setup & Radio Bearer Release message contents	F	5.3.0	5.4.0	T1-050072
TP-27	TP-050032	391	-	CR to TS 34.108 v5.3.0 - Correction to Default RADIO BEARER RELEASE message (FDD)	F	5.3.0	5.4.0	T1-050202
TP-27	TP-050032	392	-	Addition of reference radio bearer configuration for MAC-hs testing	F	5.3.0	5.4.0	T1-050239
TP-27	TP-050032	393	-	CR to 34.108 Rel-5: Update to the contents of RRC CONNECTION REQUEST message for TDD	F	5.3.0	5.4.0	T1-050295
TP-27	TP-050032	394	-	CR to 34.108 Rel-5: Update to the contents of Default System Information Block Messages for TDD	F	5.3.0	5.4.0	T1-050296
TP-27	TP-050032	395	1-	CR to 34.108 Rel-5: Add the contents of SIB 5 & 6 for HCR TDD	F	5.3.0	5.4.0	T1-050297

Meetin g-1st- Level	Doc-1st-Level	CR	Rev	Subject	Cat	Version -Current		Doc-2nd- Level
TP-27	TP-050032	396	-	Correction to TFCS ordering	F	5.3.0	5.4.0	T1-050451r1
TP-27	TP-050032	397	-	Addition of GPS scenario and A-GPS assistance data values for signalling tests to 34.108	F	5.3.0	5.4.0	T1-050458
TP-27	TP-050032	398	-	CR to TS 34.108 Rel-5; Correction to the physical channel parameters (Revison of T1-050176)	F	5.3.0	5.4.0	T1-050469
RP-28	RP-050267	399	-	Additional call setup procedures for inter RAT RRM testing	F	5.4.0	5.5.0	R5-050618
RP-28	RP-050267	400	-	CR to 34.108: Correction to RADIO BEARER SETUP message for BTFD RMC	F	5.4.0	5.5.0	R5-050704
RP-28	RP-050267	401	-	CR to 34.108: Correction to reference radio conditions for GSM	F	5.4.0	5.5.0	R5-050811
RP-28	RP-050267	402	-	Addition of RADIO BEARER SETUP Messages for Auxiliary Measurement	F	5.4.0	5.5.0	R5-050856
RP-28	RP-050267	404	-	CR 34.108 Addition of specific message content to A-GPS performance test procedures in clause 7.5	F	5.4.0	5.5.0	R5-050709
RP-28	RP-050267	405	-	CR to 34.108 Rel-5: Clarification of generic setup procedures in section 7.3.4	F	5.4.0	5.5.0	R5-050663
RP-28	RP-050267	406	-	Removal of TGPL2	F	5.4.0	5.5.0	R5-050513
RP-28	RP-050267	407	-	Addition of compressed mode pattern for Inter Frequency FDD measurement & Inter RAT measurement GSM	F	5.4.0	5.5.0	R5-050525
RP-28	RP-050267	408	-	Correction to MIB, PLMN and Cell Value Tag Value Definition to 34.108	F	5.4.0	5.5.0	R5-050608
RP-28	RP-050267	409	-	CR to 34.108 Rel-5: Corrections to the contents of System Information Block type 11 (3.84 Mcps and 1.28 Mcps TDD) in section 6.1.0b	F	5.4.0	5.5.0	R5-050613
RP-28	RP-050267	410	-	CR to 34.108 Rel-5: Corrections to the usage of "Cell info" IE in System Information Block type 11 in section 6.1.4 for TDD cell	F	5.4.0	5.5.0	R5-050619
RP-28	RP-050267	411	-	CR to 34.108 Rel-5: Corrections to the contents of System Information Block type 5 (1.28 Mcps TDD)	F	5.4.0	5.5.0	R5-050620
RP-28	RP-050267	412	-	Update to clause 8 Test USIM Parameters	F	5.4.0	5.5.0	R5-050638
RP-28	RP-050267	413	-	CR to 34.108 Rel-5: Update of SIB3, SIB4, SIB11 and SIB12 for TDD in section 6.1.0b	F	5.4.0	5.5.0	R5-050662
RP-28	RP-050267	414	-	CR to 34.108: Correction to TFCS	F	5.4.0	5.5.0	R5-050677
RP-28	RP-050267	415	-	CR to TS34.108 Rel-5; Correction to the physical channel parameter	F	5.4.0	5.5.0	R5-050724
RP-28	RP-050267	416	-	Correction to default SIB configurations	F	5.4.0	5.5.0	R5-050947
RP-28	RP-050267	417	-	CR to 34.108: Missing Rel-5 IE"s in the default Radio Bearer Setup message at section 9.1.1.	F	5.4.0	5.5.0	R5-050600
RP-28	RP-050267	418	-	CR to TS34.108 Rel-5; Clarification of the reference TFCS for three RB multiplexing option (condition A9)	F	5.4.0	5.5.0	R5-050913
	RP-050268	419	-	Addition of new HSDPA Streaming RAB configurations	F	5.4.0	5.5.0	R5-050880
	RP-050268	420	-	CR to 34.108 Rel-5: Content Correction of RRC CONNECTION SETUP message for LCR TDD in 9.1.2		5.4.0	5.5.0	R5-050585
RP-28	RP-050268	421	-	Add Default RADIO BEARER RELEASE message (3.84 Mcps TDD) Add Default Contents of RADIO BEARER	F	5.4.0	5.5.0 5.5.0	R5-050680
RP-28	RP-050268	422	_	RECONFIGURATION COMPLETE message: AM (3.84 Mcps TDD)		5.4.0		R5-050681
RP-28	RP-050268	423	-	Add Default Contents of RADIO BEARER RECONFIGURATION message: AM or UM (3.84 Mcps TDD)	F	5.4.0	5.5.0	R5-050682
RP-28	RP-050268	424	-	Add Default Contents of PHYSICAL CHANNEL RECONFIGURATION message: AM or UM (3.84 Mcps TDD)	F	5.4.0	5.5.0	R5-050683
RP-28	RP-050268	425	-	Add Default Contents of PHYSICAL CHANNEL RECONFIGURATION COMPLETE message: AM (3.84 Mcps TDD)	F	5.4.0	5.5.0	R5-050684
RP-28	RP-050268	426	-	Add Default Contents of TRANSPORT CHANNEL RECONFIGURATION message: AM or UM (3.84 Mcps TDD)	F	5.4.0	5.5.0	R5-050685
RP-28	RP-050268	427	-	Add Default Contents of TRANSPORT CHANNEL RECONFIGURATION COMPLETE message: AM (3.84 Mcps TDD)	F	5.4.0	5.5.0	R5-050686
RP-28	RP-050268	428	-	Add Default Contents of MEASUREMENT REPORT message: AM (intra/inter-frequency measurement (3.84	F	5.4.0	5.5.0	R5-050956
RP-28	RP-050268	430	-	Mcps TDD) Correction to RADIO BEARER SETUP message for HSDPA RF testing	F	5.4.0	5.5.0	R5-050879
RP-28	RP-050349	403	-	Addition of GPS scenario and assistance data for A-GPS performance tests in 34.108	В	5.4.0	5.5.0	R5-050836

Meetin g-1st- Level	Doc-1st-Level	CR	Rev	Subject	Cat	Version -Current		Doc-2nd- Level
RP-28	RP-050350	429	-	Corrections to section 10.7 and GPS data file for 34.108	F	5.4.0	5.5.0	R5-050969
RP-29	RP-050600	431	-	Feature Clean Up: Removal of DRAC from section 9 of 34.108	F	5.5.0	6.0.0	R5-051312
RP-29 RP-29	RP-050600 RP-050600	432 433	-	Feature Clean Up: Removal of SSDT from 34.108 Feature Clean Up: Removal of 80 ms TTI for DCH for all	F F	5.5.0 5.5.0	6.0.0 6.0.0	R5-051356 R5-051379
RP-29	RP-050600	434	-		С	5.5.0	6.0.0	R5-051543
RP-29	RP-050600	435	-		С	5.5.0	6.0.0	R5-051544
RP-29	RP-050600	436	-	34.108 Feature Clean Up: Removal of CPCH from section 7 & 8	С	5.5.0	6.0.0	R5-051545
RP-29	RP-050600	437	-	of 34.108 Feature Clean Up: Removal of CPCH from section 9 of 34.108	С	5.5.0	6.0.0	R5-051546
RP-29	RP-050600	438	-	Feature Clean Up: Removal of DSCH (FDD mode) from 34.108	F	5.5.0	6.0.0	R5-051548
RP-29	RP-050600	439	-	Modification to PS setup procedure for inter RAT RRM testing	F	5.5.0	6.0.0	R5-051161
RP-29	RP-050600	440	-	CR to 34.108: RRC CONNECTION SETUP exception for HSDPA testing	F	5.5.0	6.0.0	R5-051430
RP-29	RP-050600	441	-	CR to 34.108: Correction to the RADIO BEARER SETUP message for HSDPA testing	F	5.5.0	6.0.0	R5-051112
RP-29	RP-050512	442	-		F	5.5.0	6.0.0	R5-051076
RP-29	RP-050514	443	-	CR to 34.108 Rel-5: Correction of contents of RADIO BEARER SETUP message: AM or UM (1.28 Mcps TDD) in 9.2.2	F	5.5.0	6.0.0	R5-051212
RP-29	RP-050514	444	-	CR to 34.108 Rel-5: SIB default schedule in 6.1.0a - Default Master Information Block and Scheduling Block messages	F	5.5.0	6.0.0	R5-051213
RP-29	RP-050514	445	-	CR to 34.108 Rel-5: Corrections to the IE'Midamble shift and burst type' of System Information Block type 5/6 (3.84Mcps TDD) in section 6.1.0b	F	5.5.0	6.0.0	R5-051222
RP-29	RP-050514	446	-	CR to 34.108 Rel-5: Corrections to the contents of System Information Block type 5 (3.84 Mcps TDD) in section 6.1.1	F	5.5.0	6.0.0	R5-051344
RP-29	RP-050514	447	-	CR to 34.108 Rel-5: Corrections to the value of Sintrasearch and Sintersearch in 'Cell selection and reselection quality measure' of System Information Block type 3/4 (1.28Mcps TDD and 3.84Mcps TDD) in section 6.1.0b	F	5.5.0	6.0.0	R5-051536
RP-29	RP-050600	448	-	Use "Same as UL" for the Added or Reconfigured DL TrCH information of the added or reconfigured PS RAB	F	5.5.0	6.0.0	R5-051041
RP-29	RP-050600	449	-		F	5.5.0	6.0.0	R5-051044
RP-29	RP-050600	450	-	Corrections to default parameters of UL:384kbps PS Bearer	F	5.5.0	6.0.0	R5-051058
RP-29	RP-050600	451	-	Correction to NB AMR Radio Bearer Configurations	F	5.5.0	6.0.0	R5-051318
RP-29	RP-050600	452	-	Correction to default contents of Cell Update and Initial Direct transfer message for Rel-5	F	5.5.0	6.0.0	R5-051325
RP-29	RP-050600	453	-	Correction to DPCCH Power Offset IE in default contents for RRC Connection Setup and Radio Bearer Setup message	F	5.5.0	6.0.0	R5-051365
RP-29	RP-050515	454	-	Using Test USIM for VSTK generation of VGCS/VBS ciphering	В	5.5.0	6.0.0	R5-051553
RP-29	RP-050600	455	-	Correction to default contents of RADIO BEARER SETUP MESSAGE for the IE 'Number of Processes'	F	5.5.0	6.0.0	R5-051324
RP-29	RP-050600	456	-	Correction of DL channelisation code in RADIO BEARER SETUP for HSDPA configurations	F	5.5.0	6.0.0	R5-051345
RP-29	RP-050513	457	-	Clarifiation of reference radio bearer configuration for MAC-hs test case 7.1.5.2.	F	5.5.0	6.0.0	R5-051164
RP-29	RP-050600	458	-	Replacement of the technical content of 34.108 Rel-5 by a pointer to Rel-6 document		5.5.0	6.0.0	R5-051584
RP-29	RP-050600	459	-	Introduction of HSDPA + Wideband AMR radio bearer combination	F	5.5.0	6.0.0	R5-051588
RP-29	RP-050600	460	-	34.108	F	5.5.0	6.0.0	R5-051311
RP-30	RP-050767	461	-	Correction to 34.108: RF Radio Bearer setup message for HSDPA testing	F	6.0.0	6.1.0	R5-052320
RP-30	RP-050720	462	-	Changes, additions and corrections to GPS scenarios and assistance data in TS 34.108	F	6.0.0	6.1.0	R5-052017
RP-30	RP-050716	463		Generic test procedure for EDCH RF testing	F	6.0.0	6.1.0	R5-052345

Meetin	Doc-1st-Level	CR	Rev	Subject	Cat	Version	Version	Doc-2nd-
g-1st- Level						-Current		Level
	RP-050769	464	-	Correction of UE test states for RF testing.	F	6.0.0	6.1.0	R5-052302
RP-30	RP-050769	465	-	Removal of temporary BLER measurement configuration	F	6.0.0	6.1.0	R5-051933
RP-30	RP-050780	466	-	Introduction of UMTS1700 for TS34.108	В	6.0.0	6.1.0	R5-052329
RP-30	RP-050767	467	-	Re-definition of reference radio bearer configuration for MAC-hs test case 7.1.5.2	F	6.0.0	6.1.0	R5-051857
RP-30	RP-050767	468	-	Introduction of additional HSDPA radio bearer combination	F	6.0.0	6.1.0	R5-052159
RP-30	RP-050717	469	-	CR to 34.108; Correction to default message content in INITIAL DIRECT TRANSFER	F	6.0.0	6.1.0	R5-052179
RP-30	RP-050716	470	-	CR to 34.108 Rel-6; Generic Setup Procedure and Default RRC Messages for Enhanced Uplink Tests	F	6.0.0	6.1.0	R5-052192
RP-30	RP-050716	471	-	Generic reference bearer radio configurations for E-	F	6.0.0	6.1.0	R5-052167
RP-30	RP-050716	472	-	DCH testing Addition of basic radio bearer combinations for E-DCH	F	6.0.0	6.1.0	R5-052144
RP-30	RP-050718	473	-	testing CR to TS34.108; Correction to the default system	F	6.0.0	6.1.0	R5-052145
DD 00	DD 050700	47.4		information block type3 for DSAC	_	0.0.0	0.4.0	DE 054040
RP-30 RP-30	RP-050769 RP-050769	474 475	-	Editorial corrections to TS 34.108 Removal of deprecated values from the default contents	D F	6.0.0	6.1.0 6.1.0	R5-051840 R5-051848
KF-30	KF-050769	475	-	for RRC Connection Setup (Cell FACH) and RRC Connection Release (Cell DCH) messages.		6.0.0	6.1.0	K3-031646
RP-30	RP-050769	476	-	Correction to the default RRC message contents for the IE 'UARFCN uplink (Nu)'	F	6.0.0	6.1.0	R5-052155
RP-30	RP-050769	477	=	Correction of references to IB UL:8 DL:8 kbps transport channel parameters in reference radio bearer configuration 6.10.2.4.1.58a	F	6.0.0	6.1.0	R5-051858
RP-30	RP-050769	478	-	Correction of UE states tables for Generic setup procedures.	F	6.0.0	6.1.0	R5-051942
RP-30	RP-050769	479	-	Corrections to default message contents of "HANDOVER FROM UTRAN COMMAND-GSM"	F	6.0.0	6.1.0	R5-051955
DD 20	DD 050770	400		message.	_	0.0.0	0.4.0	DE 050470
RP-30 RP-30	RP-050776 RP-050769	480 481	-	Addition of multi-rate AMR-NB configuration with SRB#5 Proposed CR to 34.108 [R6 version, R99 affected] to	F	6.0.0	6.1.0 6.1.0	R5-052176 R5-052055
111 00	111 000700	701		change slot format for AMR 5.9 mono rate RAB	ľ	0.0.0	0.1.0	110 002000
RP-30	RP-050769	482	-	Correction to puncturing limit in radio bearer configuration 6.10.2.4.1.38a	F	6.0.0	6.1.0	R5-052096
RP-30	RP-050777	483	-	Introduction of third RAB sublfow to WB-AMR test configurations	F	6.0.0	6.1.0	R5-052140
RP-30	RP-050833	484	-	Correction to RADIO BEARER SETUP message for HSDPA RF testing	F	6.0.0	6.1.0	-
RP-30	RP-050832	485	-	Correction to test procedure for HSDPA RF testing	F	6.0.0	6.1.0	-
				2006-01: Editorial conversion to make file compatible with Word 2000.		6.1.0	6.1.1	
RP-31	RP-060154	486	-	Corrections to GPS data files for signalling tests.	F	6.1.1	6.2.0	R5-060522
RP-31	RP-060163	487	-	Corrections for reference RABs	F	6.1.1	6.2.0	R5-060273
RP-31	RP-060144	488	-	Corrections to the RADIO BEARER SETUP message for Enhanced uplink	F	6.1.1	6.2.0	R5-060335
RP-31	RP-060150	489	-	Correction to default message content in INITIAL DIRECT TRANSFER	F	6.1.0	6.2.0	R5-060396
RP-31	RP-060154	490	-	Corrections to default message contents for signaling	F	6.1.1	6.2.0	R5-060274
RP-31	RP-060163	491	-	Update of RB configuration 6.10.2.4.1.4b to increase test coverage for multi-mode AMR configurations	F	6.1.1	6.2.0	R5-060122
RP-31	RP-060144	492	-	Correction of UE RRC states table for common procedures (section 7.4.1)	F	6.1.1	6.2.0	R5-060268
RP-31	RP-060154	493	-	Correction to DPCCH power offset value in RADIO BEARER SETUP messages	F	6.1.1	6.2.0	R5-060459
RP-31	RP-060153	494	-	Introduction of Band VII and Band VIII to TS34.108 Chapter 5 and introduction of new UARFCN scheme	F	6.1.1	6.2.0	R5-060440
RP-31	RP-060154	495	-	Clarification of RB Test Mode State for RF testing	F	6.1.1	6.2.0	R5-060446
RP-31	RP-060144	496	-	Common message content for E-DCH RF testing	F	6.1.1	6.2.0	R5-060439
RP-31	RP-060144	497	<u> </u>	Generic test procedure for E-DCH RF testing	F	6.1.1	6.2.0	R5-060438
RP-31	RP-060166	498	-	Correction to GPS Assistance Data for Performance tests	F	6.1.1	6.2.0	R5-060007
RP-31	RP-060154	499	-	Corrections to default message contents for RF	F	6.1.1	6.2.0	R5-060257
RP-31	RP-060163	500	-	Adding of RB Configuration 6.11.4b to clause 6.11 to increase test coverage for Interactive or background PS	F	6.1.1	6.2.0	R5-060571
RP-32	RP-060331	501	-	RAB UL 0kbps/DL 0kbps. Addition of release information to A-GPS	F	6.2.0	6.3.0	R5-061454
				MEASUREMENT CONTROL message IEs				
RP-32	RP-060331	502	 -	Change to altitude of simulated UE position	F F	6.2.0	6.3.0	R5-061410
RP-32	RP-060331	503	<u> -</u>	Clarification of A-GPS simulated satellites	F	6.2.0	6.3.0	R5-061223

Meetin g-1st- Level	Doc-1st-Level	CR	Rev	Subject	Cat	Version -Current	Version -New	Doc-2nd- Level
	RP-060337	504	-	Clarification to loopback on HSDPA call set up procedure	F	6.2.0	6.3.0	R5-061046
RP-32	RP-060337	505	-	Removal of alternative procedure for HSDPA RF testing	F	6.2.0	6.3.0	R5-061212
RP-32	RP-060337	506	-	Removal of alternative RB Setup message for HSDPA RF testing	F	6.2.0	6.3.0	R5-061213
RP-32	RP-060338	507	-	CR for 34.108:Addition of RADIO BEARER SETUP default message contents for LCR TDD HSDPA RF testing	F	6.2.0	6.3.0	R5-061438
RP-32	RP-060332	508	-	Correction to RB setup message for E-DCH	F	6.2.0	6.3.0	R5-061443
RP-32	RP-060334	509	-	CR to 34.108: Addition of band IV to test frequencies for UMTS 1.7/2.1 GHz		6.2.0	6.3.0	R5-061188
RP-32	RP-060 336	510	-	Addition of radio bearer setup and release for HCR HSDPA testing to 34.108	F	6.2.0	6.3.0	R5-061148
RP-32	RP-060337	511	-	HS-SCCH and HS-PDSCH power levels in signaling tests	F	6.2.0	6.3.0	R5-061207
RP-32	RP-060338	512	-	CR for 34.108:Addition of the combinations on DPCH and HS-PDSCH for LCR TDD	F	6.2.0	6.3.0	R5-061310
RP-32	RP-060338	513	-	CR for 34.108:Correction of RADIO BEARER SETUP default message contents for LCR TDD HSDPA	F	6.2.0	6.3.0	R5-061053
RP-32	RP-060338	514	-	CR for 34.108:Correction of RADIO BEARER RELEASE default message contents for LCR TDD HSDPA	F	6.2.0	6.3.0	R5-061054
RP-32	RP-060332	515	-	Corrections to the default RADIO BEARER SETUP message for Enhanced uplink	F	6.2.0	6.3.0	R5-061314
RP-32	RP-060332	516	-	Generalize E-DCH radio bearer names and correction to section numbering for 6.10.2.4.6.3.2.1.1.2.	F	6.2.0	6.3.0	R5-061315
RP-32	RP-060332	517	-	Addition of conversational radio bearer combinations for E-DCH/HS-DSCH testing	F	6.2.0	6.3.0	R5-061266
RP-32	RP-060332	518	-	E-HICH/E-RGCH and E-AGCH codes used in Radio Bearer Setup for signaling	F	6.2.0	6.3.0	R5-061386
RP-32	RP-060332	519	-	Introduction of additional WB-AMR RAB combination for E-DCH/HS-DSCH testing	F	6.2.0	6.3.0	R5-061339
RP-32	RP-060336	520	-	Addition of combinations on DPCH and HS-DSCH for HCR to 34.108	F	6.2.0	6.3.0	R5-061149
RP-32	RP-060322	521	-	Corrections to the values for IE based on calculated ASN.1 value to 34.108 clause 9	F	6.2.0	6.3.0	R5-061369
RP-32	RP-060328	522	-		F	6.2.0	6.3.0	R5-061392
RP-32	RP-060322	523	-	Correction to specific message contents for UE Capability Information confirm message	F	6.2.0	6.3.0	R5-061139
RP-32	RP-060322	524	-	Corrections to the values for IE based on calculated ASN.1 value to 34.108 clause 6	F	6.2.0	6.3.0	R5-061281
RP-32	RP-060322	525	-	Addition of a new section for downlink physical channels code allocation for signalling in FDD	F	6.2.0	6.3.0	R5-061385
RP-33	RP-060560	526	-	Editorial changes in 34.108	F	6.3.0	6.4.0	R5-062092
	RP-060549	527	-	CR to 34.108. Correction of reference test frequencies for UMTS800 (Band VI)	F	6.3.0	6.4.0	R5-062440
RP-33	RP-060549	528	-	Correction to SIB11 in 6.1	F	6.3.0	6.4.0	R5-062427
RP-33	RP-060549	529	-	Correction to SECURITY MODE COMMAND message in 9.2.1	F	6.3.0	6.4.0	R5-062403
RP-33	RP-060562	530	-	testing	F	6.3.0	6.4.0	R5-062208
RP-33	RP-060568	531	-	CR to 34.108: Correction the contents of RADIO BEARER SETUP message: AM or UM (1.28 Mcps TDD)	F	6.3.0	6.4.0	R5-062511
RP-33	RP-060566	532	-	Addition of HSDPA cases to radio bearer setup and radio bearer release in section 9.1.2	F	6.3.0	6.4.0	R5-062253
RP-33	RP-060567	533	-	Corrections to the default PHYSICAL CHANNEL RECONFIGURATION message	F	6.3.0	6.4.0	R5-062291
RP-33	RP-060567	534	=		F	6.3.0	6.4.0	R5-062544
RP-33	RP-060562	535	-	Corrections to the default RADIO BEARER SETUP message	F	6.3.0	6.4.0	R5-062320
RP-33	RP-060562	536	-	New Test RABS for MAC-E/Es test cases	F	6.3.0	6.4.0	R5-062328
RP-33	RP-060562	537	-	Correction to radio bearer configuration 6.10.2.4.6 and 6.10.2.4.8	F	6.3.0	6.4.0	R5-062199
RP-33	RP-060562	538	-	Correction to 34.108 Section 9.1 : Corrections to Radio Bearer Setup for A12	F	6.3.0	6.4.0	R5-062348
RP-33	RP-060549	539	<u>-</u>	Clarification to section 6.10 and 6.11	F	6.3.0	6.4.0	R5-062194
RP-33	RP-060549	540	-	Correction to 34.108 Section 6.1 : Inclusion of System	F	6.3.0	6.4.0	R5-062398
DD 22	DD 000540	E 1 1		Information Block Type 5bis	_	6 2 0	6.4.0	DE 000050
RP-33	RP-060549	541	1	Corrections to maximum data rate for combinations on	F	6.3.0	6.4.0	R5-062350

Meetin g-1st- Level	Doc-1st-Level	CR	Rev	Subject	Cat	Version -Current		Doc-2nd- Level
Level				PRACH (FDD)				
RP-34	RP-060739	542	-	Assistance Data change for A-GPS Minimum Performance Test	F	6.4.0	6.5.0	R5-063400
RP-34	RP-060731	543	-	Correction to SECURITY MODE COMMAND message in 9.2.2	F	6.4.0	6.5.0	R5-063296
RP-34	RP-060735	544	-	Addition of PAGING TYPE 2 message in 9.2	F	6.4.0	6.5.0	R5-063401
RP-34	RP-060731	545	-	Correction to RADIO BEARER SETUP message in 9.2	F	6.4.0	6.5.0	R5-063402
RP-34	RP-060743	546	-	Correction to the set of Reference E-TFCIs in RB Setup default message (RF)	F	6.4.0	6.5.0	R5-063233
RP-34	RP-060731	547	-	Correction the Default System Information Block type6 Messages in 6.1.0b	F	6.4.0	6.5.0	R5-063294
RP-34	RP-060743	548	-	CR to 34.108, correction of RADIO BEARER SETUP for EDCH	F	6.4.0	6.5.0	R5-063545
RP-34	RP-060743	549	-	Correction to the set of Reference E-TFCIs in RB Setup default message (SIG)	F	6.4.0	6.5.0	R5-063240
RP-34	RP-060750	550	-	Introduction of radio bearers for MTCH	F	6.4.0	6.5.0	R5-063543
RP-34	RP-060749	551	-	Introduction of FDD interband testing in TS 34.108	F	6.4.0	6.5.0	R5-063255
RP-34	RP-060735	552	-	Correction to Radio Bearer Setup message –Mac-hs reset indicator	F	6.4.0	6.5.0	R5-063339
RP-34	RP-060731	553	-	CR to 34.108, Add MCC value for Band VI test	F	6.4.0	6.5.0	R5-063340
RP-34	RP-060731	554	-	CR to 34.108, Modify MCC value in IMSI of test USIM for Band VI test	F	6.4.0	6.5.0	R5-063341
RP-34	RP-060731	555	-	Correction to default content for System Information Block Type 7	F	6.4.0	6.5.0	R5-063079
RP-34	RP-060731	556	-	Clarification of FDD test channels used for signaling test cases		6.4.0	6.5.0	R5-063260
RP-35	RP-070111	557		34.108 v6.6.0 pointer to Release 7 version	F	6.5.0	7.0.0	R5-070338
RP-35	RP-070105	558		Correction of IE 'DL UM RLC LI size' in RF default messages for HSDPA	F	6.5.0	7.0.0	R5-070548
RP-35	RP-070096	559		Signalled Reference E-TFCIs for E-DCH RF tests	F	6.5.0	7.0.0	R5-070113
RP-35	RP-070096	560		Correction to RB setup message used for E-DCH tests	F	6.5.0	7.0.0	R5-070221
RP-35	RP-070096	561		Correction of IE 'DL UM RLC LI size' in RF default messages for E-DCH	F	6.5.0	7.0.0	R5-070549
RP-35	RP-070090	562		Generic test procedure for MBMS RF test case	F	6.5.0	7.0.0	R5-070553
RP-35	RP-070094	563		Introduction of FDD Mode Test frequencies for Operating Band X (Extended 1.7/2.1 GHz)	F	6.5.0	7.0.0	R5-070160
RP-35	RP-070094	564		Introduction of FDD Band X (Extended 1.7/2.1 GHz) to Contents of System Information Block type 5bis	F	6.5.0	7.0.0	R5-070161
RP-35	RP-070104	565		Correction to contents of System Information Block type 5 (1.28 Mcps TDD)	F	6.5.0	7.0.0	R5-070109
RP-35	RP-070104	566		Remove DCH information from RRC Connection Setup message to Cell_FACH state	F	6.5.0	7.0.0	R5-070353
RP-35	RP-070096	567		Corrections to 34.108 Radio Bearer Setup Message: AM or UM	F	6.5.0	7.0.0	R5-070038
RP-35	RP-070096	568		Introduction of radio bearers for Stand-alone SRBs for DCCH on E-DCH and HS-DSCH	F	6.5.0	7.0.0	R5-070356
RP-35	RP-070096	569		Introduction of RRC Connection setup message for Stand-alone SRBs for DCCH on E-DCH and HS-DSCH	F	6.5.0	7.0.0	R5-070357
RP-35	RP-070086	570		MBMS test - MCCH configurations	F	6.5.0	7.0.0	R5-070429
RP-35	RP-070086	571		Generic setup procedures and default values for MBMS signalling testing	F	6.5.0	7.0.0	R5-070422
RP-35	RP-070086	572	ļ	Introduction of signalling radio bearer for MCCH	F	6.5.0	7.0.0	R5-070147
RP-36	RP-070360	573		Definition of MCCH default message content	F	7.0.0	7.1.0	R5-071469
RP-36	RP-070354	574		Addition of Additional Dynamic Transport Format Information for CCCH and Additional RACH TFCS for	F	7.0.0	7.1.0	R5-071536
RP-36	RP-070354	575		CCCH in SIB5 Remove MCC codes 440/441 for Band VI test	F	7.0.0	7.1.0	R5-071036
RP-36	RP-070354	576		Modify the Physical channel parameters for HS-	F	7.0.0	7.1.0	R5-071119
RP-36	RP-070357	577		DSCH for 1.28 Mcps TDD. Modification to RB setup message used for E-DCH test	F	7.0.0	7.1.0	R5-071126
RP-36	RP-070357	578		Correction to RB setup message used for E-DCH RF	F	7.0.0	7.1.0	R5-071127
RP-36	RP-070364	579		test cases Addition of 7.68 Mcps TDD TX diversity modes to	F	7.0.0	7.1.0	R5-071270
RP-36	RP-070364	580		34.108 (section 6.7) Addition of default message contents for RF tests	F	7.0.0	7.1.0	R5-071277
RP-36	RP-070364	581		(7.68Mcps TDD) Addition of default message contents for signalling tests	F	7.0.0	7.1.0	R5-071278
RP-36	RP-070364	582		(7.68Mcps TDD) Addition of default system information for 7,68 Mcps	F	7.0.0	7.1.0	R5-071279
RP-36	RP-070364	583		TDD to 34.108 Addition of default system information for 7,68Mcps	F	7.0.0	7.1.0	R5-071280
171 -30	131 -070304	JUJ	1	production of detault system information for 1,00000ps	Į.	1.0.0	1.1.0	110-01 1200

Meetin g-1st- Level	Doc-1st-Level	CR	Rev	Subject	Cat	Version -Current	Version -New	Doc-2nd- Level
LOVOI				TDD to 34.108 for SCCPCH configuration with Stand-				
RP-36	RP-070364	584		alone SRB Addition of Reference Radio Bearer configurations used in Radio Bearer testing for 7.68 Mcps TDD	F	7.0.0	7.1.0	R5-071284
RP-36	RP-070364	585		Addition Standard TDD reference test frequencies (7.68	F	7.0.0	7.1.0	R5-071287
RP-36	RP-070363	586		Mcps option) to 34.108 Introduction of the generic test procedure for MBMS	F	7.0.0	7.1.0	R5-071378
RP-36	RP-070350	587		RF/RRM test cases Adding Radio Bearer Configurations for LCR TDD	F	7.0.0	7.1.0	R5-071423
RP-36	RP-070344	588		HSDPA Clarification of two default values for IE Scrambling	F	7.0.0	7.1.0	R5-071435
RP-36	RP-070356	589		code change Editorial corrections in the reference list	F	7.0.0	7.1.0	R5-071443
RP-36	RP-070336	590		Correction to the list of RAB combinations on DPCH and	•	7.0.0	7.1.0	R5-071448
				HS-PDSCH				
RP-36	RP-070360	591		Introduce SIB scheduling and contents for MBMS test	F	7.0.0	7.1.0	R5-071458
RP-36	RP-070360	592		Update to generic setup procedures and default values for MBMS signalling testing	F	7.0.0	7.1.0	R5-071459
RP-36	RP-070360	593		Clarification of MBMS test case default behaviour	F	7.0.0	7.1.0	R5-071460
RP-36	RP-070360	594		Downlink physical channels code allocation for MBMS test	F	7.0.0	7.1.0	R5-071487
RP-36	RP-070354	595		Changes to inclusion of Start Value in Cell Update Message from Rel-6	F	7.0.0	7.1.0	R5-071490
RP-36	RP-070354	596		Addition of Additional Transport Format and TFCS for CCCH on RACH	F	7.0.0	7.1.0	R5-071529
RP-37	RP-070600	597	-	UE performance requirements for high speed train	F	7.1.0	7.2.0	R5-072280
RP-37	RP-070596	598	-	CR to 34.108: New Requirements for Fast L1 Synchronization	F	7.1.0	7.2.0	R5-072368
RP-37	RP-070609	600	-	Addition of MTCH and MCCH to combinations on SCCPCH for 3.84 Mcps TDD	F	7.1.0	7.2.0	R5-072296
RP-37	RP-070609	601	-	Addition of MTCH and MCCH to combinations on SCCPCH for 7.68 Mcps TDD	F	7.1.0	7.2.0	R5-072297
RP-37	RP-070604	602	-	Corrections of Test Procedures for MBMS Testing (IGMP and MLD)	F	7.1.0	7.2.0	R5-072066
RP-37	RP-070604	603	-	Addition of RB combinations for PTP MBMS Testing	F	7.1.0	7.2.0	R5-072067
RP-37	RP-070604	604	-	Correction to default MBMS MCCH messages in 34.108	F	7.1.0	7.2.0	R5-072166
RP-37	RP-070596	605	-	Correction to SIB5 contents for additional RACH TFCS for CCCH	F	7.1.0	7.2.0	R5-072186
RP-37	RP-070596	606	-	Correction to default RB combinations on PRACH for additional RACH TFCS for CCCH	F	7.1.0	7.2.0	R5-072187
RP-37	RP-070608	607	-	SIB5 configuration for MBMS RF/RRM generic procedure	F	7.1.0	7.2.0	R5-072379
RP-37	RP-070604	608	-	Default message content for MBMS NEIGHBOURING CELL P-T-M RB INFORMATION	F	7.1.0	7.2.0	R5-072468
RP-37	RP-070604	609	-	Addition of PTP RB for MBMS	F	7.1.0	7.2.0	R5-072521
RP-37	RP-070604	610	-	Addition of new SIB5 configuration to have MCCH mapped on to an S-CCPCH also used for non-MBMS purposes	F	7.1.0	7.2.0	R5-072469
RP-37	RP-070593	611	-	Addition of RB combination for RoHCTesting	F	7.1.0	7.2.0	R5-072520
RP-37	RP-070611	612	-	Introduce SIB scheduling and contents for LCR TDD MBMS test	F	7.1.0	7.2.0	R5-072534
RP-37	RP-070611	613	-	Introduction of radio bearers of MTCH for LCR TDD MBMS test	F	7.1.0	7.2.0	R5-072535
RP-37	RP-070604	614	1-	Addition of MBMS PTP RB Setup message contents	F	7.1.0	7.2.0	R5-072496
RP-37	RP-070601	615	1-	Introduction of F-DPCH Support Indicator	F	7.1.0	7.2.0	R5-072568
RP-37	RP-070612	616	1-	Correction of HS-PDSCH for 64QAM Enhancement	F	7.1.0	7.2.0	R5-072559
RP-37	RP-070613	617	<u> </u>	Correction of HS-PDSCH for MIMO Enhancement	F	7.1.0	7.2.0	R5-072560
RP-37	RP-070614	618	<u> - </u>	Correction of Maximum Data Rate for E-DPDCH	F	7.1.0	7.2.0	R5-072561
RP-37	RP-070609	620	-	Addition of message contents required for 3.84Mcps and 7.68Mcps TDD to the default messages contents for signalling	F	7.1.0	7.2.0	R5-072295
RP-37	RP-070600	619	-	Production of 34.108 Rel-7 pointer version to point to Rel-8 of the spec	F	7.1.0	7.2.0	R5-072590
RP-37	RP-070599	599	-	Introduction of FDD Mode Test frequencies for Operating Band XI (UMTS1500)	F	7.1.0	8.0.0	R5-072273
RP-38	RP-070858	621	1	Addition of exceptional messages for RF test procedure	F	8.0.0	8.1.0	R5-073202
RP-38	RP-070869	622		Correction to DL RLC PDU size in 9.2 for RB setup and RRC connection setup	F	8.0.0	8.1.0	R5-073203
RP-38	RP-070858	623			F	8.0.0	8.1.0	R5-073204
	RP-070863	624	+	Addition of new IE to RRC connection setup message	F	8.0.0	8.1.0	R5-073390

Meetin g-1st- Level	Doc-1st-Level	CR	Rev	Subject	Cat	Version -Current	Version -New	Doc-2nd- Level
RP-38	RP-070858	625		Addition of test frequencies for low and high ranges for serving cell	F	8.0.0	8.1.0	R5-073311
RP-38	RP-070877	626		Update of generic setup procedure for MBMS RF/RRM testing	F	8.0.0	8.1.0	R5-073300
RP-38	RP-070877	627		Addition of specific message content for MBMS RF/RRM Testing	F	8.0.0	8.1.0	R5-073342
RP-38	RP-070886	628		Addition of combinations on HS-PDSCH and E-PUCH for 3.84Mcps TDD	F	8.0.0	8.1.0	R5-073227
RP-38	RP-070879	629		Addition of message contents required for 1.28Mcps TDD to the default messages contents for signalling	F	8.0.0	8.1.0	R5-073089
RP-38	RP-070887	630		Update of the default RADIO BEARER SETUP message to support enhanced data rates	F	8.0.0	8.1.0	R5-073436
RP-38	RP-070887	631		Update of radio bearer configuration for Enhanced Layer 2	F	8.0.0	8.1.0	R5-073402
RP-38	RP-070887	632		Introduction of new RB configuration to be used by MAC-ehs test cases	F	8.0.0	8.1.0	R5-073403
RP-38	RP-070871	633		Correction conditions table for RADIO BEARER SETUP for MBMS PtP	F	8.0.0	8.1.0	R5-073449
RP-38	RP-070871	634		Update of generic setup procedure for MBMS protocol testing	F	8.0.0	8.1.0	R5-073446
RP-38	RP-070871	635		Correction to the SIB5 when MCCH mapped on to an S-CCPCH also used for non-MBMS purposes	F	8.0.0	8.1.0	R5-073465
RP-38	RP-070871	636		Corrections to MBMS specific message content and addition of MBMS ACCESS INFORMATION	F	8.0.0	8.1.0	R5-073454
RP-38	RP-070858	637		Addition of general SS requirements for UL and DL RF signal levels	F	8.0.0	8.1.0	R5-073269
RP-38	RP-070858	638		Correction to SIB1	F	8.0.0	8.1.0	R5-073418
RP-38	RP-070858	639		Editorial moving the word "Default1" or "Default2" in the	F	8.0.0	8.1.0	R5-073425
RP-38	RP-070858	640		correct column CR wrongly indicated to be to 34.108 and hence not	-	=	-	R5-073425
RP-39	RP-080095	0641		implemented Correction to RRC Connection setup and RB setup	F	8.1.0	8.2.0	R5-080247
RP-39	RP-080103	0642		messages for 64kbps(Channel2) Addition of default message contents for MBMS	F	8.1.0	8.2.0	R5-080149
RP-39	RP-080108	0643		RF/RRM testing CR to 34.108: Introduction of the UE E-DCH 16-QAM	F	8.1.0	8.2.0	R5-080118
RP-39	RP-080106	0644		feature Addition of combinations on E-DCH to 6.11 of 34.108 for	F	8.1.0	8.2.0	R5-080346
RP-39	RP-080106	0645		3.84Mcps TDD Update of radio bearer setup in default message	F	8.1.0	8.2.0	R5-080350
DD 00	DD 000445	00.40		contents to include E-DCH conditions for 3.84Mcps and 7.68Mcps TDD	_	0.4.0	0.00	DF 000000
RP-39	RP-080115	0646		CR for 34.108:Correction of CELL UPDATE CONFIRM default message contents for LCR TDD EDCH	F	8.1.0	8.2.0	R5-080099
RP-39	RP-080115	0647		CR for 34.108:Correction of PHYSICAL CHANNEL RECONFIGURATION default message contents for LCR TDD EDCH	F	8.1.0	8.2.0	R5-080100
RP-39	RP-080115	0648		CR for 34.108:Correction of RADIO BEARER RECONFIGURATION default message contents for LCR TDD EDCH	F	8.1.0	8.2.0	R5-080101
RP-39	RP-080115	0649		CR for 34.108:Correction of RADIO BEARER RELEASE default message contents for LCR TDD EDCH	F	8.1.0	8.2.0	R5-080102
RP-39	RP-080115	0650		CR for 34.108:Correction of RADIO BEARER SETUP default message contents for LCR TDD EDCH	F	8.1.0	8.2.0	R5-080103
RP-39	RP-080115	0651		CR for 34.108:Correction of TRANSPORT CHANNEL RECONFIGURATION default message contents for LCR TDD EDCH	F	8.1.0	8.2.0	R5-080104
RP-39	RP-080115	0652		Correction to the cotents of RRC CONNECTION SETUP message: UM (Transition to CELL_DCH) (1.28 Mcps TDD option)	F	8.1.0	8.2.0	R5-080190
RP-39	RP-080108	0653		Introduction of Default Radio Bearer Setup message contents for UL 16QAM	F	8.1.0	8.2.0	R5-080480
RP-39	RP-080107	0654		Addition of HARQ transmission parameters for 64QAM	F	8.1.0	8.2.0	R5-080482
RP-39	RP-080109	0655		Update of the default RADIO BEARER SETUP message to support enhanced data rates	F	8.1.0	8.2.0	R5-080531
RP-39	RP-080109	0656		HS	F	8.1.0	8.2.0	R5-080287
RP-39	RP-080109	0657			F	8.1.0	8.2.0	R5-080289
RP-39	RP-080109	0658		Addition of enhanced L2 configurations to conversational UM PS radio bearer 6.10.2.4.6.6	F	8.1.0	8.2.0	R5-080484
RP-39	RP-080111	0659		Addition of RB setup message contents for CPC	F	8.1.0	8.2.0	R5-080512

g-1st-	Doc-1st-Level	CR	Rev	Subject	Cat	Version -Current	Version -New	Doc-2nd- Level
Level	DD 000105				_		2.2.2	D= 000=10
	RP-080105	0660		Addition of HARQ transmission parameters for MIMO	F	8.1.0	8.2.0	R5-080519
	RP-080095	0661		Correction to RB identity in RRC Connection Setup	F F	8.1.0	8.2.0	R5-080036
RP-39 RP-39	RP-080095 RP-080095	0662 0663		Addition of new RB Combination for MBMS Testing Corrections to default content of MBMS GENERAL	F	8.1.0 8.1.0	8.2.0 8.2.0	R5-080600 R5-080160
	RP-080095	0664		INFORMATION message	F	8.1.0	8.2.0	R5-080521
				MBMS Modification Request message				
	RP-080109	0665		Update of the default RRC CONNECTION SETUP message to support enhanced data rates	F	8.1.0	8.2.0	R5-080523r1
	RP-080372	0666		CR to 34.108: Correction to Contents of RADIO BEARER SETUUP message: AM or UM (E-DCH and HSDPA) for 16QAM	F	8.2.0	8.3.0	<u>R5-081140</u>
	RP-080370	0667		CR to 34.108: Introduction of Operating Bands XII XIII and XIV (UMTS700 MHz)	F	8.2.0	8.3.0	R5-081150
RP-40	RP-080364	0668		Correction to RRC Connection setup messages for 64kbps(Channel2)	F	8.2.0	8.3.0	R5-081435
RP-40	RP-080364	0669		Additional IEs for 7.8.4 of 34.121-1	F	8.2.0	8.3.0	R5-081436
RP-40	RP-080364	0670		Additional test procedure for HSDPA with F-DPCH RF	F	8.2.0	8.3.0	R5-081279
	55.00004			Performance Requirement for 7.8.5 of 34.121-1				D- 00/000
	RP-080364	0671	-	Additional RB setup message for 7.8.5 of 34.121-1	F F	8.2.0	8.3.0	R5-081280
KP-40	RP-080371	0672		Update of radio bearer setup in default message	F	8.2.0	8.3.0	R5-081336
RP-40	RP-080377	0673		contents to include E-DCH conditions for 3.84Mcps TDD CR for 34.108: Baseline radio bearer combination for	F	8.2.0	8.3.0	R5-081116
RP-40	RP-080379	0674		LCR TDD EDCH Addition of MBSFN RABs and Signalling RB for 3.84 Mcps TDD	F	8.2.0	8.3.0	R5-081034
RP-40	RP-080379	0675		Addition of MBSFN RABs and Signalling RB for 7.68 Mcps TDD	F	8.2.0	8.3.0	R5-081035
RP-40	RP-080379	0676		Initial additions to common test environment definition for HCR and VHCR TDD MBSFN	F	8.2.0	8.3.0	R5-081039
RP-40	RP-080363	0677		Clarification of TDD test channels used for signaling test cases	F	8.2.0	8.3.0	R5-081354
RP-40	RP-080373	0678		Addition of new Test Bearer for MAC CPC testing	F	8.2.0	8.3.0	R5-081219
	RP-080373	0679		CPC: Corrections to Radio Bearer Setup message	F	8.2.0	8.3.0	R5-081388
111 40	1000073	0073		contents for conditions A20 A21		0.2.0	0.5.0	10 00 1000
RP-40	RP-080365	0680		Update of radio bearer configurations for HSPA	F	8.2.0	8.3.0	R5-081194
	RP-080364	0681		Correction to the Contents of RADIO BEARER SETUP message: AM or UM for MBMS PtP Radio Bearer Setup	F	8.2.0	8.3.0	R5-081205
RP-40	RP-080365	0682		Addition of new Test Bearer for MAC-ehs testing	F	8.2.0	8.3.0	R5-081218
RP-40	RP-080365	0683		Addition of new Test Bearer for Improved L2 testing	F	8.2.0	8.3.0	R5-081220
RP-40	RP-080365	0684		Corrections to the default RADIO BEARER SETUP message	F	8.2.0	8.3.0	R5-081393
RP-40	RP-080364	0685		Correction to RB Combination for MBMS Testing	F	8.2.0	8.3.0	R5-081298
RP-40	RP-080364	0686		Removal of MBMS dispersion indicator in default message content	F	8.2.0	8.3.0	R5-081508
RP-41	RP-080561	0687		Addition of combinations on HS-DSCH and E-PUCH to typical radio parameter sets for 7.68Mcps TDD	F	8.3.0	8.4.0	R5-083075
RP-41	RP-080568	0688		Simulated network environment description for MBSFN tests	F	8.3.0	8.4.0	R5-083105
RP-41	RP-080568	0689		Add default SIB configuration for 3.84 amd 7.68 Mcps TDD MBSFN	F	8.3.0	8.4.0	R5-083106
RP-41	RP-080568	0690		Add default MCCH configurations for 3.84 Mcps and 7.68 Mcps TDD MBSFN	F	8.3.0	8.4.0	R5-083107
RP-41	RP-080568	0691		Default MBMS RRC message contents for 3.84 and 7.68 Mcps TDD MBSFN	F	8.3.0	8.4.0	R5-083108
RP-41	RP-080568	0692		Radio Bearer configurations for 7bit and 15bit UM RLC TCs for HCR and VHCR TDD MBSFN	F	8.3.0	8.4.0	R5-083109
RP-41	RP-080557	0693		Corrections to the default RADIO BEARER SETUP message for condition A22	F	8.3.0	8.4.0	R5-083179
RP-41	RP-080570	0694		Correction of HS-PDSCH for 64QAM Enhancement	F	8.3.0	8.4.0	R5-083314
RP-41	RP-080554	0695		Correction to Contents of default RADIO BEARER SET- UP messages	F	8.3.0	8.4.0	R5-083336
RP-41	RP-080557	0696		Corrections to 34.108: Radio access bearer establishment procedure for packet switched sessions (procedure P26)	F	8.3.0	8.4.0	R5-083338
RP-41	RP-080557	0697		Corrections to Radio Bearer Setup message for Rel-7	F	8.3.0	8.4.0	R5-083340
	RP-080557	0698		Corrections to RRC Connection Setup message for Rel-		8.3.0	8.4.0	R5-083341
RP-41	RP-080557	0699		New Radio Bearer Combination for testing flexible size SRB in 8.2.2.57	F	8.3.0	8.4.0	R5-083342
	RP-080567	0700		New Radio Bearer Combinations for CS over HSPA	F	8.3.0	8.4.0	R5-083360

Meetin g-1st- Level	Doc-1st-Level	CR	Rev	Subject	Cat	Version -Current		Doc-2nd- Level
	RP-080568	0701		Add setup test procedures and Access Control Class settings for MBSFN MBMS testing	F	8.3.0	8.4.0	R5-083441
RP-41	RP-080555	0702		Correction to uplink beta factors in default messages	F	8.3.0	8.4.0	R5-083566
RP-41	RP-080567	0703		New Radio Bearer Setup message contents for CS-HSPA RABS	F	8.3.0	8.4.0	R5-083591
RP-41	RP-080570	0704		Correction of HS-PDSCH physical layer categories for LCR TDD 64QAM Enhancement	F	8.3.0	8.4.0	R5-083645
RP-41	RP-080561	0705		Addition of radio bearer set-up default messages for RF testing for E-DCH and HSDPA operation for 3.84Mcps TDD and 7.68Mcps TDD	F	8.3.0	8.4.0	R5-083825
RP-42	RP-080954	0706		Correction to E-RGCH Info in Radio Bearer Setup	F	8.4.0	8.5.0	R5-085037
RP-42	RP-080952	0707		Correction to System Information Block type 11	F	8.4.0	8.5.0	R5-085039
RP-42	RP-080964	0708		Addition of Elementary Files (EFs) needed in Network Selection Enhancements tests	F	8.4.0	8.5.0	R5-085064
RP-42	RP-080968	0709		Addition of MBSFN RABs and Signalling RB for 1.28 Mcps TDD	F	8.4.0	8.5.0	R5-085130
RP-42	RP-080968	0710		Simulated network environment description for MBSFN tests	F	8.4.0	8.5.0	R5-085131
	RP-080968	0711		Default MBMS RRC message contents for LCR TDD MBSFN	F	8.4.0	8.5.0	R5-085132
RP-42	RP-080954	0712		Correction to A9 condition in RB set-up message	F	8.4.0	8.5.0	R5-085230
RP-42	RP-080967	0713		Introduction of radio bearer parameters for Improved L2 UL	F	8.4.0	8.5.0	R5-085422
RP-42	RP-080956	0714		Addition of Rel-7 IEs to default messages specified in 34.108	F	8.4.0	8.5.0	R5-085424
RP-42	RP-080956	0715		Correction of UL DPPCH slot format for default Radio Bearer Setup message for DTX/DRX	F	8.4.0	8.5.0	R5-085425
RP-42	RP-080954	0716		Addition of RF E-DCH test procedure for E-DPDCH with 2SF2+2SF4	F	8.4.0	8.5.0	R5-085726
RP-42	RP-080954	0717		Correction to Contents of RADIO BEARER SETUP message: AM or UM (HSDPA)	F	8.4.0	8.5.0	R5-085727
RP-43	RP-090203	0718	-	Correction to E-DCH Transmission Time Interval	F	8.5.0	8.6.0	R5-090167
RP-43	RP-090203	0719	-	Correction to Radio Bearer Setup message (A17 & A18)	F	8.5.0	8.6.0	R5-090168
RP-43	RP-090216	0720	-	Addition 1.28 Mcps TDD contents in 6.11.5	F	8.5.0	8.6.0	R5-090312
RP-43	RP-090203	0721	-	Correction to the default RADIO BEARER SETUP message for condition A22	F	8.5.0	8.6.0	R5-090313
RP-43	RP-090203	0722	-	Correction 1.28 Mcps TDD default RADIO BEARER SETUP message in 9.1.2	F	8.5.0	8.6.0	R5-090314
RP-43	RP-090216	0723	-	Addition 1.28 Mcps TDD contents in 9.1.3	F	8.5.0	8.6.0	R5-090316
RP-43	RP-090217	0724	-	Supported Channels for MBSFN FDD	F	8.5.0	8.6.0	R5-090368
RP-43	RP-090217	0725	-	Simulated network environment for MBSFN FDD	F	8.5.0	8.6.0	R5-090369
RP-43	RP-090217	0726	-	Generic test procedure for MBSFN FDD	F	8.5.0	8.6.0	R5-090371
RP-43	RP-090217	0727	-	MBSFN FDD configurations for signalling test	F	8.5.0	8.6.0	R5-090373
RP-43	RP-090215	0728	-	Introduction of radio bearer parameters for testing Improved L2 UL	F	8.5.0	8.6.0	R5-090445
RP-43	RP-090212	0729	-	RRC Connection Setup Default Message for HS-DSCH Reception in CELL_FACH state	F	8.5.0	8.6.0	R5-090452
RP-43	RP-090212	0730	-	New Default SIB5/SIB5bis for Enhanced CELL FACH	F	8.5.0	8.6.0	R5-090456
RP-43	RP-090212	0731	-	Addition of Radio Bearer Setup Condition for Enhanced CELL_FACH	F	8.5.0	8.6.0	R5-090459
RP-43	RP-090203	0732	_	Addition of Rel-7 IE's to RRConnectionRequest and correction to Rel-7 IEs for Cell update and URA update under default messages specified in 34.108	F	8.5.0	8.6.0	R5-090465
RP-43	RP-090203	0733	-	Addition of Code Tree Allocation Table for 64QAM HSDPA Test Cases	F	8.5.0	8.6.0	R5-090466
RP-43	RP-090203	0734	-	Correction to Radio Bearer Setup for 64QAM test cases	F	8.5.0	8.6.0	R5-090467
RP-43	RP-090215	0735	-	Additions to the default RRC messages for improved L2 in uplink	F	8.5.0	8.6.0	R5-090559

Meetin g-1st- Level	Doc-1st-Level	CR	Rev	Subject	Cat	Version -Current		Doc-2nd- Level
RP-43	RP-090218	0736	-	Addition of radio bearer parameters for UE HS-DSCH Physical Layer category 19 and 20	F	8.5.0	8.6.0	R5-090562
RP-43	RP-090203	0737	-	Correction of radio bearer parameters for UE HS-DSCH Physical Layer category 15 and 18	F	8.5.0	8.6.0	R5-090563
RP-43	RP-090203	0738	-	Correction to the RAB Setup for CS over HSPA (A23 set of parameters) in 34.108	F	8.5.0	8.6.0	R5-090564
RP-43	RP-090215	0739	2	Update of Radio Bearer Configurations for flexible RLC	F	8.5.0	8.6.0	R5-090727
RP-43	RP-090212	0740	-	Introduction of radio bearer parameters for testing HS- DSCH Reception in CELL_FACH	F	8.5.0	8.6.0	R5-090728
RP-44	RP-090443	0741	-		F	8.6.0	8.7.0	R5-092119
RP-44	RP-090443	0742	-		F	8.6.0	8.7.0	R5-092120
RP-44	RP-090445	0743	-	"6.4.1.1 - Correction to SIB5 Default Message for HS- DSCH Reception in CELL_FACH"	F	8.6.0	8.7.0	R5-092222
RP-44	RP-090443	0744	-		F	8.6.0	8.7.0	R5-092318
RP-44	RP-090433	0745	-	Correction to Radio Bearer Setup message contents (A17a)	F	8.6.0	8.7.0	R5-092537
RP-44	RP-090445	0746	-		F	8.6.0	8.7.0	R5-092544
RP-44	RP-090445	0747	-	Correction to Radio Bearer Setup Condition for Enhanced CELL FACH state	F	8.6.0	8.7.0	R5-092545
RP-44	RP-090433	0748	-	Update to Channelisation code allocation for 64QAM	F	8.6.0	8.7.0	R5-092728
RP-44	RP-090598	0749	-	Addition of Test frequencies in FDD Mode Operating Band XIX (Extended UMTS 800)	F	8.6.0	8.7.0	R5-092792
RP-44	RP-090795	0750	-		F	8.7.0	8.8.0	R5-094071
RP-44	RP-090811	0751	-	Update of the default RADIO BEARER SETUP message to support enhanced data rates for LCR TDD	F	8.7.0	8.8.0	R5-094269
RP-44	RP-090803	0752	-	Correction RAB definition for LCR TDD MBSFN in 34108	F	8.7.0	8.8.0	R5-094270
RP-44	RP-090809	0753	-	Correction to RAB configuration for Enhanced CELL_FACH	F	8.7.0	8.8.0	R5-094443
RP-44	RP-090809	0754	-	Correction to RRC Connection setup for HS-DSCH reception in CELL_FACH	F	8.7.0	8.8.0	R5-094445
RP-44	RP-090809	0755	-	Correction to SIB5 for Enhanced CELL_FACH	F	8.7.0	8.8.0	R5-094446
RP-44	RP-090809	0756	-	Correction to Radio Bearer Setup for HS-DSCH reception in CELL_FACH	F	8.7.0	8.8.0	R5-094447
RP-44	RP-090799	0757	-		F	8.7.0	8.8.0	R5-094455
RP-44	RP-090808	0758	-	Inclusion of common E-DCH info in SIB5(bis) to be used by new Enh-UL for CELL_FACH test cases	F	8.7.0	8.8.0	R5-094459
RP-44	RP-090794	0759	-	Update to Channelisation code allocation for E-DCH and 64QAM	F	8.7.0	8.8.0	R5-094464
RP-44	RP-090794	0760	-	Addition of Radio Bearer Setup Conditions for establishing radio bearers mapped onto E-DCH/HS-DSCH (MAC-ehs) for 64QAM and non 64QAM configurations	F	8.7.0	8.8.0	R5-094467
RP-44	RP-090803	0761	-	Correction the number in section 11.2 in 34108	F	8.7.0	8.8.0	R5-094511
RP-44	RP-090795	0762	-	Correction to RB setup message for CS over HSPA	F	8.7.0	8.8.0	R5-094625
RP-44	RP-090794	0763	-	Correction to Default Message contents of Radio Bearer Setup for A22	F	8.7.0	8.8.0	R5-094646
RP-44	RP-090791	0764	-	Update of 9.2 Default RF Messages	F	8.7.0	8.8.0	R5-094744
RP-44	RP-090812	0765	-	MBSFN RABs and Signalling RB for 3.84 Mcps TDD IMB	F	8.7.0	8.8.0	R5-094856
RP-44	RP-090812	0766	-	Default MBMS RRC message contents for 3.84 Mcps	F	8.7.0	8.8.0	R5-094857
RP-44	RP-090812	0767	-		F	8.7.0	8.8.0	R5-094858
RP-44	RP-090812	0768	-	Radio Bearer configurations for 7bit and 15bit UM RLC TCs for 3.84 Mcps TDD IMB	F	8.7.0	8.8.0	R5-094859
RP-44	RP-090812	0769	-	Reference radio condition for 3.84 Mcps TDD IMB	F	8.7.0	8.8.0	R5-094860
RP-44	RP-090812	0770	-	Reference test condition for MBSFN 3.84 Mcps TDD IMB	F	8.7.0	8.8.0	R5-094861

RP-44 RP-090812 0771 Default ISB configuration for 3.84 Mops TDD IMB F 8.7.0 8.8.0 R5-094862 RP-44 RP-090812 0772 Supported Channels for MBSFN 3.84 Mops TDD IMB F 8.7.0 8.8.0 R5-094863 RP-44 RP-090093 0773 New RF procedure for HSDPA in CELL_FACH F 8.7.0 8.8.0 R5-094984 RP-44 RP-090793 0775 CR0 74.0 Kg. Addition of RADIO BEARER SETUP F 8.7.0 8.8.0 R5-094984 RP-44 RP-090794 0775 Addition of Instandard TDD reference test frequencies F 8.7.0 8.8.0 R5-095014 RP-44 RP-090791 0777 Addition of section 6.1.4 kg. Default Cell parameters F 8.7.0 8.8.0 R5-095026 RP-44 RP-090791 0777 Addition of InterNal testing and with cells on the cell of the default RADIO BEARER SETUP F 8.7.0 8.8.0 R5-095022 RP-44 RP-090900 0778 Update of the default RADIO BEARER SETUP F 8.7.0 8.8.0 R5-095022 RP-44	Meetin g-1st- Level	Doc-1st-Level	CR	Rev	Subject	Cat	Version -Current		Doc-2nd- Level
RP-44 RP-090793 O773 New RF procedure for HSDPA in CELL_FACH F 6.7.0 8.8.0 R5-094984		RP-090812	0771	-	Default SIB configuration for 3.84 Mcps TDD IMB	F	8.7.0	8.8.0	R5-094862
RP-44 RP-090793 0774	RP-44	RP-090812	0772	-	Supported Channels for MBSFN 3.84 Mcps TDD IMB	F	8.7.0	8.8.0	R5-094863
RP-44 RP-090794	RP-44	RP-090809	0773	-	New RF procedure for HSDPA in CELL_FACH	F	8.7.0	8.8.0	R5-094984
RP-44 RP-090794 0775 addition of the Standard TDD reference test frequencies F 8.7.0 8.8.0 R5-095013 RP-44 RP-090794 0776 correction of RADIO BEARER SETUP message default F 8.7.0 8.8.0 R5-095014 RP-44 RP-090791 0777 - Addition of section 6.1.4.1a: Default Ceil parameters F 8.7.0 8.8.0 R5-095025 RP-44 RP-090805 0778 RP-44 RP-090805 0778 Default Ceil parameters F 8.7.0 8.8.0 R5-095062 RP-44 RP-090805 0778 RP-44 RP-090794 0779 Default Ceil Discovering Adjacent Channels for HSDPA Default RECIPION for support of Dual Carrier Adjacent Channels for HSDPA Default RADIO BEARER SETUP Ressage (FDD) for support of Dual Carrier Adjacent Channels for HSDPA RP-44 RP-090799 0781 Addition of Default Radio Bearer Conditions for HSDPA RP-45 RP-091194 0782 Addition of Default Radio Bearer Conditions for HSDPA RP-45 RP-091194 0782 Addition of Default Radio Bearer Conditions for HSDPA RP-45 RP-091118 0784 Addition of Default RADIO BEARER SETUP RESPONSIBLE ADDITION OF RESPONSIBLE AD	RP-44	RP-090793	0774	-		F	8.7.0	8.8.0	R5-094994
RP-44 RP-090791 0777 - Addition of section 6.1.4.1a: Default Cell parameters F 8.7.0 8.8.0 RS-095026 Two PLMN in UTRAN test scenario with cells on PLMN belonging to two different frequencies F 8.7.0 8.8.0 RS-095062 RP-44 RP-090805 0778 - Update of the default RADIO BEARER SETUP F 8.7.0 8.8.0 RS-095062 RP-44 RP-090794 0779 - Update of the default RADIO BEARER SETUP F 8.7.0 8.8.0 RS-095062 RP-44 RP-090800 0780 - Update of the default RADIO BEARER SETUP F 8.7.0 8.8.0 RS-095063 RP-44 RP-090800 0780 - Update of the default RADIO BEARER SETUP F 8.7.0 8.8.0 RS-095063 RR-44 RP-090800 0780 - Update of the default RADIO BEARER SETUP Reseage (PDD) for support of GACANH-MIMO for ISSDPA RS-095122 RS-095122 RS-095122 RS-095124 RS-095124 RS-095124 RS-095124 RR-44 RP-090799 0781 - Addition of Default RADIO BEARER SETUP F 8.7.0 8.8.0 RS-095130 RS-095130 RS-095130 RS-095130 RS-095130 RS-095605 RS-45 RP-091124 0782 - Addition of radio beaver parameters for UE HS-0SCH RS-095605 RS-45 RS-095130 RS-095606 RS-09	RP-44	RP-090794	0775	-		F	8.7.0	8.8.0	R5-095013
RP-44 RP-090791 0777 Addition of section 6.1.4.1a: Default Cell parameters F 8.7.0 8.8.0 R5-095026 RP-44 RP-090805 0778 - Update of the default RADIO BEARER SETUP message (FDD) for support of Dual Carrier Adjacent Channels for HSDPA F 8.7.0 8.8.0 R5-095062 RP-44 RP-090794 0779 - Update of the default RADIO BEARER SETUP message (FDD) for support of Dual Carrier Adjacent Channels for HSDPA F 8.7.0 8.8.0 R5-095063 RP-44 RP-090794 0779 - Update of the default RADIO BEARER SETUP message (FDD) for support of HADIA MIMO for message (FDD) fo	RP-44	RP-090794	0776	-		F	8.7.0	8.8.0	R5-095014
RP-44 RP-090805 0778 Update of the default RADIO BEARER SETUP message (FDD) for support of Dual Carrier Adjacent RP-090794 0779 Update of the default RADIO BEARER SETUP message (FDD) for support of Dual Carrier Adjacent RP-090800 0780 Update of the default RADIO BEARER SETUP message (FDD) for an additional RB combination RP-44 RP-090799 0781 Addition of Default Radio Bearer Conditions for RP-45 RP-091124 0782 Addition of Default Radio Bearer Conditions for RP-45 RP-091130 0784 Default SIB configuration for 3.84 Mcps TDD IMB R.8.0 R.9.0 R5-095696 RP-45 RP-091130 0786 Default SIB configuration for 3.84 Mcps TDD IMB R.8.0 R.9.0 R5-095696 RP-45 RP-091130 0786 Reference radio condition for 3.84 Mcps TDD IMB R.8.0 R.9.0 R5-095698 RP-45 RP-091130 0786 Reference radio condition for 3.84 Mcps TDD IMB R.8.0 R.9.0 R5-095698 RP-45 RP-091130 0786 Reference radio condition for 3.84 Mcps TDD IMB R.8.0 R.9.0 R5-095698 RP-45 RP-091130 0786 Reference radio condition for 3.84 Mcps TDD IMB R.8.0 R.9.0 R5-095699 RP-45 RP-091130 0786 Reference radio condition for 3.84 Mcps TDD IMB R.8.0 R.9.0 R5-095699 RP-45 RP-091130 0786 Reference radio condition for 3.84 Mcps TDD IMB R.8.0 R.9.0 R5-095699 RP-45 RP-091130 0786 Reference radio condition for 3.84 Mcps TDD IMB R.8.0 R.9.0 R5-095699 RP-45 RP-091123 0786 Update 5.5.1.4 for MBSFN TC Reference test conditions R.8.0 R.9.0 R5-095699 RP-45 RP-091123 0788 Update 5.5.1.4 for MBSFN TC Reference test conditions R.8.0 R.9.0 R5-095986 RP-45 RP-091129 0790 Addition Reference Radio Bearer configurations used in R.8.0 R.9.0 R5-095080 RP-45 RP-091112 0799 Correction to Common HS-DSCH and E-DCH into in SIBS R.8.0 R.9.0 R5-096150 RP-45 RP-091119 0797 Addition Reference Radio Bearer Configurations used in R.8.0 R.9.0 R5-096160 RP-45 RP-091119 0797 Addition Rote	RP-44	RP-090791	0777	-	Addition of section 6.1.4.1a: Default Cell parameters Two PLMN in UTRAN test scenario with cells on	F	8.7.0	8.8.0	R5-095026
RP-44 RP-090794 0779 Update of the default RADIO BEARER SETUP RP-090800 0780 Update of the default RADIO BEARER SETUP RP-090800 0780 Update of the default RADIO BEARER SETUP RP-090799 0781 National Processing (FDD) for an additional RB combination RP-44 RP-090799 0781 Addition of Default Radio Bearer Conditions for RP-45 RP-091124 0782 Addition of Iradio barer parameters for UE HS-DSCH RP-091124 0782 Addition of Iradio barer parameters for UE HS-DSCH RP-091130 O784 Default SIB configuration for 3.84 Mcps TDD IMB R 8.8.0 8.9.0 R5-095696 RP-45 RP-091130 0784 Default SIB configuration for 3.84 Mcps TDD IMB R 8.8.0 8.9.0 R5-095696 RP-45 RP-091130 0785 MBSFN service availability for 3.84 Mcps TDD IMB R 8.8.0 8.9.0 R5-095699 RP-45 RP-091130 0786 Reference radio condition for 3.84 Mcps TDD IMB R 8.8.0 8.9.0 R5-095699 RP-45 RP-091130 0786 Reference radio condition for 3.84 Mcps TDD IMB R 8.8.0 8.9.0 R5-095699 RP-45 RP-091130 0786 Reference radio condition for 3.84 Mcps TDD IMB R 8.8.0 8.9.0 R5-095699 RP-45 RP-091130 0786 Reference radio condition for 3.84 Mcps TDD IMB R 8.8.0 8.9.0 R5-095699 RP-45 RP-091123 0787 Introduction of MIMO in Typical radio parameter sets for F 8.8.0 8.9.0 R5-095986 RP-45 RP-091118 0789 Update 5.51.4 for MBSFN TC Reference test conditions F 8.8.0 8.9.0 R5-095957 RP-45 RP-091118 0789 Inclusion of common HS-DSCH and E-DCH into in SIB5 R8.0 8.9.0 R5-095957 RP-45 RP-091119 0790 Addition Reference Radio Bearer configurations used in F 8.8.0 8.9.0 R5-095957 RP-45 RP-091119 0791 Editorial correction in clause 8.12.1 F 8.8.0 8.9.0 R5-096052 RP-45 RP-091119 0794 Correction to condition A27 for Improved L2 UL Testing F 8.8.0 8.9.0 R5-096150 RP-45 RP-091119 0795 Editorial correction in clause 8.12.1 F 8.8.0 8.9.0 R5-096150 RP-45 RP-091119 0795 Addition of the default	RP-44	RP-090805	0778	-	Update of the default RADIO BEARER SETUP message (FDD) for support of Dual Carrier Adjacent	F	8.7.0	8.8.0	R5-095062
RP-44 RP-090800 0780 Digital of the default RADIO BEARER SETUP Ressage (FDD) for support of 64QAM+MIMO for HSDPA	RP-44	RP-090794	0779	-	Update of the default RADIO BEARER SETUP	F	8.7.0	8.8.0	R5-095063
RP-44 RP-090799 0781 Addition of Default Radio Bearer Conditions for Improved L2 UL MAC Lest cases in Expressed L2 UL RAC MAC Lest cases in Expressed L2 UL RAC MAC Lest cases in Expressed L2 UL RAC AM Lest cases for LCR TDD AM Lest cases in Expressed L2 UL RAC AM Lest RE-8 USIM files Exp. 48.0 8.9.0 R5-095600 R5-095600 R5-095600 R5-095600 R5-095600 R5-095600 R5-095700 R5-095600 R5-0	RP-44	RP-090800	0780	-	Update of the default RADIO BEARER SETUP message (FDD) for support of 64QAM+MIMO for	F	8.7.0	8.8.0	R5-095128
RP-45 RP-091124 0782 Addition of radio bearer parameters for UE HS-DSCH Physical Layer category 21, 22, 23 and 24 (Dual Cell) 8.0 8.9.0 R5-095605 RP-45 RP-091118 0783 Corrections to the default RRC CONNECTION SETUP Revolution of the message of the part of the part of the physical Layer category 21, 22, 23 and 24 (Dual Cell) R.0 8.9.0 R5-095696 RP-45 RP-091130 0784 Default SIB configuration for 3.84 Mcps TDD IMB F 8.8.0 8.9.0 R5-095698 RP-45 RP-091130 0786 Reference radio condition for 3.84 Mcps TDD IMB F 8.8.0 8.9.0 R5-095699 RP-45 RP-091130 0786 Reference radio condition for 3.84 Mcps TDD IMB F 8.8.0 8.9.0 R5-095700 RP-45 RP-091133 0787 Introduction of MIMO in Typical radio parameter sets for F 8.8.0 8.9.0 R5-095950 RP-45 RP-091123 0788 Update 5.5.1.4 for MBSFN TC Reference test conditions F 8.8.0 8.9.0 R5-095957 RP-45 RP-091129 0790 Addition Reference Calcio Bearer configurations used in F 8.8.0	RP-44	RP-090799	0781	-	Addition of Default Radio Bearer Conditions for	F	8.7.0	8.8.0	R5-095130
RP-45 RP-091118 0783 Corrections to the default RRC CONNECTION SETUP F 8.8.0 8.9.0 R5-095646 RP-45 RP-091130 0784 Default SIB configuration for 3.84 Mcps TDD IMB F 8.8.0 8.9.0 R5-095698 RP-45 RP-091130 0785 MBSFN service availability for 3.84 Mcps TDD IMB F 8.8.0 8.9.0 R5-095699 RP-45 RP-091130 0786 Reference radio condition for 3.84 Mcps TDD IMB F 8.8.0 8.9.0 R5-095700 RP-45 RP-091135 0787 Introduction of MIMO in Typical radio parameter sets for 1.28Mcps TDD RS-095882 RP-45 RP-091123 0788 Update 5.5.1.4 for MBSFN TC Reference test conditions F 8.8.0 8.9.0 R5-095945 RP-45 RP-091118 0789 Inclusion of common HS-DSCH and E-DCH into in SIB5 to be used by new enhanced CELL_FACH test cases for LCR TDD F 8.8.0 8.9.0 R5-095957 to be used by new enhanced CELL_FACH test cases for LCR TDD RP-45 RP-091119 0790 Addition Reference Radio Bearer configurations used in MAC-ehs and MAC-is testing for LCR TDD F 8.8.0	RP-45	RP-091124	0782	-	Addition of radio bearer parameters for UE HS-DSCH	F	8.8.0	8.9.0	R5-095605
RP-45 RP-091130 0784 Default SIB configuration for 3.84 Mcps TDD IMB F 8.8.0 8.9.0 R5-096698 RP-45 RP-091130 0785 - MBSFN service availability for 3.84 Mcps TDD IMB F 8.8.0 8.9.0 R5-095699 RP-45 RP-091130 0786 - Reference radio condition for 3.84 Mcps TDD IMB F 8.8.0 8.9.0 R5-095700 RP-45 RP-091135 0787 - Introduction of MIMO in Typical radio parameter sets for F 8.8.0 8.9.0 R5-095882 RP-45 RP-091123 0788 - Update 5.5.1.4 for MBSFN TC Reference test conditions F 8.8.0 8.9.0 R5-095945 RP-45 RP-091118 0789 - Inclusion of common HS-DSCH and E-DCH into in SIB5 F 8.8.0 8.9.0 R5-095957 RP-45 RP-091119 0790 - Addition Reference Radio Bearer configurations used in MAC-ehs and MAC-ins testing for LCR TDD R5-095958 RP-45 RP-091119 0791 - Editorial correction in clause 8 1.2.1 F 8.8.0	RP-45	RP-091118	0783	-	Corrections to the default RRC CONNECTION SETUP	F	8.8.0	8.9.0	R5-095646
RP-45 RP-091130 0786 Reference radio condition for 3.84 Mcps TDD IMB F 8.8.0 8.9.0 R5-095700 RP-45 RP-091135 0787 Introduction of MIMO in Typical radio parameter sets for F 8.8.0 8.9.0 R5-095882 RP-45 RP-091123 0788 Update 5.5.1.4 for MBSFN TC Reference test conditions F 8.8.0 8.9.0 R5-095945 RP-45 RP-091118 0789 Inclusion of common HS-DSCH and E-DCH info in SIB5 to be used by new enhanced CELL_FACH test cases for LCR TDD 8.8.0 8.9.0 R5-095957 RP-45 RP-091129 0790 Addition Reference Radio Bearer configurations used in F 8.8.0 8.9.0 R5-095958 RP-45 RP-091119 0791 Editorial correction in clause 8.1.2.1 F 8.8.0 8.9.0 R5-096049 RP-45 RP-091117 0792 Correction to RADIO BEARER SETUP for 5.2B F 8.8.0 8.9.0 R5-096052 RP-45 RP-091119 0794 Correction to Condition A27 for Improved L2 U L Testing and generic table formatiting R.8.0 8.9.0 R5-096150 RP-45 <	RP-45	RP-091130	0784	-		F	8.8.0	8.9.0	R5-095698
RP-45 RP-091135 0787 Introduction of MIMO in Typical radio parameter sets for F 8.8.0 8.9.0 R5-095882 RP-45 RP-091123 0788 Update 5.5.1.4 for MBSFN TC Reference test conditions F 8.8.0 8.9.0 R5-095945 RP-45 RP-091118 0789 Inclusion of common HS-DSCH and E-DCH info in SIB5 for LCR TDD 8.8.0 8.9.0 R5-095957 RP-45 RP-091129 0790 Addition Reference Radio Bearer configurations used in For LCR TDD 8.8.0 8.9.0 R5-095958 RP-45 RP-091129 0790 Addition Reference Radio Bearer configurations used in For LCR TDD 8.8.0 8.9.0 R5-095958 RP-45 RP-091119 0791 Editorial correction in clause 8.1.2.1 F 8.8.0 8.9.0 R5-096049 RP-45 RP-091117 0792 Correction of RADIO BEARER SETUP for 5.2B F 8.8.0 8.9.0 R5-096052 RP-45 RP-091119 0794 Correction to condition A27 for Improved L2 UL Testing and generic table formatting F 8.8.0 8.9.0 R5-096150 RP-45 RP-091119	RP-45	RP-091130	0785	-	MBSFN service availability for 3.84 Mcps TDD IMB	F	8.8.0	8.9.0	R5-095699
RP-45 RP-091123 0788 Update 5.5.1.4 for MBSFN TC Reference test conditions R5-095945 RP-45 RP-091118 0789 Inclusion of common HS-DSCH and E-DCH info in SIB5 R5-095957 RF-45 RP-091129 0790 Addition Reference Radio Bearer configurations used in MAC-ehs and MAC-ifs testing for LCR TDD Addition Reference Radio Bearer configurations used in MAC-ehs and MAC-ifs testing for LCR TDD R5-095958 R8-8.0 R5-095958 R8-9.0 R5-095958 R8-9.0 R5-095958 R8-9.0 R5-095958 R8-9.0 R5-096049 R8-9.0 R5-096049 R8-9.0 R5-096049 R8-9.0 R5-096049 R8-9.0 R5-096049 R8-9.0 R5-096052 R8-9.0 R5-096052 R8-9.0 R8-9.0 R5-096052 R8-9.0 R8-9.0 R5-096052 R8-9.0 R8-9.0 R8-9.0 R5-096150 R8-9.0 R8-9.0	RP-45	RP-091130	0786	-	Reference radio condition for 3.84 Mcps TDD IMB	F	8.8.0	8.9.0	R5-095700
RP-45 RP-0911123 0788 - Update 5.5.1.4 for MBSFN TC Reference test conditions F 8.8.0 8.9.0 R5-095945 RP-45 RP-091118 0789 - Inclusion of common HS-DSCH and E-DCH info in SIB5 for LCR TDD 8.8.0 8.9.0 R5-095957 RP-45 RP-091129 0790 - Addition Reference Radio Bearer configurations used in MAC-ehs and MAC-list setting for LCR TDD F 8.8.0 8.9.0 R5-095958 RP-45 RP-091115 0791 - Editorial correction in clause 8.1.2.1 F 8.8.0 8.9.0 R5-096049 RP-45 RP-091117 0792 - Correction to Condition A27 for Improved L2 UL Testing F 8.8.0 8.9.0 R5-096049 RP-45 RP-091119 0794 - Correction to Condition A27 for Improved L2 UL Testing F 8.8.0 8.9.0 R5-096052 RP-45 RP-091119 0795 - Correction to Default Radio Bearer Conditions for Improved L2 UL RLC AM test cases F 8.8.0 8.9.0 R5-096153 RP-45 RP-091119 0796	RP-45	RP-091135	0787	-		F	8.8.0	8.9.0	R5-095882
To be used by new enhanced CELL_FACH test cases for LCR TDD	RP-45	RP-091123	0788	-		F	8.8.0	8.9.0	R5-095945
RP-45 RP-091129 0790 - Addition Reference Radio Bearer configurations used in MAC-list sesting for LCR TDD F 8.8.0 8.9.0 R5-095958 RP-45 RP-091115 0791 - Editorial correction in clause 8.1.2.1 F 8.8.0 8.9.0 R5-096049 RP-45 RP-091117 0792 - Correction to condition A27 for Improved L2 UL Testing and generic table formatting F 8.8.0 8.9.0 R5-096052 RP-45 RP-091119 0794 - Correction to condition A27 for Improved L2 UL Testing and generic table formatting F 8.8.0 8.9.0 R5-096150 RP-45 RP-091119 0795 - Correction to Default Radio Bearer Conditions for Improved L2 UL RLC AM test cases F 8.8.0 8.9.0 R5-096153 RP-45 RP-091128 0796 1 Correction to Default message contents F 8.8.0 8.9.0 R5-096153 RP-45 RP-091119 0797 - Align USIM content to the latest REI-8 USIM files F 8.8.0 8.9.0 R5-096180 RP-45 RP-091124 0798 - Update of the default RADIO BEARER SETUP F	RP-45	RP-091118	0789	-	to be used by new enhanced CELL_FACH test cases	F	8.8.0	8.9.0	R5-095957
RP-45 RP-091115 0791 - Editorial correction in clause 8.1.2.1 F 8.8.0 8.9.0 R5-096049 RP-45 RP-091117 0792 - Correction of RADIO BEARER SETUP for 5.2B F 8.8.0 8.9.0 R5-096052 RP-45 RP-091119 0794 - Correction to condition A27 for Improved L2 UL Testing and generic table formatting and generic table formatting and generic table formatting. F 8.8.0 8.9.0 R5-096150 RP-45 RP-091119 0795 - Correction to Default Radio Bearer Conditions for Improved L2 UL RLC AM test cases. F 8.8.0 8.9.0 R5-096153 RP-45 RP-091128 0796 1 Correction to Default message contents F 8.8.0 8.9.0 R5-096171 RP-45 RP-091119 0797 - Align USIM content to the latest REI-8 USIM files F 8.8.0 8.9.0 R5-096180 RP-45 RP-091124 0798 - Update of the default RADIO BEARER SETUP message for RE testing of Dual Carrier Adjacent Channels for HSDPA F 8.8.0 8.9.0 R5-096280 <t< td=""><td>RP-45</td><td>RP-091129</td><td>0790</td><td>-</td><td>Addition Reference Radio Bearer configurations used in</td><td>F</td><td>8.8.0</td><td>8.9.0</td><td>R5-095958</td></t<>	RP-45	RP-091129	0790	-	Addition Reference Radio Bearer configurations used in	F	8.8.0	8.9.0	R5-095958
RP-45 RP-091119 0794 Correction to condition A27 for Improved L2 UL Testing and generic table formatting RP-45 RP-091119 0795 Correction to Default Radio Bearer Conditions for Improved L2 UL RP-091128 0796 1 Correction to Default Radio Bearer Conditions for Improved L2 UL RLC AM test cases RP-091128 0796 1 Correction to Default message contents F 8.8.0 8.9.0 R5-096153 RP-45 RP-091119 0797 Align USIM content to the latest REI-8 USIM files F 8.8.0 8.9.0 R5-096180 RP-45 RP-091124 0798 Update of the default RADIO BEARER SETUP F 8.8.0 8.9.0 R5-096280 RP-45 RP-091124 0799 New RF procedure for Dual Carrier Adjacent Channels for HSDPA RP-091119 0800 Correction to radio bearer configuration 6.10.2.4.6.6 for improved L2 UL RP-47 RP-100141 0801 Corrections to Radio Bearer Setup A26 F 8.9.0 8.10.0 R5-100241 Configurations RP-47 RP-100154 0803 CR to 34.108: Update of test frequencies for extended F 8.9.0 8.10.0 R5-100253 R5-100253 R5-100253 R5-100255 R5-100	RP-45	RP-091115	0791	-		F	8.8.0	8.9.0	R5-096049
and generic table formatting	RP-45	RP-091117	0792	-	Correction of RADIO BEARER SETUP for 5.2B	F	8.8.0	8.9.0	R5-096052
RP-45 RP-091119 0795 Correction to Default Radio Bearer Conditions for Improved L2 UL RLC AM test cases F 8.8.0 8.9.0 R5-096153 RP-45 RP-091128 0796 1 Correction to Default message contents F 8.8.0 8.9.0 R5-096171 RP-45 RP-091119 0797 - Align USIM content to the latest REI-8 USIM files F 8.8.0 8.9.0 R5-096180 RP-45 RP-091124 0798 - Update of the default RADIO BEARER SETUP message for RF testing of Dual Carrier Adjacent Channels for HSDPA F 8.8.0 8.9.0 R5-096280 RP-45 RP-091124 0799 - New RF procedure for Dual Cell HSDPA F 8.8.0 8.9.0 R5-096308 RP-45 RP-091119 0800 - Correction to radio bearer configuration 6.10.2.4.6.6 for improvedL2 UL F 8.8.0 8.9.0 R5-096706 RP-47 RP-100140 0801 - Corrections to Radio Bearer Setup M26 F 8.9.0 8.10.0 R5-100241 RP-47 RP-100154 0803 -	RP-45	RP-091119	0794	-		F	8.8.0	8.9.0	R5-096150
RP-45 RP-091128 0796 1 Correction to Default message contents F 8.8.0 8.9.0 R5-096171 RP-45 RP-091119 0797 - Align USIM content to the latest REI-8 USIM files F 8.8.0 8.9.0 R5-096180 RP-45 RP-091124 0798 - Update of the default RADIO BEARER SETUP message for RF testing of Dual Carrier Adjacent Channels for HSDPA F 8.8.0 8.9.0 R5-096280 RP-45 RP-091124 0799 - New RF procedure for Dual Cell HSDPA F 8.8.0 8.9.0 R5-096308 RP-45 RP-091119 0800 - Correction to radio bearer configuration 6.10.2.4.6.6 for improvedL2 UL F 8.8.0 8.9.0 R5-096706 RP-47 RP-100141 0801 - Corrections to Radio Bearer Setup A26 F 8.9.0 8.10.0 R5-100054 RP-47 RP-100140 0802 - Corrections to Radio Bearer Setup message for A17b/c Configurations F 8.9.0 8.10.0 R5-100241 RP-47 RP-100154 0803 - <td>RP-45</td> <td>RP-091119</td> <td>0795</td> <td>-</td> <td>Correction to Default Radio Bearer Conditions for</td> <td>F</td> <td>8.8.0</td> <td>8.9.0</td> <td>R5-096153</td>	RP-45	RP-091119	0795	-	Correction to Default Radio Bearer Conditions for	F	8.8.0	8.9.0	R5-096153
RP-45	RP-45	RP-091128	0796	1		F	8.8.0	8.9.0	R5-096171
Message for RF testing of Dual Carrier Adjacent Channels for HSDPA RP-091124 0799 New RF procedure for Dual Cell HSDPA F 8.8.0 8.9.0 R5-096308 RP-45 RP-091119 0800 Correction to radio bearer configuration 6.10.2.4.6.6 for F 8.8.0 8.9.0 R5-096706 RP-47 RP-100141 0801 Corrections to Radio Bearer Setup A26 F 8.9.0 8.10.0 R5-100054 RP-47 RP-100140 0802 Corrections to Radio Bearer Setup message for A17b/c F 8.9.0 8.10.0 R5-100241 RP-47 RP-100154 0803 CR to 34.108: Update of test frequencies for extended F 8.9.0 8.10.0 R5-100253 RP-47 RP-100137 0804 Addition of new combinations for LCR TDD RAB testing F 8.9.0 8.10.0 R5-100336 RP-47 RP-100151 0805 Update of the default RADIO BEARER SETUP F 8.9.0 8.10.0 R5-100337	RP-45	RP-091119	0797	-	Align USIM content to the latest REI-8 USIM files	F	8.8.0	8.9.0	R5-096180
RP-45 RP-091124 0799 - New RF procedure for Dual Cell HSDPA F 8.8.0 8.9.0 R5-096308 RP-45 RP-091119 0800 - Correction to radio bearer configuration 6.10.2.4.6.6 for improvedL2 UL F 8.8.0 8.9.0 R5-096706 RP-47 RP-100141 0801 - Corrections to Radio Bearer Setup A26 F 8.9.0 8.10.0 R5-100054 RP-47 RP-100140 0802 - Corrections to Radio Bearer Setup message for A17b/c Configurations F 8.9.0 8.10.0 R5-100241 RP-47 RP-100154 0803 - CR to 34.108: Update of test frequencies for extended UMTS1500 operating bands F 8.9.0 8.10.0 R5-100253 RP-47 RP-100137 0804 - Addition of new combinations for LCR TDD RAB testing in 34.108 F 8.9.0 8.10.0 R5-100336 RP-47 RP-100151 0805 - Update of the default RADIO BEARER SETUP F 8.9.0 8.10.0 R5-100337	RP-45	RP-091124	0798	-	message for RF testing of Dual Carrier Adjacent	F	8.8.0	8.9.0	R5-096280
ImprovedL2 UL	RP-45	RP-091124	0799	-		F	8.8.0	8.9.0	R5-096308
RP-47 RP-100141 0801 - Corrections to Radio Bearer Setup A26 F 8.9.0 8.10.0 R5-100054 RP-47 RP-100140 0802 - Corrections to Radio Bearer Setup message for A17b/c Configurations F 8.9.0 8.10.0 R5-100241 RP-47 RP-100154 0803 - CR to 34.108: Update of test frequencies for extended UMTS1500 operating bands F 8.9.0 8.10.0 R5-100253 RP-47 RP-100137 0804 - Addition of new combinations for LCR TDD RAB testing in 34.108 F 8.9.0 8.10.0 R5-100336 RP-47 RP-100151 0805 - Update of the default RADIO BEARER SETUP F 8.9.0 8.10.0 R5-100337	RP-45	RP-091119	0800	-		F	8.8.0	8.9.0	R5-096706
Configurations CR to 34.108: Update of test frequencies for extended F 8.9.0 8.10.0 R5-100253 UMTS1500 operating bands RP-47 RP-100137 0804 Addition of new combinations for LCR TDD RAB testing F 8.9.0 8.10.0 R5-100336 RP-47 RP-100151 0805 Update of the default RADIO BEARER SETUP F 8.9.0 8.10.0 R5-100337 R	RP-47	RP-100141	0801	-		F	8.9.0	8.10.0	R5-100054
RP-47 RP-100154 0803 - CR to 34.108: Update of test frequencies for extended UMTS1500 operating bands F 8.9.0 8.10.0 R5-100253 RP-47 RP-100137 0804 - Addition of new combinations for LCR TDD RAB testing in 34.108 F 8.9.0 8.10.0 R5-100336 RP-47 RP-100151 0805 - Update of the default RADIO BEARER SETUP F 8.9.0 8.10.0 R5-100337	RP-47	RP-100140	0802	-		F	8.9.0	8.10.0	R5-100241
RP-47 RP-100137 0804 - Addition of new combinations for LCR TDD RAB testing in 34.108 F 8.9.0 8.10.0 R5-100336 RP-47 RP-100151 0805 - Update of the default RADIO BEARER SETUP F 8.9.0 8.10.0 R5-100337	RP-47	RP-100154	0803	-	CR to 34.108: Update of test frequencies for extended	F	8.9.0	8.10.0	R5-100253
RP-47 RP-100151 0805 - Update of the default RADIO BEARER SETUP F 8.9.0 8.10.0 R5-100337	RP-47	RP-100137	0804	-	Addition of new combinations for LCR TDD RAB testing	F	8.9.0	8.10.0	R5-100336
	RP-47	RP-100151	0805	-		F	8.9.0	8.10.0	R5-100337

Meetin g-1st- Level	Doc-1st-Level	CR	Rev	Subject	Cat	Version -Current		Doc-2nd- Level
RP-47	RP-100157	0806		TDD Introduction of Default Message Contents for CPC of	F	8.9.0	8.10.0	R5-100388
RP-47	RP-100157	0806	-	1.28Mcps TDD	F	8.9.0	8.10.0	R5-100388
RP-47	RP-100158	0807	-	Introduction of Default Message Contents for MIMO of 1.28Mcps TDD	F	8.9.0	8.10.0	R5-100389
RP-47	RP-100141	8080	-	Addition of reference HARQ Transmission Parameters for the combination of MIMO and 64QAM	F	8.9.0	8.10.0	R5-100525
RP-47	RP-100149	0809	-	CR to 34.108: Correction to RADIO BEARER SETUP condition for sub-test 5 in 5.2B test case	F	8.9.0	8.10.0	R5-100563
RP-47	RP-100150	0810	-	Correction to SIB5 for Enhanced CELL_FACH in UL and DL	F	8.9.0	8.10.0	R5-100632
RP-47	RP-100150	0811	-	Addition of RRC Connection Setup Default Condition for Enhanced CELL_FACH in UL cases	F	8.9.0	8.10.0	R5-100634
RP-47	RP-100150	0812	-	Addition of Default Radio Bearer Conditions for Enhanced UL in CELL_FACH	F	8.9.0	8.10.0	R5-100635
RP-47	RP-100140	0814	-	Correction to default RRC Connection setup message for HS-DSCH in CELL_FACH	F	8.9.0	8.10.0	R5-100681
RP-47	RP-100142	0819	-	Update of 9.2 Default RF Messages for TC7.8.5	F	8.9.0	8.10.0	R5-100726
RP-47	RP-100149	0815	=	Update of the default RADIO BEARER SETUP message (FDD) for support of Dual Carrier Adjacent Channels for HSDPA for radio bearer testing	F	8.9.0	8.10.0	R5-100769
RP-47	RP-100149	0816	-	Introduction of test frequencies to DC-HSDPA tests	F	8.9.0	8.10.0	R5-100875
RP-47	RP-100140	0817	-	Correction to Enhanced CELL_FACH RAB configuration	F	8.9.0	8.10.0	R5-101107
RP-47	RP-100149	0818	-	Update of physical channel params on HS-PDSCH for DC-HSDPA	F	8.9.0	8.10.0	R5-101181
RP-47	-	-	-	Moved to v9.0.0 with no change	-	8.10.0	9.0.0	-
RP-48	RP-100508	0820	-	Correction to Radio Bearer Setup message for A17b & A17c Configurations	F	9.0.0	9.1.0	R5-103030
RP-48	RP-100523	0821	-	CR to 34.108: Introduction of test frequencies of band XXI to DC-HSDPA tests	F	9.0.0	9.1.0	R5-103100
RP-48	RP-100511	0822	-	Default SIB5 contents for UEs supporting Enhanced UL/DL in CELL_FACH state	F	9.0.0	9.1.0	R5-103152
RP-48	RP-100522	0823	-	Addition conditions in message RADIO BEARER SETUP and RRC CONNECTION SETUP for LCR TDD	F	9.0.0	9.1.0	R5-103182
RP-48	RP-100508	0824	-	Specify the MAC-c header for the reference RB combinations on PRACH and HS-DSCH in 6.10.2.4.7	F	9.0.0	9.1.0	R5-103286
RP-48	RP-100525	0825	-	Adding eCall services support in Elementary File USIM Service Table - EFUST	F	9.0.0	9.1.0	R5-103399
RP-48	RP-100511	0826	-	Aligning UTRAN USIM parameters for multi-RAT devices	F	9.0.0	9.1.0	R5-103659
RP-48	RP-100518	0827	-	Addition of HNB related information	F	9.0.0	9.1.0	R5-103668
RP-48	RP-100508	0828	-	Amendment to some radio bearer configurations for 7.68 Mcps TDD	F	9.0.0	9.1.0	R5-103685
RP-48	RP-100517	0829	-		F	9.0.0	9.1.0	R5-103725
RP-48	RP-100521	0833	-	Support for UMTS/LTE 800MHz for Europe in 34.108	F	9.0.0	9.1.0	R5-103766
RP-48	RP-100505	0830	-	Addition band d and band e for LCR TDD in 34.108	F	9.0.0	9.1.0	R5-103812
RP-48	RP-100519	0831	-	Correction to default Enhanced UL in CELL_FACH RB condition A29	F	9.0.0	9.1.0	R5-103862
RP-49	RP-100811	0834	-	Correction to Radio Bearer Setup message for MiMo configurations	F	9.1.0	9.2.0	R5-104320
RP-49	RP-100811	0835	-	Updating code allocation for MiMo configurations	F	9.1.0	9.2.0	R5-104321
RP-49	RP-100830	0836	-	Addition of new combinations on HS-PDSCH and E- PUCH for LCR TDD improved L2	F	9.1.0	9.2.0	R5-104359
RP-49	RP-100833	0837	-	Addition of default message contents for WLAN interworking testing	F	9.1.0	9.2.0	R5-104397
RP-49	RP-100985	0838	-	Update of the default RADIO BEARER SETUP message (FDD) for support of Dual Carrier HSDPA	F	9.1.0	9.2.0	R5-104470
RP-49	RP-100811	0839	-	Correction to RB Setup message condition used for testcase 14.7.6b	F	9.1.0	9.2.0	R5-104570
RP-49	RP-100808	0840	-	Correcting default USIM contents	F	9.1.0	9.2.0	R5-104679
RP-49	RP-100985	0841	-	Correction to the explanation of A25 set of RBsetup	F	9.1.0	9.2.0	R5-104680

Meetin g-1st- Level	Doc-1st-Level	CR	Rev	Subject	Cat	Version -Current	Version -New	Doc-2nd- Level
RP-49	RP-100811	0842	-	Change the default value of Qrxlevmin for LCR TDD	F	9.1.0	9.2.0	R5-105018
RP-49	RP-100808	0843	-	Clarification to the FDD inter-band network environment	F	9.1.0	9.2.0	R5-105031
RP-50	RP-101137	0844	-	Corrections to SIB5 contents for Enhanced Cell FACH DL testcases	F	9.2.0	9.3.0	R5-106218
RP-50	RP-101137	0845	-	Corrections to RRC Connection setup contents for Enhanced Cell FACH DL testcases	F	9.2.0	9.3.0	R5-106219
RP-50	RP-101158	0846	-	Adding new IEs related to PPAC to the default system information block type 3	F	9.2.0	9.3.0	R5-106260
RP-50	RP-101134	0847	-	Addition SIB schedule for LCR TDD two S-CCPCH or two PRACH	F	9.2.0	9.3.0	R5-106343
RP-50	RP-101134	0848	-	Correction the TTI for LCR TDD 3.4kbps SRBs (multiframe)	F	9.2.0	9.3.0	R5-106344
RP-50	RP-101134	0849	-	Update for Band IX testing	F	9.2.0	9.3.0	R5-106382
RP-50	RP-101160	0850	-	Addition of radio bearer parameters for UE HS-DSCH Physical Layer category 25 to 28	F	9.2.0	9.3.0	R5-106435
RP-50	RP-101134	0851	-	Update of the default RADIO BEARER SETUP message (FDD) for support of SRBs mapped on E- DCH/DCH	F	9.2.0	9.3.0	R5-106499
RP-50	RP-101134	0852	-	Correction to DL DPCH transmit power for 64 KBPS CS + 64 KBPS PS call	F	9.2.0	9.3.0	R5-106669
RP-50	RP-101134	0853	-	Corrections to default settings of Elementary Files (EFs) on Test USIM	F	9.2.0	9.3.0	R5-106701
RP-50	RP-101138	0854	-	GPS Assistance Data corrections	F	9.2.0	9.3.0	R5-106814
RP-51	RP-110153	0855	-	Correction Physical channel parameters of downlink 128kbps PS RAB for LCR TDD in 34.108	F	9.3.0	9.4.0	R5-110615
RP-51	RP-110153	0856	-	Correction UARFCN and Frequency of band e for LCR TDD in 34.108	F	9.3.0	9.4.0	R5-110620
RP-51	RP-110165	0857	=	Reduce the channel code for HS-SCCH and HS-SICH, and adjust channel code of E-AGCH and E-HICH for LCR TDD BADIO BEARER SETUP	F	9.3.0	9.4.0	R5-110621
RP-51	RP-110154	0858	-	Reduce the channel code for HS-SCCH and HS-SICH for LCRTDD SIB5	F	9.3.0	9.4.0	R5-110622
RP-51	RP-110165	0859	-	Addition of comments for Rel-8 UE behaviour in section 7.2.4 (session setup)	F	9.3.0	9.4.0	R5-110667
RP-51	RP-110177	0860	-	Update of the default RADIO BEARER SETUP message (FDD) for support of combination of DC- HSDPA with MIMO	F	9.3.0	9.4.0	R5-110695
RP-52	RP-110642	0861	-	Corrections to RRC Connection Setup message default contents for conditions A4 and A6	F	9.4.0	9.5.0	R5-112420
RP-52	RP-110651	0862	-	Correction to RB setup message for DC-HSDPA	F	9.4.0	9.5.0	R5-112432
RP-52	RP-110667	0863	-	Addition of DB-DC-HSDPA into 34.108	F	9.4.0	9.5.0	R5-112840
RP-53	RP-111150	0864	-	Adding RF procedure for DC-HSUPA tests	F	9.5.0	9.6.0	R5-113080
RP-53	RP-111152	0865	-	Removal of A-GPS Assistance Data	F	9.5.0	9.6.0	R5-113144
RP-53	RP-111131	0866	-	Correction the contents of PHYSICAL CHANNEL RECONFIGURATION in 34.108 for LCR TDD	F	9.5.0	9.6.0	R5-113244
RP-53	RP-111133	0867	-	Corrections to RRC Connection Setup message (Enhanced FACH Donwlink)	F	9.5.0	9.6.0	R5-113616
RP-53	RP-111146	0868	-	Modification for Rel-9 HNB protocol testing	F	9.5.0	9.6.0	R5-113777
RP-53	RP-111142	0869	-	Corrections to Radio Bearer Setup message (DC-HSDPA)	F	9.5.0	9.6.0	R5-113791
RP-53	RP-111133	0870	-	Addition of the default RADIO BEARER SETUP message (FDD) for support of 16QAM+MIMO for HSDPA.	F	9.5.0	9.6.0	R5-113799
RP-54	RP-111583	0871	-	Add new SIB scheduling for long SIB5/SIB5bis	F	9.6.0	9.7.0	R5-115102
RP-54	RP-111597	0873	-	Adding band XXII (3500MHz) to 34.108	F	9.6.0	9.7.0	R5-115192
RP-54	RP-111572	0874	-	Correction the TFCI code word / radio frame for downlink in 6.11.5.4.14 for LCR TDD	F	9.6.0	9.7.0	R5-115278
RP-54	RP-111571	0875	-	Use of IPv4 in session setup procedure	F	9.6.0	9.7.0	R5-115369
RP-54	RP-111574	0876	-	Introduction of reference radio bearer combination for NISPC testing	F	9.6.0	9.7.0	R5-115398

Meetin g-1st- Level	Doc-1st-Level	CR	Rev	Subject	Cat	Version -Current		Doc-2nd- Level
RP-54	-	-	-	Moved to Rel-10 with no change	-	9.7.0	10.0.0	-
RP-54	RP-111601	0872	-	Addition of test procedure for performance requirement under multiple-cell scenario for 1,28 Mcps TDD	F	10.0.0	11.0.0	R5-115130
RP-55	RP-120172	0879	-	LCR TDD enhancement of RRC messages to Rel-10	F	11.0.0	11.1.0	R5-120491
RP-55	RP-120194	0880	-	Addition of radio bearer parameters for UE E-DCH physical layer categories 8 and 9	F	11.0.0	11.1.0	R5-120539
RP-55	RP-120183	0881	-	Correction to Radio Bearer Setup message (mac-i/is)	F	11.0.0	11.1.0	R5-120605
RP-55	RP-120184	0882	-	Define generic procedure and default HSPA RB for IMS emergency call setup.	F	11.0.0	11.1.0	R5-120687
RP-56	RP-120663	0883	-	Introduction of default messages for ANR for UTRAN test cases	F	11.1.0	11.2.0	R5-121101
RP-56	RP-120655	0884	-	Addition of Generic IMS Emergency call set up procedure for mobile originating packet switched sessions - Limited Service	F	11.1.0	11.2.0	R5-121115
RP-56	RP-120664	0885	-	Update of System Information Block Type 3	F	11.1.0	11.2.0	R5-121117
RP-56	RP-120664	0886	-	Addition of 4C-HSDPA into 34.108	F	11.1.0	11.2.0	R5-121119
RP-56	RP-120648	0887	-	Introduce an access control class default value	F	11.1.0	11.2.0	R5-121120
RP-56	RP-120636	0888	-	Addition of default power levels of physical channels for LCR TDD	F	11.1.0	11.2.0	R5-121124
RP-56	RP-120669	0889	-	Correction to references for A-GPS	F	11.1.0	11.2.0	R5-121125
RP-56	RP-120656	0890	-	Introduction of default RRC messages for DC-HSUPA	F	11.1.0	11.2.0	R5-121255
RP-56	RP-120656	0891	-	Introduction of new reference radio bearer combination for DC-HSUPA MAC testing	F	11.1.0	11.2.0	R5-121355
RP-56	RP-120635	0892	-	Correction to QoS for requested bearer	F	11.1.0	11.2.0	R5-121434
RP-56	RP-120648	0893	-	Clarification of the scope of Band a for 1.28 Mcps TDD option in TS 34.108	F	11.1.0	11.2.0	R5-121454
RP-56	RP-120640	0894	-	Correction to RF Default Messages for TDD in 34.108	F	11.1.0	11.2.0	R5-121537
RP-56	RP-120648	0895	-	Correction of enhanced CELL_FACH uplink channel configuration	F	11.1.0	11.2.0	R5-121688
RP-56	RP-120648	0896	-	Addition of default System Information Block Type 19 into 34.108	F	11.1.0	11.2.0	R5-121718
RP-56	RP-120664	0897	-	Update of Radio Bearer Reconfiguration Message	F	11.1.0	11.2.0	R5-121818
RP-56	RP-120664	0898	-	Update of the default RADIO BEARER SETUP message (FDD) for support of 4C HSDPA	F	11.1.0	11.2.0	R5-121819
RP-56	RP-120640	0899	-	Correction to Default SI Messages for TDD in 34.108	F	11.1.0	11.2.0	R5-121943
RP-56	RP-120656	0900	-	Definition of default RB SETUP message for DC- HSUPA RF tests in section 9.2	F	11.1.0	11.2.0	R5-121953
RP-56	RP-120656	0901	-	RB SETUP message for DC-HSUPA RF tests	F	11.1.0	11.2.0	R5-121993
RP-57	RP-121090	0902	-	Change the UL and DL Transport channel information common in RB release message for A5-A8 and A10 for LCR TDD in 34.108	F	11.2.0	11.3.0	R5-123193
RP-57	RP-121093	0903	-	Addition some IE's default value for LCR TDD in 34.108	F	11.2.0	11.3.0	R5-123195
RP-57	RP-121109	0904	-	Correction to radio beared message content for DC-HSUPA tests	F	11.2.0	11.3.0	R5-123240
RP-57	RP-121103	0905	-	Correction of reference test frequency in band e for 1.28 Mcps option	F	11.2.0	11.3.0	R5-123374
RP-57	RP-121109	0906	-	Correction to RADIO BEARER SETUP message for DC-HSUPA protocol testing	F	11.2.0	11.3.0	R5-123471
RP-57	RP-121111	0907	-	Adding FDD reference test frequencies for Operating Band XXV	F	11.2.0	11.3.0	R5-123711
RP-57	RP-121094	0908	-	Correction to Default SIB5 for TDD in 34.108	F	11.2.0	11.3.0	R5-123717
RP-57	RP-121102	0909	-	Correction to default contents of Radio Bearer Setup message for configuration A19a in 34.108	F	11.2.0	11.3.0	R5-123745
RP-57	RP-121090	0910	-	Addition default physical channels code allocation for Signalling for LCR TDD in 34.108	F	11.2.0	11.3.0	R5-123770
RP-58	RP-121654	0911	-	Addition of new condition A19b to defualt message content for Radio Bearer setup message	F	11.3.0	11.4.0	R5-125082

Meetin g-1st- Level	Doc-1st-Level	CR	Rev	Subject	Cat	Version -Current		Doc-2nd- Level
RP-58	RP-121673	0912	-	Addition of 16QAM releted IEs to RB Setup message for DC-HSUPA	F	11.3.0	11.4.0	R5-125248
RP-58	RP-121663	0913	-	Correction to MAC-ehs window size in RB SETUP message(DC-HSDPA)	F	11.3.0	11.4.0	R5-125400
RP-58	RP-121705	0914	-	Addition of a connection set up procedure for CS+PS multi RAB combination.	F	11.3.0	11.4.0	R5-125480
RP-58	RP-121663	0915	-	Clarification of IPv6 signalling	F	11.3.0	11.4.0	R5-125676
RP-58	RP-121654	0916	-	Correction to default RADIO BEARER SETUP message (FDD) condition A28a for support of MIMO/Non-MIMO Co-existence Tests	F	11.3.0	11.4.0	R5-125677
RP-58	RP-121680	0917	-	Update of the default RADIO BEARER SETUP message (FDD) for support of 4C HSDPA	F	11.3.0	11.4.0	R5-125688
RP-58	RP-121653	0918	-	Correction some parameters value in 34.108 for LCR TDD	F	11.3.0	11.4.0	R5-126014
RP-59	RP-130145	0919	-	Correction the default value of RACH and E-RUCCH in SIB5 for 1.28Mcps TDD	F	11.4.0	11.5.0	R5-130165
RP-59	RP-130145	0920	-		F	11.4.0	11.5.0	R5-130235
RP-59	RP-130145	0921	-	Addition of test frequencies for DC-HSUPA	F	11.4.0	11.5.0	R5-130236
RP-60	RP-130625	0922	-	Addition of default IEs for MDT	F	11.5.0	11.6.0	R5-131420
RP-60	RP-130609	0923	-	Addition of FDD reference test frequencies for Operating Band XXVI (FDD26) into TS 34.108	F	11.5.0	11.6.0	R5-131755
RP-60	RP-130621	0924	-	Test frequencies for 3C/4C HSDPA	F	11.5.0	11.6.0	R5-131773
RP-60	RP-130611	0925	-	Update the default message content of RRC CONNECTION REQUEST	F	11.5.0	11.6.0	R5-131874
RP-61	RP-131099	0926	-	Correction of specific Message contents of Radio Bearer Setup message for condition A25b, A17d and A17e	F	11.6.0	11.7.0	R5-133096
RP-61	RP-131102	0927	-	Correction the contents of condition A19 and A20 for RADIO BEARER SETUP of 1.28Mcps TDD	F	11.6.0	11.7.0	R5-133209
RP-61	RP-131112	0928	-	Correction to default ACTIVE SET UPDATE message	F	11.6.0	11.7.0	R5-133211
RP-61	RP-131100	0929	-	Correction to Midamble configuration in SIB5(1.28 Mcps TDD)	F	11.6.0	11.7.0	R5-133439
RP-61	RP-131100	0930	-	/	F	11.6.0	11.7.0	R5-133560
RP-61	RP-131100	0931	-	Definition of default contents for EF HPLMNwAcT on TestUSIM	F	11.6.0	11.7.0	R5-133561
RP-61	RP-131112	0932	-	Update of RB Setup for Conditions A33, A34, A35 and A36	F	11.6.0	11.7.0	R5-133634
RP-61	RP-131257	0933	-	Correction the default configuration for FACH of 1.28Mcps TDD	F	11.6.0	11.7.0	R5-133724
RP-61	RP-131121	0934	-	Addition of test procedure for RF to configure UL CLTD	F	11.6.0	11.7.0	R5-133877
RP-62	RP-131875	0935	-	Update of RB Setup for Conditions A33, A34, A35 and A36 and addition of new condition A37	F	11.7.0	11.8.0	R5-134693
RP-62	RP-131875	0936	-	Introduction of FDD downlink physical channels code allocation for E-DCH signalling testing using HSDPA configuration with 64QAM and MIMO	F	11.7.0	11.8.0	R5-134694
RP-62	RP-131858	0937	-	Correction of the value of UL target SIR for DPCH for LCR TDD	F	11.7.0	11.8.0	R5-134734
RP-62	RP-131857	0938	-	Correction to reference test frequencies for Band XII, XXV and XXVI	F	11.7.0	11.8.0	R5-134905
RP-62	RP-131878	0939	-	Addition of default IEs for eMDT	F	11.7.0	11.8.0	R5-134915
RP-62	RP-131881	0940	-	Addition of test procedure for UL OLTD	F	11.7.0	11.8.0	R5-134971
RP-63	RP-140303	0941	-	Correction of Midamble Configuration for LCR TDD	F	11.8.0	11.9.0	R5-140195
RP-63	RP-140324	0942	-	Addition of test procedure to configure UL CLTD with EDCH	F	11.8.0	11.9.0	R5-140472
RP-63	RP-140324	0943	-	Addition of test procedure for RF to configure UL OLTD with E-DCH	F	11.8.0	11.9.0	R5-140533
RP-63	RP-140308	0944	-	Correction to Default Radio Bearer Setup message	F	11.8.0	11.9.0	R5-140676
RP-63	R5-140319	0945		Minor correction of 4C-HSDPA RADIO BEARER SETUP	F	11.8.0	11.9.0	R5-140677

Meetin g-1st- Level	Doc-1st-Level	CR	Rev	Subject	Cat	Version -Current	Version -New	Doc-2nd- Level
RP-63	RP-140306	0946	-	Correction to default RADIO BEARER SETUP message (DC-HSDPA, DB-DC-HSDPA and 4C)	F	11.8.0	11.9.0	R5-140678
RP-63	RP-140306	0947	-	Introduction of generic HOLD and MPTY set up procedures	F	11.8.0	11.9.0	R5-140683
RP-63	RP-140306	0948	-	Adding default messages for supplementary service testing	F	11.8.0	11.9.0	R5-140684
RP-63	RP-140330	0949	-	Update Radio Bearer Setup message for Multiflow HSDPA tests	F	11.8.0	11.9.0	R5-140964
RP-64	RP-140836	0950	-	Update Radio Bearer Setup message for Multiflow HSDPA tests	F	11.9.0	11.10.0	R5-142116
RP-64	RP-140811	0951	-	Update to clause 6.10.2.4.6.1.	F	11.9.0	11.10.0	R5-142118
RP-64	RP-140812	0952	-	Correction to MPTY call setup procedure	F	11.9.0	11.10.0	R5-142136
RP-64	RP-140810	0953	-	Correction of Midamble Configuration of FPACH for LCR TDD	F	11.9.0	11.10.0	R5-142291
RP-64	RP-140837	0954	-	Addition of default message content for SIB21	F	11.9.0	11.10.0	R5-142418
RP-64	RP-140810	0955	-	Correction to Radio Bearer Setup Message for TD- SCDMA	F	11.9.0	11.10.0	R5-142431
RP-64	RP-140836	0956	-	Addition of Multiflow HSDPA into TS 34.108	F	11.9.0	11.10.0	R5-142805
RP-64	RP-140837	0957	-	Addition of SIB schedule for EAB test cases	F	11.9.0	11.10.0	R5-142807
RP-65	RP-141592	0958	-	Update Radio Bearer Setup message for Multiflow HSDPA tests	F	11.10.0	11.11.0	R5-144261
RP-65	RP-141575	0959	-	Updates to section 7.5 and addition of new clauses 7.5.6, 7.5.7, 7.5.8 and 7.5.9 of 34.108	F	11.10.0	11.11.0	R5-144408
RP-65	RP-141575	0960	-	Update to missing dual band combinations of 4C-HSDPA configurations	F	11.10.0	11.11.0	R5-144532
RP-65	RP-141570	0961	-	Editorial correction to Radio bearer Setup Message for TD-SCDMA	F	11.10.0	11.11.0	R5-144623
RP-65	RP-141591	0962	-	Adding SIB22 scheduling and SIB22 default message for Enhanced CELL_FACH testing	F	11.10.0	11.11.0	R5-144708
RP-65	RP-141575	0963	-	Addition of E-UTRA Capability in RRC Connection Setup	F	11.10.0	11.11.0	R5-144813
RP-66	RP-142053	0964	-	Corrections to the default message contents for SS	F	11.11.0	11.12.0	R5-145090
RP-66	RP-142072	0965	-	New common procedure for Active Set Update	F	11.11.0	11.12.0	R5-145141
RP-66	RP-142053	0966	-	Correction to frequency band indicator for SIB5	F	11.11.0	11.12.0	R5-145171
RP-66	RP-142053	0967	-	Correction to default value of System Information Block type 5 for FDD	F	11.11.0	11.12.0	R5-145647
RP-66	RP-142058	0968	-		F	11.11.0	11.12.0	R5-145758
RP-66	RP-142072	0969	-	Corrections in the default RADIO BEARER SETUP message for Multiflow	F	11.11.0	11.12.0	R5-145759
RP-66	RP-142072	0970	-	Introduction of a new configuration A17f in default RADIO BEARER SETUP message	F	11.11.0	11.12.0	R5-145760
RP-67	RP-150322	0971	-	Correction to Contents of System Information Block Type 5 for condition B2 & B3	F	11.12.0	11.13.0	R5-150096
RP-67	RP-150322	0972	-		F	11.12.0	11.13.0	R5-150153
RP-67	RP-150325	0973	-	Corrections in the default RADIO BEARER SETUP	F	11.12.0	11.13.0	R5-150541
RP-67	RP-150327	0974	-	message for DC-HSDPA with MIMO Corrections in the default RADIO BEARER SETUP	F	11.12.0	11.13.0	R5-150542
RP-67	RP-150339	0975	-	message for 4C-HSDPA Corrections in the default RADIO BEARER SETUP	F	11.12.0	11.13.0	R5-150544
RP-67	RP-150322	0976	-	1 0	F	11.12.0	11.13.0	R5-150605
RP-67	RP-150321	0977	-	Correction to the default RADIO BEARER SETUP	F	11.12.0	11.13.0	R5-150619
RP-68	RP-150886	0983	-	message for A28a MIMO/nonMIMO Correction to RADIO BEARER SETUP message	F	11.13.0	11.14.0	R5-151712
RP-70	RP-151696	0987	-	condition A25c Removal of technical content in 34.108 v11.14.0 and	F	11.14.0	11.15.0	R5-155025
<u> </u>	<u> </u>	<u> </u>	1	substitution with pointer to the next Release	<u> </u>	<u>I</u>	l	

History

	Document history								
V11.3.0	October 2012	Publication							
V11.4.0	February 2013	Publication							
V11.5.0	May 2013	Publication							
V11.6.0	July 2013	Publication							
V11.7.0	October 2013	Publication							
V11.8.0	February 2014	Publication							
V11.9.0	April 2014	Publication							
V11.10.0	August 2014	Publication							
V11.11.0	October 2014	Publication							
V11.12.0	January 2015	Publication							
V11.13.0	April 2015	Publication							
V11.14.0	August 2015	Publication							
V11.15.0	January 2016	Publication							