
## ETSITS 134 108 V6.6.0 (2007-03)

Technical Specification

Universal Mobile Telecommunications System (UMTS); Common test environments for User Equipment (UE); Conformance testing (3GPP TS 34.108 version 6.6.0 Release 6)



Reference
RTS/TSGR-0534108v660

Keywords
UMTS

#### **ETSI**

650 Route des Lucioles F-06921 Sophia Antipolis Cedex - FRANCE

Tel.: +33 4 92 94 42 00 Fax: +33 4 93 65 47 16

Siret N° 348 623 562 00017 - NAF 742 C Association à but non lucratif enregistrée à la Sous-Préfecture de Grasse (06) N° 7803/88

#### Important notice

Individual copies of the present document can be downloaded from: <u>http://www.etsi.org</u>

The present document may be made available in more than one electronic version or in print. In any case of existing or perceived difference in contents between such versions, the reference version is the Portable Document Format (PDF). In case of dispute, the reference shall be the printing on ETSI printers of the PDF version kept on a specific network drive within ETSI Secretariat.

Users of the present document should be aware that the document may be subject to revision or change of status.

Information on the current status of this and other ETSI documents is available at

<a href="http://portal.etsi.org/tb/status/status.asp">http://portal.etsi.org/tb/status/status.asp</a></a>

#### **Copyright Notification**

No part may be reproduced except as authorized by written permission. The copyright and the foregoing restriction extend to reproduction in all media.

© European Telecommunications Standards Institute 2007. All rights reserved.

**DECT**<sup>TM</sup>, **PLUGTESTS**<sup>TM</sup> and **UMTS**<sup>TM</sup> are Trade Marks of ETSI registered for the benefit of its Members. **TIPHON**<sup>TM</sup> and the **TIPHON logo** are Trade Marks currently being registered by ETSI for the benefit of its Members. **3GPP**<sup>TM</sup> is a Trade Mark of ETSI registered for the benefit of its Members and of the 3GPP Organizational Partners.

## Intellectual Property Rights

IPRs essential or potentially essential to the present document may have been declared to ETSI. The information pertaining to these essential IPRs, if any, is publicly available for **ETSI members and non-members**, and can be found in ETSI SR 000 314: "Intellectual Property Rights (IPRs); Essential, or potentially Essential, IPRs notified to ETSI in respect of ETSI standards", which is available from the ETSI Secretariat. Latest updates are available on the ETSI Web server (http://webapp.etsi.org/IPR/home.asp).

Pursuant to the ETSI IPR Policy, no investigation, including IPR searches, has been carried out by ETSI. No guarantee can be given as to the existence of other IPRs not referenced in ETSI SR 000 314 (or the updates on the ETSI Web server) which are, or may be, or may become, essential to the present document.

#### **Foreword**

This Technical Specification (TS) has been produced by ETSI 3rd Generation Partnership Project (3GPP).

The present document may refer to technical specifications or reports using their 3GPP identities, UMTS identities or GSM identities. These should be interpreted as being references to the corresponding ETSI deliverables.

The cross reference between GSM, UMTS, 3GPP and ETSI identities can be found under <a href="http://webapp.etsi.org/key/queryform.asp">http://webapp.etsi.org/key/queryform.asp</a>.

## Contents

Inte	llectual Property Rights	2
Fore	eword	2
Fore	eword	4
	oduction	
	Scope	
	References	
3	Definitions, abbreviations and symbols	5
	Requirements	
	10 Void	
Anı	nex A - C: Void	6
Anı	nex D (informative): Change history	7
	· · ·	

#### **Foreword**

This Technical Specification has been produced by the 3<sup>rd</sup> Generation Partnership Project (3GPP).

The contents of the present document are subject to continuing work within the TSG and may change following formal TSG approval. Should the TSG modify the contents of the present document, it will be re-released by the TSG with an identifying change of release date and an increase in version number as follows:

Version x.y.z

where:

- x the first digit:
  - 1 presented to TSG for information;
  - 2 presented to TSG for approval;
  - 3 or greater indicates TSG approved document under change control.
- y the second digit is incremented for all changes of substance, i.e. technical enhancements, corrections, updates, etc.
- z the third digit is incremented when editorial only changes have been incorporated in the document.

#### Introduction

The definition of the Conformance Tests for UE in 3G will be a complex task as the complete test suite covers RF, EMC and Protocol aspects of the UE.

Each test requires a Test Environment to be defined in which the UE has to operate to defined standards, constraints and performance. The overall task can be simplified if there are a number of well defined and agreed Common Test Environments where every one can be used for a number of tests. Hence the present documents defines testing conditions that are common to several tests avoiding the need to duplicate the same information for every single test.

The present document defines default values for a variety of common areas. Where values are not specified in test cases, the defaults in the present document will apply. If specified, the test case values will take precedence.

The present document addresses the FDD mode as well as the TDD mode.

## 1 Scope

The present document contains definitions of reference conditions and test signals, default parameters, reference radio bearer configurations used in radio bearer interoperability testing, common radio bearer configurations for other test purposes, common requirements for test equipment and generic set-up procedures for use in UE conformance tests.

### 2 References

The following documents contain provisions which, through reference in this text, constitute provisions of the present document.

- References are either specific (identified by date of publication, edition number, version number, etc.) or non-specific.
- For a specific reference, subsequent revisions do not apply.
- For a non-specific reference, the latest version applies. In the case of a reference to a 3GPP document (including a GSM document), a non-specific reference implicitly refers to the latest version of that document *in the same Release as the present document*.
- [1] 3GPP TS 34.108 (Release 7): "Common test environments for User Equipment (UE) conformance testing".

## 3 Definitions, abbreviations and symbols

(void)

## 4 Requirements

The requirements of the present document are provided in 3GPP TS 34.108 Release 7 [1].

#### 5 - 10 Void

Annex A - C: Void

# Annex D (informative): Change history

Meetin g-1st- Level	Doc-1st-Level	CR	Rev	Subject	Cat	Version -Current		Doc-2nd- Level
TP-08				Approval of the specification		2.0.0	3.0.0	
TP-09	TP-000131	001		RRC Message Contents: RLCSize	С	3.0.1	3.1.0	T1-000190
TP-09	TP-000131	002		RRC Message Contents: RLCParam	С	3.0.1	3.1.0	T1-000191
TP-09	TP-000131	003		RRC Message Contents: PCPreamble	С	3.0.1	3.1.0	T1-000192
TP-09	TP-000131	004		RRC Message Contents: RBIdentity	С	3.0.1	3.1.0	T1-000193
TP-09	TP-000131	005		RRC Message Contents: TrCHParam	С	3.0.1	3.1.0	T1-000194
TP-09	TP-000131	006		RRC Message Contents: UECapability	С	3.0.1	3.1.0	T1-000195
TP-09	TP-000131	007		RRC Message Contents: RBMapping	С	3.0.1	3.1.0	T1-000196
TP-09	TP-000131	800		RRC Message Contents: PagingCause	С	3.0.1	3.1.0	T1-000197
TP-09	TP-000131	009		RRC Message Contents: CipheringAndIntegrity	С	3.0.1	3.1.0	T1-000198
TP-09	TP-000131	010		RRC Message Contents: RLCInfo	С	3.0.1	3.1.0	T1-000199
TP-09	TP-000131	011		RRC Message Contents: CompressedMode	С	3.0.1	3.1.0	T1-000200
TP-09 TP-09	TP-000131 TP-000131	012 013		RRC Message Contents: SIB	С	3.0.1	3.1.0 3.1.0	T1-000201 T1-000202
TP-09	TP-000131			RRC Message Contents: PhyCH	С	3.0.1		
TP-09	TP-000131	014 015		RRC Message Contents: Measurement RRC Message Contents: TFCS	С	3.0.1	3.1.0	T1-000203 T1-000204
TP-09	TP-000131	016		RRC Message Contents: DPCHFrameOffset	С	3.0.1	3.1.0	T1-000204
TP-09	TP-000131	017		Test USIM Parameters	F	3.0.1	3.1.0	T1-000203
TP-09	TP-000131	017		Correction to definition of the test algorithm for	F	3.0.1	3.1.0	T1-000213
11-09	11-000131	010		authentication (clause 8.1.2)		3.0.1	3.1.0	11-000104
TP-09	TP-000131	019		Reference Radio Bearer Configurations	F	3.0.1	3.1.0	T1-000212
TP-09	TP-000131	020		TDD Single mode	F.	3.0.1	3.1.0	T1-000212
TP-10	TP-000215	021		Common generic procedure for AS testing	В	3.1.0	3.2.0	T1-000294
TP-10	TP-000215	022		Requirements for the system simulator for support of	F	3.1.0	3.2.0	T1-000303
	11 000210	022		Tcell parameter		0.1.0	0.2.0	
TP-10	TP-000215	023		Minimum Performance Levels	F	3.1.0	3.2.0	T1-000306
TP-10	TP-000215	024		Downlink signal conditions and propagation conditions	D	3.1.0	3.2.0	T1-000307
TP-10	TP-000215	025		Updating 34.108 v3.1.0 to TDD single mode	F	3.1.0	3.2.0	T1-000281
TP-10	TP-000215	026		Application of integrity mode protection to signalling	F	3.1.0	3.2.0	T1-000296
				message by default				
TP-10	TP-000215	027		Updates to the default message contents in clause 9	С	3.1.0	3.2.0	T1-000282
TP-10	TP-000215	028		Updates to System Information Block (SIB) and Master Information Block (MIB) messages	С	3.1.0	3.2.0	T1-000283
TP-10	TP-000215	029		Application of ciphering during conformance testing	С	3.1.0	3.2.0	T1-000285
TP-10	TP-000215	030		Addition for System Information parameters (34.108 clause 6.1)	F	3.1.0	3.2.0	T1-000304
TP-10	TP-000215	031		Correction for Generic Setup Procedures (34.108 clause 7.2)	F	3.1.0	3.2.0	T1-000305
TP-11	TP-010018	032		Default radio conditions for multi-cell environment	F	3.2.0	3.3.0	T1-010078
TP-11	TP-010018	033		Correction for Generic Setup Procedures (34.108 clause 7.2)	F	3.2.0	3.3.0	T1-010079
TP-11	TP-010018	034		Corrections for Test USIM Parameters(34.108 clause 8)	F	3.2.0	3.3.0	T1-010080
TP-11	TP-010018	035		Correction of clause number in TS 34.108.	D	3.2.0	3.3.0	T1-010081
TP-11	TP-010018	036		Update of authentication test algorithm	С	3.2.0	3.3.0	T1-010082
TP-11	TP-010018	037		Updates to clause 9 of TS 34.108 v3.2.0	F	3.2.0	3.3.0	T1-010084
	TP-010018	038		Updating to TDD single mode	F	3.2.0	3.3.0	T1-010088
TP-11	TP-010018	039		Simulated network environments for TDD mode (SIB)	F	3.2.0	3.3.0	T1-010089
TP-12	TP-010118	040		Corrections to clause 6.10 FDD parameters	F	3.3.0	3.4.0	T1-010205
TP-12	TP-010118	041		Corrections to clause 6.10 TDD parameters	F	3.3.0	3.4.0	T1-010206
TP-12	TP-010118	042		Adding section for radio bearer configurations intended for functional testing	D	3.3.0	3.4.0	T1-010210
TP-12	TP-010118	043		Update of list of abbreviations	D	3.3.0	3.4.0	T1-010211
TP-12	TP-010118	044	<u> </u>	Updates to clause 6.1 and 9	F	3.3.0	3.4.0	T1-010212
	TP-010118	045		Updates to clause 7.4	F	3.3.0	3.4.0	T1-010213
TP-12	TP-010118	046		clause 6.1: System Information Blocks for TDD Mode	F	3.3.0	3.4.0	T1-010214
TP-12	TP-010118	047		Editorial corrections and removal of a reference document	F	3.3.0	3.4.0	T1-010215
TP-13	TP-010215	048		Correction to reference	F	3.4.0	3.5.0	T1-010275
TP-13	TP-010215	049		Editorial modification for References	F	3.4.0	3.5.0	T1-010276
	TP-010215	050	<u> </u>	Some corrections in clause 5	F	3.4.0	3.5.0	T1-010277
TP-13	TP-010215	051		Update to Scope Statement	F	3.4.0	3.5.0	T1-010278
TP-13	TP-010215	052		Clause 6.10 Definition of RB configurations, TDD parameters	F	3.4.0	3.5.0	T1-010279
TP-13	TP-010215	053		Updates to clause 6.1, clause 7.4 and clause 9	F	3.4.0	3.5.0	T1-010280

Meetin	Doc-1st-Level	CR	Rev	Subject	Cat	Version	Version	Doc-2nd-
g-1st- Level						-Current	-New	Level
TP-13	TP-010215	054		Clause 6.1: Default radio conditions for Signalling tests	F	3.4.0	3.5.0	T1-010281
TP-13	TP-010215	055		Correction of Radio Bearer Configurations for FDD Mode	F	3.4.0	3.5.0	T1-010282
TP-13	TP-010215	056		Correction of Radio Bearer Configurations for TDD Mode	F	3.4.0	3.5.0	T1-010283
TP-13	TP-010215	057		Changes to Signalling Radio Bearer (SRB) numbering	F	3.4.0	3.5.0	T1-010284
	TP-010215	058		Missing bearers in tables 6.10.2.1.1 and 6.10.3.1.1	F	3.4.0	3.5.0	T1-010285
TP-13	TP-010215	059		Correction of system information block 5	F	3.4.0	3.5.0	T1-010286
TP-13	TP-010215	060		Introducing of 1.28 Mcps TDD Mode in clauses 4, 5 and	F	3.4.0	4.0.0	T1-010287
TP-13	TP-010215	061		6 Introduction of System Information Blocks for 1.28	F	3.4.0	4.0.0	T1-010288
TP-13	TP-010215	062		Mcps TDD Mode Introduction of typical radio parameters for 1.28	F	3.4.0	4.0.0	T1-010289
	TP-010215	063		McpsTDD Clause 6.11 RBs for RLC and PDCP testing	F	3.4.0	3.5.0	T1-010290
	TP-010215	065	1	Correction to 6.1 Contents of System Information Blocks	•	4.0.0	4.1.0	T1-010230
	TP-010285	067	1	Corrections to clause 6.1. 7.4 and 9	Α	4.0.0		T1-010473
	TP-010258	069		Reference Radio Conditions	Α	4.0.0	4.1.0	T1-010461
	TP-010258	071		Modification of Test procedures for RF tests	A	4.0.0	4.1.0	T1-010463
	TP-010258	073		Default message contents for RF tests	A	4.0.0	4.1.0	T1-010465
	TP-010258	075		Correction to 6.10 Reference Radio Bearer configurations	A	4.0.0	4.1.0	T1-010467
TP-14	TP-010258	077		Definition of default value of rate matching attribute	Α	4.0.0	4.1.0	T1-010469
	TP-010258	079		Update of clause 7.4 and 6.10	A	4.0.0	4.1.0	T1-010471
	TP-010292	081		Correction on introduction of clause 6.10	A	4.0.0	4.1.0	
	TP-020038	083		Replacement of Block STTD by Space Code Transmit Diversity (SCTD) (Rel-4)	A	4.1.0	4.2.0	T1-020092
TP-15	TP-020038	085		Update of reference radio conditions (Rel-4)	Α	4.1.0	4.2.0	T1-020098
TP-15	TP-020038	087		Update of system reference configurations and default	Α	4.1.0	4.2.0	T1-020100
	11 020000	001		messages (Rel-4)	ľ ·	1	1.2.0	11 020100
TP-15	TP-020038	089		Corrections to 34108-410	Α	4.1.0	4.2.0	T1-020102
	TP-020038	091		Introduction of new Reference RABs (Rel-4)	Α	4.1.0		T1-020195
TP-15	TP-020038	094		Update of SIBs for TDD (both modes) in TS 34.108 (Rel4)	F	4.1.0	4.2.0	T1-020107
TP-15	TP-020038	095		Clarification of bit rate of Interactive/Background PS RAB function (Rel-4)	A	4.1.0	4.2.0	T1-020184
				Correction of CR implementation errors in clauses: 6.10.2.2 and 6.10.2.4.1.58.2.1.1		4.2.0	4.2.1	
TP-16	TP-020141	108		Clause 7(reference) Update of generic setup procedures to use 13.6 kbps SRB in RRC connection establishment TDD (3.84 Mcps and 1.28 Mcps)	F	4.2.1	4.3.0	T1-020289
TP-16	TP-020141	109		Correction to clause 7.3.3.4 RADIO BEARER SETUP message	A	4.2.1	4.3.0	T1-020291
TP-16	TP-020141	110		Change of RM attribute of DL:3.4 kbps SRBs for DCCH in for REL4	Α	4.2.1	4.3.0	T1-020292
TP-16	TP-020141	111		New additional RAB configuration (R1-020669) for REL4	Α	4.2.1	4.3.0	T1-020293
TP-16	TP-020141	112		Correction of Puncturing Limit for RABs for REL4	Α	4.2.1	4.3.0	T1-020294
TP-16	TP-020141	113		Test USIM	A	4.2.1	4.3.0	T1-020295
TP-16	TP-020141	114		Clause 6.1 (SIBs)Rel 4 (3.84 Mcps and 1.28 Mcps TDD)		4.2.1	4.3.0	T1-020296
TP-16	TP-020141	115		Clause 6.10 References for TDD about Clarification of bit rate of Interactive/Background PS RAB	Α		4.3.0	T1-020297
TP-16	TP-020141	116		Correction to default message in clause 9 for Rel4	Α	4.2.1	4.3.0	T1-020298
TP-16	TP-020141	117		Correction to clause 6.1 for Rel4	Α	4.2.1	4.3.0	T1-020299
TP-16	TP-020141	118		WCDMA1800 additions for Rel4	Α	4.2.1	4.3.0	T1-020300
TP-16	TP-020141	119		Clause 9.1 Default message contents for TDD (3.84 Mcps and 1.28 Mcps) R4	F	4.2.1	4.3.0	T1-020301
TP-16	TP-020141	121		Update of generic setup procedures to use 13.6 kbps SRB in RRC connection establishment	Α	4.2.1	4.3.0	T1-020434
TP-17	TP-020184	123	-	Alignment of reference configurations on S-CCPCH with default system information messages	A	4.3.0	4.4.0	T1-020503
TP-17	TP-020184	125	-	Addition of reference compressed mode pattern	Α	4.3.0	4.4.0	T1-020505
TP-17	TP-020184	127	-	Corrections to default message contents as T1S- 020347rev1	A	4.3.0	4.4.0	T1-020507
TP-17	TP-020184	129	<u> </u>	Additional default message contents for RF Testing	Α	4.3.0	4.4.0	T1-020509
TP-17	TP-020184	131	-	Corrections related to SIB11, SIB12 and to the	A	4.3.0	4.4.0	T1-020505
TP-17		133		MEASUREMENT CONTROL message	A			
TP-17	TP-020184 TP-020184	133	-	Corrections to clause 6.1 (T1S-020349rev1) Introduction of reference configurations on S-CCPCH		4.3.0 4.3.0	4.4.0 4.4.0	T1-020530 T1-020539
			-	and PRACH with two interactive PS domain RABs	A			
TP-17	TP-020184	137	<u> -</u>	Removal of reference radio bearer configurations for	Α	4.3.0	4.4.0	T1-020541

Meetin g-1st-	Doc-1st-Level	CR	Rev	Subject	Cat	Version -Current		Doc-2nd- Level
Level						-Current	-New	Level
TP-17	TP-020184	140	_	unidirectional streaming CS RABa above 64 kbps Some corrections and updates in clause 6.1 for TDD	F	4.3.0	4.4.0	T1-020576
11 -17	11 -020104			mode	•	4.5.0	4.4.0	
TP-17	TP-020184	142	-	Inclusion of default message contents for RF in clause 9.2 for TDD mode	F	4.3.0	4.4.0	T1-020578
TP-18	TP-020293	144	-	Correction to default messages in 9.1 and 9.2	Α	4.4.0	4.5.0	T1-020658
TP-18	TP-020293	146	-	Corrections in the TDD test frequencies according to core specs	Α	4.4.0	4.5.0	T1-020674
TP-18	TP-020293	148	-	Addition of alternative configuration using Turbo Coding for Interactive or background / UL:8 DL:8 kbps / PS RAB + UL:3.4 DL:3.4 kbps SRBs for DCCH	Α	4.4.0	4.5.0	T1-020694
TP-18	TP-020293	150	-	Correction to content of clause 6.10.2.	Α	4.4.0	4.5.0	T1-020709
TP-18	TP-020293	152	-	Correction to SIB 11/12 definition	Α	4.4.0	4.5.0	T1-020712
TP-18	TP-020293	154	-	Reference Measurement Channels	Α	4.4.0	4.5.0	T1-020768
TP-18	TP-020293	156	-	Transferring system information definition using ASN.1 description to PRD	Α	4.4.0	4.5.0	T1-020778
TP-18	TP-020293	158	-	Correction to RLC RAB TFCS	Α	4.4.0	4.5.0	T1-020780
TP-18	TP-020293	160	-	Default Message contents : Correction from CRs approved in RP17meeting	Α	4.4.0	4.5.0	T1-020783
TP-18	TP-020293	162	-	Corrections to SIB1 to SIB6	Α	4.4.0	4.5.0	T1-020799
TP-18	TP-020293	164	-	Correction to RAB configurations as revision of T1S020756	Α	4.4.0	4.5.0	T1-020801
TP-18	TP-020293	166	-	Parameter addition for Reference RABs based on LS from RAN2	Α	4.4.0	4.5.0	T1-020803
TP-18	TP-020293	168	-	Addition to clause 7.4 for multi call as T1S-020577rev2 (revision to T1S020820)	Α	4.4.0	4.5.0	T1-020818
TP-18	TP-020293	169	-	RAB Combinations for IMS Services	F	4.4.0	4.5.0	T1-020819
TP-18	TP-020293	171	-	Correction to Contents of the Scheduling Block Syste Information in clause 6.1.3.	F	4.4.0	4.5.0	T1-020844
TP-19	TP-030044	173	_		Α	4.5.0	4.6.0	T1-030037
TP-19	TP-030044	175	-	Combine all Radio Bearer Setup messages into one	Α	4.5.0	4.6.0	T1-030040
				table				
TP-19	TP-030044	177	-	Corrections to SB and SIB configurations in clause 6.1 as T1S030046rev1	Α	4.5.0	4.6.0	T1-030042
TP-19	TP-030044	179	-	Correction to TS 34.108 Rel-4 ; PAGING TYPE1 message (Packet in PS)	Α	4.5.0	4.6.0	T1-030044
TP-19	TP-030044	181	-	Clarification of autentication test algorithm and GSM cipher key	Α	4.5.0	4.6.0	T1-030046
TP-19	TP-030044	183	-	Addition of simulated network environment for inter-RAT test cases	A	4.5.0	4.6.0	T1-030048
TP-19	TP-030044	185	-	Corrections to SIB1 to align with default values for LAC and RAC in 51.010-1.	Α	4.5.0	4.6.0	T1-030050
TP-19	TP-030044	187	-	Addition of default inter-RAT handover messages	Α	4.5.0	4.6.0	T1-030052
TP-19	TP-030044	189	-	Correction of activation time IEs in default messages	Α	4.5.0	4.6.0	T1-030054
TP-19	TP-030044	191	-	Correction to default SECURITY MODE COMMAND message	Α	4.5.0	4.6.0	T1-030056
TP-19	TP-030044	193	-	Addition of option for UL CM only in default reference CM patterns	Α	4.5.0	4.6.0	T1-030058
TP-19	TP-030044	195	-	Introduction of a reference RB configuration for RMC for BTFD tests (Rel4)	Α	4.5.0	4.6.0	T1-030060
TP-19	TP-030044	197	-	Update of the RRC connection request messages in 34.108 Rel4	Α	4.5.0	4.6.0	T1-030063
TP-19	TP-030043	198	-	Introduction of Conversational PS RABs in Rel 4 TS 34.108 as T1S030003rev1	F	4.5.0	4.6.0	T1-030107
TP-19	TP-030043	200	-	Update of default parameters for 1 to 8 cell environments (TDD), clause 6.1.4, Rel 4	Α	4.5.0	4.6.0	T1-030208
TP-19	TP-030043	202	-	Update of Multi-cell environment for default radio	Α	4.5.0	4.6.0	T1-030210
TP-19	TP-030043	204	1_	conditions (TDD), clause 6.1.6 (Inclusion of cell 4), Rel 4 Modification to Generic Registration Procedures	Α	4.5.0	4.6.0	T1-030222
TP-19	TP-030043	206	<del> </del> -		A	4.5.0	4.6.0	T1-030222
<u> </u>				end UE				
TP-20	TP-030098	208	-	Reinstate parameters for Interactive or background /UL:64 kbps / PS RAB	Α	4.6.0	4.7.0	T1-030437
TP-20	TP-030098	210	1-	Correction to Figure 7.4.1.1 (Rel-4)	Α	4.6.0	4.7.0	T1-030483
TP-20	TP-030098	212	-	Update of SIB 11 and 12 in clause 6.1.0b in TS 34.108 (TDD)	Α	4.6.0	4.7.0	T1-030507
TP-20	TP-030098	214	-	Update of Default parameters for 1 to 8 cell environments in TS 34.108 (TDD)	Α	4.6.0	4.7.0	T1-030509
TP-20	TP-030098	216	-	Correction of default messages according to 25331 CR1823	Α	4.6.0	4.7.0	T1-030632
TP-20	TP-030098	218	†-	Clause 8.2: Definition of default values for	Α	4.6.0	4.7.0	T1-030644
	]	<u> </u>	1	authentication key K on test USIM				

Meetin g-1st-	Doc-1st-Level	CR	Rev	Subject	Cat	Version -Current	Version -New	Doc-2nd- Level
Level TP-20	TP-030098	219	_	Update of Reconfiguration messages	A	4.6.0	4.7.0	T1-030692
	TP-030098	221	-	Correction to RADIO BEARER RELEASE and RRC	Α	4.6.0	4.7.0	T1-030692
				CONNECTION SETUP messages (Revision of T1- 030569)				
TP-20	TP-030140	226	-	Correction to default SIB5 (FDD)	Α	4.6.0.	4.7.0	T1-030745
TP-21	TP-030191	228	-	CR to 34.108, Rel-4, Clarification of seg_count in 6.1.0a.3	Α	4.7.0	4.8.0	T1-030827
TP-21	TP-030191	230	-	General correction in clause 7.4 for Common generic procedures for AS testing	Α	4.7.0	4.8.0	T1-030976
TP-21	TP-030191	233	-	Incorrect activation time in CELL_FACH state .	Α	4.7.0	4.8.0	T1-031064
TP-21	TP-030191	235	-	Incorrect Transport channel Parameters	Α	4.7.0	4.8.0	T1-031066
TP-21	TP-030191	237	-	Corrections to TS 34.108 common procedures in clause 7.4 of Rel-4 of TS 34.108	Α	4.7.0	4.8.0	T1-031095
TP-21	TP-030191	239	-	Removal of RLC AM in the Default Message Content	Α	4.7.0	4.8.0	T1-031151
TP-21	TP-030191	242	-	CR 34.108 Rel-4: Manual attach in State 7 Registrated Idle Mode on CS/PS	Α	4.7.0	4.8.0	T1-031175
TP-21	TP-030191	244	-	URA Identity in Cell Update Confirm and URA Update Confirm	Α	4.7.0	4.8.0	T1-031179
TP-21	TP-030191	246	-	CR to 34.108 R4; Correction to specification to reflect a change already approved in TTCN CR T1-030396	Α	4.7.0	4.8.0	T1-031241
TP-21	TP-030191	248	-	CR to 34.108 REL-4; Correction to clause 7.3 Test	Α	4.7.0	4.8.0	T1-031251
TP-21	TP-030191	240	-	procedures for RF test  RB configuration for the support of wideband AMR	F	4.7.0	4.8.0	T1-031154
TD 22	TD 020270	251	1	speech telephony services	F	4 9 0	400	T1 024650
	TP-030279 TP-030279	251 252	1	Addition of Default message contents for TDD Addition of Default message contents for TDD	F	4.8.0 4.8.0	4.9.0 4.9.0	T1-031659 T1-031660
	TP-030279 TP-030279	252	1	Addition of Default message contents for TDD  Addition of Default message contents for TDD	F	4.8.0	4.9.0	T1-031660
	TP-030279	254	1	Addition of Default message contents for TDD	F	4.8.0	4.9.0	T1-031662
	TP-030279	255	1	Addition of Default message contents for TDD	F	4.8.0	4.9.0	T1-031663
	TP-030279	256	1	Addition of Default message contents for TDD	F	4.8.0	4.9.0	T1-031664
	TP-030279	257	1	Addition of Default message contents for TDD	F	4.8.0	4.9.0	T1-031665
	TP-030279	258	1	Addition of Default message contents for TDD	F	4.8.0	4.9.0	T1-031666
TP-22	TP-030279	260	2	CR on PAGING TYPE 1, RRC CONNECTION	A	4.8.0	4.9.0	T1-031596
	11 000210	200		REQUEST and RRC CONNECTION SETUP messages for MT RR Connection		1.0.0	1.0.0	
TP-22	TP-030279	262		CR 34.108 Rel-4: EFRPLMNACT (RPLMN Last used Access Technology) removed	Α	4.8.0	4.9.0	T1-031381
TP-22	TP-030279	264	1	Update of default messages for RRC CONNECTION SETUP and SECURITY MODE COMMAND	Α	4.8.0	4.9.0	T1-031547
TP-22	TP-030279	266	1	Description and corrections of channels for minimum performance levels, TDD mode.	F	4.8.0	4.9.0	T1-031645
TP-22	TP-030279	268	1	Test frequencies of UMTS800MHz band VI	Α	4.8.0	4.9.0	T1-031555
TP-22	TP-030279	269		CR 34.108 Rel-4: Addition of Bearer combination for Interactive/background UL 64 kbps DL 768 kbps for Rel-5	F	4.8.0	4.9.0	T1-031441
TP-22	TP-030279	271	1	Update of generic test procedure for TX, RX and Performance Requirement	Α	4.8.0	4.9.0	T1-031610
TP-22	TP-030279	273	1	Introduction of generic test procedure for RRM handover test cases	А	4.8.0	4.9.0	T1-031608
TP-22	TP-030279	275	1	Correction of CM TGD parameter	Α	4.8.0	4.9.0	T1-031591
	TP-030279	277	1	Corrections to default message contents of Radio Bearer Release	F	4.8.0	4.9.0	T1-031594
TP-22	TP-030279	279	1	Modification to default DPCCH_Power_offset value	Α	4.8.0	4.9.0	T1-031598
	TP-030279	283	İ	Correction of TFCS for radio bearer combination 6.10.2.4.1.51b	Α	4.8.0	4.9.0	T1-031527
TP-23	TP-040037	284	-	New Radio Bearer Setup (FDD) message for RF (Revision of T1-040258)	F	4.9.0	4.10.0	T1-040417
TP-23	TP-040037	287	-	Corrections to default message contents of RRC Connection Setup message -> 2nd change not	A	4.9.0	4.10.0	T1-040080
TP-23	TP-040037	289	-	implemented (not implementable)  Correction to Default parameters for Cells 1 to 8 in  MultiPLMN cell environments - Rel-4	A	4.9.0	4.10.0	T1-040095
TP-23	TP-040037	291	<u> </u>	Corrections to TDD HCR RABs	Α	4.9.0	4.10.0	T1-040103
TP-23	TP-040037	296	-	LCR Corrections to TDD RABs merge of T1-040104, T1-040201 and T1-040203	F	4.9.0	4.10.0	T1-040299
TP-23	TP-040037	298	-	Correction to handling of Entered Parameter IE in default contents for Initial Direct Transfer	Α	4.9.0	4.10.0	T1-040411
TP-23	TP-040037	300	-	The diverse operation in TDD mode updating according	Α	4.9.0	4.10.0	T1-040368
TP-23	TP-040037	302	-	to the core specification correction of measurement control default message contents for TDD -> Not implemented (not implementable)	F	4.9.0	4.10.0	T1-040370

Meetin g-1st- Level	Doc-1st-Level	CR	Rev	Subject	Cat	Version -Current		Doc-2nd- Level
TP-23	TP-040037	303	-	correction of RADIO BEARER SETUP default message contents for 1.28 Mcps TDD	F	4.9.0	4.10.0	T1-040371
TP-23	TP-040037	304	-	Correction of RADIO BEARER RELEASE default message contents for TDD: AM or UM (1.28 Mcps TDD)	F	4.9.0	4.10.0	T1-040372
TP-23	TP-040037	305	-		F	4.9.0	4.10.0	T1-040373
TP-23	TP-040037	292	-	New I/B UL:64 DL:768 kbps PS RAB misplaced	F	4.10.0	5.0.0	T1-040109
TP-23	TP-040037	294	-		F	4.10.0	5.0.0	T1-040271
TP-23	TP-040037	295	-	Baseline radio bearer combination for HSDPA support	В	4.10.0	5.0.0	T1-040273
TP-24	TP-040112	308	_	Correction to IEs "START" and	F	5.0.0	5.1.0	T1-040512
TP-24	TP-040112	309	-	"ul_CounterSynchronisationInfo". Correction to HSDPA reference radio bearer	F	5.0.0	5.1.0	T1-040522
			-	configurations	F			
TP-24 TP-24	TP-040112 TP-040112	310 315	-	Addition of test procedure for HSDPA RF testing Corrections to default RRC messages	F	5.0.0	5.1.0 5.1.0	T1-040546 T1-040593
TP-24	TP-040112	318	<u> </u>	Change of default LAC/RAC for inter-RAT test cases	А	5.0.0	5.1.0	T1-040595
TP-24	TP-040112	319	=	Contents of Physical channel Reconfiguration message modified to incorporate transition to URA_PCH or CELL_PCH	F	5.0.0	5.1.0	T1-040673
TP-24	TP-040112	320	-	Correction of reference test frequencies for UMTS800(band VI)	F	5.0.0	5.1.0	T1-040701
TP-24	TP-040112	325	-	Update of generic setup procedures in clauses 7.3.4 and 7.3.5.	Α	5.0.0	5.1.0	T1-040754
TP-24	TP-040112	326	=	Physical channel parameters for AM RLC 7 bit Length Indicator TestCases (Rel-5)	F	5.0.0	5.1.0	T1-040902
TP-24	TP-040112	327	=	Corrections to the default contents of Security Mode Command (Rel-5)	F	5.0.0	5.1.0	T1-040903
TP-24	TP-040112	330	-	Corrections to Contents of Scheduling Block 1 (FDD)	F	5.0.0	5.1.0	T1-040909
TP-24	TP-040112	331	-	Corrections to Contents of PHYSICAL CHANNEL RECONFIGURATION message: AM or UM	F	5.0.0	5.1.0	T1-040911
TP-24	TP-040112	332	-	Corrections to Contents of RRC CONNECTION SETUP message: UM	F	5.0.0	5.1.0	T1-040913
TP-24	TP-040112	333	-	RADIO BEARER SETUP message (FDD) for Test Loop Mode2.	F	5.0.0	5.1.0	T1-040917
TP-24	TP-040112	335	-	Changes to establish one version of 34.108 covering all releases	Α	5.0.0	5.1.0	T1-040931
TP-24	TP-040112	338	-	Addition of generic test procedure for AS test cases using the test loop	Α	5.0.0	5.1.0	T1-040934
TP-24	TP-040112	339	-	Corrections to LCR TDD RABs	F	5.0.0	5.1.0	T1-040935
TP-25	TP-040157	343	-	Correction to generic test procedure in clause 7.4.2.6a.	F	5.1.0	5.2.0	T1-041040
TP-25	TP-040157	344	-	Addition of default messages for Signalling (FDD)	F	5.1.0	5.2.0	T1-041044
TP-25	TP-040157	345	-	Minor change to terminology in SRB tables of clause 6.10	F	5.1.0	5.2.0	T1-041140
TP-25	TP-040157	346	-		F	5.1.0	5.2.0	T1-041154
TP-25	TP-040157	347	-		D	5.1.0	5.2.0	T1-041171
TP-25	TP-040157	348	1-	Corrections to clause 9	F	5.1.0	5.2.0	T1-041223
TP-25	TP-040157	349	-	Corrections to HCR TDD RAB combinations	F	5.1.0	5.2.0	T1-041235
TP-25	TP-040157	350	-	Adding missing clause 6.10.2.4.1.62.1	F	5.1.0	5.2.0	T1-041252
TP-25	TP-040157	351	-	Modification of AICH power offset in SysInfo 5 and 6.	F	5.1.0	5.2.0	T1-041253
TP-25	TP-040157	352	-	Correction to Default Message Content for Radio Bearer Setup Message.		5.1.0	5.2.0	T1-041259
TP-25	TP-040157	353	-	Correction to Default Message Content for Radio Bearer Reconfiguration Message for Condition A6	F	5.1.0	5.2.0	T1-041266
TP-25	TP-040157	354	-	CR to 34.108: introduction of default RB SETUP message from cell_FACH state for HSDPA	F	5.1.0	5.2.0	T1-041298
TP-25	TP-040157	355	-	Corrections to Contents of RADIO BEARER SETUP message: BTFD RMC	F	5.1.0	5.2.0	T1-041317
TP-25	TP-040157	340	-	Resolution of downlink code conflict between OCNS DPCH and S-CCPCH	F	5.1.0	5.2.0	T1-041327
TP-25	TP-040157	361	-	Correction to test procedure for test cases using Cell_PCH or URA_PCH state	F	5.1.0	5.2.0	T1-041346
TP-25	TP-040157	362	-	Removal of DCCH dummy transmission for RF testing	F	5.1.0	5.2.0	T1-041350
TP-25	TP-040157	341	-	Correct title to test procedure for test cases using Cell_PCH or URA_PCH state	F	5.1.0	5.2.0	T1-041354
TP-25	TP-040157	363	1-	Addition of intra frequency cell to cell environments	F	5.1.0	5.2.0	T1-041356
TP-25	TP-040157	342	-	Correct primary scrambling code usage in default message contents in clause 9.2.1	F	5.1.0	5.2.0	T1-041365
TP-25	TP-040157	356	-	HSDPA downlink code allocation	F	5.1.0	5.2.0	T1-041374

Meetin g-1st- Level	Doc-1st-Level	CR	Rev	Subject	Cat	Version -Current	Version -New	Doc-2nd- Level
TP-25	TP-040157	357	-	Correction to test procedure for test cases using CELL_FACH state	F	5.1.0	5.2.0	T1-041376
TP-25	TP-040157	358	-	Varying DPCH Power Offset according to data transmission rate	F	5.1.0	5.2.0	T1-041416
TP-25	TP-040157	359	-	Corrections to default message for RADIO BEARER SETUP message in clause 9.2.1 (HSDPA RF)	F	5.1.0	5.2.0	T1-041418
TP-25	TP-040157	360	-	Test SIB schedule for two S-CCPCH or two PRACH in 34.108	F	5.1.0	5.2.0	T1-041422
TP-25	TP-040157	364	-	Correction to Default Message Content for Radio Bearer Setup Message re: RM Attribute values	F	5.1.0	5.2.0	T1-041433
TP-26	TP-040233	365	-	CR to 34.108 Rel-5:Correction to default value of Qrxlevmin	F	5.2.0	5.3.0	T1-041532
TP-26	TP-040233	366	-	CR to 34.108 Rel-5: Corrections of the values in 6.11.5.4 for LCR TDD	F	5.2.0	5.3.0	T1-041573
TP-26	TP-040233	367	-	Alignment of Prose to TTCN for SCH power level	F	5.2.0	5.3.0	T1-041584
TP-26	TP-040233	368	-	Addition of new HSDPA RAB configurations with UL 64 kbps	F	5.2.0	5.3.0	T1-041651
TP-26	TP-040233	369	-	Correction to initial conditions and references in clause 7.3	F	5.2.0	5.3.0	T1-041654
TP-26	TP-040233	370	-	Introduction of reference radio bearer combination for PS streaming and downlink rate up to 128 kbps	F		5.3.0	T1-041685
TP-26	TP-040233	371	-	Correction of clause 6.1 (Simulated network environment)	F	5.2.0	5.3.0	T1-041686
TP-26	TP-040233	372	-	Correction to generic Call Setup procedure for mobile terminating circuit switched calls	F	5.2.0	5.3.0	T1-041699
TP-26	TP-040233	373	-	CR to 34.108 Rel-5; Corrections to the default RADIO BEARER SETUP message for HSDPA	F	5.2.0	5.3.0	T1-041754
TP-26	TP-040233	374	-	Physical layer multiplexing configuration in case of AMR and two PS RABs	F	5.2.0	5.3.0	T1-041801
TP-26	TP-040233	375	-	Addition of new HSDPA RAB configurations	F	5.2.0	5.3.0	T1-041802
TP-26	TP-040233	376	-	Introduction of information for tests for Performance requirements for A-GPS.	В	5.2.0	5.3.0	T1-041850
TP-26	TP-040233	377	-	Introduction of UMTS-850 MHz band V	F	5.2.0	5.3.0	T1-041874
TP-26	TP-040233	378	-	CR to TS 34.108 Rel-5; Adding a new test condition for RADIO BEARER RELEASE Procedure (Revision of T1-041716).	F	5.2.0	5.3.0	T1-041933
TP-26	TP-040233	379	-	Update of Reference Radio Bearer for Conversational / speech / UL:5.9 DL:5.9 kbps / CS RAB for DL SF=256	F	5.2.0	5.3.0	T1-041942
TP-26	TP-040233	380	-	CR to 34.108: Correction to the maximum bit rate for HS-PDSCH	F	5.2.0	5.3.0	T1-041943
TP-26	TP-040233	381	-	Alignment of Prose to TTCN for RRC Connection Release (Cell DCH state) and RRC Connection Setup Message (Cell FACH State).	F	5.2.0	5.3.0	T1-041965
TP-27	TP-050032	382	-	Updates from core specification changes	F	5.3.0	5.4.0	T1-050095
	TP-050032	383	-	Correction to Hand over test procedure in CELL_DCH	F	5.3.0	5.4.0	T1-050350
TP-27	TP-050032	384	-	CR to 34.108: Changes to test frequencies for UMTS 850 Band	В	5.3.0	5.4.0	T1-050380
TP-27	TP-050032	385	-	Correction to default SIB configurations	F	5.3.0	5.4.0	T1-050019
TP-27	TP-050032	386	-	Editorial corrections in HSDPA RAB configurations 6.10.2.4.5.2 and 6.10.2.4.5.4.	D	5.3.0	5.4.0	T1-050052
TP-27	TP-050032	387	-	CR to 34.108 Rel-5: Update to the contents of PHYSICAL CHANNEL RECONFIGURATION message for 1.28 Mcps TDD	F	5.3.0	5.4.0	T1-050064
TP-27	TP-050032	388	-	CR to 34.108 Rel-5: Update to the contents of TRANSPORT CHANNEL RECONFIGURATION message for 1.28 Mcps TDD	F	5.3.0	5.4.0	T1-050065
TP-27	TP-050032	389	-	CR to 34.108 Rel-5: Update to the contents of RRC CONNECTION REQUEST message for TDD	F	5.3.0	5.4.0	T1-050066
TP-27	TP-050032	390	-	Correction to the HSDPA RB Identity in Radio Bearer Setup & Radio Bearer Release message contents	F	5.3.0	5.4.0	T1-050072
TP-27	TP-050032	391	-	CR to TS 34.108 v5.3.0 - Correction to Default RADIO BEARER RELEASE message (FDD)	F	5.3.0	5.4.0	T1-050202
TP-27	TP-050032	392	-	Addition of reference radio bearer configuration for MAC-hs testing	F	5.3.0	5.4.0	T1-050239
TP-27	TP-050032	393	-	CR to 34.108 Rel-5: Update to the contents of RRC CONNECTION REQUEST message for TDD	F	5.3.0	5.4.0	T1-050295
TP-27	TP-050032	394	-	CR to 34.108 Rel-5: Update to the contents of Default System Information Block Messages for TDD	F	5.3.0	5.4.0	T1-050296
TP-27	TP-050032	395	-	CR to 34.108 Rel-5: Add the contents of SIB 5 & 6 for HCR TDD	F	5.3.0	5.4.0	T1-050297
TP-27	TP-050032	396	Ŀ	Correction to TFCS ordering	F	5.3.0	5.4.0	T1-050451r1
TP-27	TP-050032	397	-	Addition of GPS scenario and A-GPS assistance data	F	5.3.0	5.4.0	T1-050458

Meetin g-1st- Level	Doc-1st-Level	CR	Rev	Subject	Cat	Version -Current		Doc-2nd- Level
				values for signalling tests to 34.108				
TP-27	TP-050032	398	-	CR to TS 34.108 Rel-5; Correction to the physical channel parameters (Revison of T1-050176)	F	5.3.0	5.4.0	T1-050469
RP-28	RP-050267	399	-	Additional call setup procedures for inter RAT RRM testing	F	5.4.0	5.5.0	R5-050618
RP-28	RP-050267	400	-	CR to 34.108: Correction to RADIO BEARER SETUP message for BTFD RMC	F	5.4.0	5.5.0	R5-050704
RP-28	RP-050267	401	-	CR to 34.108: Correction to reference radio conditions for GSM	F	5.4.0	5.5.0	R5-050811
RP-28	RP-050267	402	-	Addition of RADIO BEARER SETUP Messages for Auxiliary Measurement	F	5.4.0	5.5.0	R5-050856
RP-28	RP-050267	404	-	CR 34.108 Addition of specific message content to A- GPS performance test procedures in clause 7.5	F	5.4.0	5.5.0	R5-050709
RP-28	RP-050267	405	-	CR to 34.108 Rel-5: Clarification of generic setup procedures in section 7.3.4	F	5.4.0	5.5.0	R5-050663
RP-28	RP-050267	406	-	Removal of TGPL2	F	5.4.0	5.5.0	R5-050513
RP-28	RP-050267	407	-	Addition of compressed mode pattern for Inter Frequency FDD measurement & Inter RAT measurement GSM	F	5.4.0	5.5.0	R5-050525
RP-28	RP-050267	408	-	Correction to MIB, PLMN and Cell Value Tag Value Definition to 34.108	F	5.4.0	5.5.0	R5-050608
RP-28	RP-050267	409	-	CR to 34.108 Rel-5: Corrections to the contents of System Information Block type 11 (3.84 Mcps and 1.28 Mcps TDD) in section 6.1.0b	F	5.4.0	5.5.0	R5-050613
RP-28	RP-050267	410	-	CR to 34.108 Rel-5: Corrections to the usage of 'Cell info' IE in System Information Block type 11 in section 6.1.4 for TDD cell	F	5.4.0	5.5.0	R5-050619
RP-28	RP-050267	411	-	CR to 34.108 Rel-5: Corrections to the contents of System Information Block type 5 (1.28 Mcps TDD)	F	5.4.0	5.5.0	R5-050620
RP-28	RP-050267	412	-	Update to clause 8 Test USIM Parameters	F	5.4.0	5.5.0	R5-050638
RP-28	RP-050267	413	-	CR to 34.108 Rel-5: Update of SIB3, SIB4, SIB11 and SIB12 for TDD in section 6.1.0b	F	5.4.0	5.5.0	R5-050662
RP-28	RP-050267	414	-	CR to 34.108: Correction to TFCS	F	5.4.0	5.5.0	R5-050677
RP-28	RP-050267	415	-	CR to TS34.108 Rel-5; Correction to the physical channel parameter	F	5.4.0	5.5.0	R5-050724
RP-28 RP-28	RP-050267 RP-050267	416 417	-	Correction to default SIB configurations CR to 34.108: Missing Rel-5 IE's in the default Radio Bearer Setup message at section 9.1.1.	F F	5.4.0 5.4.0	5.5.0 5.5.0	R5-050947 R5-050600
RP-28	RP-050267	418	-	CR to TS34.108 Rel-5; Clarification of the reference TFCS for three RB multiplexing option (condition A9)	F	5.4.0	5.5.0	R5-050913
RP-28	RP-050268	419	-	Addition of new HSDPA Streaming RAB configurations	F	5.4.0	5.5.0	R5-050880
RP-28	RP-050268	420	-	CR to 34.108 Rel-5: Content Correction of RRC CONNECTION SETUP message for LCR TDD in 9.1.2	F	5.4.0	5.5.0	R5-050585
	RP-050268	421	-	Add Default RADIO BEARER RELEASE message (3.84 Mcps TDD)			5.5.0	R5-050680
RP-28	RP-050268	422	-	Add Default Contents of RADIO BEARER RECONFIGURATION COMPLETE message: AM (3.84 Mcps TDD)	F	5.4.0	5.5.0	R5-050681
RP-28	RP-050268	423	-	Add Default Contents of RADIO BEARER RECONFIGURATION message: AM or UM (3.84 Mcps TDD)	F	5.4.0	5.5.0	R5-050682
RP-28	RP-050268	424	-	Add Default Contents of PHYSICAL CHANNEL RECONFIGURATION message: AM or UM (3.84 Mcps TDD)	F	5.4.0	5.5.0	R5-050683
RP-28	RP-050268	425	-	Add Default Contents of PHYSICAL CHANNEL RECONFIGURATION COMPLETE message: AM (3.84 Mcps TDD)	F	5.4.0	5.5.0	R5-050684
RP-28	RP-050268	426	-	Add Default Contents of TRANSPORT CHANNEL RECONFIGURATION message: AM or UM (3.84 Mcps TDD)	F	5.4.0	5.5.0	R5-050685
RP-28	RP-050268	427	-	Add Default Contents of TRANSPORT CHANNEL RECONFIGURATION COMPLETE message: AM (3.84 Mcps TDD)	F	5.4.0	5.5.0	R5-050686
RP-28	RP-050268	428	-	Add Default Contents of MEASUREMENT REPORT message: AM (intra/inter-frequency measurement (3.84 Mcps TDD)	F	5.4.0	5.5.0	R5-050956
RP-28	RP-050268	430	-	Correction to RADIO BEARER SETUP message for HSDPA RF testing	F	5.4.0	5.5.0	R5-050879
RP-28	RP-050349	403	-	Addition of GPS scenario and assistance data for A-GPS performance tests in 34.108	В	5.4.0	5.5.0	R5-050836
RP-28	RP-050350	429	<u> </u>	Corrections to section 10.7 and GPS data file for 34.108	F	5.4.0	5.5.0	R5-050969
RP-29	RP-050600	431	-	Feature Clean Up: Removal of DRAC from section 9 of	F	5.5.0	6.0.0	R5-051312

Meetin g-1st- Level	Doc-1st-Level	CR	Rev	Subject	Cat	Version -Current		Doc-2nd- Level
20101				34.108				
RP-29	RP-050600	432	-	Feature Clean Up: Removal of SSDT from 34.108	F	5.5.0	6.0.0	R5-051356
RP-29	RP-050600	433	-	Feature Clean Up: Removal of 80 ms TTI for DCH for all cases except when the UE supports SF512 from 34.108	F	5.5.0	6.0.0	R5-051379
RP-29	RP-050600	434	-	Feature Clean Up: Removal of CPCH from section 4 of 34.108	С	5.5.0	6.0.0	R5-051543
RP-29	RP-050600	435	-	Feature Clean Up: Removal of CPCH from section 6 of 34.108	С	5.5.0	6.0.0	R5-051544
RP-29	RP-050600	436	-	Feature Clean Up: Removal of CPCH from section 7 & 8 of 34.108	С	5.5.0	6.0.0	R5-051545
RP-29	RP-050600	437	-	Feature Clean Up: Removal of CPCH from section 9 of 34.108	С	5.5.0	6.0.0	R5-051546
RP-29	RP-050600	438	-	Feature Clean Up: Removal of DSCH (FDD mode) from 34.108	F	5.5.0	6.0.0	R5-051548
RP-29	RP-050600	439	-	Modification to PS setup procedure for inter RAT RRM testing	F	5.5.0	6.0.0	R5-051161
RP-29	RP-050600	440	-	CR to 34.108: RRC CONNECTION SETUP exception for HSDPA testing	F	5.5.0	6.0.0	R5-051430
RP-29	RP-050600	441	-	CR to 34.108: Correction to the RADIO BEARER SETUP message for HSDPA testing	F	5.5.0	6.0.0	R5-051112
RP-29	RP-050512	442	-	Changes to GPS Scenarios and Assistance data in TS 34.108	F	5.5.0	6.0.0	R5-051076
RP-29	RP-050514	443	-	CR to 34.108 Rel-5: Correction of contents of RADIO BEARER SETUP message: AM or UM (1.28 Mcps TDD) in 9.2.2	F	5.5.0	6.0.0	R5-051212
RP-29	RP-050514	444	=	CR to 34.108 Rel-5: SIB default schedule in 6.1.0a - Default Master Information Block and Scheduling Block messages	F	5.5.0	6.0.0	R5-051213
RP-29	RP-050514	445	=	CR to 34.108 Rel-5: Corrections to the IE"Midamble shift and burst type" of System Information Block type 5/6 (3.84Mcps TDD) in section 6.1.0b	F	5.5.0	6.0.0	R5-051222
RP-29	RP-050514	446	-	CR to 34.108 Rel-5: Corrections to the contents of System Information Block type 5 (3.84 Mcps TDD) in section 6.1.1	F	5.5.0	6.0.0	R5-051344
RP-29	RP-050514	447	-	CR to 34.108 Rel-5: Corrections to the value of Sintrasearch and Sintersearch in "Cell selection and reselection quality measure" of System Information Block type 3/4 (1.28Mcps TDD and 3.84Mcps TDD) in section 6.1.0b	F	5.5.0	6.0.0	R5-051536
RP-29	RP-050600	448	-	Use 'Same as UL' for the Added or Reconfigured DL TrCH information of the added or reconfigured PS RAB	F	5.5.0	6.0.0	R5-051041
RP-29	RP-050600	449	-	Correction to the default contents for Radio Bearer Setup message	F	5.5.0	6.0.0	R5-051044
RP-29	RP-050600	450	-	Corrections to default parameters of UL:384kbps PS Bearer	F	5.5.0	6.0.0	R5-051058
RP-29	RP-050600	451	-	Correction to NB AMR Radio Bearer Configurations	F	5.5.0	6.0.0	R5-051318
RP-29	RP-050600	452	-	Correction to default contents of Cell Update and Initial Direct transfer message for Rel-5	F	5.5.0	6.0.0	R5-051325
RP-29	RP-050600	453	-	Correction to DPCCH Power Offset IE in default contents for RRC Connection Setup and Radio Bearer Setup message	F	5.5.0	6.0.0	R5-051365
RP-29	RP-050515	454	-	Using Test USIM for VSTK generation of VGCS/VBS ciphering	В	5.5.0	6.0.0	R5-051553
RP-29	RP-050600	455	-	Correction to default contents of RADIO BEARER SETUP MESSAGE for the IE "Number of Processes"	F	5.5.0	6.0.0	R5-051324
RP-29	RP-050600	456	-	Correction of DL channelisation code in RADIO BEARER SETUP for HSDPA configurations	F	5.5.0	6.0.0	R5-051345
RP-29	RP-050513	457	-	Clarifiation of reference radio bearer configuration for MAC-hs test case 7.1.5.2.	F	5.5.0	6.0.0	R5-051164
RP-29	RP-050600	458	-	Replacement of the technical content of 34.108 Rel-5 by a pointer to Rel-6 document	F	5.5.0	6.0.0	R5-051584
RP-29	RP-050600	459	-	Introduction of HSDPA + Wideband AMR radio bearer combination	F	5.5.0	6.0.0	R5-051588
RP-29	RP-050600	460	-	34.108	F	5.5.0	6.0.0	R5-051311
RP-30	RP-050767	461	-	Correction to 34.108: RF Radio Bearer setup message for HSDPA testing	F	6.0.0	6.1.0	R5-052320
RP-30	RP-050720	462	-	Changes, additions and corrections to GPS scenarios and assistance data in TS 34.108	F	6.0.0	6.1.0	R5-052017
RP-30	RP-050716	463	-	Generic test procedure for EDCH RF testing	F	6.0.0	6.1.0	R5-052345
RP-30	RP-050769	464	<u> </u>	Correction of UE test states for RF testing.	F	6.0.0	6.1.0	R5-052302
RP-30	RP-050769	465	<u> -</u>	Removal of temporary BLER measurement	F	6.0.0	6.1.0	R5-051933

Combination   RP-050717   469   CR to 34.108; Correction to default message content in   F   6.0.0   6.1.0   RS-052179   RP-30   RP-050716   470   CR to 34.108; Correction to default message content in   F   6.0.0   6.1.0   RS-052182   RP-30   RP-050716   471   CR to 34.108; Correction to Default RRC Messages for Enhanced Uplink Tests   RP-30   RP-050716   472   CR to 34.108; Correction to the default system   F   6.0.0   6.1.0   RS-052147   RP-30   RP-050718   473   CR to 1534.108; Correction to the default system   F   6.0.0   6.1.0   RS-052144   RRC Messages of the default system   F   6.0.0   6.1.0   RS-052148   RP-30   RP-050769   474   Editorial corrections to TS 34.108   D   6.0.0   6.1.0   RS-051848   RP-30   RP-050769   475   Editorial corrections to TS 34.108   D   6.0.0   6.1.0   RS-051848   RP-30   RP-050769   476   Editorial corrections to TS 34.108   RP-30   RP-050769   476   Correction to the default RRC message contents for the   F   6.0.0   6.1.0   RS-051848   RP-30   RP-050769   476   Correction to the default RRC message contents for the   F   6.0.0   6.1.0   RS-051858   RP-30   RP-050769   476   Correction to the default RRC message contents for the   F   6.0.0   6.1.0   RS-051858   RP-30   RP-050769   478   Correction to the default RRC message contents for the   F   6.0.0   6.1.0   RS-051858   RR-30   RP-050769   478   Correction to 1UE states tables for Generic setup   F   6.0.0   6.1.0   RS-051955   RR-30   RP-050769   479   Correction to default message contents of H   RRC   RR-30   RR-305769   481   Correction to the default message contents of H   RRC   RR-30   RR-305769   481   Correction to the default message contents of H   RRC   RR-30   RR-305769   481   RR-30   R	Meetin	Doc-1st-Level	CR	Rev	Subject	Cat	Version	Version	Doc-2nd-
RP-30 RP-0576780   466   Introduction of UMTS1700 for TS34.108   6.0.0   6.1.0   R5-062329							-Current	-New	Level
RP-950/RP         467         Re-definition of reference radio bearer configuration for F         6.0.0         6.1.0         RS-051857           RP-30         RP-050767         468         Introduction of additional HSDPA radio bearer         F         6.0.0         6.1.0         RS-052159           RP-30         RP-307         RP	DD 00	DD 050700	400			_	0.0.0	0.4.0	DE 050000
RP-30   RP-050767   468				-					
RP-30   RP-050767   468	KF-30	KP-030767	467	-		Г	6.0.0	6.1.0	K3-031037
RP-30   RP-050716   469	RP-30	RP-050767	468	-		F	6.0.0	6.1.0	R5-052159
RP-30									
RP-30   RP-050716   470   CR to 34.108 Rel-6, Generic Setup Procedure and F   6.0.0   6.1.0   R5-052192   RP-30   RP-050716   471   Generic reference bearer radio configurations for E   F   6.0.0   6.1.0   R5-052167   RP-30   RP-050716   472   Addition of basic radio bearer combinations for E-DCH   F   6.0.0   6.1.0   R5-052167   RP-30   RP-050718   473   CR to TS34.106; Correction to the default system   F   6.0.0   6.1.0   R5-052148   RP-30   RP-050769   474   CR to TS34.106; Correction to the default contents   F   6.0.0   6.1.0   R5-052145   RP-30   RP-050769   475   Removal of depressed values from the default contents   F   6.0.0   6.1.0   R5-051849   RP-30   RP-050769   476   Correction to the default RRC message contents for the   F   6.0.0   6.1.0   R5-052155   RP-30   RP-050769   476   Correction to the default RRC message contents for the   F   6.0.0   6.1.0   R5-052155   RP-30   RP-050769   477   Correction to the default RRC message contents for the   F   6.0.0   6.1.0   R5-052155   RP-30   RP-050769   477   Correction of references to IB UL-8 DL-8 kbps transport   F   6.0.0   6.1.0   R5-051858   RP-30   RP-050769   477   Correction of UE states tables for Generic setup   F   6.0.0   6.1.0   R5-051858   RP-30   RP-050769   478   Correction of UE states tables for Generic setup   F   6.0.0   6.1.0   R5-051858   RP-30   RP-050769   479   Correction of UE states tables for Generic setup   F   6.0.0   6.1.0   R5-051955   RP-30   RP-050769   482   Correction of UE states tables for Generic setup   F   6.0.0   6.1.0   R5-051955   RP-30   RP-050769   482   Correction of UE states tables for Generic setup   F   6.0.0   6.1.0   R5-051955   RP-30   RP-050776   480   Addition of multi-rate AMR-NIS configuration with SRB#5   F   6.0.0   6.1.0   R5-052056   RP-30   RP-050776   480   Addition of multi-rate AMR-NIS configuration with SRB#5   F   6.0.0   6.1.0   R5-052056   RP-30   RP-050777   483   Correction to Park AMR Sublibou to WB-AMR test   F   6.0.0   6.1.0   R5-052056   RP-30   RP-050777   483   Correct	RP-30	RP-050717	469	-	,	F	6.0.0	6.1.0	R5-052179
RP-30   RP-050716   471   Canacir reference basin radio configurations for E - DCH testing   RP-30   RP-050718   472   Addition of basic radio basic	RP-30	RP-050716	470	_		F	600	610	R5-052192
RP-30   RP-050716   472   Addition of basic radio bearer combinations for E-DCH   F   6.0.0   6.1.0   R5-052145   RP-30   RP-050769   474   Second of the	111 00				Default RRC Messages for Enhanced Uplink Tests	ľ			110 002102
RP-30   RP-050716   472   Addition of basic radio bearer combinations for E-DCH   F   6.0.0   6.1.0   R5-052144   testing   RP-30   RP-050769   474   Editorial corrections to TS 34.108   DA   6.0.0   6.1.0   R5-052145   RP-30   RP-050769   474   Editorial corrections to TS 34.108   DA   6.0.0   6.1.0   R5-051840   RP-30   RP-050769   475   Removal of deprecated values from the default contents   F   6.0.0   6.1.0   R5-051840   RP-30   RP-050769   476   Correction Setup (Cell FACH) and RRC   Connection Release (Cell DCH) message   RP-30   RP-050769   477   Correction Release (Cell DCH) message   RP-30   RP-050769   477   Correction Release (Cell DCH) message   RP-30   RP-050769   477   Correction of references to IB UL-8 DL-8 kpbs transport   F   6.0.0   6.1.0   R5-051848   RP-30   RP-050769   478   Correction of UE states tables for Generic setup   F   6.0.0   6.1.0   R5-051858   Correction of UE states tables for Generic setup   F   6.0.0   6.1.0   R5-051958   RP-30   RP-050769   479   Correction of UE states tables for Generic setup   F   6.0.0   6.1.0   R5-051958   RP-30   RP-050776   480   Addition of multi-rate AMR-NB configuration with SRB#\$   F   6.0.0   6.1.0   R5-052176   RP-30   RP-050776   480   Addition of multi-rate AMR-NB configuration with SRB#\$   F   6.0.0   6.1.0   R5-052056   RP-30   RP-050777   483   Proposed CR to 34.108   RR version, R99 affected to   F   6.0.0   6.1.0   R5-052056   RP-30   RP-050777   483   Correction to puncturing limit in radio bearer   F   6.0.0   6.1.0   R5-05206   RP-30   RP-050777   483   Correction to puncturing limit in radio bearer   F   6.0.0   6.1.0   R5-05206   RP-30   RP-050777   483   Correction to puncturing limit in radio bearer   F   6.0.0   6.1.0   R5-05206   RP-30   RP-050777   483   Correction to the puncturing limit in radio bearer   F   6.0.0   6.1.0   R5-05206   RP-30   RP-050777   483   Correction to first RP-050789   RP-050777   483   Correction to first RP-050789   RP-050777   483   Correction to first RP-050789   RP-050777   RP-050789   RP-0507	RP-30	RP-050716	471	-	Generic reference bearer radio configurations for E-	F	6.0.0	6.1.0	R5-052167
RP-30   RP-050718   473   CR to T334.108; Correction to the default system   F   6.0.0   6.1.0   R5-052145   RP-30   RP-050769   474   Editorial corrections to T5 34.108   D   6.0.0   6.1.0   R5-051840   RP-30   RP-050769   475   Removal of deprecated values from the default contents   F   6.0.0   6.1.0   R5-051840   RP-30   RP-050769   476   Removal of deprecated values from the default contents   F   6.0.0   6.1.0   R5-051840   RP-30   RP-050769   476   Correction to the default RRC message contents for the   F   6.0.0   6.1.0   R5-051848   RP-30   RP-050769   477   Correction of the default RRC message contents for the   F   6.0.0   6.1.0   R5-051850   RP-30   RP-050769   477   Correction of references to IB UL-8 DL-8 kbps transport   F   6.0.0   6.1.0   R5-051858   RP-30   RP-050769   478   Correction of the default message contents for the   F   6.0.0   6.1.0   R5-051858   RP-30   RP-050769   478   Correction of UE states tables for Generic setup   F   6.0.0   6.1.0   R5-051942   RP-30   RP-050769   479   Corrections to default message contents of   F   6.0.0   6.1.0   R5-051955   RP-30   RP-050776   480   Addition of multi-rate AMR-NB configuration with SRBM5   F   6.0.0   6.1.0   R5-051955   RP-30   RP-050769   481   Proposed CR to 34.108   R9 version R9 states tables for Generic set RB   RP-30   RP-050769   481   Proposed CR to 34.108   R9 version R9 states tables for Generic set RB   RP-30   RP-050769   481   Proposed CR to 34.108   R9 version R9 states tables for Generic set RB   RP-30   RP-050769   482   Correction to puncturing limit in radio bearer   F   6.0.0   6.1.0   R5-052055   RP-30   RP-050769   481   Proposed CR to 34.108   R9 version R9 states tables for Generic set RB   RP-30   RP-050789   481   Proposed CR to 34.108   R9 version R9 states tables for Generic set RB   RP-050777   483   Introduction of third RAB subliow to WB-AMR test   Generic set RB   RP-050777   483   Introduction of third RAB subliow to WB-AMR test   Generic set RB   RP-050777   RP-050777   RP-050777   RP-050777   RP-0	DD 00	DD 050740	470			_	0.0.0	0.4.0	DE 050444
RP-30   RP-050718   473   CR to TS34.108   Correction to the default system   F   6.0.0   6.1.0   R5-05146   RP-30   RP-050769   474   Editorial corrections to TS 34.108   D   6.0.0   6.1.0   R5-051840   RP-30   RP-050769   475   Removal of deprecated values from the default contents   F   6.0.0   6.1.0   R5-051840   RP-30   RP-050769   476   Correction for the default RRC message contents for the   F   6.0.0   6.1.0   R5-051840   RP-30   RP-050769   476   Correction to the default RRC message contents for the   F   6.0.0   6.1.0   R5-052155   RP-30   RP-050769   477   Correction to the default RRC message contents for the   F   6.0.0   6.1.0   R5-051858   RP-30   RP-050769   478   Correction of references to IB UL3 DL3 kbps transport   F   6.0.0   6.1.0   R5-051858   RP-30   RP-050769   478   Correction of UE states tables for Generic setup   F   6.0.0   6.1.0   R5-051858   RP-30   RP-050769   478   Correction of UE states tables for Generic setup   F   6.0.0   6.1.0   R5-051955   RP-30   RP-050769   479   Corrections to default message contents of   HANDOVER FROM UTRAN COMMAND-GSM   F   6.0.0   6.1.0   R5-051955   RP-30   RP-050769   480   Addition of multi-rate AMR-NB configuration with SRBe5   F   6.0.0   6.1.0   R5-052176   RR-30   RP-050769   481   Proposed CR to 34.108   R6 version, R99 affected   to   F   6.0.0   6.1.0   R5-052056   RR-30   RP-050769   482   Correction to puncturing limit in radio bearer   F   6.0.0   6.1.0   R5-052056   RR-30   RP-050777   483   Introduction of third RAB sulflow to WB-AMR test   F   6.0.0   6.1.0   R5-052056   RR-30   RP-050833   484   Correction to Tablo BEARER SETUP message for   F   6.0.0   6.1.0   R5-052140   RR-30   RR-050833   484   Corrections to RAB sulflow to WB-AMR test   F   6.0.0   6.1.0   R5-052140   RR-30   RR-050154   486   Corrections to RAB sulflow to WB-AMR test   F   6.0.0   6.1.0   R5-052140   RR-30   RR-050154   486   Corrections to RAB sulflow to WB-AMR test   F   6.0.0   6.1.0   R5-052140   RR-30   RR-050154   486   Corrections to RAB sulflow t	RP-30	RP-050716	4/2	-		F	6.0.0	6.1.0	R5-052144
RP-30 RP-050769 476	RP-30	RP-050718	473	-	U U	F	6.0.0	6.1.0	R5-052145
RP-30   RP-050769   475   Removal of deprecated values from the default contents   F   6.0.0   6.1.0   R5-051848   for RRC Connection Release (Cell DCH) and RRC Connection Release (Cell DCH) and RRC Connection Release (Cell DCH) messages.   RP-050769   476   Correction to the default RRC message contents for the   F   6.0.0   6.1.0   R5-051858   RP-30   RP-050769   477   Correction of references to IB UL-8 DL-8 kpps transport   F   6.0.0   6.1.0   R5-051858   RP-30   RP-050769   478   Correction of references to IB UL-8 DL-8 kpps transport   F   6.0.0   6.1.0   R5-051858   RP-30   RP-050769   478   Correction of UE states tables for Generic setup   F   6.0.0   6.1.0   R5-051952   RP-30   RP-050769   479   Correction of UE states tables for Generic setup   F   6.0.0   6.1.0   R5-051955   RP-30   RP-050769   480   Addition of multi-rate AMR-NB configuration with SRB#5   F   6.0.0   6.1.0   R5-051955   RP-30   RP-050769   481   Proposed CR to 34.108 (R8 version, R99 affected) to change sol format for AMR 5.9 mono rate RAB   F   6.0.0   6.1.0   R5-052056   RP-30   RP-050769   482   Correction to puncturing limit in radio bearer   F   6.0.0   6.1.0   R5-052068   RP-30   RP-050777   483   Introduction of third RAB subllow to WB-AMR test   F   6.0.0   6.1.0   R5-052046   RP-30   RP-050833   484   Correction to RAB   Subllow to WB-AMR test   F   6.0.0   6.1.0   R5-052140   RP-31   RP-060154   486   Correction to Telephone (RP-31   RP-060154   486   Corrections for reference RABS   RP-31   RP-060154   487   Correction to telephone (RP-31   RP-060154   487   Correction to telephone (RP-31   RP-060154   487   Corrections for reference RABS   RP-31   RP-060154   489   Corrections for reference RABS   RP-31   RP-060154   489   Corrections for reference RABS   RP-31   RP-060154   490   Corre					information block type3 for DSAC				
Tor RRC Connection Setup (Cell FACH) and RRC   Connection Release (Cell DCH) messages.   F   6.0.0   6.1.0   R5-052155   RP-30   RP-050769   476   Correction to the default RRC message contents for the   F   6.0.0   6.1.0   R5-051858   RP-30   RP-050769   477   Correction of references to IB UL-8 DL-8 kbps transport   F   6.0.0   6.1.0   R5-051858   RP-30   RP-050769   478   Correction of UE states tables for Generic setup   F   6.0.0   6.1.0   R5-051942   RP-30   RP-050769   479   Corrections to default message contents of   F   6.0.0   6.1.0   R5-051942   RP-30   RP-050769   479   Corrections to default message contents of   F   6.0.0   6.1.0   R5-051955   HANDOVER FROM UTRAN COMMAND-GSM' message.   RP-30   RP-050769   481   Proposed CR to 34-108   RF versions to MR versions of the RP-30   RP-050769   481   Proposed CR to 34-108   RF version RP-30   RP-050769   482   Correction to puncturing limit in radio bearer   G.0.0   6.1.0   R5-052056   Connection to puncturing limit in radio bearer   G.0.0   6.1.0   R5-05208   Correction to puncturing limit in radio bearer   G.0.0   6.1.0   R5-052140   Correction to puncturing limit in radio bearer   G.0.0   6.1.0   R5-052140   Correction to puncturing limit in radio bearer   G.0.0   6.1.0   R5-052140   Correction to Puncturing limit in radio bearer   G.0.0   6.1.0   R5-052140   Correction to RAB Sublice to WB-AMR test   G.0.0   6.1.0   R5-052140   Correction to RAB Sublice to WB-AMR test   G.0.0   6.1.0   R5-052140   Correction to RAB Sublice to WB-AMR test   G.0.0   6.1.0   R5-052140   RP-30   RP-050832   485   Corrections to February Residence   G.0.0   6.1.0   R8-052140   RP-31   RP-060153   486   Corrections to GPS data files for signalling tests.   F   6.1.1   6.2.0   R5-060273   RP-31   RP-060163   487   Corrections to GPS data files for signaling tests.   F   6.1.1   6.2.0   R5-060273   RP-31   RP-060163   489   Corrections to PR-21   RP-060154   490   Corrections to MR PAD BAR Filesting   F   6.1.1   6.2.0   R5-060274   RP-31   RP-060154   490   Corrections			474	-					
Connection Release (Celi DCH) messages contents for the   F   6.0.0   6.1.0   R5-052155	RP-30	RP-050769	4/5	-		F	6.0.0	6.1.0	R5-051848
RP-30   RP-050769   476   Correction to the default RRC message contents for the   F   6.0.0   6.1.0   R5-052155   RP-30   RP-050769   477   Correction of references to IB UL-8 DL-8 kbps transport   F   6.0.0   6.1.0   R5-051858   RP-30   RP-050769   478   Correction of UE states tables for Generic setup   F   6.0.0   6.1.0   R5-051942   RP-30   RP-050769   479   Corrections to default message contents of   F   6.0.0   6.1.0   R5-051942   RP-30   RP-050769   479   Corrections to default message contents of   F   6.0.0   6.1.0   R5-051955   RP-30   RP-050769   480   Addition of multi-rate AMR-NB configuration with SRB#5   F   6.0.0   6.1.0   R5-051955   RP-30   RP-050769   481   Proposed CR to 34-108   RP-050769   RP-30   RP-050769   482   Corrections to default message contents of change slot format for AMR-S 9 monor rate RAB   RP-30   RP-050769   482   Correction to puncturing limit in radio bearer   F   6.0.0   6.1.0   R5-052055   RP-30   RP-050777   483   Introduction of third RAB sublibov to WB-AMR test   6.0.0   6.1.0   R5-052406   RP-30   RP-050833   484   Correction to RADIO BEARER SETUP message for   F   6.0.0   6.1.0   R5-052406   RP-30   RP-050832   485   Correction to RADIO BEARER SETUP message for   F   6.0.0   6.1.0   RP-308   RP-30   RP-060154   486   Corrections to GPS data files for signalling tests.   F   6.1.1   6.2.0   R5-060527   RP-31   RP-060154   486   Corrections to GPS data files for signalling tests.   F   6.1.1   6.2.0   R5-060362   RP-31   RP-060154   486   Corrections to GPS data files for signalling tests.   F   6.1.1   6.2.0   R5-060362   RP-31   RP-060154   489   Corrections to GPS data files for signalling tests.   F   6.1.1   6.2.0   R5-060362   RP-31   RP-060154   490   Corrections to GPS data files for signalling tests.   F   6.1.1   6.2.0   R5-060362   RP-31   RP-060154   490   Corrections to GPS data files for signalling tests.   F   6.1.1   6.2.0   R5-060362   RP-31   RP-060154   490   Corrections to GPS data files for signalling tests.   F   6.1.1   6.2.0   R5-060362									
RP-30   RP-050769   477   Correction of references to IB UL.8 DL:8 kbps transport channel parameters in reference radio bearer configuration 6.10.2.4.1.58a	RP-30	RP-050769	476	-		F	6.0.0	6.1.0	R5-052155
Carrection to UE states tables for Generic setup									
RP-30   RP-050769   478   Correction of UE states tables for Generic setup   F   6.0.0   6.1.0   R5-051942   Procedures.   RP-30   RP-050769   479   - Introduction of UE states tables for Generic setup   F   6.0.0   6.1.0   R5-051955   RP-30   RP-050769   480   - Addition of multi-rate AMR-NB configuration with SRB#5   F   6.0.0   6.1.0   R5-051955   RP-30   RP-050769   481   - Proposed CR to 34.108 [R8 version, R99 affected] to change slot format for AMR 5.9 monor rate RAB   RP-30   RP-050769   481   - Proposed CR to 34.108 [R8 version, R99 affected] to change slot format for AMR 5.9 monor rate RAB   RP-30   RP-050769   482   - Correction to puncturing limit in radio bearer   Configuration 6.10.2.4.1.38a   RP-30   RP-050777   483   Introduction of third RAB subflow to WB-AMR test   Configuration 6.10.2.4.1.38a   Introduction of third RAB subflow to WB-AMR test   Configuration 6.10.2.4.1.38a   Introduction of third RAB subflow to WB-AMR test   Configuration 6.10.2.4.1.38a   RP-30   RP-050832   485   Correction to RADIO BEARER SETUP message for   RP-050832   485   Correction to RADIO BEARER SETUP message for   RP-050832   486   Correction to test procedure for HSDPA RF testing   RP-060154   486   Correction to GPS data files for signalling tests.   RP-060163   487   Corrections for reference RABS   F   6.1.1   6.2.0   R5-060325   RP-31   RP-060163   487   Corrections for reference RABS   F   6.1.1   6.2.0   R5-060335   RP-31   RP-060163   489   Corrections for reference RABS   F   6.1.1   6.2.0   R5-060335   RP-31   RP-060163   490   Corrections for default message content in INITIAL   F   6.1.0   6.2.0   R5-060335   RP-31   RP-060163   491   Corrections for default message content in INITIAL   F   6.1.0   6.2.0   R5-060335   RP-31   RP-060163   491   Corrections for default message content in INITIAL   F   6.1.1   6.2.0   R5-060345   RP-31   RP-060163   491   Corrections for default message content in INITIAL   F   6.1.1   6.2.0   R5-060469   RP-31   RP-060154   492   Correction for GPC HS RESEARER SETUP mess	RP-30	RP-050769	477	-		F	6.0.0	6.1.0	R5-051858
RP-30   RP-050769   478   Correction of UE states tables for Generic setup   F   6.0.0   6.1.0   R5-051942									
RP-30   RP-050769   479   Corrections to default message contents of HANDOVER FROM UTRAN COMMAND-GSM' message.   Addition of multi-rate AMR-NB configuration with SRB#5   F. 6.0.0   6.1.0   R5-052176   RP-30   RP-050769   481   Proposed CR to 34.108 [R6 version, R99 affected] to change slot format for AMR 5.9 mono rate RAB   Proposed CR to 34.108 [R6 version, R99 affected] to change slot format for AMR 5.9 mono rate RAB   RP-050769   482   Correction to puncturing limit in radio bearer configuration 6.10.2.4.1.38a   F. 6.0.0   6.1.0   R5-052096   RP-30   RP-050777   483   Introduction of third RAB subflow to WB-AMR test configurations   Correction to puncturing limit in radio bearer configurations   RP-30   RP-050833   484   Correction to DEADRA F SETUP message for HSDPA RF testing   F. 6.0.0   6.1.0   R5-052140   RP-30   RP-050832   485   Correction to RADIO BEARER SETUP message for HSDPA RF testing   RP-30   RP-050832   486   Correction to test procedure for HSDPA RF testing   F. 6.0.0   6.1.0   R5-052140   RP-31   RP-060154   486   Corrections to GPS data files for signalling tests.   F. 6.1.1   6.2.0   R5-060522   RP-31   RP-060163   487   Corrections to GPS data files for signalling tests.   F. 6.1.1   6.2.0   R5-060273   RP-31   RP-060154   488   Corrections to the RADIO BEARER SETUP message   F. 6.1.1   6.2.0   R5-06035   RP-31   RP-060154   490   Corrections to the RADIO BEARER SETUP message   F. 6.1.1   6.2.0   R5-060362   RP-31   RP-060154   490   Corrections to default message contents for signaling   F. 6.1.1   6.2.0   R5-060274   RP-31   RP-060154   490   Corrections to default message contents for signaling   RP-31   RP-060154   491   Update of RB configuration 6.10.2.4.1   4b1 bincrease   test coverage for multi-mode AMR configurations   RP-31   RP-060154   491   Update of RB configuration 6.10.2.4.1   4b1 bincrease   test coverage for multi-mode AMR configurations   RP-31   RP-060154   493   Correction of UERCN stets table for common   F. 6.1.1   6.2.0   R5-060274   RP-31   RP-060154   493   Co	RP-30	RP-050769	478	-		F	6.0.0	6.1.0	R5-051942
HANDOVER FROM UTRAN COMMAND-GSM'   message.   RP-30   RP-050776   480   Addition of multi-rate AMR-NB configuration with SRB#5   F   6.0.0   6.1.0   R5-052055   RP-30   RP-050769   481   Proposed CR to 34.108 [R6 version, R99 affected]   F   6.0.0   6.1.0   R5-052055   RP-30   RP-050769   482   Correction to puncturing limit in radio bearer   F   6.0.0   6.1.0   R5-052056   Change slot format for AMR 5.9 mono rate RAB   RP-050777   483   Introduction of third RAB sublitow to WB-AMR test   F   6.0.0   6.1.0   R5-052040   Configuration 6.10.2.4.1.38a   Correction to RADIO BEARER SETUP message for HSDPA RF testing   RP-30   RP-050832   485   Correction to RADIO BEARER SETUP message for HSDPA RF testing   RP-30   RP-050832   485   Correction to test procedure for HSDPA RF testing   F   6.0.0   6.1.0   6.1.1   RP-31   RP-060154   486   Corrections to GPS data files for signalling tests.   F   6.1.1   6.2.0   R5-060522   RP-31   RP-060163   487   Corrections to GPS data files for signalling tests.   F   6.1.1   6.2.0   R5-060335   for Enhanced uplink   RP-31   RP-060154   488   Corrections to the RADIO BEARER SETUP message   F   6.1.1   6.2.0   R5-060335   for Enhanced uplink   RP-31   RP-060154   489   Corrections to the RADIO BEARER SETUP message   F   6.1.1   6.2.0   R5-060335   RP-31   RP-060163   487   Corrections to the RADIO BEARER SETUP message   F   6.1.1   6.2.0   R5-060335   RP-31   RP-060154   490   Corrections to the RADIO BEARER SETUP message   F   6.1.1   6.2.0   R5-060360   RP-31   RP-060163   491   Update of RB configuration 6.10.2.4.1.4b to increase   F   6.1.1   6.2.0   R5-060360   RP-31   RP-060163   491   Update of RB configuration 6.10.2.4.1.4b to increase   F   6.1.1   6.2.0   R5-060429   RP-31   RP-060164   492   Corrections to default message content in INITIAL   F   6.1.1   6.2.0   R5-060429   RP-31   RP-060164   493   Corrections to default message content for Experimental RP-060164   492   Correction to DPCCH power offset value in RADIO   F   6.1.1   6.2.0   R5-060459   RP-31   RP-060164									
RP-30 RP-050776   480	RP-30	RP-050769	479	-		F	6.0.0	6.1.0	R5-051955
RP-30         RP-050776         480         Addition of multi-rate AMR-NB configuration with SRB#5 F         6.0.0         6.1.0         RF-052176           RP-30         RP-050769         481         - Proposed CR to 34.108 [R6 version, R99 affected] to change slot format for AMR 5.9 mono rate RAB         F         6.0.0         6.1.0         RF-052055           RP-30         RP-050769         482         Correction to puncturing limit in radio bearer configurations of configurations of third RAB subflow to WB-AMR test configurations configurations         6.0.0         6.1.0         RF-052086           RP-30         RP-050833         484         - Correction to RADIO BEARER SETUP message for F         6.0.0         6.1.0         - RF-052140           RP-30         RP-050832         485         - Correction to RADIO BEARER SETUP message for F         6.0.0         6.1.0         - RF-050140           RP-31         RP-060154         486         - Corrections to test procedure for HSDPA RF testing F         6.0.0         6.1.1         6.1.1         6.1.1         6.1.1         6.1.1         6.1.1         6.1.1         6.2.0         RF-060522         RF-060154         486         - Corrections to test procedure for HSDPA RF testing F         6.1.1         6.2.0         RF-060522         RF-060154         488         - Corrections to GPS data files for signalling tests.         F									
Change slot format for AMR 5.9 mono rate RAB   Correction to puncturing limit in radio bearer   F   6.0.0   6.1.0   R5-052096	RP-30	RP-050776	480	-		F	6.0.0	6.1.0	R5-052176
RP-30   RP-050769   482   Correction to puncturing limit in radio bearer   F   6.0.0   6.1.0   R5-05296   RP-30   RP-050777   483   Introduction of third RAB subflow to WB-AMR test   F   6.0.0   6.1.0   R5-052140   RP-30   RP-050833   484   Correction to RADIO BEARER SETUP message for   F   6.0.0   6.1.0   R5-052140   RP-30   RP-050832   485   Correction to RADIO BEARER SETUP message for   F   6.0.0   6.1.0   RP-30   RP-050832   485   Correction to test procedure for HSDPA RF testing   F   6.0.0   6.1.0   RP-31   RP-050832   485   Correction to test procedure for HSDPA RF testing   F   6.0.0   6.1.0   RP-31   RP-050154   486   Corrections to the state of the	RP-30	RP-050769	481	-		F	6.0.0	6.1.0	R5-052055
RP-30   RP-050777   483   Introduction of third RAB sublfow to WB-AMR test   F   6.0.0   6.1.0   R5-052140	DD 20	DD 050700	400			_	0.0.0	0.4.0	DE 050000
RP-30   RP-050777   483	KP-30	RP-050769	402	-	configuration 6.10.2.4.1.38a	Г	6.0.0	6.1.0	R5-052096
RP-30   RP-050833   484   Correction to RADIO BEARER SETUP message for   F   6.0.0   6.1.0	RP-30	RP-050777	483	-		F	6.0.0	6.1.0	R5-052140
RP-30 RP-050832									
RP-30   RP-050832   485   Correction to test procedure for HSDPA RF testing   Constitution   C	RP-30	RP-050833	484	-	Correction to RADIO BEARER SETUP message for	F	6.0.0	6.1.0	-
RP-31 RP-060154	RP-30	RP-050832	485	_		F	600	610	_
RP-31         RP-060154         486         Corrections to GPS data files for signalling tests.         F         6.1.1         6.2.0         R5-060522           RP-31         RP-060163         487         -         Corrections for reference RABs         F         6.1.1         6.2.0         R5-060273           RP-31         RP-060144         488         -         Corrections to the RADIO BEARER SETUP message for Enhanced uplink         F         6.1.1         6.2.0         R5-060335           RP-31         RP-060150         489         -         Correction to default message content in INITIAL DIRECT TRANSFER         F         6.1.0         6.2.0         R5-060366           RP-31         RP-060154         490         -         Corrections to default message contents for signaling signaling rest.         F         6.1.1         6.2.0         R5-06036           RP-31         RP-060163         491         -         Update of RB configuration 6.10.2.4.1.4b to increase test.         F         6.1.1         6.2.0         R5-060274           RP-31         RP-060163         491         -         Update of RB configuration 6.10.2.4.1.4b to increase test.         F         6.1.1         6.2.0         R5-06022           RP-31         RP-060163         492         -         Correction of UE RRC state	111 00	111 000002	100				6.1.0	6.1.1	
RP-31         RP-060163         487         Corrections for reference RABs         F         6.1.1         6.2.0         R5-060273           RP-31         RP-060144         488         Corrections to the RADIO BEARER SETUP message         F         6.1.1         6.2.0         R5-060335           RP-31         RP-060150         489         Correction to default message content in INITIAL DIRECT TRANSFER         F         6.1.0         6.2.0         R5-060360           RP-31         RP-060163         490         Correction to default message contents for signalling Procedures (section 7.4.1)         F         6.1.1         6.2.0         R5-060274           RP-31         RP-060163         491         Update of RB configuration 6.10.2.4.1.4b to increase test coverage for multi-mode AMR configurations         F         6.1.1         6.2.0         R5-060274           RP-31         RP-060144         492         Correction of UE RRC states table for common procedures (section 7.4.1)         F         6.1.1         6.2.0         R5-060268           RP-31         RP-060154         493         Correction to DPCCH power offset value in RADIO procedures (section 7.4.1)         F         6.1.1         6.2.0         R5-060459           RP-31         RP-060153         494         Introduction of Band VII and Band VIII to TS34.108         F         6									
RP-31   RP-060154   488   -     Corrections to the RADIO BEARER SETUP message   F   6.1.1   6.2.0   R5-060335   for Enhanced uplink   F   6.1.0   6.2.0   R5-060365   RP-31   RP-060150   489   -   Correction to default message content in INITIAL   F   6.1.0   6.2.0   R5-060396   DIRECT TRANSFER   RP-31   RP-060154   490   -   Corrections to default message contents for signaling   F   6.1.1   6.2.0   R5-060274   RP-31   RP-060163   491   -   Update of RB configuration 6.10.2.4.1.4b to increase   F   6.1.1   6.2.0   R5-060122   test coverage for multi-mode AMR configurations   F   6.1.1   6.2.0   R5-060122   RR-31   RP-060144   492   -   Correction of UE RRC states table for common   F   6.1.1   6.2.0   R5-060268   RP-31   RP-060154   493   -   Correction to DPCCH power offset value in RADIO   F   6.1.1   6.2.0   R5-060459   BEARER SETUP messages   RR-31   RP-060153   494   -   Introduction of Band VIII and Band VIII to TS34.108   F   6.1.1   6.2.0   R5-060440   RR-31   RP-060154   495   -   Clarification of RB Test Mode State for RF testing   F   6.1.1   6.2.0   R5-060440   RR-31   RP-060144   496   -   Common message content for E-DCH RF testing   F   6.1.1   6.2.0   R5-060438   RR-31   RP-060164   496   -   Common message content for E-DCH RF testing   F   6.1.1   6.2.0   R5-060438   RR-31   RP-060164   498   -   Correction to GPS Assistance Data for Performance   F   6.1.1   6.2.0   R5-060438   RR-31   RP-060163   500   -   Adding of RB Configuration 6.11.4b to clause 6.11 to increase test coverage for Interactive or background PS   RR-060331   501   -   Adding of RB Configuration 6.11.4b to clause 6.11 to increase test coverage for Interactive or background PS   RR-060331   502   -   Change to altitude of simulated UE position   F   6.2.0   6.3.0   R5-061223   RR-060337   504   -   Clarification to loopback on HSDPA call set up   F   6.2.0   6.3.0   R5-061410   R5-061046   RR-32   RR-060331   503   -     Clarification to loopback on HSDPA call set up   F   6.2.0   6.3.0   R5-061046   RR-32   RR-060331   50		55.000100	407	-	0 " ( , , , , , , , , , , , , , , , , , ,	F	0.4.4	000	DE 000070
For Enhanced uplink				-		F			
RP-31   RP-060150   489   Correction to default message content in INITIAL   F   6.1.0   6.2.0   R5-060396	101-51	1000144	400			l'	0.1.1	0.2.0	113-000333
RP-31 RP-060154	RP-31	RP-060150	489	-	Correction to default message content in INITIAL	F	6.1.0	6.2.0	R5-060396
RP-31         RP-060163         491         - Update of RB configuration 6.10.2.4.1.4b to increase test coverage for multi-mode AMR configurations         F         6.1.1         6.2.0         R5-060122           RP-31         RP-060144         492         - Correction of UE RRC states table for common procedures (section 7.4.1)         F         6.1.1         6.2.0         R5-060268           RP-31         RP-060154         493         - Correction to DPCCH power offset value in RADIO BEARER SETUP messages         F         6.1.1         6.2.0         R5-060459           RP-31         RP-060153         494         - Introduction of Band VII and Band VIII to TS34.108         F         6.1.1         6.2.0         R5-060440           Chapter 5 and introduction of new UARFCN scheme         Chapter 5 and introduction of new UARFCN scheme         F         6.1.1         6.2.0         R5-060440           RP-31         RP-060154         495         - Clarification of RB Test Mode State for RF testing         F         6.1.1         6.2.0         R5-060446           RP-31         RP-060144         496         - Common message content for E-DCH RF testing         F         6.1.1         6.2.0         R5-060439           RP-31         RP-060166         498         - Correction to GPS Assistance Data for Performance tests         F         6.1.1 <td< td=""><td>DD 04</td><td>DD 000454</td><td>100</td><td></td><td></td><td>_</td><td>0.4.4</td><td>0.0.0</td><td>DE 000074</td></td<>	DD 04	DD 000454	100			_	0.4.4	0.0.0	DE 000074
RP-31   RP-060154   493   -     Correction of UE RRC states table for common   F   6.1.1   6.2.0   R5-060459				-					
RP-31         RP-060144         492         Correction of UE RRC states table for common procedures (section 7.4.1)         F         6.1.1         6.2.0         R5-060268           RP-31         RP-060154         493         - Correction to DPCCH power offset value in RADIO BEARER SETUP messages         F         6.1.1         6.2.0         R5-060459           RP-31         RP-060153         494         - Introduction of Band VII and Band VIII to TS34.108         F         6.1.1         6.2.0         R5-060440           Chapter 5 and introduction of new UARFCN scheme         Chapter 5 and introduction of new UARFCN scheme         F         6.1.1         6.2.0         R5-060440           RP-31         RP-060154         495         - Clarification of RB Test Mode State for RF testing         F         6.1.1         6.2.0         R5-060446           RP-31         RP-060144         496         - Common message content for E-DCH RF testing         F         6.1.1         6.2.0         R5-060439           RP-31         RP-060166         498         - Correction to GPS Assistance Data for Performance tests         F         6.1.1         6.2.0         R5-060031           RP-31         RP-060154         499         - Corrections to default message contents for RF         F         6.1.1         6.2.0         R5-060257 <tr< td=""><td>101-51</td><td>1000103</td><td>431</td><td></td><td></td><td>l'</td><td>0.1.1</td><td>0.2.0</td><td>113-000122</td></tr<>	101-51	1000103	431			l'	0.1.1	0.2.0	113-000122
RP-31   RP-060154   493   -     Correction to DPCCH power offset value in RADIO   BEARER SETUP messages   RP-31   RP-060153   494   -   Introduction of Band VII and Band VIII to TS34.108   F   6.1.1   6.2.0   R5-060440   Chapter 5 and introduction of new UARFCN scheme   RP-31   RP-060154   495   -   Clarification of RB Test Mode State for RF testing   F   6.1.1   6.2.0   R5-060446   RP-31   RP-060144   496   -   Common message content for E-DCH RF testing   F   6.1.1   6.2.0   R5-060439   RP-31   RP-060144   497   -   Generic test procedure for E-DCH RF testing   F   6.1.1   6.2.0   R5-060439   RP-31   RP-060166   498   -     Correction to GPS Assistance Data for Performance   F   6.1.1   6.2.0   R5-060007   RP-31   RP-060163   500   -   Adding of RB Configuration 6.11.4b to clause 6.11 to increase test coverage for Interactive or background PS   RAB UL Okbps/DL Okbps.   RP-32   RP-060331   501   -   Addition of release information to A-GPS   RP-32   RP-060331   502   -   Change to altitude of simulated UE position   F   6.2.0   6.3.0   R5-061454   RP-32   RP-060337   504   -   Clarification to loopback on HSDPA call set up   F   6.2.0   6.3.0   R5-061046   RP-32   RP-060337   504   -     Clarification to loopback on HSDPA call set up   F   6.2.0   6.3.0   R5-061046	RP-31	RP-060144	492	-	Correction of UE RRC states table for common	F	6.1.1	6.2.0	R5-060268
RP-31   RP-060153   494   -   Introduction of Band VII and Band VIII to TS34.108   F   6.1.1   6.2.0   R5-060440	DD 04	DD 000454	400			_	0.4.4	0.0.0	DE 000450
RP-31   RP-060153   494   -   Introduction of Band VII and Band VIII to TS34.108   F   6.1.1   6.2.0   R5-060440	RP-31	RP-060154	493	-		F	6.1.1	6.2.0	R5-060459
Chapter 5 and introduction of new UARFCN scheme	RP-31	RP-060153	494	-		F	6.1.1	6.2.0	R5-060440
RP-31   RP-060144   496   -   Common message content for E-DCH RF testing   F   6.1.1   6.2.0   R5-060439					Chapter 5 and introduction of new UARFCN scheme				
RP-31         RP-060144         497         Generic test procedure for E-DCH RF testing         F         6.1.1         6.2.0         R5-060438           RP-31         RP-060166         498         Correction to GPS Assistance Data for Performance tests         F         6.1.1         6.2.0         R5-060007           RP-31         RP-060154         499         Corrections to default message contents for RF         F         6.1.1         6.2.0         R5-060257           RP-31         RP-060163         500         Adding of RB Configuration 6.11.4b to clause 6.11 to increase test coverage for Interactive or background PS RAB UL 0kbps/DL 0kbps.         F         6.1.1         6.2.0         R5-060571           RP-32         RP-060331         501         Addition of release information to A-GPS MEASUREMENT CONTROL message IEs         F         6.2.0         6.3.0         R5-061454           RP-32         RP-060331         502         Change to altitude of simulated UE position         F         6.2.0         6.3.0         R5-061410           RP-32         RP-060337         504         Clarification to loopback on HSDPA call set up         F         6.2.0         6.3.0         R5-061046				-					
RP-31         RP-060166         498         -         Correction to GPS Assistance Data for Performance tests         F         6.1.1         6.2.0         R5-060007           RP-31         RP-060154         499         -         Corrections to default message contents for RF         F         6.1.1         6.2.0         R5-060257           RP-31         RP-060163         500         -         Adding of RB Configuration 6.11.4b to clause 6.11 to increase test coverage for Interactive or background PS RAB UL 0kbps/DL 0kbps.         F         6.1.1         6.2.0         R5-060571           RP-32         RP-060331         501         -         Addition of release information to A-GPS MEASUREMENT CONTROL message IEs         F         6.2.0         6.3.0         R5-061454           RP-32         RP-060331         502         -         Change to altitude of simulated UE position         F         6.2.0         6.3.0         R5-061410           RP-32         RP-060331         503         -         Clarification of A-GPS simulated satellites         F         6.2.0         6.3.0         R5-061223           RP-32         RP-060337         504         -         Clarification to loopback on HSDPA call set up         F         6.2.0         6.3.0         R5-061046				-					
RP-31   RP-060154   499   -   Corrections to default message contents for RF   F   6.1.1   6.2.0   R5-060257				[-					
RP-31         RP-060163         500         -         Adding of RB Configuration 6.11.4b to clause 6.11 to increase test coverage for Interactive or background PS RAB UL 0kbps/DL 0kbps.         F         6.1.1         6.2.0         R5-060571           RP-32         RP-060331         501         -         Addition of release information to A-GPS MEASUREMENT CONTROL message IEs         F         6.2.0         6.3.0         R5-061454           RP-32         RP-060331         502         -         Change to altitude of simulated UE position         F         6.2.0         6.3.0         R5-061410           RP-32         RP-060331         503         -         Clarification of A-GPS simulated satellites         F         6.2.0         6.3.0         R5-061223           RP-32         RP-060337         504         -         Clarification to loopback on HSDPA call set up         F         6.2.0         6.3.0         R5-061046					tests				
Increase test coverage for Interactive or background PS   RAB UL 0kbps/DL 0kbps.   RAB UL 0kbps/DL 0kbps.   RP-32   RP-060331   501   Addition of release information to A-GPS   MEASUREMENT CONTROL message IEs   RP-32   RP-060331   502   Change to altitude of simulated UE position   F   6.2.0   6.3.0   R5-061410   RP-32   RP-060331   503   Clarification of A-GPS simulated satellites   F   6.2.0   6.3.0   R5-061223   RP-32   RP-060337   504   Clarification to loopback on HSDPA call set up   F   6.2.0   6.3.0   R5-061046				-					R5-060257
RAB UL 0kbps/DL 0kbps.   RAB UL 0kbps/DL 0kbps.   RP-32   RP-060331   501   - Addition of release information to A-GPS   F   6.2.0   6.3.0   R5-061454   RP-32   RP-060331   502   - Change to altitude of simulated UE position   F   6.2.0   6.3.0   R5-061410   RP-32   RP-060331   503   - Clarification of A-GPS simulated satellites   F   6.2.0   6.3.0   R5-061223   RP-32   RP-060337   504   - Clarification to loopback on HSDPA call set up   F   6.2.0   6.3.0   R5-061046	RP-31	RP-060163	500	-		F	6.1.1	6.2.0	R5-060571
RP-32         RP-060331         501         -         Addition of release information to A-GPS MEASUREMENT CONTROL message IEs         F         6.2.0         6.3.0         R5-061454           RP-32         RP-060331         502         -         Change to altitude of simulated UE position         F         6.2.0         6.3.0         R5-061410           RP-32         RP-060331         503         -         Clarification of A-GPS simulated satellites         F         6.2.0         6.3.0         R5-061223           RP-32         RP-060337         504         -         Clarification to loopback on HSDPA call set up         F         6.2.0         6.3.0         R5-061046									
MEASUREMENT CONTROL message IEs	RP-32	RP-060331	501	-	Addition of release information to A-GPS	F	6.2.0	6.3.0	R5-061454
RP-32         RP-060331         503         -         Clarification of A-GPS simulated satellites         F         6.2.0         6.3.0         R5-061223           RP-32         RP-060337         504         -         Clarification to loopback on HSDPA call set up         F         6.2.0         6.3.0         R5-061046					MEASUREMENT CONTROL message IEs				
RP-32 RP-060337 504 - Clarification to loopback on HSDPA call set up F 6.2.0 6.3.0 R5-061046				-	Ů ,	-			R5-061410
				<u> -</u>					
ı ı procedure I I I I	117-32	111-000337	304		procedure	[	0.2.0	0.3.0	13-001040

Meetin g-1st- Level	Doc-1st-Level	CR	Rev	Subject	Cat	Version -Current		Doc-2nd- Level
RP-32	RP-060337	505	-	Removal of alternative procedure for HSDPA RF testing	F	6.2.0	6.3.0	R5-061212
RP-32	RP-060337	506	-	Removal of alternative RB Setup message for HSDPA RF testing	F	6.2.0	6.3.0	R5-061213
RP-32	RP-060338	507	-	CR for 34.108:Addition of RADIO BEARER SETUP default message contents for LCR TDD HSDPA RF testing	F	6.2.0	6.3.0	R5-061438
RP-32	RP-060332	508	-	Correction to RB setup message for E-DCH	F	6.2.0	6.3.0	R5-061443
RP-32	RP-060334	509	-	CR to 34.108: Addition of band IV to test frequencies for UMTS 1.7/2.1 GHz	F	6.2.0	6.3.0	R5-061188
RP-32	RP-060 336	510	-	Addition of radio bearer setup and release for HCR HSDPA testing to 34.108	F	6.2.0	6.3.0	R5-061148
RP-32	RP-060337	511	-	HS-SCCH and HS-PDSCH power levels in signaling tests	F	6.2.0	6.3.0	R5-061207
RP-32	RP-060338	512	-	CR for 34.108:Addition of the combinations on DPCH and HS-PDSCH for LCR TDD	F	6.2.0	6.3.0	R5-061310
RP-32	RP-060338	513	-	CR for 34.108:Correction of RADIO BEARER SETUP default message contents for LCR TDD HSDPA	F	6.2.0	6.3.0	R5-061053
RP-32	RP-060338	514	-	CR for 34.108:Correction of RADIO BEARER RELEASE default message contents for LCR TDD HSDPA	F	6.2.0	6.3.0	R5-061054
RP-32	RP-060332	515	-	Corrections to the default RADIO BEARER SETUP message for Enhanced uplink	F	6.2.0	6.3.0	R5-061314
RP-32	RP-060332	516	-	Generalize E-DCH radio bearer names and correction to section numbering for 6.10.2.4.6.3.2.1.1.2.	F	6.2.0	6.3.0	R5-061315
RP-32	RP-060332	517	-	Addition of conversational radio bearer combinations for E-DCH/HS-DSCH testing	F	6.2.0	6.3.0	R5-061266
RP-32	RP-060332	518	-	E-HICH/E-RGCH and E-AGCH codes used in Radio Bearer Setup for signaling	F	6.2.0	6.3.0	R5-061386
RP-32	RP-060332	519	-	Introduction of additional WB-AMR RAB combination for E-DCH/HS-DSCH testing	F	6.2.0	6.3.0	R5-061339
RP-32	RP-060336	520	-	Addition of combinations on DPCH and HS-DSCH for HCR to 34.108	F	6.2.0	6.3.0	R5-061149
RP-32	RP-060322	521	-	Corrections to the values for IE based on calculated ASN.1 value to 34.108 clause 9	F	6.2.0	6.3.0	R5-061369
RP-32	RP-060328	522	-	CR to 34.108 Rel-6: Supplement to the UTRAN mobility information procedure in TDD	F	6.2.0	6.3.0	R5-061392
RP-32	RP-060322	523	-	Correction to specific message contents for UE Capability Information confirm message	F	6.2.0	6.3.0	R5-061139
RP-32	RP-060322	524	-	Corrections to the values for IE based on calculated ASN.1 value to 34.108 clause 6	F	6.2.0	6.3.0	R5-061281
RP-32	RP-060322	525	-	Addition of a new section for downlink physical channels code allocation for signalling in FDD	F	6.2.0	6.3.0	R5-061385
RP-33	RP-060560	526	-	Editorial changes in 34.108	F	6.3.0	6.4.0	R5-062092
RP-33	RP-060549	527	-	CR to 34.108: Correction of reference test frequencies for UMTS800 (Band VI)	F	6.3.0	6.4.0	R5-062440
RP-33	RP-060549	528	-	Correction to SIB11 in 6.1	F	6.3.0	6.4.0	R5-062427
RP-33	RP-060549	529	-	Correction to SECURITY MODE COMMAND message in 9.2.1	F	6.3.0	6.4.0	R5-062403
RP-33	RP-060562	530	-	Correction to RB Setup default message for E-DCH RF testing	F	6.3.0	6.4.0	R5-062208
RP-33	RP-060568	531	-	CR to 34.108: Correction the contents of RADIO BEARER SETUP message: AM or UM (1.28 Mcps TDD)	F	6.3.0	6.4.0	R5-062511
RP-33	RP-060566	532	-	Addition of HSDPA cases to radio bearer setup and radio bearer release in section 9.1.2	F	6.3.0	6.4.0	R5-062253
RP-33	RP-060567	533	-	Corrections to the default PHYSICAL CHANNEL RECONFIGURATION message	F	6.3.0	6.4.0	R5-062291
RP-33	RP-060567	534	-	Corrections to specification of HARQ RV sequence and retransmissions for 34.123-1 test cases configuring HSDPA	F	6.3.0	6.4.0	R5-062544
RP-33	RP-060562	535	-	Corrections to the default RADIO BEARER SETUP message	F	6.3.0	6.4.0	R5-062320
RP-33	RP-060562	536	-	New Test RABS for MAC-E/Es test cases	F	6.3.0	6.4.0	R5-062328
RP-33	RP-060562	537	-	Correction to radio bearer configuration 6.10.2.4.6 and 6.10.2.4.8	F	6.3.0	6.4.0	R5-062199
RP-33	RP-060562	538	-	Correction to 34.108 Section 9.1 : Corrections to Radio Bearer Setup for A12	F	6.3.0	6.4.0	R5-062348
RP-33	RP-060549	539	-	Clarification to section 6.10 and 6.11	F	6.3.0	6.4.0	R5-062194
RP-33	RP-060549	540	_	Correction to 34.108 Section 6.1 : Inclusion of System Information Block Type 5bis	F	6.3.0	6.4.0	R5-062398
RP-33	RP-060549	541		Corrections to maximum data rate for combinations on PRACH (FDD)	F	6.3.0	6.4.0	R5-062350
RP-34	RP-060739	542	-	Assistance Data change for A-GPS Minimum	F	6.4.0	6.5.0	R5-063400

Meetin g-1st- Level	Doc-1st-Level	CR	Rev	Subject	Cat	Version -Current		Doc-2nd- Level
				Performance Test				
RP-34	RP-060731	543	-	Correction to SECURITY MODE COMMAND message in 9.2.2	F	6.4.0	6.5.0	R5-063296
RP-34	RP-060735	544	-	Addition of PAGING TYPE 2 message in 9.2	F	6.4.0	6.5.0	R5-063401
RP-34	RP-060731	545	-	Correction to RADIO BEARER SETUP message in 9.2	F	6.4.0	6.5.0	R5-063402
RP-34	RP-060743	546	-	Correction to the set of Reference E-TFCIs in RB Setup default message (RF)	F	6.4.0	6.5.0	R5-063233
RP-34	RP-060731	547	-	Correction the Default System Information Block type6 Messages in 6.1.0b	F	6.4.0	6.5.0	R5-063294
RP-34	RP-060743	548	-	CR to 34.108, correction of RADIO BEARER SETUP for EDCH		6.4.0	6.5.0	R5-063545
RP-34	RP-060743	549	-	Correction to the set of Reference E-TFCIs in RB Setup default message (SIG)		6.4.0	6.5.0	R5-063240
RP-34	RP-060750	550	-	Introduction of radio bearers for MTCH	F	6.4.0	6.5.0	R5-063543
RP-34	RP-060749	551	-	Introduction of FDD interband testing in TS 34.108	F	6.4.0	6.5.0	R5-063255
RP-34	RP-060735	552	-	Correction to Radio Bearer Setup message –Mac-hs reset indicator	F	6.4.0	6.5.0	R5-063339
RP-34	RP-060731	553	-	CR to 34.108, Add MCC value for Band VI test	F	6.4.0	6.5.0	R5-063340
RP-34	RP-060731	554	-	CR to 34.108, Modify MCC value in IMSI of test USIM for Band VI test	F	6.4.0	6.5.0	R5-063341
	RP-060731	555	-	Correction to default content for System Information Block Type 7	F	6.4.0	6.5.0	R5-063079
RP-34	RP-060731	556	-	Clarification of FDD test channels used for signaling test cases	F	6.4.0	6.5.0	R5-063260
RP-35	RP-070105	558	-	Correction of IE "DL UM RLC LI size" in RF default messages for HSDPA	F	6.5.0	6.6.0	R5-070548
RP-35	RP-070096	559	1-	Signalled Reference E-TFCIs for E-DCH RF tests	F	6.5.0	6.6.0	R5-070113
	RP-070096	560	-	Correction to RB setup message used for E-DCH tests	F	6.5.0	6.6.0	R5-070221
RP-35	RP-070096	561	-	Correction of IE "DL UM RLC LI size" in RF default messages for E-DCH	F	6.5.0	6.6.0	R5-070549
RP-35	RP-070104	565	-	Correction to contents of System Information Block type 5 (1.28 Mcps TDD)	F	6.5.0	6.6.0	R5-070109
RP-35	RP-070104	566	-	Remove DCH information from RRC Connection Setup message to Cell_FACH state	F	6.5.0	6.6.0	R5-070353
RP-35	RP-070096	567	-	Corrections to 34.108 Radio Bearer Setup Message: AM or UM	F	6.5.0	6.6.0	R5-070038
RP-35	RP-070096	568	-	Introduction of radio bearers for Stand-alone SRBs for DCCH on E-DCH and HS-DSCH	F	6.5.0	6.6.0	R5-070356
RP-35	RP-070096	569	-	Introduction of RRC Connection setup message for Stand-alone SRBs for DCCH on E-DCH and HS-DSCH	F	6.5.0	6.6.0	R5-070357
RP-35	RP-070086	570	-	MBMS test - MCCH configurations	F	6.5.0	6.6.0	R5-070429
	RP-070086	571	-	Generic setup procedures and default values for MBMS signalling testing	F	6.5.0	6.6.0	R5-070422
RP-35	RP-070086	572	-	Introduction of signalling radio bearer for MCCH	F	6.5.0	6.6.0	R5-070147
	RP-070111	557	-	34.108 v6.6.0 pointer to Release 7 version	F	6.5.0	6.6.0	R5-070338
	1. 1. 0. 0 1 1 1	001	1	o il loo vololo politici to reciodoo i volololi		5.0.0	5.0.0	

## History

Document history		
V6.0.0	October 2005	Publication
V6.1.1	January 2006	Publication
V6.2.0	March 2006	Publication
V6.3.0	June 2006	Publication
V6.4.0	October 2006	Publication
V6.5.0	December 2006	Publication
V6.6.0	March 2007	Publication