ETSITS 134 108 V8.11.0 (2010-06)

Technical Specification

Universal Mobile Telecommunications System (UMTS);
LTE;
Common test environments for User Equipment (UE);
Conformance testing
(3GPP TS 34.108 version 8.11.0 Release 8)



Reference
RTS/TSGR-0534108v8b0

Keywords
LTE, UMTS

ETSI

650 Route des Lucioles F-06921 Sophia Antipolis Cedex - FRANCE

Tel.: +33 4 92 94 42 00 Fax: +33 4 93 65 47 16

Siret N° 348 623 562 00017 - NAF 742 C Association à but non lucratif enregistrée à la Sous-Préfecture de Grasse (06) N° 7803/88

Important notice

Individual copies of the present document can be downloaded from: http://www.etsi.org

The present document may be made available in more than one electronic version or in print. In any case of existing or perceived difference in contents between such versions, the reference version is the Portable Document Format (PDF). In case of dispute, the reference shall be the printing on ETSI printers of the PDF version kept on a specific network drive within ETSI Secretariat.

Users of the present document should be aware that the document may be subject to revision or change of status.

Information on the current status of this and other ETSI documents is available at

http://portal.etsi.org/tb/status/status.asp

If you find errors in the present document, please send your comment to one of the following services: http://portal.etsi.org/chaircor/ETSI_support.asp

Copyright Notification

No part may be reproduced except as authorized by written permission. The copyright and the foregoing restriction extend to reproduction in all media.

© European Telecommunications Standards Institute 2010. All rights reserved.

DECTTM, **PLUGTESTS**TM, **UMTS**TM, **TIPHON**TM, the TIPHON logo and the ETSI logo are Trade Marks of ETSI registered for the benefit of its Members.

3GPP[™] is a Trade Mark of ETSI registered for the benefit of its Members and of the 3GPP Organizational Partners. **LTE**[™] is a Trade Mark of ETSI currently being registered

for the benefit of its Members and of the 3GPP Organizational Partners. **GSM**® and the GSM logo are Trade Marks registered and owned by the GSM Association.

Intellectual Property Rights

IPRs essential or potentially essential to the present document may have been declared to ETSI. The information pertaining to these essential IPRs, if any, is publicly available for **ETSI members and non-members**, and can be found in ETSI SR 000 314: "Intellectual Property Rights (IPRs); Essential, or potentially Essential, IPRs notified to ETSI in respect of ETSI standards", which is available from the ETSI Secretariat. Latest updates are available on the ETSI Web server (http://webapp.etsi.org/IPR/home.asp).

Pursuant to the ETSI IPR Policy, no investigation, including IPR searches, has been carried out by ETSI. No guarantee can be given as to the existence of other IPRs not referenced in ETSI SR 000 314 (or the updates on the ETSI Web server) which are, or may be, or may become, essential to the present document.

Foreword

This Technical Specification (TS) has been produced by ETSI 3rd Generation Partnership Project (3GPP).

The present document may refer to technical specifications or reports using their 3GPP identities, UMTS identities or GSM identities. These should be interpreted as being references to the corresponding ETSI deliverables.

The cross reference between GSM, UMTS, 3GPP and ETSI identities can be found under http://webapp.etsi.org/key/queryform.asp.

Contents

Inte	ellectual Property Rights	2
For	eword	2
For	eword	4
	oduction	
	Scope	
	References	
	Definitions, abbreviations and symbols	
	Common requirements of test equipment	
	11 Void	
Anı	nex A to C: Void	6
Anı	nex D (informative): Change history	7
	tory	25

Foreword

This Technical Specification has been produced by the 3rd Generation Partnership Project (3GPP).

The contents of the present document are subject to continuing work within the TSG and may change following formal TSG approval. Should the TSG modify the contents of the present document, it will be re-released by the TSG with an identifying change of release date and an increase in version number as follows:

Version x.y.z

where:

- x the first digit:
 - 1 presented to TSG for information;
 - 2 presented to TSG for approval;
 - 3 or greater indicates TSG approved document under change control.
- y the second digit is incremented for all changes of substance, i.e. technical enhancements, corrections, updates, etc.
- z the third digit is incremented when editorial only changes have been incorporated in the document.

Introduction

The definition of the Conformance Tests for UE in 3G will be a complex task as the complete test suite covers RF, EMC and Protocol aspects of the UE.

Each test requires a Test Environment to be defined in which the UE has to operate to defined standards, constraints and performance. The overall task can be simplified if there are a number of well defined and agreed Common Test Environments where every one can be used for a number of tests. Hence the present documents defines testing conditions that are common to several tests avoiding the need to duplicate the same information for every single test.

The present document defines default values for a variety of common areas. Where values are not specified in test cases, the defaults in the present document will apply. If specified, the test case values will take precedence.

The present document addresses the FDD mode as well as the TDD mode.

1 Scope

The present document contains definitions of reference conditions and test signals, default parameters, reference radio bearer configurations used in radio bearer interoperability testing, common radio bearer configurations for other test purposes, common requirements for test equipment and generic set-up procedures for use in UE conformance tests.

2 References

The following documents contain provisions which, through reference in this text, constitute provisions of the present document.

- References are either specific (identified by date of publication, edition number, version number, etc.) or non-specific.
- For a specific reference, subsequent revisions do not apply.
- For a non-specific reference, the latest version applies. In the case of a reference to a 3GPP document (including a GSM document), a non-specific reference implicitly refers to the latest version of that document *in the same Release as the present document*.

[1] to [45] (void)

[46] 3GPP TS 34.108: "Common test environments for User Equipment (UE); Conformance testing".

3 Definitions, abbreviations and symbols

Void

4 Common requirements of test equipment

The requirements of the present document are provided in 3GPP TS 34.108 Release 9 [46].

5 to 11 Void

Annex A to C: Void

Annex D (informative): Change history

Meetin g-1st- Level	Doc-1st-Level	CR	Rev	Subject	Cat	Version -Current		Doc-2nd- Level
TP-08				Approval of the specification		2.0.0	3.0.0	
	TP-000131	001		RRC Message Contents: RLCSize	С	3.0.1	3.1.0	T1-000190
	TP-000131	002		RRC Message Contents: RLCParam	С	3.0.1	3.1.0	T1-000191
TP-09	TP-000131	003		RRC Message Contents: PCPreamble	С	3.0.1	3.1.0	T1-000192
TP-09	TP-000131	004		RRC Message Contents: RBIdentity	С	3.0.1	3.1.0	T1-000193
	TP-000131	005		RRC Message Contents: TrCHParam	С	3.0.1	3.1.0	T1-000194
	TP-000131	006		RRC Message Contents: UECapability	С	3.0.1	3.1.0	T1-000195
TP-09	TP-000131	007		RRC Message Contents: RBMapping	С	3.0.1	3.1.0	T1-000196
TP-09 TP-09	TP-000131 TP-000131	008 009		RRC Message Contents: PagingCause	С	3.0.1	3.1.0 3.1.0	T1-000197
		010		RRC Message Contents: CipheringAndIntegrity RRC Message Contents: RLCInfo	С	3.0.1	3.1.0	T1-000198 T1-000199
TP-09	TP-000131	010		RRC Message Contents: CompressedMode	С	3.0.1	3.1.0	T1-000199
TP-09		012		RRC Message Contents: SIB	С	3.0.1	3.1.0	T1-000200
TP-09	TP-000131	013		RRC Message Contents: PhyCH	D	3.0.1	3.1.0	T1-000201
TP-09	TP-000131	014		RRC Message Contents: Measurement	С	3.0.1	3.1.0	T1-000202
TP-09	TP-000131	015		RRC Message Contents: TFCS	С	3.0.1	3.1.0	T1-000203
TP-09	TP-000131	016		RRC Message Contents: DPCHFrameOffset	C	3.0.1	3.1.0	T1-000204
TP-09	TP-000131	017	1	Test USIM Parameters	F	3.0.1	3.1.0	T1-000215
TP-09	TP-000131	018		Correction to definition of the test algorithm for	F	3.0.1	3.1.0	T1-000164
		0.0		authentication (clause 8.1.2)		0.0.1	0.1.0	11 000101
TP-09	TP-000131	019		Reference Radio Bearer Configurations	F	3.0.1	3.1.0	T1-000212
TP-09	TP-000131	020		TDD Single mode	F	3.0.1	3.1.0	T1-000220
TP-10	TP-000215	021		Common generic procedure for AS testing	В	3.1.0	3.2.0	T1-000294
TP-10	TP-000215	022		Requirements for the system simulator for support of Tcell parameter	F	3.1.0	3.2.0	T1-000303
TP-10	TP-000215	023		Minimum Performance Levels	F	3.1.0	3.2.0	T1-000306
TP-10	TP-000215	024		Downlink signal conditions and propagation conditions	D	3.1.0	3.2.0	T1-000307
TP-10	TP-000215	025		Updating 34.108 v3.1.0 to TDD single mode	F	3.1.0	3.2.0	T1-000281
TP-10	TP-000215	026		Application of integrity mode protection to signalling message by default	F	3.1.0	3.2.0	T1-000296
TP-10	TP-000215	027		Updates to the default message contents in clause 9	С	3.1.0	3.2.0	T1-000282
TP-10	TP-000215	028		Updates to System Information Block (SIB) and Master Information Block (MIB) messages	С	3.1.0	3.2.0	T1-000283
TP-10	TP-000215	029		Application of ciphering during conformance testing	С	3.1.0	3.2.0	T1-000285
TP-10	TP-000215	030		Addition for System Information parameters (34.108 clause 6.1)	F	3.1.0	3.2.0	T1-000304
TP-10	TP-000215	031		Correction for Generic Setup Procedures (34.108 clause 7.2)	F	3.1.0	3.2.0	T1-000305
TP-11		032		Default radio conditions for multi-cell environment	F	3.2.0	3.3.0	T1-010078
TP-11	TP-010018	033		Correction for Generic Setup Procedures (34.108 clause 7.2)	F	3.2.0	3.3.0	T1-010079
TP-11	TP-010018	034		Corrections for Test USIM Parameters (34.108 clause 8)	F	3.2.0	3.3.0	T1-010080
TP-11	TP-010018	035		Correction of clause number in TS 34.108.	D	3.2.0	3.3.0	T1-010081
		036		Update of authentication test algorithm	С		3.3.0	T1-010082
	TP-010018	037		Updates to clause 9 of TS 34.108 v3.2.0	F	3.2.0	3.3.0	T1-010084
		038	<u> </u>	Updating to TDD single mode	F	3.2.0	3.3.0	T1-010088
	TP-010018	039	1	Simulated network environments for TDD mode (SIB)	F	3.2.0	3.3.0	T1-010089
		040	<u> </u>	Corrections to clause 6.10 FDD parameters	F	3.3.0	3.4.0	T1-010205
TP-12 TP-12	TP-010118 TP-010118	041 042		Corrections to clause 6.10 TDD parameters Adding section for radio bearer configurations intended for functional testing	F D	3.3.0 3.3.0	3.4.0 3.4.0	T1-010206 T1-010210
TP-12	TP-010118	043		Update of list of abbreviations	D	3.3.0	3.4.0	T1-010211
		044		Updates to clause 6.1 and 9	F	3.3.0	3.4.0	T1-010211
	TP-010118	045		Updates to clause 6.1 and 9 Updates to clause 7.4	F	3.3.0	3.4.0	T1-010212
	TP-010118	046		clause 6.1: System Information Blocks for TDD Mode	F	3.3.0	3.4.0	T1-010213
TP-12	TP-010118	047		Editorial corrections and removal of a reference	F	3.3.0	3.4.0	T1-010215
TP-13	TP-010215	048		Correction to reference	F	3.4.0	3.5.0	T1-010275
	TP-010215	049	1	Editorial modification for References	F.	3.4.0	3.5.0	T1-010276
	TP-010215	050		Some corrections in clause 5	F	3.4.0	3.5.0	T1-010277
TP-13	TP-010215	051		Update to Scope Statement	F	3.4.0	3.5.0	T1-010278
TP-13	TP-010215	052		Clause 6.10 Definition of RB configurations, TDD parameters	F	3.4.0	3.5.0	T1-010279
TP-13	TP-010215	053		Updates to clause 6.1, clause 7.4 and clause 9	F	3.4.0	3.5.0	T1-010280

Meetin g-1st-	Doc-1st-Level	CR	Rev	Subject	Cat	Version -Current		Doc-2nd- Level
Level						Junion	I TOW	20101
TP-13	TP-010215	054		Clause 6.1: Default radio conditions for Signalling tests	F	3.4.0	3.5.0	T1-010281
TP-13	TP-010215	055		Correction of Radio Bearer Configurations for FDD Mode	F	3.4.0	3.5.0	T1-010282
TP-13	TP-010215	056		Correction of Radio Bearer Configurations for TDD Mode	F	3.4.0	3.5.0	T1-010283
TP-13	TP-010215	057		Changes to Signalling Radio Bearer (SRB) numbering	F	3.4.0	3.5.0	T1-010284
	TP-010215	058		Missing bearers in tables 6.10.2.1.1 and 6.10.3.1.1	F	3.4.0	3.5.0	T1-010285
TP-13	TP-010215	059		Correction of system information block 5	F	3.4.0	3.5.0	T1-010286
TP-13	TP-010215	060		Introducing of 1.28 Mcps TDD Mode in clauses 4, 5 and 6	F	3.4.0	4.0.0	T1-010287
TP-13	TP-010215	061		Introduction of System Information Blocks for 1.28 Mcps TDD Mode	F	3.4.0	4.0.0	T1-010288
TP-13	TP-010215	062		Introduction of typical radio parameters for 1.28 McpsTDD	F	3.4.0	4.0.0	T1-010289
TP-13	TP-010215	063		Clause 6.11 RBs for RLC and PDCP testing	F	3.4.0	3.5.0	T1-010290
	TP-010285	065	1	Correction to 6.1 Contents of System Information Blocks	Α	4.0.0	4.1.0	T1-010475
	TP-010285	067	1	Corrections to clause 6.1, 7.4 and 9	Α	4.0.0	4.1.0	T1-010473
	TP-010258	069		Reference Radio Conditions	Α	4.0.0	4.1.0	T1-010461
TP-14	TP-010258	071		Modification of Test procedures for RF tests	Α	4.0.0	4.1.0	T1-010463
TP-14	TP-010258	073		Default message contents for RF tests	Α	4.0.0	4.1.0	T1-010465
TP-14	TP-010258	075		Correction to 6.10 Reference Radio Bearer configurations	Α	4.0.0	4.1.0	T1-010467
TP-14	TP-010258	077		Definition of default value of rate matching attribute	Α	4.0.0	4.1.0	T1-010469
TP-14	TP-010258	079		Update of clause 7.4 and 6.10	Α	4.0.0	4.1.0	T1-010471
TP-14	TP-010292	081		Correction on introduction of clause 6.10	Α	4.0.0	4.1.0	
TP-15	TP-020038	083		Replacement of Block STTD by Space Code Transmit Diversity (SCTD) (Rel-4)	Α	4.1.0	4.2.0	T1-020092
TP-15	TP-020038	085		Update of reference radio conditions (Rel-4)	Α	4.1.0	4.2.0	T1-020098
TP-15	TP-020038	087		Update of system reference configurations and default messages (Rel-4)	Α	4.1.0	4.2.0	T1-020100
TP-15	TP-020038	089		Corrections to 34108-410	Α	4.1.0	4.2.0	T1-020102
TP-15	TP-020038	091		Introduction of new Reference RABs (Rel-4)	Α	4.1.0	4.2.0	T1-020195
TP-15	TP-020038	094		Update of SIBs for TDD (both modes) in TS 34.108 (Rel4)	F	4.1.0	4.2.0	T1-020107
TP-15	TP-020038	095		Clarification of bit rate of Interactive/Background PS RAB function (Rel-4)	Α	4.1.0	4.2.0	T1-020184
				Correction of CR implementation errors in clauses: 6.10.2.2 and 6.10.2.4.1.58.2.1.1		4.2.0	4.2.1	
TP-16	TP-020141	108		Clause 7(reference) Update of generic setup procedures to use 13.6 kbps SRB in RRC connection	F	4.2.1	4.3.0	T1-020289
TP-16	TP-020141	109		establishment TDD (3.84 Mcps and 1.28 Mcps) Correction to clause 7.3.3.4 RADIO BEARER SETUP	Α	4.2.1	4.3.0	T1-020291
TP-16	TP-020141	110		message Change of RM attribute of DL:3.4 kbps SRBs for DCCH	Α	4.2.1	4.3.0	T1-020292
TP-16	TP-020141	111		in for REL4 New additional RAB configuration (R1-020669) for	Α	4.2.1	4.3.0	T1-020293
TP-16	TD 020444	112	1	REL4 Correction of Puncturing Limit for RABs for REL4	Α	4.2.1	420	T1 020204
	TP-020141 TP-020141	113		Test USIM	A		4.3.0	T1-020294
	TP-020141 TP-020141	114	1	Clause 6.1 (SIBs)Rel 4 (3.84 Mcps and 1.28 Mcps TDD)	F	4.2.1 4.2.1	4.3.0	T1-020295 T1-020296
TP-16	TP-020141	115		Clause 6.10 References for TDD about Clarification of bit rate of Interactive/Background PS RAB	А	4.2.1	4.3.0	T1-020296
TP-16	TP-020141	116	1	Correction to default message in clause 9 for Rel4	Α	4.2.1	4.3.0	T1-020298
	TP-020141	117	1	Correction to clause 6.1 for Rel4	A	4.2.1	4.3.0	T1-020298
	TP-020141	118	1	WCDMA1800 additions for Rel4	A	4.2.1	4.3.0	T1-020299
TP-16	TP-020141	119		Clause 9.1 Default message contents for TDD (3.84 Mcps and 1.28 Mcps) R4	F	4.2.1	4.3.0	T1-020301
TP-16	TP-020141	121		Update of generic setup procedures to use 13.6 kbps SRB in RRC connection establishment	А	4.2.1	4.3.0	T1-020434
TP-17	TP-020184	123	-	Alignment of reference configurations on S-CCPCH with default system information messages	А	4.3.0	4.4.0	T1-020503
TP-17	TP-020184	125	<u> </u>	Addition of reference compressed mode pattern	Α	4.3.0	4.4.0	T1-020505
TP-17	TP-020184	127	-	Corrections to default message contents as T1S- 020347rev1	A	4.3.0	4.4.0	T1-020507
TP-17	TP-020184	129	 	Additional default message contents for RF Testing	Α	4.3.0	4.4.0	T1-020509
TP-17	TP-020184	131	-	Corrections related to SIB11, SIB12 and to the	A	4.3.0	4.4.0	T1-020509
TD 4-	TD 00046	400		MEASUREMENT CONTROL message	^	4.0.0	4.4.0	T4 000500
TP-17	TP-020184	133	1-	Corrections to clause 6.1 (T1S-020349rev1)	A	4.3.0	4.4.0	T1-020530
TP-17	TP-020184	135	_	Introduction of reference configurations on S-CCPCH and PRACH with two interactive PS domain RABs	Α	4.3.0	4.4.0	T1-020539

g-1st-	Doc-1st-Level	CR	Rev	Subject	Cat	Version -Current	Version -New	Doc-2nd- Level
TP-17	TP-020184	137	-	Removal of reference radio bearer configurations for unidirectional streaming CS RABa above 64 kbps	A	4.3.0	4.4.0	T1-020541
TP-17	TP-020184	140	-	Some corrections and updates in clause 6.1 for TDD mode	F	4.3.0	4.4.0	T1-020576
TP-17	TP-020184	142	-	Inclusion of default message contents for RF in clause 9.2 for TDD mode	F	4.3.0	4.4.0	T1-020578
TP-18	TP-020293	144	-	Correction to default messages in 9.1 and 9.2	Α	4.4.0	4.5.0	T1-020658
TP-18	TP-020293	146	-	Corrections in the TDD test frequencies according to core specs	Α	4.4.0	4.5.0	T1-020674
TP-18	TP-020293	148	-	Addition of alternative configuration using Turbo Coding for Interactive or background / UL:8 DL:8 kbps / PS RAB + UL:3.4 DL:3.4 kbps SRBs for DCCH	Α	4.4.0	4.5.0	T1-020694
TP-18	TP-020293	150	-	Correction to content of clause 6.10.2.	Α	4.4.0	4.5.0	T1-020709
TP-18	TP-020293	152	-	Correction to SIB 11/12 definition	Α	4.4.0	4.5.0	T1-020712
TP-18	TP-020293	154	-	Reference Measurement Channels	Α	4.4.0	4.5.0	T1-020768
TP-18	TP-020293	156	-	Transferring system information definition using ASN.1 description to PRD	A	4.4.0	4.5.0	T1-020778
TP-18	TP-020293	158	-	Correction to RLC RAB TFCS	Α	4.4.0	4.5.0	T1-020780
TP-18	TP-020293	160	-	Default Message contents : Correction from CRs approved in RP17meeting	A	4.4.0	4.5.0	T1-020783
TP-18	TP-020293	162	-	Corrections to SIB1 to SIB6	Α	4.4.0	4.5.0	T1-020799
TP-18	TP-020293	164	-	Correction to RAB configurations as revision of T1S020756	Α	4.4.0	4.5.0	T1-020801
TP-18	TP-020293	166	-	Parameter addition for Reference RABs based on LS from RAN2	A	4.4.0	4.5.0	T1-020803
TP-18	TP-020293	168	-	Addition to clause 7.4 for multi call as T1S-020577rev2 (revision to T1S020820)	A	4.4.0	4.5.0	T1-020818
TP-18	TP-020293	169	-	RAB Combinations for IMS Services	F	4.4.0	4.5.0	T1-020819
TP-18	TP-020293	171	-	Correction to Contents of the Scheduling Block Syste Information in clause 6.1.3.	F	4.4.0	4.5.0	T1-020844
TP-19	TP-030044	173	-		Α	4.5.0	4.6.0	T1-030037
TP-19	TP-030044	175	-	Combine all Radio Bearer Setup messages into one table	Α	4.5.0	4.6.0	T1-030040
TP-19	TP-030044	177	-	Corrections to SB and SIB configurations in clause 6.1 as T1S030046rev1	A	4.5.0	4.6.0	T1-030042
TP-19	TP-030044	179	-	Correction to TS 34.108 Rel-4 ; PAGING TYPE1 message (Packet in PS)	A	4.5.0	4.6.0	T1-030044
TP-19	TP-030044	181	-	Clarification of autentication test algorithm and GSM cipher key	A	4.5.0	4.6.0	T1-030046
TP-19	TP-030044	183	-	Addition of simulated network environment for inter-RAT test cases		4.5.0	4.6.0	T1-030048
TP-19	TP-030044	185	-	Corrections to SIB1 to align with default values for LAC and RAC in 51.010-1.	A	4.5.0	4.6.0	T1-030050
	TP-030044	187	-	Addition of default inter-RAT handover messages	A	4.5.0	4.6.0	T1-030052
TP-19	TP-030044	189	-	Correction of activation time IEs in default messages	A	4.5.0	4.6.0	T1-030054
TP-19	TP-030044	191	-	Correction to default SECURITY MODE COMMAND message	A	4.5.0	4.6.0	T1-030056
TP-19	TP-030044	193	-	Addition of option for UL CM only in default reference CM patterns	A	4.5.0	4.6.0	T1-030058
TP-19	TP-030044	195	-	Introduction of a reference RB configuration for RMC for BTFD tests (Rel4)		4.5.0	4.6.0	T1-030060
TP-19	TP-030044	197	-	Update of the RRC connection request messages in 34.108 Rel4	A	4.5.0	4.6.0	T1-030063
TP-19	TP-030043	198	-	Introduction of Conversational PS RABs in Rel 4 TS 34.108 as T1S030003rev1	F	4.5.0	4.6.0	T1-030107
TP-19	TP-030043	200	-	Update of default parameters for 1 to 8 cell environments (TDD), clause 6.1.4, Rel 4	A	4.5.0	4.6.0	T1-030208
TP-19	TP-030043	202	-	Update of Multi-cell environment for default radio conditions (TDD), clause 6.1.6 (Inclusion of cell 4), Rel 4	Α	4.5.0	4.6.0	T1-030210
TP-19	TP-030043	204	-	Modification to Generic Registration Procedures	Α	4.5.0	4.6.0	T1-030222
TP-19	TP-030043	206	-	end UE	A	4.5.0	4.6.0	T1-030228
TP-20	TP-030098	208	-	Reinstate parameters for Interactive or background /UL:64 kbps / PS RAB	A	4.6.0	4.7.0	T1-030437
TP-20 TP-20	TP-030098 TP-030098	210 212	-		A A	4.6.0 4.6.0	4.7.0 4.7.0	T1-030483 T1-030507
TP-20	TP-030098	214	-	(TDD) Update of Default parameters for 1 to 8 cell	A	4.6.0	4.7.0	T1-030509
TP-20	TP-030098	216	-	environments in TS 34.108 (TDD) Correction of default messages according to 25331	A	4.6.0	4.7.0	T1-030632
		Ì	1	CR1823	ĺ	1	I	

TP-20	Meetin g-1st- Level	Doc-1st-Level	CR	Rev	Subject	Cat	Version -Current		Doc-2nd- Level
TP-20		TP-030098	218	-		А	4.6.0	4.7.0	T1-030644
TP-20	TP-20	TP-030098	219	-		Α	4.6.0	4.7.0	T1-030692
TP-21 TP-030191 228 CR to 34.108, Ret-4, Clarification of seg_count in			:	-	Correction to RADIO BEARER RELEASE and RRC CONNECTION SETUP messages (Revision of T1-030569)			4.7.0	
1.0.3 Seneral correction in clause 7.4 for Common generic proceedures for A3 testing procedures in clause A				-					
Procedures for A5 testing				-	6.1.0a.3				
TP-241 TP-030191 235 . Incorrect Transport channel Parameters				-	procedures for AS testing				
TP-23 TP-030191 237 Corrections to Ts 34.108 common procedures in clause A 4.70 4.80 T1-031095 T7-21 TP-030191 239 Removal of RLC AM in the Default Message Content A 4.70 4.80 T1-031151 TP-21 TP-030191 244 CR 34.108 Re4-4 Imanual attach in State 7 Registrated A 4.70 4.80 T1-031151 TP-21 TP-030191 244 URA Identity in Cell Update Confirm and URA Update A 4.70 4.80 T1-031179 TP-21 TP-030191 246 CR 63.4108 R4; Correction to specification to reflect a A 4.70 4.80 T1-031179 TP-21 TP-030191 248 CR 63.4108 R4; Correction to Specification to reflect a A 4.70 4.80 T1-031241 TP-21 TP-030191 240 RE4 CR 63.4108 R4; Correction to Specification to reflect a A 4.70 4.80 T1-031241 TP-21 TP-030191 240 RE4 CR 63.4108 R4; Correction to Specification to reflect a A 4.70 4.80 T1-031241 TP-21 TP-030191 240 RE4 CR 63.4108 R4; Correction to Calava 7.3 Test A 4.70 4.80 T1-031251 TP-22 TP-030279 251 Addition of Default message contents for TDD F 4.80 4.90 T1-031659 TP-22 TP-030279 252 Addition of Default message contents for TDD F 4.80 4.90 T1-031662 TP-22 TP-030279 254 Addition of Default message contents for TDD F 4.80 4.90 T1-031662 TP-22 TP-030279 256 Addition of Default message contents for TDD F 4.80 4.90 T1-031662 TP-22 TP-030279 258 Addition of Default message contents for TDD F 4.80 4.90 T1-031662 TP-22 TP-030279 258 Addition of Default message contents for TDD F 4.80 4.90 T1-031662 TP-22 TP-030279 258 Addition of Default message contents for TDD F 4.80 4.90 T1-031662 TP-22 TP-030279 258 Addition of Default message contents for TDD F 4.80 4.90 T1-031664 TP-22 TP-030279 258 Addition of Default message contents for TDD F 4.80 4.90 T1-031664 TP-22 TP-030279 258 Addition of Default message contents for TDD F 4.80 4.90 T1-031664				-					
T-21				-					
TP-21				-	7.4 of Rel-4 of TS 34.108				
Italia				-	Removal of RLC AM in the Default Message Content				
Confirm				-	Idle Mode on CS/PS				
Change already approved in TTCN CR T1-030396 Change already approved in TTCN CR T1-030396 TP-22				-	Confirm				
TP-21	TP-21	TP-030191	246	-		Α	4.7.0	4.8.0	T1-031241
TP-22	TP-21	TP-030191	248	-	CR to 34.108 REL-4; Correction to clause 7.3 Test	Α	4.7.0	4.8.0	T1-031251
TP-22	TP-21	TP-030191	240	-	RB configuration for the support of wideband AMR	F	4.7.0	4.8.0	T1-031154
TP-22	TP-22	TP-030279	251	1		F	480	490	T1-031659
TP-22 TP-030279 253 1 Addition of Default message contents for TDD F 4.8.0 4.9.0 T1-031661									
TP-22 TP-030279 254				-					
TP-22 TP-030279 255 1 Addition of Default message contents for TDD									
TP-22 TP-030279 256 1 Addition of Default message contents for TDD F 4.8.0 4.9.0 T1-031665				1					
TP-22 TP-030279 257 1 Addition of Default message contents for TDD				1					
TP-22 TP-030279 258 1 Addition of Default message contents for TDD F 4.8.0 4.9.0 T1-031666 TP-22 TP-030279 260 2 CR on PAGING TYPE 1, RRC CONNECTION SETUP messages for MT RR CONSTANT RR CONNECTION SETUP messages for MT RR CONSTANT									
TP-22 TP-030279 260 2 CR on PAGING TYPE 1, RRC CONNECTION A 4.8.0 4.9.0 T1-031596						F			
TP-22 TP-030279 262 CR 34.108 Rel-4: EFRPLMNACT (RPLMN Last used A d.8.0 4.9.0 T1-031381					CR on PAGING TYPE 1, RRC CONNECTION REQUEST and RRC CONNECTION SETUP messages	A			
TP-22 TP-030279 264 1 Update of default messages for RRC CONNECTION SETUP and SECURITY MODE COMMAND A 4.8.0 4.9.0 T1-031547 TP-22 TP-030279 266 1 Description and corrections of channels for minimum performance levels, TDD mode. F 4.8.0 4.9.0 T1-031645 TP-22 TP-030279 268 1 Test frequencies of UMTS800MHz band VI A 4.8.0 4.9.0 T1-031555 TP-22 TP-030279 269 CR 34.108 Rel-4: Addition of Bearer combination for Interactive/background UL 64 kbps DL 768 kbps for Rel-5 F 4.8.0 4.9.0 T1-031641 TP-22 TP-030279 271 1 Update of generic test procedure for TX, RX and Performance Requirement A 4.8.0 4.9.0 T1-031610 TP-22 TP-030279 273 1 Introduction of generic test procedure for RRM Anadover test cases A 4.8.0 4.9.0 T1-031608 TP-22 TP-030279 275 1 Corrections to default message contents of Radio F 4.8.0 4.9.0 T1-031591 TP-22 <t< td=""><td>TP-22</td><td>TP-030279</td><td>262</td><td></td><td></td><td>A</td><td>4.8.0</td><td>4.9.0</td><td>T1-031381</td></t<>	TP-22	TP-030279	262			A	4.8.0	4.9.0	T1-031381
TP-22 TP-030279 266 1 Description and corrections of channels for minimum performance levels, TDD mode. 4.8.0 4.9.0 T1-031645 TP-22 TP-030279 268 1 Test frequencies of UMTS800MHz band VI A 4.8.0 4.9.0 T1-031555 TP-22 TP-030279 269 CR 34.108 Rel-4: Addition of Bearer combination for Interactive/background UL 64 kbps DL 768 kbps for Rel-5 F 4.8.0 4.9.0 T1-031441 TP-22 TP-030279 271 1 Update of generic test procedure for TX, RX and Performance Requirement A 4.8.0 4.9.0 T1-031610 TP-22 TP-030279 273 1 Introduction of generic test procedure for RRM Andover test cases A 4.8.0 4.9.0 T1-031608 TP-22 TP-030279 275 1 Corrections to GM TGD parameter A 4.8.0 4.9.0 T1-031591 TP-22 TP-030279 275 1 Corrections to default message contents of Radio F 4.8.0 4.9.0 T1-031594 TP-22 TP-030279 279 1 <	TP-22	TP-030279	264	1	Update of default messages for RRC CONNECTION	Α	4.8.0	4.9.0	T1-031547
TP-22 TP-030279 268 1 Test frequencies of UMTS800MHz band VI A. 4.8.0 A. 4.8.0 4.9.0 T1-031555 TP-22 TP-030279 269 CR 34.108 Rel-4: Addition of Bearer combination for Interactive/background UL 64 kbps DL 768 kbps for Rel-5 F. 4.8.0 4.9.0 T1-031441 TP-22 TP-030279 271 1 Update of generic test procedure for TX, RX and Performance Requirement A. 4.8.0 4.9.0 T1-031610 TP-22 TP-030279 273 1 Introduction of generic test procedure for RRM handover test cases A. 4.8.0 4.9.0 T1-031608 TP-22 TP-030279 275 1 Correction of CM TGD parameter A. 4.8.0 4.9.0 T1-031591 TP-22 TP-030279 275 1 Corrections to default message contents of Radio Bearer Release F. 4.8.0 4.9.0 T1-031594 TP-22 TP-030279 279 1 Modification to default DPCCH_Power_offset value A. 4.8.0 4.9.0 T1-031598 TP-22 TP-030279 283 Correction to TFCS for radio bearer combination A. 4.8.0 4.9.0 T1-0	TP-22	TP-030279	266	1	Description and corrections of channels for minimum	F	4.8.0	4.9.0	T1-031645
TP-22 TP-030279 269 CR 34.108 Rel-4: Addition of Bearer combination for Interactive/background UL 64 kbps DL 768 kbps for Rel-5 F 4.8.0 4.9.0 T1-031441 TP-22 TP-030279 271 1 Update of generic test procedure for TX, RX and Performance Requirement A 4.8.0 4.9.0 T1-031610 TP-22 TP-030279 273 1 Introduction of generic test procedure for RRM handover test cases A 4.8.0 4.9.0 T1-031608 TP-22 TP-030279 275 1 Correction of CM TGD parameter A 4.8.0 4.9.0 T1-031591 TP-22 TP-030279 277 1 Corrections to default message contents of Radio Bearer Release F 4.8.0 4.9.0 T1-031594 TP-22 TP-030279 279 1 Modification to default DPCCH_Power_offset value A 4.8.0 4.9.0 T1-031598 TP-22 TP-030279 283 Correction of TFCS for radio bearer combination A. 1.9.0 4.8.0 4.9.0 4.9.0 T1-031527 TP-23 TP-040037 284 - New Radio	TP-22	TP-030279	268	1		Α	4.8.0	4.9.0	T1-031555
Performance Requirement		TP-030279	269		CR 34.108 Rel-4: Addition of Bearer combination for Interactive/background UL 64 kbps DL 768 kbps for Rel-5	F	4.8.0	4.9.0	T1-031441
handover test cases	TP-22	TP-030279		1		Α	4.8.0	4.9.0	T1-031610
TP-22 TP-030279 275 1 Correction of CM TGD parameter A 4.8.0 4.9.0 T1-031591 TP-22 TP-030279 277 1 Corrections to default message contents of Radio Bearer Release F 4.8.0 4.9.0 T1-031594 TP-22 TP-030279 279 1 Modification to default DPCCH_Power_offset value A 4.8.0 4.9.0 T1-031598 TP-22 TP-030279 283 Correction of TFCS for radio bearer combination 6.10.2.4.1.51b A 4.8.0 4.9.0 T1-031598 TP-23 TP-040037 284 - New Radio Bearer Setup (FDD) message for RF (Revision of T1-040258) F 4.9.0 4.10.0 T1-040417 TP-23 TP-040037 287 - Corrections to default message contents of RRC Connection Setup message -> 2nd change not implemented (not implementable) A 4.9.0 4.10.0 T1-040080 TP-23 TP-040037 289 - Correction to Default parameters for Cells 1 to 8 in MultiPLMN cell environments - Rel-4 A 4.9.0 4.10.0 T1-040095 TP-23 TP-0	TP-22		273	1		Α	4.8.0	4.9.0	T1-031608
TP-22 TP-030279 277 1 Corrections to default message contents of Radio Bearer Release F 4.8.0 4.9.0 T1-031594 TP-22 TP-030279 279 1 Modification to default DPCCH_Power_offset value A 4.8.0 4.9.0 T1-031598 TP-22 TP-030279 283 Correction of TFCS for radio bearer combination 6.10.2.4.1.51b A 4.8.0 4.9.0 T1-031527 TP-23 TP-040037 284 - New Radio Bearer Setup (FDD) message for RF (Revision of T1-040258) F 4.9.0 4.10.0 T1-040417 TP-23 TP-040037 287 - Corrections to default message contents of RRC Connection Setup message -> 2nd change not implemented (not implementable) A 4.9.0 4.10.0 T1-040080 TP-23 TP-040037 289 - Correction to Default parameters for Cells 1 to 8 in MultiPLMN cell environments - Rel-4 A 4.9.0 4.10.0 T1-040095 TP-23 TP-040037 296 - Corrections to TDD RABs merge of T1-040104 , T1-040204 , T1-040209 F 4.9.0 4.10.0 T1-040209	TP-22	TP-030279		1	Correction of CM TGD parameter	Α	4.8.0	4.9.0	T1-031591
TP-22 TP-030279 279 1 Modification to default DPCCH_Power_offset value A 4.8.0 4.9.0 T1-031598 TP-22 TP-030279 283 Correction of TFCS for radio bearer combination 6.10.2.4.1.51b A 4.8.0 4.9.0 T1-031527 TP-23 TP-040037 284 - New Radio Bearer Setup (FDD) message for RF (Revision of T1-040258) F 4.9.0 4.10.0 T1-040417 TP-23 TP-040037 287 - Corrections to default message contents of RRC Connection Setup message -> 2nd change not implemented (not implementable) A 4.9.0 4.10.0 T1-040080 TP-23 TP-040037 289 - Correction to Default parameters for Cells 1 to 8 in MultiPLMN cell environments - Rel-4 A 4.9.0 4.10.0 T1-040095 TP-23 TP-040037 291 - Corrections to TDD RABs merge of T1-040104 , T1-040103 F 4.9.0 4.10.0 T1-040299 TP-23 TP-040037 298 - Correction to handling of Entered Parameter IE in default contents for Initial Direct Transfer A 4.9.0 4.10.0 T1-040368	TP-22	TP-030279		1		F	4.8.0	4.9.0	T1-031594
TP-22 TP-030279 283 Correction of TFCS for radio bearer combination 6.10.2.4.1.51b A 4.8.0 4.9.0 T1-031527 TP-23 TP-040037 284 - New Radio Bearer Setup (FDD) message for RF (Revision of T1-040258) F 4.9.0 4.10.0 T1-040417 TP-23 TP-040037 287 - Corrections to default message contents of RRC Connection Setup message -> 2nd change not implemented (not implementable) A 4.9.0 4.10.0 T1-040080 TP-23 TP-040037 289 - Correction to Default parameters for Cells 1 to 8 in MultiPLMN cell environments - Rel-4 A 4.9.0 4.10.0 T1-040095 TP-23 TP-040037 291 - Corrections to TDD HCR RABs A 4.9.0 4.10.0 T1-040103 TP-23 TP-040037 296 - LCR Corrections to TDD RABs merge of T1-040104 , T1-040203 F 4.9.0 4.10.0 T1-040211 TP-23 TP-040037 298 - Correction to handling of Entered Parameter IE in default contents for Initial Direct Transfer A 4.9.0 4.10.0 T1-040368 <td>TP-22</td> <td>TP-030279</td> <td>279</td> <td>1</td> <td></td> <td>Α</td> <td>4.8.0</td> <td>4.9.0</td> <td>T1-031598</td>	TP-22	TP-030279	279	1		Α	4.8.0	4.9.0	T1-031598
TP-23 TP-040037 284 - New Radio Bearer Setup (FDD) message for RF (Revision of T1-040258) F 4.9.0 4.10.0 T1-040417 TP-23 TP-040037 287 - Corrections to default message contents of RRC Connection Setup message -> 2nd change not implemented (not implementable) A 4.9.0 4.10.0 T1-040080 TP-23 TP-040037 289 - Correction to Default parameters for Cells 1 to 8 in MultiPLMN cell environments - Rel-4 A 4.9.0 4.10.0 T1-040095 TP-23 TP-040037 291 - Corrections to TDD HCR RABs A 4.9.0 4.10.0 T1-040103 TP-23 TP-040037 296 - LCR Corrections to TDD RABs merge of T1-040104 , T1-040203 F 4.9.0 4.10.0 T1-040299 TP-23 TP-040037 298 - Correction to handling of Entered Parameter IE in default contents for Initial Direct Transfer A 4.9.0 4.10.0 T1-040368 TP-23 TP-040037 300 - The diverse operation in TDD mode updating according A 4.9.0 4.10.0 T1-040368 <td></td> <td></td> <td></td> <td></td> <td>Correction of TFCS for radio bearer combination</td> <td>Α</td> <td></td> <td></td> <td>T1-031527</td>					Correction of TFCS for radio bearer combination	Α			T1-031527
TP-23 TP-040037 287 Corrections to default message contents of RRC Connection Setup message -> 2nd change not implemented (not implementable) A 4.9.0 4.10.0 T1-040080 TP-23 TP-040037 289 - Correction to Default parameters for Cells 1 to 8 in MultiPLMN cell environments - Rel-4 A 4.9.0 4.10.0 T1-040095 TP-23 TP-040037 291 - Corrections to TDD HCR RABs A 4.9.0 4.10.0 T1-040103 TP-23 TP-040037 296 - LCR Corrections to TDD RABs merge of T1-040104 , T1-040209 F 4.9.0 4.10.0 T1-040299 TP-23 TP-040037 298 - Correction to handling of Entered Parameter IE in default contents for Initial Direct Transfer A 4.9.0 4.10.0 T1-040411 TP-23 TP-040037 300 - The diverse operation in TDD mode updating according A 4.9.0 4.10.0 T1-040368	TP-23	TP-040037	284	-	New Radio Bearer Setup (FDD) message for RF	F	4.9.0	4.10.0	T1-040417
TP-23 TP-040037 289 Correction to Default parameters for Cells 1 to 8 in MultiPLMN cell environments - Rel-4 A 4.9.0 4.10.0 T1-040095 TP-23 TP-040037 291 - Corrections to TDD HCR RABs A 4.9.0 4.10.0 T1-040103 TP-23 TP-040037 296 - LCR Corrections to TDD RABs merge of T1-040104 , T1-040209 F 4.9.0 4.10.0 T1-040299 TP-23 TP-040037 298 - Correction to handling of Entered Parameter IE in default contents for Initial Direct Transfer A 4.9.0 4.10.0 T1-040411 TP-23 TP-040037 300 - The diverse operation in TDD mode updating according A 4.9.0 4.10.0 T1-040368	TP-23	TP-040037	287	-	Corrections to default message contents of RRC Connection Setup message -> 2nd change not	Α	4.9.0	4.10.0	T1-040080
TP-23 TP-040037 291 - Corrections to TDD HCR RABs A 4.9.0 4.10.0 T1-040103 TP-23 TP-040037 296 - LCR Corrections to TDD RABs merge of T1-040104 , T1-040209 F 4.9.0 4.10.0 T1-040299 TP-23 TP-040037 298 - Correction to handling of Entered Parameter IE in default contents for Initial Direct Transfer A 4.9.0 4.10.0 T1-040411 TP-23 TP-040037 300 - The diverse operation in TDD mode updating according A A 4.9.0 4.10.0 T1-040368	TP-23	TP-040037	289	-	Correction to Default parameters for Cells 1 to 8 in	Α	4.9.0	4.10.0	T1-040095
TP-23 TP-040037 296 - LCR Corrections to TDD RABs merge of T1-040104 , T1-040209 F 4.9.0 4.10.0 T1-040299 TP-23 TP-040037 298 - Correction to handling of Entered Parameter IE in default contents for Initial Direct Transfer A 4.9.0 4.10.0 T1-040411 TP-23 TP-040037 300 - The diverse operation in TDD mode updating according A A 4.9.0 4.10.0 T1-040368	TP-23	TP-040037	291	<u> </u>		Α	490	4 10 0	T1-040103
TP-23 TP-040037 298 - Correction to handling of Entered Parameter IE in default contents for Initial Direct Transfer TP-23 TP-040037 300 - The diverse operation in TDD mode updating according A 4.9.0 4.10.0 T1-040368				-	LCR Corrections to TDD RABs merge of T1-040104,				
TP-23 TP-040037 300 - The diverse operation in TDD mode updating according A 4.9.0 4.10.0 T1-040368	TP-23	TP-040037	298	-	Correction to handling of Entered Parameter IE in	Α	4.9.0	4.10.0	T1-040411
	TP-23	TP-040037	300	-	The diverse operation in TDD mode updating according	A	4.9.0	4.10.0	T1-040368

Meetin g-1st- Level	Doc-1st-Level	CR	Rev	Subject	Cat	Version -Current		Doc-2nd- Level
TP-23	TP-040037	302	-	correction of measurement control default message contents for TDD -> Not implemented (not implementable)	F	4.9.0	4.10.0	T1-040370
TP-23	TP-040037	303	-	,	F	4.9.0	4.10.0	T1-040371
TP-23	TP-040037	304	-	Correction of RADIO BEARER RELEASE default message contents for TDD: AM or UM (1.28 Mcps TDD)	F	4.9.0	4.10.0	T1-040372
TP-23	TP-040037	305	-	Contents of RRC CONNECTION SETUP message: UM (Transition to CELL_DCH) (1.28 Mcps TDD) -> Not	F	4.9.0	4.10.0	T1-040373
TP-23	TP-040037	292	L	implemented (not implementable) New I/B UL:64 DL:768 kbps PS RAB misplaced	F	4.10.0	5.0.0	T1-040109
	TP-040037	294	-		F	4.10.0	5.0.0	T1-040109
TP-23	TP-040037	295	-	Baseline radio bearer combination for HSDPA support	В	4.10.0	5.0.0	T1-040273
TP-24	TP-040112	308	_	Correction to IEs "START" and	F	5.0.0	5.1.0	T1-040512
TP-24	TP-040112	309	-	"ul_CounterSynchronisationInfo". Correction to HSDPA reference radio bearer	F	5.0.0	5.1.0	T1-040522
			_	configurations				
	TP-040112	310	-	Addition of test procedure for HSDPA RF testing	F	5.0.0	5.1.0	T1-040546
	TP-040112	315	<u> </u>	Corrections to default RRC messages	F	5.0.0	5.1.0	T1-040593
	TP-040112	318	<u> </u>	Change of default LAC/RAC for inter-RAT test cases	A	5.0.0	5.1.0	T1-040656
TP-24	TP-040112	319	Ξ	Contents of Physical channel Reconfiguration message modified to incorporate transition to URA_PCH or CELL_PCH	F	5.0.0	5.1.0	T1-040673
TP-24	TP-040112	320	-	Correction of reference test frequencies for UMTS800(band VI)	F	5.0.0	5.1.0	T1-040701
TP-24	TP-040112	325	-	Update of generic setup procedures in clauses 7.3.4 and 7.3.5.	Α	5.0.0	5.1.0	T1-040754
TP-24	TP-040112	326	=	Physical channel parameters for AM RLC 7 bit Length Indicator TestCases (Rel-5)	F	5.0.0	5.1.0	T1-040902
TP-24	TP-040112	327	=	Corrections to the default contents of Security Mode Command (Rel-5)	F	5.0.0	5.1.0	T1-040903
TP-24	TP-040112	330	-	Corrections to Contents of Scheduling Block 1 (FDD)	F	5.0.0	5.1.0	T1-040909
	TP-040112	331	-	Corrections to Contents of PHYSICAL CHANNEL RECONFIGURATION message: AM or UM	F	5.0.0	5.1.0	T1-040911
TP-24	TP-040112	332	-	Corrections to Contents of RRC CONNECTION SETUP message: UM	F	5.0.0	5.1.0	T1-040913
TP-24	TP-040112	333	-	RADIO BEARER SETUP message (FDD) for Test Loop Mode2.	F	5.0.0	5.1.0	T1-040917
TP-24	TP-040112	335	-	Changes to establish one version of 34.108 covering all releases	Α	5.0.0	5.1.0	T1-040931
TP-24	TP-040112	338	-	Addition of generic test procedure for AS test cases using the test loop	Α	5.0.0	5.1.0	T1-040934
TP-24	TP-040112	339	-	Corrections to LCR TDD RABs	F	5.0.0	5.1.0	T1-040935
	TP-040157	343	-	Correction to generic test procedure in clause 7.4.2.6a.	F	5.1.0	5.2.0	T1-041040
TP-25	TP-040157	344	1-	Addition of default messages for Signalling (FDD)	F	5.1.0	5.2.0	T1-041044
TP-25	TP-040157	345	-	Minor change to terminology in SRB tables of clause 6.10	F	5.1.0	5.2.0	T1-041140
TP-25	TP-040157	346	-	Default Message Content for System Information Block type 5 (FDD) and type 6 (FDD)	F	5.1.0	5.2.0	T1-041154
TP-25	TP-040157	347	-		D	5.1.0	5.2.0	T1-041171
TP-25	TP-040157	348	-	Corrections to clause 9	F	5.1.0	5.2.0	T1-041223
TP-25	TP-040157	349	-	Corrections to HCR TDD RAB combinations	F	5.1.0	5.2.0	T1-041235
	TP-040157	350	-	Adding missing clause 6.10.2.4.1.62.1	F	5.1.0	5.2.0	T1-041252
TP-25	TP-040157	351	-	Modification of AICH power offset in SysInfo 5 and 6.	F	5.1.0	5.2.0	T1-041253
TP-25	TP-040157	352	-	Correction to Default Message Content for Radio Bearer Setup Message.		5.1.0	5.2.0	T1-041259
TP-25	TP-040157	353	-	Correction to Default Message Content for Radio Bearer Reconfiguration Message for Condition A6	F	5.1.0	5.2.0	T1-041266
TP-25	TP-040157	354	-	CR to 34.108: introduction of default RB SETUP message from cell_FACH state for HSDPA	F	5.1.0	5.2.0	T1-041298
TP-25	TP-040157	355	-	Corrections to Contents of RADIO BEARER SETUP message: BTFD RMC	F	5.1.0	5.2.0	T1-041317
TP-25	TP-040157	340	-	Resolution of downlink code conflict between OCNS DPCH and S-CCPCH	F	5.1.0	5.2.0	T1-041327
TP-25	TP-040157	361	-	Correction to test procedure for test cases using Cell_PCH or URA_PCH state	F	5.1.0	5.2.0	T1-041346
TP-25	TP-040157	362	-	Removal of DCCH dummy transmission for RF testing	F	5.1.0	5.2.0	T1-041350
TP-25	TP-040157	341	-	Correct title to test procedure for test cases using Cell_PCH or URA_PCH state	F		5.2.0	T1-041354
TP-25	TP-040157	363	1-	Addition of intra frequency cell to cell environments	F	5.1.0	5.2.0	T1-041356

Meetin g-1st- Level	Doc-1st-Level	CR	Rev	Subject	Cat	Version -Current		Doc-2nd- Level
TP-25	TP-040157	342	-	Correct primary scrambling code usage in default message contents in clause 9.2.1	F	5.1.0	5.2.0	T1-041365
TP-25	TP-040157	356	-	HSDPA downlink code allocation	F	5.1.0	5.2.0	T1-041374
TP-25	TP-040157	357	-	Correction to test procedure for test cases using CELL_FACH state	F	5.1.0	5.2.0	T1-041376
TP-25	TP-040157	358	-	Varying DPCH Power Offset according to data transmission rate	F	5.1.0	5.2.0	T1-041416
TP-25	TP-040157	359	ı	Corrections to default message for RADIO BEARER SETUP message in clause 9.2.1 (HSDPA RF)	F	5.1.0	5.2.0	T1-041418
TP-25	TP-040157	360	-	Test SIB schedule for two S-CCPCH or two PRACH in 34.108	F	5.1.0	5.2.0	T1-041422
TP-25	TP-040157	364	-	Correction to Default Message Content for Radio Bearer Setup Message re: RM Attribute values	F	5.1.0	5.2.0	T1-041433
TP-26	TP-040233	365	-	CR to 34.108 Rel-5:Correction to default value of Qrxlevmin	F	5.2.0	5.3.0	T1-041532
TP-26	TP-040233	366	-	CR to 34.108 Rel-5: Corrections of the values in 6.11.5.4 for LCR TDD	F	5.2.0	5.3.0	T1-041573
TP-26	TP-040233	367	-	Alignment of Prose to TTCN for SCH power level	F	5.2.0	5.3.0	T1-041584
TP-26	TP-040233	368	-	Addition of new HSDPA RAB configurations with UL 64 kbps	F	5.2.0	5.3.0	T1-041651
TP-26	TP-040233	369	-	Correction to initial conditions and references in clause 7.3	F	5.2.0	5.3.0	T1-041654
TP-26	TP-040233	370	-	Introduction of reference radio bearer combination for PS streaming and downlink rate up to 128 kbps	F	5.2.0	5.3.0	T1-041685
TP-26	TP-040233	371	-	Correction of clause 6.1 (Simulated network environment)	F	5.2.0	5.3.0	T1-041686
TP-26	TP-040233	372	-	Correction to generic Call Setup procedure for mobile terminating circuit switched calls	F	5.2.0	5.3.0	T1-041699
TP-26	TP-040233	373	-	CR to 34.108 Rel-5; Corrections to the default RADIO BEARER SETUP message for HSDPA	F	5.2.0	5.3.0	T1-041754
TP-26	TP-040233	374	-	Physical layer multiplexing configuration in case of AMR and two PS RABs		5.2.0	5.3.0	T1-041801
TP-26	TP-040233	375	-	Addition of new HSDPA RAB configurations	F	5.2.0	5.3.0	T1-041802
TP-26	TP-040233	376	-	Introduction of information for tests for Performance requirements for A-GPS.	В	5.2.0	5.3.0	T1-041850
TP-26	TP-040233	377	-	Introduction of UMTS-850 MHz band V	F	5.2.0	5.3.0	T1-041874
TP-26	TP-040233	378	-	CR to TS 34.108 Rel-5; Adding a new test condition for RADIO BEARER RELEASE Procedure (Revision of T1-041716).	F	5.2.0	5.3.0	T1-041933
TP-26	TP-040233	379	-	Update of Reference Radio Bearer for Conversational / speech / UL:5.9 DL:5.9 kbps / CS RAB for DL SF=256	F	5.2.0	5.3.0	T1-041942
TP-26	TP-040233	380	-	CR to 34.108: Correction to the maximum bit rate for HS-PDSCH	F	5.2.0	5.3.0	T1-041943
TP-26	TP-040233	381	-	Alignment of Prose to TTCN for RRC Connection Release (Cell DCH state) and RRC Connection Setup Message (Cell FACH State).	F	5.2.0	5.3.0	T1-041965
TP-27	TP-050032	382	-	Updates from core specification changes	F	5.3.0	5.4.0	T1-050095
TP-27	TP-050032	383	-	Correction to Hand over test procedure in CELL_DCH	F	5.3.0	5.4.0	T1-050350
TP-27	TP-050032	384	-	CR to 34.108: Changes to test frequencies for UMTS 850 Band	В	5.3.0	5.4.0	T1-050380
TP-27	TP-050032	385	-	Correction to default SIB configurations	F	5.3.0	5.4.0	T1-050019
TP-27	TP-050032	386	-	Editorial corrections in HSDPA RAB configurations 6.10.2.4.5.2 and 6.10.2.4.5.4.	D	5.3.0	5.4.0	T1-050052
TP-27	TP-050032	387	-	CR to 34.108 Rel-5: Update to the contents of PHYSICAL CHANNEL RECONFIGURATION message for 1.28 Mcps TDD	F	5.3.0	5.4.0	T1-050064
TP-27	TP-050032	388	-	CR to 34.108 Rel-5: Update to the contents of TRANSPORT CHANNEL RECONFIGURATION message for 1.28 Mcps TDD	F	5.3.0	5.4.0	T1-050065
TP-27	TP-050032	389	-	CR to 34.108 Rel-5: Update to the contents of RRC CONNECTION REQUEST message for TDD	F	5.3.0	5.4.0	T1-050066
TP-27	TP-050032	390	-	Correction to the HSDPA RB Identity in Radio Bearer Setup & Radio Bearer Release message contents	F	5.3.0	5.4.0	T1-050072
TP-27	TP-050032	391	-	CR to TS 34.108 v5.3.0 - Correction to Default RADIO BEARER RELEASE message (FDD)	F	5.3.0	5.4.0	T1-050202
TP-27	TP-050032	392	-	Addition of reference radio bearer configuration for MAC-hs testing	F	5.3.0	5.4.0	T1-050239
TP-27	TP-050032	393	-	CR to 34.108 Rel-5: Update to the contents of RRC CONNECTION REQUEST message for TDD	F	5.3.0	5.4.0	T1-050295
TP-27	TP-050032	394	-	CONNECTION REQUEST message for TDD CR to 34.108 Rel-5: Update to the contents of Default System Information Block Messages for TDD	F	5.3.0	5.4.0	T1-050296
	I	1	1	10 your million and a block incosages for TDD	1	1	1	l

Meetin g-1st- Level	Doc-1st-Level	CR	Rev	Subject	Cat	Version -Current		Doc-2nd- Level
TP-27	TP-050032	395	-	CR to 34.108 Rel-5: Add the contents of SIB 5 & 6 for HCR TDD	F	5.3.0	5.4.0	T1-050297
TP-27	TP-050032	396	-	Correction to TFCS ordering	F	5.3.0	5.4.0	T1-050451r1
TP-27	TP-050032	397	-	Addition of GPS scenario and A-GPS assistance data values for signalling tests to 34.108	F	5.3.0	5.4.0	T1-050458
TP-27	TP-050032	398	-	CR to TS 34.108 Rel-5; Correction to the physical channel parameters (Revison of T1-050176)	F	5.3.0	5.4.0	T1-050469
RP-28	RP-050267	399	-	Additional call setup procedures for inter RAT RRM testing	F	5.4.0	5.5.0	R5-050618
RP-28	RP-050267	400	-	CR to 34.108: Correction to RADIO BEARER SETUP message for BTFD RMC	F	5.4.0	5.5.0	R5-050704
RP-28	RP-050267	401	-	CR to 34.108: Correction to reference radio conditions for GSM	F	5.4.0	5.5.0	R5-050811
RP-28	RP-050267	402	-	Addition of RADIO BEARER SETUP Messages for Auxiliary Measurement	F	5.4.0	5.5.0	R5-050856
RP-28	RP-050267	404	-	CR 34.108 Addition of specific message content to A-GPS performance test procedures in clause 7.5	F	5.4.0	5.5.0	R5-050709
RP-28	RP-050267	405	-	CR to 34.108 Rel-5: Clarification of generic setup procedures in section 7.3.4	F	5.4.0	5.5.0	R5-050663
RP-28	RP-050267	406	-	Removal of TGPL2	F	5.4.0	5.5.0	R5-050513
RP-28	RP-050267	407	-	Addition of compressed mode pattern for Inter Frequency FDD measurement & Inter RAT	F	5.4.0	5.5.0	R5-050525
RP-28	RP-050267	408	-	measurement GSM Correction to MIB, PLMN and Cell Value Tag Value Definition to 34.108	F	5.4.0	5.5.0	R5-050608
RP-28	RP-050267	409	-	CR to 34.108 Rel-5: Corrections to the contents of System Information Block type 11 (3.84 Mcps and 1.28 Mcps TDD) in section 6.1.0b	F	5.4.0	5.5.0	R5-050613
RP-28	RP-050267	410	-	CR to 34.108 Rel-5: Corrections to the usage of 'Cell info' IE in System Information Block type 11 in section 6.1.4 for TDD cell	F	5.4.0	5.5.0	R5-050619
RP-28	RP-050267	411	-	CR to 34.108 Rel-5: Corrections to the contents of System Information Block type 5 (1.28 Mcps TDD)	F	5.4.0	5.5.0	R5-050620
RP-28	RP-050267	412	-	Update to clause 8 Test USIM Parameters	F	5.4.0	5.5.0	R5-050638
RP-28	RP-050267	413	-	CR to 34.108 Rel-5: Update of SIB3, SIB4, SIB11 and SIB12 for TDD in section 6.1.0b	F	5.4.0	5.5.0	R5-050662
RP-28	RP-050267	414	-	CR to 34.108: Correction to TFCS	F	5.4.0	5.5.0	R5-050677
RP-28	RP-050267	415	-	CR to TS34.108 Rel-5; Correction to the physical channel parameter	F	5.4.0	5.5.0	R5-050724
RP-28	RP-050267	416	-	Correction to default SIB configurations	F	5.4.0	5.5.0	R5-050947
RP-28	RP-050267	417	-	CR to 34.108: Missing Rel-5 IE's in the default Radio Bearer Setup message at section 9.1.1.	F	5.4.0	5.5.0	R5-050600
RP-28	RP-050267	418	-	CR to TS34.108 Rel-5; Clarification of the reference TFCS for three RB multiplexing option (condition A9)	F	5.4.0	5.5.0	R5-050913
RP-28	RP-050268	419	-	Addition of new HSDPA Streaming RAB configurations	F	5.4.0	5.5.0	R5-050880
RP-28	RP-050268	420	-	CR to 34.108 Rel-5: Content Correction of RRC CONNECTION SETUP message for LCR TDD in 9.1.2	F	5.4.0	5.5.0	R5-050585
RP-28	RP-050268	421	-	Add Default RADIO BEARER RELEASE message (3.84 Mcps TDD)		5.4.0	5.5.0	R5-050680
RP-28	RP-050268	422	_	Add Default Contents of RADIO BEARER RECONFIGURATION COMPLETE message: AM (3.84 Mcps TDD)	F	5.4.0	5.5.0	R5-050681
RP-28	RP-050268	423	_	Add Default Contents of RADIO BEARER RECONFIGURATION message: AM or UM (3.84 Mcps TDD)	F	5.4.0	5.5.0	R5-050682
RP-28	RP-050268	424	-	Add Default Contents of PHYSICAL CHANNEL RECONFIGURATION message: AM or UM (3.84 Mcps TDD)	F	5.4.0	5.5.0	R5-050683
RP-28	RP-050268	425	-	Add Default Contents of PHYSICAL CHANNEL RECONFIGURATION COMPLETE message: AM (3.84 Mcps TDD)	F	5.4.0	5.5.0	R5-050684
RP-28	RP-050268	426	-	Add Default Contents of TRANSPORT CHANNEL RECONFIGURATION message: AM or UM (3.84 Mcps TDD)	F	5.4.0	5.5.0	R5-050685
RP-28	RP-050268	427	-	Add Default Contents of TRANSPORT CHANNEL RECONFIGURATION COMPLETE message: AM (3.84 Mcps TDD)	F	5.4.0	5.5.0	R5-050686
RP-28	RP-050268	428	-	Add Default Contents of MEASUREMENT REPORT message: AM (intra/inter-frequency measurement (3.84 Mcps TDD)	F	5.4.0	5.5.0	R5-050956
RP-28	RP-050268	430	-	Correction to RADIO BEARER SETUP message for HSDPA RF testing	F	5.4.0	5.5.0	R5-050879

Meetin g-1st- Level	Doc-1st-Level	CR	Rev	Subject	Cat	Version -Current		Doc-2nd- Level
	RP-050349	403	-	Addition of GPS scenario and assistance data for A-GPS performance tests in 34.108	В	5.4.0	5.5.0	R5-050836
RP-28	RP-050350	429	-	Corrections to section 10.7 and GPS data file for 34.108	F	5.4.0	5.5.0	R5-050969
	RP-050600	431	-	34.108	F	5.5.0	6.0.0	R5-051312
	RP-050600	432	-	Feature Clean Up: Removal of SSDT from 34.108	F	5.5.0	6.0.0	R5-051356
	RP-050600	433	-	Feature Clean Up: Removal of 80 ms TTI for DCH for all cases except when the UE supports SF512 from 34.108		5.5.0	6.0.0	R5-051379
	RP-050600	434	-	34.108	С	5.5.0	6.0.0	R5-051543
RP-29	RP-050600	435	-	34.108	С	5.5.0	6.0.0	R5-051544
RP-29	RP-050600	436	-	Feature Clean Up: Removal of CPCH from section 7 & 8 of 34.108	С	5.5.0	6.0.0	R5-051545
RP-29	RP-050600	437	-	Feature Clean Up: Removal of CPCH from section 9 of 34.108	С	5.5.0	6.0.0	R5-051546
RP-29	RP-050600	438	-	Feature Clean Up: Removal of DSCH (FDD mode) from 34.108	F	5.5.0	6.0.0	R5-051548
RP-29	RP-050600	439	-	Modification to PS setup procedure for inter RAT RRM testing	F	5.5.0	6.0.0	R5-051161
RP-29	RP-050600	440	-	CR to 34.108: RRC CONNECTION SETUP exception for HSDPA testing	F	5.5.0	6.0.0	R5-051430
RP-29	RP-050600	441	-	CR to 34.108: Correction to the RADIO BEARER SETUP message for HSDPA testing	F	5.5.0	6.0.0	R5-051112
RP-29	RP-050512	442	-	Changes to GPS Scenarios and Assistance data in TS 34.108	F	5.5.0	6.0.0	R5-051076
RP-29	RP-050514	443	-	CR to 34.108 Rel-5: Correction of contents of RADIO BEARER SETUP message: AM or UM (1.28 Mcps TDD) in 9.2.2	F	5.5.0	6.0.0	R5-051212
RP-29	RP-050514	444	-	CR to 34.108 Rel-5: SIB default schedule in 6.1.0a - Default Master Information Block and Scheduling Block messages	F	5.5.0	6.0.0	R5-051213
RP-29	RP-050514	445	-	CR to 34.108 Rel-5: Corrections to the IE"Midamble shift and burst type" of System Information Block type 5/6 (3.84Mcps TDD) in section 6.1.0b	F	5.5.0	6.0.0	R5-051222
RP-29	RP-050514	446	-	CR to 34.108 Rel-5: Corrections to the contents of System Information Block type 5 (3.84 Mcps TDD) in section 6.1.1	F	5.5.0	6.0.0	R5-051344
RP-29	RP-050514	447	-	CR to 34.108 Rel-5: Corrections to the value of Sintrasearch and Sintersearch in "Cell selection and reselection quality measure" of System Information Block type 3/4 (1.28Mcps TDD and 3.84Mcps TDD) in section 6.1.0b	F	5.5.0	6.0.0	R5-051536
RP-29	RP-050600	448	-		F	5.5.0	6.0.0	R5-051041
RP-29	RP-050600	449	-	Correction to the default contents for Radio Bearer Setup message	F	5.5.0	6.0.0	R5-051044
RP-29	RP-050600	450	-	Corrections to default parameters of UL:384kbps PS Bearer	F	5.5.0	6.0.0	R5-051058
RP-29	RP-050600	451	_	Correction to NB AMR Radio Bearer Configurations	F	5.5.0	6.0.0	R5-051318
	RP-050600	452	-	Correction to default contents of Cell Update and Initial Direct transfer message for Rel-5	F	5.5.0	6.0.0	R5-051325
RP-29	RP-050600	453	-	Correction to DPCCH Power Offset IE in default contents for RRC Connection Setup and Radio Bearer Setup message	F	5.5.0	6.0.0	R5-051365
RP-29	RP-050515	454	-	1 0	В	5.5.0	6.0.0	R5-051553
RP-29	RP-050600	455	-	Correction to default contents of RADIO BEARER SETUP MESSAGE for the IE "Number of Processes"	F	5.5.0	6.0.0	R5-051324
RP-29	RP-050600	456	-	Correction of DL channelisation code in RADIO BEARER SETUP for HSDPA configurations	F	5.5.0	6.0.0	R5-051345
RP-29	RP-050513	457	-	Clarifiation of reference radio bearer configuration for MAC-hs test case 7.1.5.2.	F	5.5.0	6.0.0	R5-051164
RP-29	RP-050600	458	-	Replacement of the technical content of 34.108 Rel-5 by a pointer to Rel-6 document	F	5.5.0	6.0.0	R5-051584
RP-29	RP-050600	459	-	Introduction of HSDPA + Wideband AMR radio bearer combination	F	5.5.0	6.0.0	R5-051588
RP-29	RP-050600	460	-		F	5.5.0	6.0.0	R5-051311
RP-30	RP-050767	461	-	Correction to 34.108: RF Radio Bearer setup message for HSDPA testing	F	6.0.0	6.1.0	R5-052320

Meetin g-1st- Level	Doc-1st-Level	CR	Rev	Subject	Cat	Version -Current		Doc-2nd- Level
RP-30	RP-050720	462	-	Changes, additions and corrections to GPS scenarios and assistance data in TS 34.108	F	6.0.0	6.1.0	R5-052017
RP-30	RP-050716	463	-	Generic test procedure for EDCH RF testing	F	6.0.0	6.1.0	R5-052345
RP-30	RP-050769	464	-	Correction of UE test states for RF testing.	F	6.0.0	6.1.0	R5-052302
RP-30	RP-050769	465	-	Removal of temporary BLER measurement configuration	F	6.0.0	6.1.0	R5-051933
RP-30	RP-050780	466	-	Introduction of UMTS1700 for TS34.108	В	6.0.0	6.1.0	R5-052329
RP-30	RP-050767	467	_	Re-definition of reference radio bearer configuration for MAC-hs test case 7.1.5.2	F	6.0.0	6.1.0	R5-051857
RP-30	RP-050767	468	-	Introduction of additional HSDPA radio bearer combination	F	6.0.0	6.1.0	R5-052159
RP-30	RP-050717	469	-	CR to 34.108; Correction to default message content in INITIAL DIRECT TRANSFER	F	6.0.0	6.1.0	R5-052179
RP-30	RP-050716	470	-	CR to 34.108 Rel-6; Generic Setup Procedure and Default RRC Messages for Enhanced Uplink Tests	F	6.0.0	6.1.0	R5-052192
RP-30	RP-050716	471	-	Generic reference bearer radio configurations for E- DCH testing	F	6.0.0	6.1.0	R5-052167
RP-30	RP-050716	472	-	Addition of basic radio bearer combinations for E-DCH testing	F	6.0.0	6.1.0	R5-052144
RP-30	RP-050718	473	-	CR to TS34.108; Correction to the default system information block type3 for DSAC	F	6.0.0	6.1.0	R5-052145
RP-30	RP-050769	474	-	Editorial corrections to TS 34.108	D	6.0.0	6.1.0	R5-051840
RP-30	RP-050769	475	-	Removal of deprecated values from the default contents for RRC Connection Setup (Cell FACH) and RRC Connection Release (Cell DCH) messages.		6.0.0	6.1.0	R5-051848
RP-30	RP-050769	476	ı	Correction to the default RRC message contents for the IE "UARFCN uplink (Nu)"	F	6.0.0	6.1.0	R5-052155
RP-30	RP-050769	477	-	Correction of references to IB UL:8 DL:8 kbps transport channel parameters in reference radio bearer configuration 6.10.2.4.1.58a	F	6.0.0	6.1.0	R5-051858
RP-30	RP-050769	478	-	Correction of UE states tables for Generic setup procedures.	F	6.0.0	6.1.0	R5-051942
RP-30	RP-050769	479	-	Corrections to default message contents of 'HANDOVER FROM UTRAN COMMAND-GSM' message.	F	6.0.0	6.1.0	R5-051955
RP-30	RP-050776	480	-	Addition of multi-rate AMR-NB configuration with SRB#5	F	6.0.0	6.1.0	R5-052176
RP-30	RP-050769	481	-	Proposed CR to 34.108 [R6 version, R99 affected] to change slot format for AMR 5.9 mono rate RAB	F	6.0.0	6.1.0	R5-052055
RP-30	RP-050769	482	-	Correction to puncturing limit in radio bearer configuration 6.10.2.4.1.38a	F	6.0.0	6.1.0	R5-052096
RP-30	RP-050777	483	-	Introduction of third RAB sublfow to WB-AMR test configurations	F	6.0.0	6.1.0	R5-052140
RP-30	RP-050833	484	-	Correction to RADIO BEARER SETUP message for HSDPA RF testing	F	6.0.0	6.1.0	-
RP-30	RP-050832	485	-	Correction to test procedure for HSDPA RF testing	F	6.0.0	6.1.0	-
				2006-01: Editorial conversion to make file compatible with Word 2000.		6.1.0	6.1.1	
RP-31	RP-060154	486	-	Corrections to GPS data files for signalling tests.	F	6.1.1	6.2.0	R5-060522
RP-31	RP-060163	487	-	Corrections for reference RABs Corrections to the RADIO BEARER SETUP message	F F	6.1.1	6.2.0	R5-060273
RP-31 RP-31	RP-060144 RP-060150	488 489	-	for Enhanced uplink Correction to default message content in INITIAL	F	6.1.1	6.2.0 6.2.0	R5-060335 R5-060396
NF-31	175-000190	409	-	DIRECT TRANSFER		0.1.0	0.2.0	179-000390
RP-31	RP-060154	490		Corrections to default message contents for signaling	F	6.1.1	6.2.0	R5-060274
RP-31	RP-060163	491	-	Update of RB configuration 6.10.2.4.1.4b to increase test coverage for multi-mode AMR configurations	F	6.1.1	6.2.0	R5-060122
RP-31	RP-060144	492		Correction of UE RRC states table for common procedures (section 7.4.1)	F	6.1.1	6.2.0	R5-060268
RP-31	RP-060154	493	-	Correction to DPCCH power offset value in RADIO BEARER SETUP messages	F	6.1.1	6.2.0	R5-060459
RP-31	RP-060153	494	-	Introduction of Band VII and Band VIII to TS34.108 Chapter 5 and introduction of new UARFCN scheme	F	6.1.1	6.2.0	R5-060440
RP-31	RP-060154	495		Clarification of RB Test Mode State for RF testing	F	6.1.1	6.2.0	R5-060446
RP-31	RP-060144	496	-	Common message content for E-DCH RF testing	F	6.1.1	6.2.0	R5-060439
RP-31	RP-060144	497	<u> - </u>	Generic test procedure for E-DCH RF testing	F	6.1.1	6.2.0	R5-060438
RP-31	RP-060166	498	-	Correction to GPS Assistance Data for Performance	F	6.1.1	6.2.0	R5-060007
RP-31	RP-060154	499	<u> </u>	tests Corrections to default message contents for RF	F	6.1.1	6.2.0	P5_060257
RP-31	RP-060154	500	<u> </u>	Adding of RB Configuration 6.11.4b to clause 6.11 to	F	6.1.1	6.2.0	R5-060257 R5-060571
31	555156			increase test coverage for Interactive or background PS RAB UL 0kbps/DL 0kbps.		J	5.2.0	

Meetin g-1st- Level	Doc-1st-Level	CR	Rev	Subject	Cat	Version -Current		Doc-2nd- Level
	RP-060331	501	-	Addition of release information to A-GPS MEASUREMENT CONTROL message IEs	F	6.2.0	6.3.0	R5-061454
RP-32	RP-060331	502	-	Change to altitude of simulated UE position	F	6.2.0	6.3.0	R5-061410
	RP-060331	503	-	Clarification of A-GPS simulated satellites	F	6.2.0	6.3.0	R5-061223
	RP-060337	504	-	Clarification to loopback on HSDPA call set up procedure	F	6.2.0	6.3.0	R5-061046
	RP-060337	505	-	Removal of alternative procedure for HSDPA RF testing	F	6.2.0	6.3.0	R5-061212
RP-32	RP-060337	506	-	Removal of alternative RB Setup message for HSDPA RF testing	F	6.2.0	6.3.0	R5-061213
RP-32	RP-060338	507	-	CR for 34.108:Addition of RADIO BEARER SETUP default message contents for LCR TDD HSDPA RF testing	F	6.2.0	6.3.0	R5-061438
RP-32	RP-060332	508	-	Correction to RB setup message for E-DCH	F	6.2.0	6.3.0	R5-061443
RP-32	RP-060334	509	-	CR to 34.108: Addition of band IV to test frequencies for UMTS 1.7/2.1 GHz		6.2.0	6.3.0	R5-061188
RP-32	RP-060 336	510	-	Addition of radio bearer setup and release for HCR HSDPA testing to 34.108	F	6.2.0	6.3.0	R5-061148
RP-32	RP-060337	511	-	HS-SCCH and HS-PDSCH power levels in signaling tests	F	6.2.0	6.3.0	R5-061207
RP-32	RP-060338	512	-	CR for 34.108:Addition of the combinations on DPCH and HS-PDSCH for LCR TDD	F	6.2.0	6.3.0	R5-061310
RP-32	RP-060338	513	-	CR for 34.108:Correction of RADIO BEARER SETUP default message contents for LCR TDD HSDPA	F	6.2.0	6.3.0	R5-061053
RP-32	RP-060338	514	-	CR for 34.108:Correction of RADIO BEARER RELEASE default message contents for LCR TDD HSDPA	F	6.2.0	6.3.0	R5-061054
RP-32	RP-060332	515	-	Corrections to the default RADIO BEARER SETUP message for Enhanced uplink	F	6.2.0	6.3.0	R5-061314
RP-32	RP-060332	516	-	Generalize E-DCH radio bearer names and correction to section numbering for 6.10.2.4.6.3.2.1.1.2.	F	6.2.0	6.3.0	R5-061315
RP-32	RP-060332	517	-	Addition of conversational radio bearer combinations for E-DCH/HS-DSCH testing	F	6.2.0	6.3.0	R5-061266
RP-32	RP-060332	518	-	E-HICH/E-RGCH and E-AGCH codes used in Radio Bearer Setup for signaling	F	6.2.0	6.3.0	R5-061386
RP-32	RP-060332	519	-	Introduction of additional WB-AMR RAB combination for E-DCH/HS-DSCH testing	F	6.2.0	6.3.0	R5-061339
RP-32	RP-060336	520	-	Addition of combinations on DPCH and HS-DSCH for HCR to 34.108	F	6.2.0	6.3.0	R5-061149
RP-32	RP-060322	521	-	Corrections to the values for IE based on calculated ASN.1 value to 34.108 clause 9	F	6.2.0	6.3.0	R5-061369
RP-32	RP-060328	522	-		F	6.2.0	6.3.0	R5-061392
RP-32	RP-060322	523	-	Correction to specific message contents for UE Capability Information confirm message	F	6.2.0	6.3.0	R5-061139
RP-32	RP-060322	524	-	Corrections to the values for IE based on calculated ASN.1 value to 34.108 clause 6	F	6.2.0	6.3.0	R5-061281
RP-32	RP-060322	525	-	Addition of a new section for downlink physical channels code allocation for signalling in FDD	F	6.2.0	6.3.0	R5-061385
RP-33	RP-060560	526	-	Editorial changes in 34.108	F	6.3.0	6.4.0	R5-062092
RP-33	RP-060549	527	-	CR to 34.108: Correction of reference test frequencies for UMTS800 (Band VI)	F	6.3.0	6.4.0	R5-062440
RP-33	RP-060549	528	-	Correction to SIB11 in 6.1	F	6.3.0	6.4.0	R5-062427
RP-33	RP-060549	529	-	Correction to SECURITY MODE COMMAND message in 9.2.1	F	6.3.0	6.4.0	R5-062403
RP-33	RP-060562	530	-	Correction to RB Setup default message for E-DCH RF testing	F	6.3.0	6.4.0	R5-062208
RP-33	RP-060568	531	-	CR to 34.108: Correction the contents of RADIO BEARER SETUP message: AM or UM (1.28 Mcps TDD)	F	6.3.0	6.4.0	R5-062511
RP-33	RP-060566	532	-	Addition of HSDPA cases to radio bearer setup and radio bearer release in section 9.1.2	F	6.3.0	6.4.0	R5-062253
RP-33	RP-060567	533	-	Corrections to the default PHYSICAL CHANNEL RECONFIGURATION message	F	6.3.0	6.4.0	R5-062291
RP-33	RP-060567	534	-		F	6.3.0	6.4.0	R5-062544
RP-33	RP-060562	535	-	Corrections to the default RADIO BEARER SETUP message	F	6.3.0	6.4.0	R5-062320
RP-33	RP-060562	536	-	New Test RABS for MAC-E/Es test cases	F	6.3.0	6.4.0	R5-062328
RP-33	RP-060562	537	-	Correction to radio bearer configuration 6.10.2.4.6 and 6.10.2.4.8	F	6.3.0	6.4.0	R5-062199
RP-33	RP-060562	538	-	Correction to 34.108 Section 9.1 : Corrections to Radio Bearer Setup for A12	F	6.3.0	6.4.0	R5-062348

Meetin g-1st- Level	Doc-1st-Level	CR	Rev	Subject	Cat	Version -Current		Doc-2nd- Level
RP-33	RP-060549	539	-	Clarification to section 6.10 and 6.11	F	6.3.0	6.4.0	R5-062194
RP-33	RP-060549	540	-	Correction to 34.108 Section 6.1 : Inclusion of System Information Block Type 5bis	F	6.3.0	6.4.0	R5-062398
RP-33	RP-060549	541		Corrections to maximum data rate for combinations on PRACH (FDD)	F	6.3.0	6.4.0	R5-062350
RP-34	RP-060739	542		Assistance Data change for A-GPS Minimum Performance Test	F	6.4.0	6.5.0	R5-063400
RP-34	RP-060731	543	-	Correction to SECURITY MODE COMMAND message in 9.2.2	F		6.5.0	R5-063296
RP-34	RP-060735	544	-	Addition of PAGING TYPE 2 message in 9.2	F	6.4.0	6.5.0	R5-063401
RP-34	RP-060731	545	-	Correction to RADIO BEARER SETUP message in 9.2	F	6.4.0	6.5.0	R5-063402
	RP-060743	546	-	Correction to the set of Reference E-TFCIs in RB Setup default message (RF)	F	6.4.0	6.5.0	R5-063233
RP-34	RP-060731	547	-	Correction the Default System Information Block type6 Messages in 6.1.0b	F	6.4.0	6.5.0	R5-063294
RP-34	RP-060743	548	-	CR to 34.108, correction of RADIO BEARER SETUP for EDCH		6.4.0	6.5.0	R5-063545
RP-34	RP-060743	549	-	Correction to the set of Reference E-TFCIs in RB Setup default message (SIG)	F	6.4.0	6.5.0	R5-063240
RP-34	RP-060750	550		Introduction of radio bearers for MTCH	F	6.4.0	6.5.0	R5-063543
RP-34	RP-060749	551	-	Introduction of FDD interband testing in TS 34.108	FL	6.4.0	6.5.0	R5-063255
	RP-060735	552	-	Correction to Radio Bearer Setup message –Mac-hs reset indicator	F	6.4.0	6.5.0	R5-063339
	RP-060731	553	-	CR to 34.108, Add MCC value for Band VI test	F	6.4.0	6.5.0	R5-063340
RP-34	RP-060731	554	-	CR to 34.108, Modify MCC value in IMSI of test USIM for Band VI test		6.4.0	6.5.0	R5-063341
RP-34	RP-060731	555	-	Correction to default content for System Information Block Type 7	F	6.4.0	6.5.0	R5-063079
	RP-060731	556	-	Clarification of FDD test channels used for signaling test cases		6.4.0	6.5.0	R5-063260
RP-35	RP-070111	557		34.108 v6.6.0 pointer to Release 7 version	F	6.5.0	7.0.0	R5-070338
RP-35	RP-070105	558		Correction of IE "DL UM RLC LI size" in RF default messages for HSDPA	F	6.5.0	7.0.0	R5-070548
RP-35	RP-070096	559		Signalled Reference E-TFCIs for E-DCH RF tests	F	6.5.0	7.0.0	R5-070113
RP-35	RP-070096	560		Correction to RB setup message used for E-DCH tests	F	6.5.0	7.0.0	R5-070221
RP-35	RP-070096	561		Correction of IE "DL UM RLC LI size" in RF default messages for E-DCH	F	6.5.0	7.0.0	R5-070549
RP-35	RP-070090	562		Generic test procedure for MBMS RF test case	F	6.5.0	7.0.0	R5-070553
	RP-070094	563		Introduction of FDD Mode Test frequencies for Operating Band X (Extended 1.7/2.1 GHz)	F	6.5.0	7.0.0	R5-070160
	RP-070094	564		Introduction of FDD Band X (Extended 1.7/2.1 GHz) to Contents of System Information Block type 5bis	F	6.5.0	7.0.0	R5-070161
	RP-070104	565		5 (1.28 Mcps TDD)	F	6.5.0	7.0.0	R5-070109
	RP-070104	566		message to Cell_FACH state	F	6.5.0	7.0.0	R5-070353
RP-35	RP-070096	567		Corrections to 34.108 Radio Bearer Setup Message: AM or UM	F	6.5.0	7.0.0	R5-070038
RP-35	RP-070096	568		Introduction of radio bearers for Stand-alone SRBs for DCCH on E-DCH and HS-DSCH	F	6.5.0	7.0.0	R5-070356
RP-35	RP-070096	569		Introduction of RRC Connection setup message for Stand-alone SRBs for DCCH on E-DCH and HS-DSCH	F	6.5.0	7.0.0	R5-070357
RP-35 RP-35	RP-070086 RP-070086	570 571		MBMS test - MCCH configurations Generic setup procedures and default values for MBMS signalling testing	F F	6.5.0 6.5.0	7.0.0 7.0.0	R5-070429 R5-070422
RP-35	RP-070086	572		Introduction of signalling radio bearer for MCCH	F	6.5.0	7.0.0	R5-070147
RP-36	RP-070360	573		Definition of MCCH default message content	F	7.0.0	7.1.0	R5-071469
RP-36	RP-070354	574		Addition of Additional Dynamic Transport Format Information for CCCH and Additional RACH TFCS for CCCH in SIB5	F	7.0.0	7.1.0	R5-071536
RP-36	RP-070354	575		Remove MCC codes 440/441 for Band VI test	F	7.0.0	7.1.0	R5-071036
RP-36	RP-070350	576		Modify the Physical channel parameters for HS- DSCH for 1.28 Mcps TDD.	F	7.0.0	7.1.0	R5-071119
RP-36	RP-070357	577		Modification to RB setup message used for E-DCH test cases	F	7.0.0	7.1.0	R5-071126
RP-36	RP-070357	578		Correction to RB setup message used for E-DCH RF test cases	F	7.0.0	7.1.0	R5-071127
RP-36	RP-070364	579		Addition of 7.68 Mcps TDD TX diversity modes to 34.108 (section 6.7)	F	7.0.0	7.1.0	R5-071270
RP-36	RP-070364	580		Addition of default message contents for RF tests (7.68Mcps TDD)	F	7.0.0	7.1.0	R5-071277

Meetin g-1st- Level	Doc-1st-Level	CR	Rev	Subject	Cat	Version -Current		Doc-2nd- Level
RP-36	RP-070364	581		Addition of default message contents for signalling tests (7.68Mcps TDD)	F	7.0.0	7.1.0	R5-071278
RP-36	RP-070364	582		Addition of default system information for 7,68 Mcps TDD to 34.108	F	7.0.0	7.1.0	R5-071279
RP-36	RP-070364	583		Addition of default system information for 7,68Mcps TDD to 34.108 for SCCPCH configuration with Stand- alone SRB	F	7.0.0	7.1.0	R5-071280
RP-36	RP-070364	584		Addition of Reference Radio Bearer configurations used in Radio Bearer testing for 7.68 Mcps TDD	F	7.0.0	7.1.0	R5-071284
RP-36	RP-070364	585		Addition Standard TDD reference test frequencies (7.68 Mcps option) to 34.108	F	7.0.0	7.1.0	R5-071287
RP-36	RP-070363	586		Introduction of the generic test procedure for MBMS RF/RRM test cases	F	7.0.0	7.1.0	R5-071378
	RP-070350	587		Adding Radio Bearer Configurations for LCR TDD HSDPA	F	7.0.0	7.1.0	R5-071423
RP-36	RP-070344	588		Clarification of two default values for IE Scrambling code change	F	7.0.0	7.1.0	R5-071435
RP-36	RP-070356	589		Editorial corrections in the reference list	F	7.0.0	7.1.0	R5-071443
RP-36	RP-070344	590		Correction to the list of RAB combinations on DPCH and HS-PDSCH	F	7.0.0	7.1.0	R5-071448
RP-36	RP-070360	591		Introduce SIB scheduling and contents for MBMS test	F	7.0.0	7.1.0	R5-071458
RP-36	RP-070360	592		Update to generic setup procedures and default values for MBMS signalling testing	F	7.0.0	7.1.0	R5-071459
RP-36	RP-070360	593		Clarification of MBMS test case default behaviour	F	7.0.0	7.1.0	R5-071460
RP-36	RP-070360	594		Downlink physical channels code allocation for MBMS test	F	7.0.0	7.1.0	R5-071487
RP-36	RP-070354	595		Changes to inclusion of Start Value in Cell Update Message from Rel-6	F	7.0.0	7.1.0	R5-071490
RP-36	RP-070354	596		Addition of Additional Transport Format and TFCS for CCCH on RACH	F	7.0.0	7.1.0	R5-071529
RP-37	RP-070600	597	-	UE performance requirements for high speed train	F	7.1.0	7.2.0	R5-072280
RP-37	RP-070596	598	-	CR to 34.108: New Requirements for Fast L1 Synchronization	F	7.1.0	7.2.0	R5-072368
RP-37	RP-070609	600	-	Addition of MTCH and MCCH to combinations on SCCPCH for 3.84 Mcps TDD	F	7.1.0	7.2.0	R5-072296
RP-37	RP-070609	601	-	Addition of MTCH and MCCH to combinations on SCCPCH for 7.68 Mcps TDD	F	7.1.0	7.2.0	R5-072297
RP-37	RP-070604	602	-	Corrections of Test Procedures for MBMS Testing (IGMP and MLD)	F	7.1.0	7.2.0	R5-072066
RP-37	RP-070604	603	-	Addition of RB combinations for PTP MBMS Testing	F	7.1.0	7.2.0	R5-072067
RP-37	RP-070604	604	-	Correction to default MBMS MCCH messages in 34.108	F	7.1.0	7.2.0	R5-072166
RP-37	RP-070596	605	-	Correction to SIB5 contents for additional RACH TFCS for CCCH	F	7.1.0	7.2.0	R5-072186
RP-37	RP-070596	606	-	Correction to default RB combinations on PRACH for additional RACH TFCS for CCCH	F	7.1.0	7.2.0	R5-072187
RP-37	RP-070608	607	-	SIB5 configuration for MBMS RF/RRM generic procedure	F	7.1.0	7.2.0	R5-072379
RP-37	RP-070604	608	-	Default message content for MBMS NEIGHBOURING CELL P-T-M RB INFORMATION	F	7.1.0	7.2.0	R5-072468
RP-37	RP-070604	609	-	Addition of PTP RB for MBMS	F	7.1.0	7.2.0	R5-072521
RP-37	RP-070604	610	-	Addition of new SIB5 configuration to have MCCH mapped on to an S-CCPCH also used for non-MBMS purposes	F	7.1.0	7.2.0	R5-072469
RP-37 RP-37	RP-070593 RP-070611	611 612	-	Addition of RB combination for RoHCTesting Introduce SIB scheduling and contents for LCR TDD	F F	7.1.0 7.1.0	7.2.0 7.2.0	R5-072520 R5-072534
RP-37	RP-070611	613		MBMS test Introduction of radio bearers of MTCH for LCR TDD	F	7.1.0	7.2.0	R5-072535
RP-37	RP-070604	614	-	MBMS test Addition of MBMS PTP RB Setup message contents	F	7.1.0	7.2.0	R5-072496
RP-37	RP-070601	615	-	Introduction of F-DPCH Support Indicator	F	7.1.0	7.2.0	R5-072568
RP-37	RP-070612	616	-	Correction of HS-PDSCH for 64QAM Enhancement	F	7.1.0	7.2.0	R5-072559
	RP-070613	617	-	Correction of HS-PDSCH for MIMO Enhancement	F	7.1.0	7.2.0	R5-072560
RP-37	RP-070614	618	-	Correction of Maximum Data Rate for E-DPDCH	F	7.1.0	7.2.0	R5-072561
RP-37	RP-070609	620	-	Addition of message contents required for 3.84Mcps and 7.68Mcps TDD to the default messages contents for signalling	F	7.1.0	7.2.0	R5-072295
RP-37	RP-070600	619		Production of 34.108 Rel-7 pointer version to point to Rel-8 of the spec	F	7.1.0	7.2.0	R5-072590
RP-37	RP-070599	599	-	Introduction of FDD Mode Test frequencies for	F	7.1.0	8.0.0	R5-072273

Page 18	Meetin g-1st-	Doc-1st-Level	CR	Rev	Subject	Cat	Version -Current		Doc-2nd- Level
RP-36 RP-070869 622 Correction to DL RLC PDU size in 9.2 for RB setup and F 8.0.0 8.1.0 R 5-073203 RP-38 RP-070858 623 Correction to DL RLC PDU size in 9.1 for RB setup and F 8.0.0 8.1.0 R 5-073204 RP-38 RP-070853 624 Addition of the site frequencies for low and high ranges for F 8.0.0 8.1.0 R 5-073304 RP-38 RP-070877 626 Londing of the site frequencies for low and high ranges for F 8.0.0 8.1.0 R 5-073300 RP-38 RP-070877 626 Londing of the site frequencies for low and high ranges for F 8.0.0 8.1.0 R 5-073300 RP-38 RP-070877 627 Addition of specific message content for MBMS RF/RRM F 8.0.0 8.1.0 R 5-073302 RP-38 RP-0708767 628 Addition of specific message content for MBMS RF/RRM F 8.0.0 8.1.0 R 5-073302 RP-38 RP-0708767 630 Dudate of prediction message contents for signaling F 8.0.0 8.1.0 R 5-073402 RP-38 RP-070887 631	Level								
RRC connection setup						F			
RP-36 RP-070853 624 Addition of these if to RRC connection setup message F 8.0.0 8.1.0 R5-073391					RRC connection setup	-			
RP-30 RP-070858 625 Addition of test frequencies for low and high ranges for F F 8.0.0 8.1.0 R5-073311 RP-38 RP-070877 626 Update of generic setup procedure for MBMS RF/RRM F 8.0.0 8.1.0 R5-073300 RP-38 RP-070876 627 Addition of specific message content for MBMS F 8.0.0 8.1.0 R.0.0 8.0.0<	RP-38	RP-070858	623		RRC connection setup	F	8.0.0	8.1.0	R5-073204
RP-38 RP-070877 026 Update of generic setup procedure for MBMS RF/RRM F 8.0.0 8.1.0 R5-073300						•			
Reside Re-070877 627 Addition of specific message content for MBMS F 8.0.0 8.1.0 R5-073342	RP-38	RP-070858	625			F	8.0.0	8.1.0	R5-073311
RP-36 RP-070877 627 Addition of specific message content for MBMS F 8.0.0 8.1.0 R5-073342 RP-38 RP-070886 628 Addition of combinations on HS-PDSCH and E-PUCH F 8.0.0 8.1.0 R5-073227 RP-38 RP-070879 629 Addition of message contents for signalling F 8.0.0 8.1.0 R5-073089 RP-38 RP-070887 630 Update of the default message contents for signalling F 8.0.0 8.1.0 R5-073436 RP-38 RP-070887 631 Update of fadio bearer configuration for Enhanced Layer 2 Leyer 2 RF-38 RP-070877 632 Introduction of new RB configuration to be used by F 8.0.0 8.1.0 R5-073402 RP-38 RP-070871 633 Correction to new RB configuration to be used by F 8.0.0 8.1.0 R5-073449 RP-38 RP-070871 633 Correction to the SIBs when MCCH mapped on to an S-073449 F 8.0.0 8.1.0 R5-073449 RP-38 RP-070871 636 Correction to the SIBs when MCCH mapp	RP-38	RP-070877	626			F	8.0.0	8.1.0	R5-073300
RP-38 RP-070886 628 Addition of combinations on HS-PDSCH and E-PUCH F 8.0.0 8.1.0 R5-073227 RP-38 RP-070879 629 Addition of message contents required for 1.28ktps F 8.0.0 8.1.0 R5-073089 RP-38 RP-070887 630 Update of the default message contents for signalling F 8.0.0 8.1.0 R5-073436 RP-38 RP-070887 631 Update of radio bearer configuration for Enhanced F 8.0.0 8.1.0 R5-073402 RP-38 RP-070871 632 Introduction of new RB configuration to be used by F 8.0.0 8.1.0 R5-073402 RP-38 RP-070871 633 Correction of new RB configuration to be used by F 8.0.0 8.1.0 R5-073449 RP-38 RP-070871 633 Correction to the SiBS when MCCH mapped on to an S-F 8.0.0 8.1.0 R5-073449 RP-38 RP-070871 636 Correction to the SiBS when MCCH mapped on to an S-F 8.0.0 8.1.0 R5-073455 RP-38 RP-070871 636	RP-38	RP-070877	627		Addition of specific message content for MBMS	F	8.0.0	8.1.0	R5-073342
RP-37 88 P-970879 629 E29 Addition of message contents required for 1.28Mcps F 8.0.0 8.1.0 R5-073089 RP-38 RP-970887 630 Update of the default RADIO BEARER SETUP message to support enhanced data rates F 8.0.0 8.1.0 R5-073436 RP-38 RP-970887 631 Update of radio bearer configuration for Enhanced F 8.0.0 8.1.0 R5-073402 RP-38 RP-970871 632 Introduction of new RB configuration to be used by for MBMS professor F 8.0.0 8.1.0 R5-073403 RP-38 RP-970871 633 Correction conditions table for RADIO BEARER SETUP for MBMS professor F 8.0.0 8.1.0 R6-073449 RP-38 RP-070871 634 Update of generic setup procedure for MBMS protocol F 8.0.0 8.1.0 R6-073446 RP-38 RP-070871 636 Correction to the SIB5 when MCCH mapped on to an S-F 8.0.0 8.1.0 R6-073455 RP-38 RP-070858 637 Addition of MBMS Apcesific message content and addition of MBMS Apcesition for MBMS process Information F 8.0.0 8.1.0 R6-073455 RP-38 RP-070858 639	RP-38	RP-070886	628		Addition of combinations on HS-PDSCH and E-PUCH	F	8.0.0	8.1.0	R5-073227
RP-36 RP-070887 630 Update of the default RADIO BEARER SETUP F 8.0.0 8.1.0 R5-073436 RP-38 RP-070887 631 Update of radio bearer configuration for Enhanced F 8.0.0 8.1.0 R5-073402 RP-38 RP-070871 632 Introduction of new RB configuration to be used by MAC-e-bit sets cases R-38 RP-070871 633 Correction conditions table for RADIO BEARER SETUP F 8.0.0 8.1.0 R5-073449 RP-38 RP-070871 634 Update of generic setup procedure for MBMS protocol F 8.0.0 8.1.0 R5-073446 RP-38 RP-070871 635 Correction to the SIBS when MCCH mapped on to an S-F 8.0.0 8.1.0 R5-073456 CCPCH also used for non-MBMS purposes RP-38 RP-070871 636 Correction to MBMS Specific message content and addition of MBMS ACCESS INFORMATION 8.0.0 8.1.0 8.5-073458 RP-38 RP-070858 637 Addition of MBMS ACCESS INFORMATION F 8.0.0 8.1.0 8.5-073452 RP-38 RP-070858 638 Correction to	RP-38	RP-070879	629		Addition of message contents required for 1.28Mcps	F	8.0.0	8.1.0	R5-073089
RP-38 RP-070887 631 Update of radio bearer configuration for Enhanced F 8.0.0 8.1.0 R5-073402 RP-38 RP-070887 632 Introduction of new RB configuration to be used by MAC-best best cases F 8.0.0 8.1.0 R5-073403 RP-38 RP-070871 633 Correction conditions table for RADIO BEARER SETUP F 8.0.0 8.1.0 R5-073449 RP-38 RP-070871 634 Update of generic setup procedure for MBMS protocol F 8.0.0 8.1.0 R5-073446 RP-38 RP-070871 635 Correction to the SIB5 when MCCH mapped on to an S- COPCH also used for non-MBMS purposes R5-073456 635 Correction to MBMS specific message content and addition of MBMS ACCESS INPORNATION R5-073454 88-0.0 8.1.0 R5-073456 RP-38 RP-070858 637 Addition of general St requirements for UL and DL RF F 8.0.0 8.1.0 R5-073454 RP-38 RP-070858 638 Correction to SIB1 F 8.0.0 8.1.0 R5-073458 RP-38 RP-070858 639 Editionial movi	RP-38	RP-070887	630		Update of the default RADIO BEARER SETUP	F	8.0.0	8.1.0	R5-073436
RP-38 RP-070887 632 Introduction of new RB configuration to be used by MAC-ehs test cases F 8.0.0 8.1.0 R5-073403 RP-38 RP-070871 633 Correction conditions table for RADIO BEARER SETUP F 8.0.0 8.1.0 R5-073449 RP-38 RP-070871 634 Update of generic setup procedure for MBMS protocol testing F 8.0.0 8.1.0 R5-073446 RP-38 RP-070871 635 Correction to the SIB5 when MCCH mapped on to an S-CCPCH also used for non-MBMS purposes 636 Correction to MBMS absociate message content and addition of MBMS ACCESS INFORMATION F 8.0.0 8.1.0 R5-073456 RP-38 RP-070858 637 Addition of MBMS ACCESS INFORMATION F 8.0.0 8.1.0 R5-073454 RP-38 RP-070858 638 Correction to SIB1 F 8.0.0 8.1.0 R5-073425 RP-38 RP-070858 639 Editionial moving the word "Default1" or "Default2" in the correct column F 8.0.0 8.1.0 R5-073425 RP-39 RP-080099 6641 Correction to RRC Connection setup a	RP-38	RP-070887	631		Update of radio bearer configuration for Enhanced	F	8.0.0	8.1.0	R5-073402
RP-38 RP-070871 633 Correction conditions table for RADIO BEARER SETUP F 8.0.0 8.1.0 R5-073449 RP-38 RP-070871 634 Update of generic setup procedure for MBMS protocol F 8.0.0 8.1.0 R5-073446 RP-38 RP-070871 635 Correction to the SIB5 when MCCH mapped on to an S-CCPCH also used for non-MBMS purposes R8-070871 636 Correction to SIBMS specific message content and addition of MBMS ACCESS INFORMATION F 8.0.0 8.1.0 R5-073454 RP-38 RP-070858 637 Addition of MBMS ACCESS INFORMATION F 8.0.0 8.1.0 R5-073454 RP-38 RP-070858 639 Editorial moving the word "Default1" or "Default2" in the F 8.0.0 8.1.0 R5-073418 RP-38 RP-070858 639 Editorial moving the word "Default1" or "Default2" in the F 8.0.0 8.1.0 R5-073425 RP-38 RP-070858 639 Editorial moving the word "Default1" or "Default2" in the F 8.0.0 8.1.0 8.1.0 R5-073425 RP-38 RP-080095 6641 Crorrection to RFC Connection setu	RP-38	RP-070887	632		Introduction of new RB configuration to be used by	F	8.0.0	8.1.0	R5-073403
RP-38 RP-070871 634 Update of generic setup procedure for MBMS protocol F 8.0.0 8.1.0 R5-073446 RP-38 RP-070871 635 Correction to the SIBS when MCCH mapped on to an S-CCPCH also used for non-MBMS purposes F 8.0.0 8.1.0 R5-073465 RP-38 RP-070871 636 Corrections to MBMS specific message content and addition of MBMS ACCESS INFORMATION F 8.0.0 8.1.0 R5-073454 RP-38 RP-070858 637 Addition of general SS requirements for UL and DL RF F 8.0.0 8.1.0 R5-073269 RP-38 RP-070858 638 Correction to SIB1 F 8.0.0 8.1.0 R5-073418 RP-38 RP-070858 639 Editorial moving the word "Default1" or "Default2" in the correct column F 8.0.0 8.1.0 R5-073425 RP-38 RP-070858 640 CR wrongly indicated to be to 34.108 and hence not implemented message cortect column F 8.0.0 8.1.0 R5-073425 RP-39 RP-080103 0642 Addition of Central message contents for MBMS F 8.1.0	RP-38	RP-070871	633		Correction conditions table for RADIO BEARER SETUP	F	8.0.0	8.1.0	R5-073449
RP-38 RP-070871 635 Correction to the SIBS when MCCH mapped on to an S- E CCPCH also used for non-MBMS purposes 8.0.0 8.1.0 R5-073465 RP-38 RP-070871 636 Corrections to MBMS specific message content and addition of MBMS ACCESS INFORMATION F 8.0.0 8.1.0 R5-073454 RP-38 RP-070858 637 Addition of general SS requirements for UL and DL RF signal levels F 8.0.0 8.1.0 R5-073454 RP-38 RP-070858 638 Correction to SIB1 F 8.0.0 8.1.0 R5-073418 RP-38 RP-070858 639 Editorial moving the word "Default1" or "Default2" in the correct column 60 60 8.1.0 R5-073425 RP-38 RP-070858 640 CR wrongly indicated to be to 34.108 and hence not implemented. F 8.0.0 8.1.0 R5-073425 RP-39 RP-080103 0641 Correction to RRC Connection setup and RB setup message for 64kbps(Channel2) F 8.1.0 8.2.0 R5-080447 RP-39 RP-080103 0642 Addition of default message contents for MBMS RF/RRM testing F 8.1.	RP-38	RP-070871	634		Update of generic setup procedure for MBMS protocol	F	8.0.0	8.1.0	R5-073446
RP-38 RP-070871 636 Corrections to MBMS specific message content and F 8.0.0 8.1.0 R5-073454 addition of MBMS ACCESS INFORMATION RP-38 RP-070858 637 Addition of general SS requirements for UL and DL RF F 8.0.0 8.1.0 R5-073269 signal levels RP-38 RP-070858 638 Correction to SIB1 F 8.0.0 8.1.0 R5-073418 R5-073425 correct column RP-38 RP-070858 639 Editorial moving the word "Default1" or "Default2" in the F 8.0.0 8.1.0 R5-073425 correct column RP-38 RP-070858 640 CR wrongly indicated to be to 34.108 and hence not implemented implem	RP-38	RP-070871	635		Correction to the SIB5 when MCCH mapped on to an S-	F	8.0.0	8.1.0	R5-073465
RP-38 RP-070858 637	RP-38	RP-070871	636		Corrections to MBMS specific message content and	F	8.0.0	8.1.0	R5-073454
RP-38 RP-070858 638 Correction to SIB1 F 8.0.0 8.1.0 R5-073418 RP-38 RP-070858 639 Editorial moving the word "Default1" or "Default2" in the F 8.0.0 8.1.0 R5-073425 RP-38 RP-070858 640 CR wrongly indicated to be to 34.108 and hence not implemented - - - - R5-073425 RP-39 RP-080095 0641 Correction to RRC Connection setup and RB setup messages for 64kbps(Channel2) F 8.1.0 8.2.0 R5-080247 RP-39 RP-080103 0642 Addition of default message contents for MBMS F 8.1.0 8.2.0 R5-080149 RP-39 RP-080108 0643 CR for 04108: Introduction of the UE E-DCH 16-QAM F F 8.1.0 8.2.0 R5-080118 RP-39 RP-080106 0644 Addition of combinations on E-DCH to 6.11 of 34.108 for F 8.1.0 8.2.0 R5-080346 RP-39 RP-080106 0645 Update of radio bearer setup in default message on the properties of the proper	RP-38	RP-070858	637		Addition of general SS requirements for UL and DL RF	F	8.0.0	8.1.0	R5-073269
RP-38 RP-070858 639 Editorial moving the word "Default1" or "Default2" in the correct column 8.0.0 8.1.0 R5-073425 RP-38 RP-070858 640 CR wrongly indicated to be to 34.108 and hence not implemented. - - - R5-073425 RP-39 RP-080095 0641 Correction to RRC Connection setup and RB setup message for 64kbps(Channel2) F 8.1.0 8.2.0 R5-080247 RP-39 RP-080103 0642 Addition of default message contents for MBMS F 8.1.0 8.2.0 R5-080149 RF-39 RP-080108 0643 CR to 34.108: Introduction of the UE E-DCH 16-QAM feature F 8.1.0 8.2.0 R5-080149 RF-39 RP-080106 0644 Addition of combinations on E-DCH to 6.11 of 34.108 for 3.440kps TDD 8.1.0 8.2.0 R5-080346 RP-39 RP-080106 0645 Update of radio bearer setup in default message contents for LCR TDD EDCH default message contents to include E-DCH conditions for 3.84Mcps and 7.68Mcps TDD F 8.1.0 8.2.0 R5-080350 RP-39 RP-080115 0646 CR for 34.108:Correction of CR TDD EDCH <t< td=""><td></td><td></td><td></td><td></td><td>U</td><td></td><td></td><td></td><td></td></t<>					U				
Correct column						•			
Implemented					correct column	F	8.0.0	8.1.0	
RP-39 RP-080103 0642 Addition of default message contents for MBMS F 8.1.0 8.2.0 R5-080149 RP-39 RP-080108 0643 CR to 34.108: Introduction of the UE E-DCH 16-QAM F 8.1.0 8.2.0 R5-080118 feature Addition of combinations on E-DCH to 6.11 of 34.108 for F 8.1.0 8.2.0 R5-080118 RP-39 RP-080106 0644 Addition of combinations on E-DCH to 6.11 of 34.108 for F 8.1.0 8.2.0 R5-080346 3.84Mcps TDD S.84Mcps TDD RP-39 RP-080106 0645 Update of radio bearer setup in default message contents to include E-DCH conditions for 3.84Mcps and 7.68Mcps TDD RP-39 RP-080115 0646 CR for 34.108:Correction of CELL UPDATE CONFIRM F 8.1.0 8.2.0 R5-080099 RP-39 RP-080115 0647 CR for 34.108:Correction of PHYSICAL CHANNEL F 8.1.0 8.2.0 R5-080100 RECONFIGURATION default message contents for LCR TDD EDCH RP-39 RP-080115 0648 CR for 34.108:Correction of RADIO BEARER F 8.1.0 8.2.0 R5-080101 RP-39 RP-080115 0649 CR for 34.108:Correction of RADIO BEARER RELEASE F 8.1.0 8.2.0 R5-080102 RP-39 RP-080115 0650 CR for 34.108:Correction of RADIO BEARER RELEASE F 8.1.0 8.2.0 R5-080103 RP-39 RP-080115 0651 CR for 34.108:Correction of RADIO BEARER SETUP F 8.1.0 8.2.0 R5-080104 RP-39 RP-080115 0652 CR for 34.108:Correction of RADIO BEARER SETUP F 8.1.0 8.2.0 R5-080104 RP-39 RP-080115 0652 Correction of RRO CONNECTION SETUP message: UM (Transition to CELL_DCH) (1.28 Mcps TDD option) SETUP message: UM (Transition to CELL_DCH) (1.28 Mcps TDD option) Introduction of Default Radio Bearer Setup message R1.0 8.2.0 R5-080480 contents for UL 16QAM RP-080107 0654 Addition of HARQ transmission parameters for 64QAM F 8.1.0 8.2.0 R5-080531 R7-080109 0655 Update of the default RADIO BEARER SETUP F 8.1.0 8.2.0 R5-080531 R7-080109 0655 Update of the default RADIO BEARER SETUP F 8.1.0 8.2.0 R5-080531 R7-080109 0655 Update of the					implemented	-	-	-	
RF/RRM testing					messages for 64kbps(Channel2)				
RP-39 RP-080106 0644 Addition of combinations on E-DCH to 6.11 of 34.108 for S.1.0 8.2.0 R5-080346 3.84Mcps TDD RP-39 RP-080106 0645 Update of radio bearer setup in default message contents to include E-DCH conditions for 3.84Mcps and 7.68Mcps TDD CR for 34.108:Correction of CELL UPDATE CONFIRM F. 8.1.0 8.2.0 R5-080350 RP-39 RP-080115 0646 CR for 34.108:Correction of CELL UPDATE CONFIRM F. 8.1.0 8.2.0 R5-080099 RP-39 RP-080115 0647 CR for 34.108:Correction of PHYSICAL CHANNEL F. 8.1.0 8.2.0 R5-080100 RECONFIGURATION default message contents for LCR TDD EDCH RECONFIGURATION default message contents for LCR TDD EDCH RECONFIGURATION default message contents for LCR TDD EDCH RP-39 RP-080115 0649 CR for 34.108:Correction of RADIO BEARER RELEASE R.1.0 8.2.0 R5-080102 RP-39 RP-080115 0650 CR for 34.108:Correction of RADIO BEARER SETUP F. 8.1.0 8.2.0 R5-080103 R5-080104 RECONFIGURATION default message contents for LCR TDD EDCH RECONFIGURATION default message contents for LCR TDD EDCH RP-39 RP-080115 0651 CR for 34.108:Correction of RADIO BEARER SETUP F. 8.1.0 8.2.0 R5-080104 R5-080115 R5-080115 CR for 34.108:Correction of TRANSPORT CHANNEL RECONFIGURATION default message contents for LCR TDD EDCH RECONFIGURATION default message CDC R5-080190 R5-0					RF/RRM testing	-			
RP-39 RP-080106 0645 Update of radio bearer setup in default message contents to include E-DCH conditions for 3.84Mcps and 7.68Mcps TDD CR for 34.108:Correction of CELL UPDATE CONFIRM F 8.1.0 8.2.0 R5-080099 RP-39 RP-080115 0646 CR for 34.108:Correction of CELL UPDATE CONFIRM F 8.1.0 8.2.0 R5-080099 RP-39 RP-080115 0647 CR for 34.108:Correction of PHYSICAL CHANNEL F 8.1.0 8.2.0 R5-080100 RECONFIGURATION default message contents for LCR TDD EDCH RECONFIGURATION default message contents for LCR TDD EDCH RECONFIGURATION default message contents for LCR TDD EDCH RP-39 RP-080115 0649 CR for 34.108:Correction of RADIO BEARER RELEASE F 8.1.0 8.2.0 R5-080101 RP-39 RP-080115 0650 CR for 34.108:Correction of RADIO BEARER RELEASE RECONFIGURATION default message contents for LCR TDD EDCH RP-39 RP-080115 0651 CR for 34.108:Correction of RADIO BEARER SETUP RECONFIGURATION default message contents for LCR TDD EDCH RP-39 RP-080115 0651 CR for 34.108:Correction of RADIO BEARER SETUP RECONFIGURATION default message contents for LCR TDD EDCH RP-39 RP-080115 0652 Correction to the cotents of RRC CONNECTION SETUP message: UM (Transition to CELL_DCH) (1.28 Mcps TDD option) SETUP message: UM (Transition to CELL_DCH) (1.28 Mcps TDD option) RP-39 RP-080108 0653 Introduction of Default Radio Bearer Setup message F 8.1.0 8.2.0 R5-080480 RP-39 RP-080109 0655 Update of the default RADIO BEARER SETUP F 8.1.0 8.2.0 R5-080482 RP-39 RP-080109 0655 Update of the default RADIO BEARER SETUP F 8.1.0 8.2.0 R5-080531					feature				
Contents to include E-DCH conditions for 3.84Mcps and 7.68Mcps TDD	RP-39	RP-080106	0644			F	8.1.0	8.2.0	R5-080346
RP-39 RP-080115 0646 CR for 34.108:Correction of CELL UPDATE CONFIRM default message contents for LCR TDD EDCH F 8.1.0 8.2.0 R5-080099 RP-39 RP-080115 0647 CR for 34.108:Correction of PHYSICAL CHANNEL RECONFIGURATION default message contents for LCR TDD EDCH F 8.1.0 8.2.0 R5-080100 RP-39 RP-080115 0648 CR for 34.108:Correction of RADIO BEARER RELEASE RECONFIGURATION default message contents for LCR TDD EDCH F 8.1.0 8.2.0 R5-080101 RP-39 RP-080115 0649 CR for 34.108:Correction of RADIO BEARER RELEASE default message contents for LCR TDD EDCH F 8.1.0 8.2.0 R5-080102 RP-39 RP-080115 0650 CR for 34.108:Correction of RADIO BEARER SETUP default message contents for LCR TDD EDCH F 8.1.0 8.2.0 R5-080102 RP-39 RP-080115 0651 CR for 34.108:Correction of TRANSPORT CHANNEL RECONFIGURATION default message contents for LCR TDD EDCH F 8.1.0 8.2.0 R5-080104 RP-39 RP-080115 0652 Correction to the cotents of RRC CONNECTION SETUP message: UM (Transition to CELL_DCH) (1.28 Mcps TDD option) F 8.1.0 <t< td=""><td>RP-39</td><td>RP-080106</td><td>0645</td><td></td><td>contents to include E-DCH conditions for 3.84Mcps and</td><td>F</td><td>8.1.0</td><td>8.2.0</td><td>R5-080350</td></t<>	RP-39	RP-080106	0645		contents to include E-DCH conditions for 3.84Mcps and	F	8.1.0	8.2.0	R5-080350
RP-39 RP-080115 0647 CR for 34.108:Correction of PHYSICAL CHANNEL RECONFIGURATION default message contents for LCR TDD EDCH F 8.1.0 8.2.0 R5-080100 RP-39 RP-080115 0648 CR for 34.108:Correction of RADIO BEARER RELEASE RECONFIGURATION default message contents for LCR TDD EDCH F 8.1.0 8.2.0 R5-080101 RP-39 RP-080115 0649 CR for 34.108:Correction of RADIO BEARER RELEASE default message contents for LCR TDD EDCH F 8.1.0 8.2.0 R5-080102 RP-39 RP-080115 0650 CR for 34.108:Correction of RADIO BEARER SETUP default message contents for LCR TDD EDCH F 8.1.0 8.2.0 R5-080103 RP-39 RP-080115 0651 CR for 34.108:Correction of TRANSPORT CHANNEL RECONFIGURATION default message contents for LCR TDD EDCH F 8.1.0 8.2.0 R5-080104 RP-39 RP-080115 0652 Correction to the cotents of RRC CONNECTION SETUP message: UM (Transition to CELL_DCH) (1.28 Mcps TDD option) F 8.1.0 8.2.0 R5-080190 RP-39 RP-080108 0653 Introduction of Default Radio Bearer Setup message contents for G4QAM F 8.1.0 8.2.0	RP-39	RP-080115	0646		CR for 34.108:Correction of CELL UPDATE CONFIRM	F	8.1.0	8.2.0	R5-080099
RP-39 RP-080115 0648 CR for 34.108:Correction of RADIO BEARER RECONFIGURATION default message contents for LCR TDD EDCH F 8.1.0 8.2.0 R5-080101 RP-39 RP-080115 0649 CR for 34.108:Correction of RADIO BEARER RELEASE default message contents for LCR TDD EDCH F 8.1.0 8.2.0 R5-080102 RP-39 RP-080115 0650 CR for 34.108:Correction of RADIO BEARER SETUP default message contents for LCR TDD EDCH F 8.1.0 8.2.0 R5-080103 RP-39 RP-080115 0651 CR for 34.108:Correction of TRANSPORT CHANNEL RECONFIGURATION default message contents for LCR TDD EDCH F 8.1.0 8.2.0 R5-080104 RP-39 RP-080115 0652 Correction to the cotents of RRC CONNECTION SETUP message: UM (Transition to CELL_DCH) (1.28 Mcps TDD option) F 8.1.0 8.2.0 R5-080190 RP-39 RP-080108 0653 Introduction of Default Radio Bearer Setup message contents for UL 16QAM F 8.1.0 8.2.0 R5-080480 RP-39 RP-080107 0654 Addition of HARQ transmission parameters for 64QAM F 8.1.0 8.2.0 R5-080482 RP-39<	RP-39	RP-080115	0647		CR for 34.108:Correction of PHYSICAL CHANNEL RECONFIGURATION default message contents for	F	8.1.0	8.2.0	R5-080100
RP-39 RP-080115 0649 CR for 34.108:Correction of RADIO BEARER RELEASE feature default message contents for LCR TDD EDCH 8.1.0 8.2.0 R5-080102 RP-39 RP-080115 0650 CR for 34.108:Correction of RADIO BEARER SETUP default message contents for LCR TDD EDCH F 8.1.0 8.2.0 R5-080103 RP-39 RP-080115 0651 CR for 34.108:Correction of TRANSPORT CHANNEL RECONFIGURATION default message contents for LCR TDD EDCH F 8.1.0 8.2.0 R5-080104 RP-39 RP-080115 0652 Correction to the cotents of RRC CONNECTION SETUP message: UM (Transition to CELL_DCH) (1.28 Mcps TDD option) F 8.1.0 8.2.0 R5-080190 RP-39 RP-080108 0653 Introduction of Default Radio Bearer Setup message contents for UL 16QAM F 8.1.0 8.2.0 R5-080480 RP-39 RP-080107 0654 Addition of HARQ transmission parameters for 64QAM F 8.1.0 8.2.0 R5-080482 RP-39 RP-080109 0655 Update of the default RADIO BEARER SETUP F 8.1.0 8.2.0 R5-080531	RP-39	RP-080115	0648		CR for 34.108:Correction of RADIO BEARER RECONFIGURATION default message contents for	F	8.1.0	8.2.0	R5-080101
RP-39 RP-080115 0650 CR for 34.108:Correction of RADIO BEARER SETUP default message contents for LCR TDD EDCH F 8.1.0 8.2.0 R5-080103 RP-39 RP-080115 0651 CR for 34.108:Correction of TRANSPORT CHANNEL RECONFIGURATION default message contents for LCR TDD EDCH F 8.1.0 8.2.0 R5-080104 RP-39 RP-080115 0652 Correction to the cotents of RRC CONNECTION SETUP message: UM (Transition to CELL_DCH) (1.28 Mcps TDD option) F 8.1.0 8.2.0 R5-080190 RP-39 RP-080108 0653 Introduction of Default Radio Bearer Setup message contents for UL 16QAM F 8.1.0 8.2.0 R5-080480 RP-39 RP-080107 0654 Addition of HARQ transmission parameters for 64QAM F 8.1.0 8.2.0 R5-080482 RP-39 RP-080109 0655 Update of the default RADIO BEARER SETUP F 8.1.0 8.2.0 R5-080531	RP-39	RP-080115	0649		CR for 34.108:Correction of RADIO BEARER RELEASE	F	8.1.0	8.2.0	R5-080102
RP-39 RP-080115 0651 CR for 34.108:Correction of TRANSPORT CHANNEL RECONFIGURATION default message contents for LCR TDD EDCH F 8.1.0 8.2.0 R5-080104 RP-39 RP-080115 0652 Correction to the cotents of RRC CONNECTION SETUP message: UM (Transition to CELL_DCH) (1.28 Mcps TDD option) F 8.1.0 8.2.0 R5-080190 RP-39 RP-080108 0653 Introduction of Default Radio Bearer Setup message contents for UL 16QAM F 8.1.0 8.2.0 R5-080480 RP-39 RP-080107 0654 Addition of HARQ transmission parameters for 64QAM F 8.1.0 8.2.0 R5-080482 RP-39 RP-080109 0655 Update of the default RADIO BEARER SETUP F 8.1.0 8.2.0 R5-080531	RP-39	RP-080115	0650		CR for 34.108:Correction of RADIO BEARER SETUP	F	8.1.0	8.2.0	R5-080103
RP-39 RP-080115 0652 Correction to the cotents of RRC CONNECTION SETUP message: UM (Transition to CELL_DCH) (1.28 Mcps TDD option) F 8.1.0 8.2.0 R5-080190 RP-39 RP-080108 0653 Introduction of Default Radio Bearer Setup message contents for UL 16QAM F 8.1.0 8.2.0 R5-080480 RP-39 RP-080107 0654 Addition of HARQ transmission parameters for 64QAM F 8.1.0 8.2.0 R5-080482 RP-39 RP-080109 0655 Update of the default RADIO BEARER SETUP F 8.1.0 8.2.0 R5-080531	RP-39	RP-080115	0651		CR for 34.108:Correction of TRANSPORT CHANNEL RECONFIGURATION default message contents for	F	8.1.0	8.2.0	R5-080104
RP-39 RP-080108 0653 Introduction of Default Radio Bearer Setup message contents for UL 16QAM F 8.1.0 8.2.0 R5-080480 RP-39 RP-080107 0654 Addition of HARQ transmission parameters for 64QAM F 8.1.0 8.2.0 R5-080482 RP-39 RP-080109 0655 Update of the default RADIO BEARER SETUP F 8.1.0 8.2.0 R5-080531	RP-39	RP-080115	0652		Correction to the cotents of RRC CONNECTION SETUP message: UM (Transition to CELL_DCH) (1.28	F	8.1.0	8.2.0	R5-080190
RP-39 RP-080107 0654 Addition of HARQ transmission parameters for 64QAM F 8.1.0 8.2.0 R5-080482 RP-39 RP-080109 0655 Update of the default RADIO BEARER SETUP F 8.1.0 8.2.0 R5-080531	RP-39	RP-080108	0653		Introduction of Default Radio Bearer Setup message	F	8.1.0	8.2.0	R5-080480
RP-39 RP-080109 0655 Update of the default RADIO BEARER SETUP F 8.1.0 8.2.0 R5-080531	RP-39	RP-080107	0654		Addition of HARQ transmission parameters for 64QAM	F	8.1.0	8.2.0	R5-080482
	RP-39	RP-080109	0655			F	8.1.0	8.2.0	R5-080531

Meetin g-1st- Level	Doc-1st-Level	CR	Rev	Subject	Cat	Version -Current		Doc-2nd- Level
RP-39	RP-080109	0656		Addition of enhanced L2 configurations for DL SRBs on HS	F	8.1.0	8.2.0	R5-080287
RP-39	RP-080109	0657		Correction of physical layer parameters for radio bearer configuration 6.10.2.4.5 and HSPA	F	8.1.0	8.2.0	R5-080289
RP-39	RP-080109	0658		Addition of enhanced L2 configurations to conversational UM PS radio bearer 6.10.2.4.6.6	F	8.1.0	8.2.0	R5-080484
RP-39	RP-080111	0659		Addition of RB setup message contents for CPC	F	8.1.0	8.2.0	R5-080512
RP-39	RP-080105	0660		Addition of HARQ transmission parameters for MIMO	F	8.1.0	8.2.0	R5-080519
RP-39	RP-080095	0661		Correction to RB identity in RRC Connection Setup	F	8.1.0	8.2.0	R5-080036
RP-39	RP-080095	0662		Addition of new RB Combination for MBMS Testing	F	8.1.0	8.2.0	R5-080600
RP-39	RP-080095	0663		Corrections to default content of MBMS GENERAL INFORMATION message	F	8.1.0	8.2.0	R5-080160
RP-39	RP-080095	0664		MBMS Modification Request message	F	8.1.0	8.2.0	R5-080521
RP-39	RP-080109	0665		Update of the default RRC CONNECTION SETUP message to support enhanced data rates	F	8.1.0	8.2.0	R5-080523r1
RP-40	RP-080372	0666		CR to 34.108: Correction to Contents of RADIO BEARER SETUUP message: AM or UM (E-DCH and HSDPA) for 16QAM	F	8.2.0	8.3.0	R5-081140
RP-40	RP-080370	0667		CR to 34.108: Introduction of Operating Bands XII XIII and XIV (UMTS700 MHz)	F	8.2.0	8.3.0	R5-081150
RP-40	RP-080364	0668		Correction to RRC Connection setup messages for 64kbps(Channel2)	F	8.2.0	8.3.0	R5-081435
RP-40	RP-080364	0669		Additional IEs for 7.8.4 of 34.121-1	F	8.2.0	8.3.0	R5-081436
RP-40	RP-080364	0670		Additional test procedure for HSDPA with F-DPCH RF Performance Requirement for 7.8.5 of 34.121-1	F	8.2.0	8.3.0	R5-081279
RP-40	RP-080364	0671		Additional RB setup message for 7.8.5 of 34.121-1	F	8.2.0	8.3.0	R5-081280
RP-40	RP-080371	0672		Update of radio bearer setup in default message contents to include E-DCH conditions for 3.84Mcps TDD	F	8.2.0	8.3.0	R5-081336
RP-40	RP-080377	0673		CR for 34.108: Baseline radio bearer combination for LCR TDD EDCH	F	8.2.0	8.3.0	R5-081116
RP-40	RP-080379	0674		Addition of MBSFN RABs and Signalling RB for 3.84 Mcps TDD	F	8.2.0	8.3.0	R5-081034
RP-40	RP-080379	0675		Addition of MBSFN RABs and Signalling RB for 7.68 Mcps TDD	F	8.2.0	8.3.0	R5-081035
RP-40	RP-080379	0676		Initial additions to common test environment definition for HCR and VHCR TDD MBSFN	F	8.2.0	8.3.0	R5-081039
RP-40	RP-080363	0677		Clarification of TDD test channels used for signaling test cases		8.2.0	8.3.0	R5-081354
RP-40	RP-080373	0678		Addition of new Test Bearer for MAC CPC testing	F	8.2.0	8.3.0	R5-081219
RP-40	RP-080373	0679		CPC: Corrections to Radio Bearer Setup message contents for conditions A20 A21	F	8.2.0	8.3.0	R5-081388
	RP-080365	0680		Update of radio bearer configurations for HSPA	F	8.2.0	8.3.0	R5-081194
	RP-080364	0681		message: AM or UM for MBMS PtP Radio Bearer Setup			8.3.0	R5-081205
RP-40 RP-40	RP-080365	0682		Addition of new Test Bearer for MAC-ehs testing	F	8.2.0	8.3.0	R5-081218
RP-40	RP-080365 RP-080365	0683 0684		Addition of new Test Bearer for Improved L2 testing Corrections to the default RADIO BEARER SETUP message	F F	8.2.0 8.2.0	8.3.0 8.3.0	R5-081220 R5-081393
RP-40	RP-080364	0685		Correction to RB Combination for MBMS Testing	F	8.2.0	8.3.0	R5-081298
RP-40	RP-080364	0686		Removal of MBMS dispersion indicator in default message content	F	8.2.0	8.3.0	R5-081508
RP-41	RP-080561	0687		Addition of combinations on HS-DSCH and E-PUCH to typical radio parameter sets for 7.68Mcps TDD	F	8.3.0	8.4.0	R5-083075
RP-41	RP-080568	0688		Simulated network environment description for MBSFN tests	F	8.3.0	8.4.0	R5-083105
RP-41	RP-080568	0689		Add default SIB configuration for 3.84 amd 7.68 Mcps TDD MBSFN	F	8.3.0	8.4.0	R5-083106
RP-41	RP-080568	0690		Add default MCCH configurations for 3.84 Mcps and 7.68 Mcps TDD MBSFN	F	8.3.0	8.4.0	R5-083107
RP-41	RP-080568	0691		Default MBMS RRC message contents for 3.84 and 7.68 Mcps TDD MBSFN	F	8.3.0	8.4.0	R5-083108
RP-41	RP-080568	0692		Radio Bearer configurations for 7bit and 15bit UM RLC TCs for HCR and VHCR TDD MBSFN	F	8.3.0	8.4.0	R5-083109
RP-41	RP-080557	0693		Corrections to the default RADIO BEARER SETUP message for condition A22	F	8.3.0	8.4.0	R5-083179
RP-41	RP-080570	0694		Correction of HS-PDSCH for 64QAM Enhancement	F	8.3.0	8.4.0	R5-083314
RP-41	RP-080554	0695		Correction to Contents of default RADIO BEARER SET- UP messages	F	8.3.0	8.4.0	R5-083336

Meetin g-1st- Level	Doc-1st-Level	CR	Rev	Subject	Cat	Version -Current		Doc-2nd- Level
RP-41	RP-080557	0696		Corrections to 34.108: Radio access bearer establishment procedure for packet switched sessions (procedure P26)	F	8.3.0	8.4.0	R5-083338
RP-41	RP-080557	0697		Corrections to Radio Bearer Setup message for Rel-7	F	8.3.0	8.4.0	R5-083340
RP-41	RP-080557	0698		Corrections to RRC Connection Setup message for Rel-		8.3.0	8.4.0	R5-083341
RP-41	RP-080557	0699		New Radio Bearer Combination for testing flexible size SRB in 8.2.2.57	F	8.3.0	8.4.0	R5-083342
RP-41	RP-080567	0700		New Radio Bearer Combinations for CS over HSPA	F	8.3.0	8.4.0	R5-083360
RP-41	RP-080568	0701		Add setup test procedures and Access Control Class settings for MBSFN MBMS testing	F	8.3.0	8.4.0	R5-083441
RP-41	RP-080555	0702		Correction to uplink beta factors in default messages	F	8.3.0	8.4.0	R5-083566
RP-41	RP-080567	0703		New Radio Bearer Setup message contents for CS-HSPA RABS	F	8.3.0	8.4.0	R5-083591
RP-41	RP-080570	0704		Correction of HS-PDSCH physical layer categories for LCR TDD 64QAM Enhancement	F	8.3.0	8.4.0	R5-083645
RP-41	RP-080561	0705		Addition of radio bearer set-up default messages for RF testing for E-DCH and HSDPA operation for 3.84Mcps TDD and 7.68Mcps TDD		8.3.0	8.4.0	R5-083825
RP-42	RP-080954	0706		Correction to E-RGCH Info in Radio Bearer Setup	F	8.4.0	8.5.0	R5-085037
RP-42	RP-080952	0707		Correction to System Information Block type 11	F	8.4.0	8.5.0	R5-085039
RP-42	RP-080964	0708		Addition of Elementary Files (EFs) needed in Network Selection Enhancements tests	F	8.4.0	8.5.0	R5-085064
RP-42	RP-080968	0709		Addition of MBSFN RABs and Signalling RB for 1.28 Mcps TDD	F	8.4.0	8.5.0	R5-085130
RP-42	RP-080968	0710		Simulated network environment description for MBSFN tests	F	8.4.0	8.5.0	R5-085131
RP-42	RP-080968	0711		Default MBMS RRC message contents for LCR TDD MBSFN	F	8.4.0	8.5.0	R5-085132
RP-42	RP-080954	0712		Correction to A9 condition in RB set-up message	F	8.4.0	8.5.0	R5-085230
RP-42	RP-080967	0713		Introduction of radio bearer parameters for Improved L2 UL	F	8.4.0	8.5.0	R5-085422
RP-42	RP-080956	0714		Addition of Rel-7 IEs to default messages specified in 34.108	F	8.4.0	8.5.0	R5-085424
RP-42	RP-080956	0715		Correction of UL DPPCH slot format for default Radio Bearer Setup message for DTX/DRX	F	8.4.0	8.5.0	R5-085425
RP-42	RP-080954	0716		Addition of RF E-DCH test procedure for E-DPDCH with 2SF2+2SF4	F	8.4.0	8.5.0	R5-085726
RP-42	RP-080954	0717		Correction to Contents of RADIO BEARER SETUP message: AM or UM (HSDPA)	F	8.4.0	8.5.0	R5-085727
RP-43	RP-090203	0718	-	Correction to E-DCH Transmission Time Interval	F	8.5.0	8.6.0	R5-090167
RP-43	RP-090203	0719	-	Correction to Radio Bearer Setup message (A17 & A18)	F	8.5.0	8.6.0	R5-090168
RP-43	RP-090216	0720	-	Addition 1.28 Mcps TDD contents in 6.11.5	F	8.5.0	8.6.0	R5-090312
RP-43	RP-090203	0721	-	Correction to the default RADIO BEARER SETUP message for condition A22	F	8.5.0	8.6.0	R5-090313
RP-43	RP-090203	0722	-	Correction 1.28 Mcps TDD default RADIO BEARER SETUP message in 9.1.2	F	8.5.0	8.6.0	R5-090314
RP-43	RP-090216	0723	-	Addition 1.28 Mcps TDD contents in 9.1.3	F	8.5.0	8.6.0	R5-090316
RP-43	RP-090217	0724	-	Supported Channels for MBSFN FDD	F	8.5.0	8.6.0	R5-090368
RP-43	RP-090217	0725	-	Simulated network environment for MBSFN FDD	F	8.5.0	8.6.0	R5-090369
RP-43	RP-090217	0726	-	Generic test procedure for MBSFN FDD	F	8.5.0	8.6.0	R5-090371
RP-43	RP-090217	0727	-	MBSFN FDD configurations for signalling test	F	8.5.0	8.6.0	R5-090373
RP-43	RP-090215	0728	-	Introduction of radio bearer parameters for testing Improved L2 UL	F	8.5.0	8.6.0	R5-090445
RP-43	RP-090212	0729	-		F	8.5.0	8.6.0	R5-090452
RP-43	RP-090212	0730	-	New Default SIB5/SIB5bis for Enhanced CELL FACH	F	8.5.0	8.6.0	R5-090456
RP-43	RP-090212	0731	-	Addition of Radio Bearer Setup Condition for Enhanced CELL_FACH	F	8.5.0	8.6.0	R5-090459
				_				

Meetin g-1st- Level	Doc-1st-Level	CR	Rev	Subject	Cat	Version -Current		Doc-2nd- Level
	RP-090203	0732	-	Addition of Rel-7 IE's to RRConnectionRequest and correction to Rel-7 IEs for Cell update and URA update under default messages specified in 34.108	F	8.5.0	8.6.0	R5-090465
RP-43	RP-090203	0733	-	Addition of Code Tree Allocation Table for 64QAM HSDPA Test Cases	F	8.5.0	8.6.0	R5-090466
RP-43	RP-090203	0734	-		F	8.5.0	8.6.0	R5-090467
RP-43	RP-090215	0735	-	Additions to the default RRC messages for improved L2 in uplink	F	8.5.0	8.6.0	R5-090559
RP-43	RP-090218	0736	-	Addition of radio bearer parameters for UE HS-DSCH Physical Layer category 19 and 20	F	8.5.0	8.6.0	R5-090562
RP-43	RP-090203	0737	-	Correction of radio bearer parameters for UE HS-DSCH Physical Layer category 15 and 18	F	8.5.0	8.6.0	R5-090563
RP-43	RP-090203	0738	-	Correction to the RAB Setup for CS over HSPA (A23 set of parameters) in 34.108	F	8.5.0	8.6.0	R5-090564
RP-43	RP-090215	0739	2	Update of Radio Bearer Configurations for flexible RLC	F	8.5.0	8.6.0	R5-090727
RP-43	RP-090212	0740	-	Introduction of radio bearer parameters for testing HS- DSCH Reception in CELL_FACH	F	8.5.0	8.6.0	R5-090728
RP-44	RP-090443	0741	-	Addition of MBSFN IDLE and MCCH configurations for LCR TDD MBSFN in 34.108	F	8.6.0	8.7.0	R5-092119
RP-44	RP-090443	0742	-	Addition of default SIB for LCR TDD MBSFN in 34.108	F	8.6.0	8.7.0	R5-092120
RP-44	RP-090445	0743	-	"6.4.1.1 - Correction to SIB5 Default Message for HS- DSCH Reception in CELL_FACH"	F	8.6.0	8.7.0	R5-092222
RP-44	RP-090443	0744	-	New Radio Bearer Configurations for 1.28TDD 64QAM	F	8.6.0	8.7.0	R5-092318
RP-44	RP-090433	0745	-	Correction to Radio Bearer Setup message contents (A17a)	F	8.6.0	8.7.0	R5-092537
RP-44	RP-090445	0746	-	Correction to RRC Connection Setup Default Message for HS-DSCH Reception in CELL_FACH state	F	8.6.0	8.7.0	R5-092544
RP-44	RP-090445	0747	-	Correction to Radio Bearer Setup Condition for Enhanced CELL FACH state	F	8.6.0	8.7.0	R5-092545
RP-44	RP-090433	0748	-	Update to Channelisation code allocation for 64QAM	F	8.6.0	8.7.0	R5-092728
RP-44	RP-090598	0749	-	Addition of Test frequencies in FDD Mode Operating Band XIX (Extended UMTS 800)	F	8.6.0	8.7.0	R5-092792
RP-44	RP-090795	0750	-	Introduction of two new SIBs configurations in UTRA cell for interRAT LTE test	F	8.7.0	8.8.0	R5-094071
RP-44	RP-090811	0751	-	Update of the default RADIO BEARER SETUP message to support enhanced data rates for LCR TDD	F	8.7.0	8.8.0	R5-094269
RP-44	RP-090803	0752	-	Correction RAB definition for LCR TDD MBSFN in 34108	F	8.7.0	8.8.0	R5-094270
RP-44	RP-090809	0753	-	Correction to RAB configuration for Enhanced CELL FACH	F	8.7.0	8.8.0	R5-094443
RP-44	RP-090809	0754	-	Correction to RRC Connection setup for HS-DSCH reception in CELL_FACH	F	8.7.0	8.8.0	R5-094445
RP-44	RP-090809	0755	-	Correction to SIB5 for Enhanced CELL_FACH	F	8.7.0	8.8.0	R5-094446
RP-44	RP-090809	0756	-	Correction to Radio Bearer Setup for HS-DSCH reception in CELL FACH	F	8.7.0	8.8.0	R5-094447
RP-44	RP-090799	0757	-	Correction to Radio Bearer Configuration for Improved L2 UL Testing	F	8.7.0	8.8.0	R5-094455
RP-44	RP-090808	0758	-	Inclusion of common E-DCH info in SIB5(bis) to be used by new Enh-UL for CELL_FACH test cases	F	8.7.0	8.8.0	R5-094459
RP-44	RP-090794	0759	-	Update to Channelisation code allocation for E-DCH and 64QAM	F	8.7.0	8.8.0	R5-094464
RP-44	RP-090794	0760	-	Addition of Radio Bearer Setup Conditions for establishing radio bearers mapped onto E-DCH/HS-DSCH (MAC-ehs) for 64QAM and non 64QAM configurations	F	8.7.0	8.8.0	R5-094467
RP-44	RP-090803	0761	-	Correction the number in section 11.2 in 34108	F	8.7.0	8.8.0	R5-094511
RP-44	RP-090795	0762	-	Correction to RB setup message for CS over HSPA	F	8.7.0	8.8.0	R5-094625
RP-44	RP-090794	0763	-	Correction to Default Message contents of Radio Bearer Setup for A22	F	8.7.0	8.8.0	R5-094646
RP-44	RP-090791	0764	-	Update of 9.2 Default RF Messages	F	8.7.0	8.8.0	R5-094744
RP-44	RP-090812	0765	-	MBSFN RABs and Signalling RB for 3.84 Mcps TDD IMB	F	8.7.0	8.8.0	R5-094856

Meetin g-1st- Level	Doc-1st-Level	CR	Rev	Subject	Cat	Version -Current		Doc-2nd- Level
	RP-090812	0766	-	Default MBMS RRC message contents for 3.84 Mcps TDD IMB	F	8.7.0	8.8.0	R5-094857
RP-44	RP-090812	0767	-	Default MCCH configurations for 3.84 Mcps TDD IMB	F	8.7.0	8.8.0	R5-094858
RP-44	RP-090812	0768	-	Radio Bearer configurations for 7bit and 15bit UM RLC TCs for 3.84 Mcps TDD IMB	F	8.7.0	8.8.0	R5-094859
RP-44	RP-090812	0769	-	Reference radio condition for 3.84 Mcps TDD IMB	F	8.7.0	8.8.0	R5-094860
RP-44	RP-090812	0770	-	Reference test condition for MBSFN 3.84 Mcps TDD IMB	F	8.7.0	8.8.0	R5-094861
RP-44	RP-090812	0771	-	Default SIB configuration for 3.84 Mcps TDD IMB	F	8.7.0	8.8.0	R5-094862
RP-44	RP-090812	0772	-	Supported Channels for MBSFN 3.84 Mcps TDD IMB	F	8.7.0	8.8.0	R5-094863
RP-44	RP-090809	0773	-	New RF procedure for HSDPA in CELL_FACH	F	8.7.0	8.8.0	R5-094984
RP-44	RP-090793	0774	-	CR to 34.108: Addition of RADIO BEARER SETUP condition for test case 5.2B in 34.121-1	F	8.7.0	8.8.0	R5-094994
RP-44	RP-090794	0775	-	addition of the Standard TDD reference test frequencies	F	8.7.0	8.8.0	R5-095013
RP-44	RP-090794	0776	-	correction of RADIO BEARER SETUP message default content	F	8.7.0	8.8.0	R5-095014
RP-44	RP-090791	0777	-	Addition of section 6.1.4.1a: Default Cell parameters Two PLMN in UTRAN test scenario with cells on PLMN1 belonging to two different frequencies	F	8.7.0	8.8.0	R5-095026
RP-44	RP-090805	0778	-	Update of the default RADIO BEARER SETUP message (FDD) for support of Dual Carrier Adjacent Channels for HSDPA	F	8.7.0	8.8.0	R5-095062
RP-44	RP-090794	0779	-	Update of the default RADIO BEARER SETUP message (FDD) for an additional RB combination	F	8.7.0	8.8.0	R5-095063
RP-44	RP-090800	0780	-	Update of the default RADIO BEARER SETUP message (FDD) for support of 64QAM+MIMO for HSDPA	F	8.7.0	8.8.0	R5-095128
RP-44	RP-090799	0781	-	Addition of Default Radio Bearer Conditions for Improved L2 UL MAC test cases	F	8.7.0	8.8.0	R5-095130
RP-45	RP-091124	0782	-	Addition of radio bearer parameters for UE HS-DSCH Physical Layer category 21, 22, 23 and 24 (Dual Cell)	F	8.8.0	8.9.0	R5-095605
RP-45	RP-091118	0783	-	Corrections to the default RRC CONNECTION SETUP message	F	8.8.0	8.9.0	R5-095646
RP-45	RP-091130	0784	-	Default SIB configuration for 3.84 Mcps TDD IMB	F	8.8.0	8.9.0	R5-095698
RP-45	RP-091130	0785	-	MBSFN service availability for 3.84 Mcps TDD IMB	F	8.8.0	8.9.0	R5-095699
RP-45	RP-091130	0786	-	Reference radio condition for 3.84 Mcps TDD IMB	F	8.8.0	8.9.0	R5-095700
RP-45	RP-091135	0787	-	Introduction of MIMO in Typical radio parameter sets for 1.28Mcps TDD	F	8.8.0	8.9.0	R5-095882
RP-45	RP-091123	0788	-	Update 5.5.1.4 for MBSFN TC Reference test conditions	F	8.8.0	8.9.0	R5-095945
RP-45	RP-091118	0789	-	Inclusion of common HS-DSCH and E-DCH info in SIB5 to be used by new enhanced CELL_FACH test cases for LCR TDD	F	8.8.0	8.9.0	R5-095957
RP-45	RP-091129	0790	-	Addition Reference Radio Bearer configurations used in MAC-ehs and MAC-i/is testing for LCR TDD	F	8.8.0	8.9.0	R5-095958
RP-45	RP-091115	0791	-	Editorial correction in clause 8.1.2.1	F	8.8.0	8.9.0	R5-096049
RP-45	RP-091117	0792	-	Correction of RADIO BEARER SETUP for 5.2B	F	8.8.0	8.9.0	R5-096052
RP-45	RP-091119	0794	-	Correction to condition A27 for Improved L2 UL Testing and generic table formatting	F	8.8.0	8.9.0	R5-096150
RP-45	RP-091119	0795	-	Correction to Default Radio Bearer Conditions for Improved L2 UL RLC AM test cases	F	8.8.0	8.9.0	R5-096153
RP-45	RP-091128	0796	1	Correction to Default message contents	F	8.8.0	8.9.0	R5-096171
RP-45	RP-091119	0797	-	Align USIM content to the latest REI-8 USIM files	F	8.8.0	8.9.0	R5-096180
RP-45	RP-091124	0798	-	Update of the default RADIO BEARER SETUP message for RF testing of Dual Carrier Adjacent Channels for HSDPA	F	8.8.0	8.9.0	R5-096280
RP-45	RP-091124	0799	-	New RF procedure for Dual Cell HSDPA	F	8.8.0	8.9.0	R5-096308
RP-45	RP-091119	0800	-	Correction to radio bearer configuration 6.10.2.4.6.6 for improvedL2 UL	F	8.8.0	8.9.0	R5-096706

Meetin g-1st- Level		CR	Rev	Subject	Cat	Version -Current	-New	Doc-2nd- Level
RP-47	RP-100141	0801	-	Corrections to Radio Bearer Setup A26	F	8.9.0	8.10.0	R5-100054
RP-47	RP-100140	0802	-	Configurations	F	8.9.0	8.10.0	R5-100241
RP-47	RP-100154	0803	-	CR to 34.108: Update of test frequencies for extended UMTS1500 operating bands	F	8.9.0	8.10.0	R5-100253
RP-47	RP-100137	0804	-	Addition of new combinations for LCR TDD RAB testing in 34.108	F	8.9.0	8.10.0	R5-100336
RP-47	RP-100151	0805	-	Update of the default RADIO BEARER SETUP message to support enhanced CELL_FACH for LCR TDD	F	8.9.0	8.10.0	R5-100337
RP-47	RP-100157	0806	-	Introduction of Default Message Contents for CPC of 1.28Mcps TDD	F	8.9.0	8.10.0	R5-100388
RP-47	RP-100158	0807	-	Introduction of Default Message Contents for MIMO of 1.28Mcps TDD	F	8.9.0	8.10.0	R5-100389
RP-47	RP-100141	8080	-	Addition of reference HARQ Transmission Parameters for the combination of MIMO and 64QAM	F	8.9.0	8.10.0	R5-100525
RP-47	RP-100149	0809	-	CR to 34.108: Correction to RADIO BEARER SETUP condition for sub-test 5 in 5.2B test case	F	8.9.0	8.10.0	R5-100563
RP-47	RP-100150	0810	-	Correction to SIB5 for Enhanced CELL_FACH in UL and DL	F	8.9.0	8.10.0	R5-100632
RP-47	RP-100150	0811	-	Addition of RRC Connection Setup Default Condition for Enhanced CELL_FACH in UL cases	F	8.9.0	8.10.0	R5-100634
RP-47	RP-100150	0812	-	Addition of Default Radio Bearer Conditions for Enhanced UL in CELL FACH	F	8.9.0	8.10.0	R5-100635
RP-47	RP-100140	0814	-	Correction to default RRC Connection setup message for HS-DSCH in CELL_FACH	F	8.9.0	8.10.0	R5-100681
RP-47	RP-100142	0819	-	Update of 9.2 Default RF Messages for TC7.8.5	F	8.9.0	8.10.0	R5-100726
RP-47	RP-100149	0815	-	Update of the default RADIO BEARER SETUP message (FDD) for support of Dual Carrier Adjacent Channels for HSDPA for radio bearer testing	F	8.9.0	8.10.0	R5-100769
RP-47	RP-100149	0816	-	Introduction of test frequencies to DC-HSDPA tests	F	8.9.0	8.10.0	R5-100875
RP-47	RP-100140	0817	-	Correction to Enhanced CELL_FACH RAB configuration	F	8.9.0	8.10.0	R5-101107
RP-47	RP-100149	0818	-	Update of physical channel params on HS-PDSCH for DC-HSDPA	F	8.9.0	8.10.0	R5-101181
RP-48	RP-100511	0832	-	Removal of technical content in 34.108 v8.10.0 and substitution with pointer to the next Release	В	8.10.0	8.11.0	R5-103229

History

		Document history
V8.0.0	October 2007	Publication
V8.1.0	January 2008	Publication
V8.2.0	April 2008	Publication
V8.3.0	July 2008	Publication
V8.4.0	October 2008	Publication
V8.5.0	January 2009	Publication
V8.6.0	April 2009	Publication
V8.7.0	August 2009	Publication
V8.8.0	November 2009	Publication
V8.9.0	April 2010	Publication
V8.10.0	June 2010	Publication
V8.11.0	June 2010	Publication