ETSITS 134 229-3 V10.8.0 (2016-01)



Universal Mobile Telecommunications System (UMTS); LTE;

Internet Protocol (IP) multimedia call control protocol based on Session Initiation Protocol (SIP) and Session Description Protocol (SDP);
User Equipment (UE) conformance specification;
Part 3: Abstract test suite (ATS)

(3GPP TS 34.229-3 version 10.8.0 Release 10)



Reference RTS/TSGR-0534229-3va80 Keywords LTE.UMTS

ETSI

650 Route des Lucioles F-06921 Sophia Antipolis Cedex - FRANCE

Tel.: +33 4 92 94 42 00 Fax: +33 4 93 65 47 16

Siret N° 348 623 562 00017 - NAF 742 C Association à but non lucratif enregistrée à la Sous-Préfecture de Grasse (06) N° 7803/88

Important notice

The present document can be downloaded from: http://www.etsi.org/standards-search

The present document may be made available in electronic versions and/or in print. The content of any electronic and/or print versions of the present document shall not be modified without the prior written authorization of ETSI. In case of any existing or perceived difference in contents between such versions and/or in print, the only prevailing document is the print of the Portable Document Format (PDF) version kept on a specific network drive within ETSI Secretariat.

Users of the present document should be aware that the document may be subject to revision or change of status.

Information on the current status of this and other ETSI documents is available at

http://portal.etsi.org/tb/status/status.asp

If you find errors in the present document, please send your comment to one of the following services: https://portal.etsi.org/People/CommiteeSupportStaff.aspx

Copyright Notification

No part may be reproduced or utilized in any form or by any means, electronic or mechanical, including photocopying and microfilm except as authorized by written permission of ETSI.

The content of the PDF version shall not be modified without the written authorization of ETSI.

The copyright and the foregoing restriction extend to reproduction in all media.

© European Telecommunications Standards Institute 2016.
All rights reserved.

DECTTM, **PLUGTESTS**TM, **UMTS**TM and the ETSI logo are Trade Marks of ETSI registered for the benefit of its Members. **3GPP**TM and **LTE**TM are Trade Marks of ETSI registered for the benefit of its Members and of the 3GPP Organizational Partners.

GSM® and the GSM logo are Trade Marks registered and owned by the GSM Association.

Intellectual Property Rights

IPRs essential or potentially essential to the present document may have been declared to ETSI. The information pertaining to these essential IPRs, if any, is publicly available for **ETSI members and non-members**, and can be found in ETSI SR 000 314: "Intellectual Property Rights (IPRs); Essential, or potentially Essential, IPRs notified to ETSI in respect of ETSI standards", which is available from the ETSI Secretariat. Latest updates are available on the ETSI Web server (https://ipr.etsi.org/).

Pursuant to the ETSI IPR Policy, no investigation, including IPR searches, has been carried out by ETSI. No guarantee can be given as to the existence of other IPRs not referenced in ETSI SR 000 314 (or the updates on the ETSI Web server) which are, or may be, or may become, essential to the present document.

Foreword

This Technical Specification (TS) has been produced by ETSI 3rd Generation Partnership Project (3GPP).

The present document may refer to technical specifications or reports using their 3GPP identities, UMTS identities or GSM identities. These should be interpreted as being references to the corresponding ETSI deliverables.

The cross reference between GSM, UMTS, 3GPP and ETSI identities can be found under http://webapp.etsi.org/key/queryform.asp.

Modal verbs terminology

In the present document "shall", "shall not", "should", "should not", "may", "need not", "will", "will not", "can" and "cannot" are to be interpreted as described in clause 3.2 of the <u>ETSI Drafting Rules</u> (Verbal forms for the expression of provisions).

"must" and "must not" are NOT allowed in ETSI deliverables except when used in direct citation.

Contents

| Inte | lectual Property Rights | | 2 |
|------|-------------------------|------------------|----|
| | | | |
| | | | |
| | | | |
| | | | |
| 1 | | | |
| 2 | | | |
| 3 | | eviations | |
| 4 | | TTCN development | |
| 5 to | - | | |
| Ann | ex A to H: | Void | 6 |
| | | Change history | |
| Hist | | S | 18 |

Foreword

This Technical Specification has been produced by the 3rd Generation Partnership Project (3GPP).

The contents of the present document are subject to continuing work within the TSG and may change following formal TSG approval. Should the TSG modify the contents of the present document, it will be re-released by the TSG with an identifying change of release date and an increase in version number as follows:

Version x.y.z

where:

- x the first digit:
 - 1 presented to TSG for information;
 - 2 presented to TSG for approval;
 - 3 or greater indicates TSG approved document under change control.
- Y the second digit is incremented for all changes of substance, i.e. technical enhancements, corrections, updates, etc.
- Z the third digit is incremented when editorial only changes have been incorporated in the document.

Introduction

The present document is 3rd part of a multi-part conformance test specification for UE and is *valid for 3GPP Release 5* and above. The specification contains a TTCN design frame work and the detailed test specifications in TTCN for the UE conformance at the Gm reference point.

3GPP TS 34.229-1 [5] contains a conformance test description in prose.

3GPP TS 34.229-2 [6] contains a pro-forma for the UE Implementation Conformance Statement (ICS).

3GPP TS 34.229-3 the present document.

1 Scope

The present document specifies the protocol conformance testing in TTCN for the 3GPP User Equipment (UE) at the Gm interface.

The present document is the 3rd part of a multi-part test specification, 3GPP TS 34.229. The following TTCN test specification and design considerations can be found in the present document:

- the overall test suite structure;
- the testing architecture;
- the test methods and PCO definitions:
- the test configurations;
- the design principles, assumptions, and used interfaces to the TTCN tester (System Simulator);
- TTCN styles and conventions;
- the partial PIXIT proforma;
- the TTCN files for the mentioned protocols tests.

The Abstract Test Suites designed in the document are based on the test cases specified in prose (3GPP TS 34.229-1 [5]).

The present document is valid for UE implemented according 3GPP Releases starting from Release 5 up to the Release indicated on the cover page of the present document.

2 References

The following documents contain provisions which, through reference in this text, constitute provisions of the present document.

- References are either specific (identified by date of publication, edition number, version number, etc.) or non-specific.
- For a specific reference, subsequent revisions do not apply.
- For a non-specific reference, the latest version applies. In the case of a reference to a 3GPP document (including a GSM document), a non-specific reference implicitly refers to the latest version of that document in the same Release as the present document.
 - For a Release 5 UE, references to 3GPP documents are to version 5.x.y, when available.
 - For a Release 6 UE, references to 3GPP documents are to version 6.x.y, when available.

[1] to [50] (void)

[51] 3GPP TS 34.229-3 Release 11: "Internet Protocol (IP) multimedia call control protocol based on Session Initiation Protocol (SIP) and Session Description Protocol (SDP); User Equipment (UE) conformance specification; Part 3: Abstract Test Suite (ATS)"

3 Definitions and abbreviations

Void

4 Requirements on the TTCN development

The requirements of the present document are provided in 3GPP TS 34.229-3 Release 11 [51].

5 to 8 Void

Annex A to H: Void

Annex I (informative): Change history

| Meet- ing | TSG doc | CR | Rev | Subject | Cat | Old vers | New vers | WG doc |
|--------------|-----------|------|-----|---|-----|-------------|-------------|-----------|
| RP-31 | RP-060054 | - | - | Update to version 1.0.0 and present to RAN#31 for information | - | - | 1.0.0 | R5-060513 |
| RP-34 | RP-060664 | - | - | Present version 1.3.0 to RAN#34 for information | - | - | 1.3.0 | R5-063500 |
| RP-35 | RP-070010 | - | - | Presented as version 2.0.0 for approval to go under revision control | - | - | 2.0.0 | R5-070456 |
| - | - | - | - | Upgraded to version 5.0.0 by the 3GPP support | - | - | 5.0.0 | - |
| RP-36 | RP-070352 | 0001 | - | Addition of IMS-CC test case 8.6 to IMS_CC ATS V1.3.0 | F | 5.0.0 | 5.1.0 | R5s070101 |
| RP-36 | RP-070353 | 0002 | = | CR to 34.229-3: Add new verified and e-mail agreed TTCN test cases in the TC lists in 34.229-3 (prose), Annex A | F | 5.0.0 | 5.1.0 | - |
| RP-37 | RP-070594 | 0003 | - | Extension to TTCN ASP DeactivatePDPContextReq | F | 5.1.0 | 5.2.0 | R5-072509 |
| RP-37 | RP-070594 | 0004 | - | IMS CC / PIXIT parameter px_CellId | F | 5.1.0 | 5.2.0 | R5-072546 |
| RP-38 | RP-070870 | 0007 | | Addition of IMS-CC test case 8.5 to IMS_CC ATS V5.1.0 | В | 5.2.0 | 5.3.0 | R5s070489 |
| RP-38 | RP-070870 | 8000 | | Addition of IMS-CC test case 8.7 to IMS_CC ATS V5.3.0 | В | 5.2.0 | 5.3.0 | R5s070259 |
| RP-38 | RP-070870 | 0009 | | Addition of IMS-CC test case 9.1 to IMS_CC ATS V5.3.0 | В | 5.2.0 | 5.3.0 | R5s070261 |
| RP-38 | RP-070889 | 0010 | | CR to 34.229-3: Add new verified and e-mail agreed TTCN test cases in the TC lists in 34.229-3 (prose), Annex A | F | 5.2.0 | 5.3.0 | - |
| RP-38 | RP-070869 | 0006 | | Production of 34.229-3 pointer version in Rel-5 pointing to Rel-6 version | F | 5.2.0 | 5.3.0 | R5-073439 |
| RP-38 | RP-070869 | 0005 | | Addition of an MMI command | F | 5.2.0 | 6.0.0 | R5-073046 |
| RP-39 | RP-080098 | 0011 | | Update of MMI command strings | F | 6.0.0 | 6.1.0 | R5-080041 |
| RP-39 | RP-080089 | 0012 | | CR to 34.229-3: Add new verified and e-mail agreed TTCN test cases in the TC lists in 34.229-3 (prose), Annex A | F | 6.0.0 | 6.1.0 | - |
| RP-39 | RP-080094 | 0013 | | Addition of IMS-CC test case 7.2 to IMS_CC ATS V5.3.0 | В | 6.0.0 | 6.1.0 | R5s070535 |
| RP-39 | RP-080094 | 0014 | | Addition of IMS-CC test case 10.1 to IMS_CC ATS V5.1.0 | В | 6.0.0 | 6.1.0 | R5s070549 |
| RP-39 | RP-080094 | 0015 | | Addition of IMS-CC test case 8.3 to IMS_CC ATS V5.1.0 | В | 6.0.0 | 6.1.0 | R5s070545 |
| RP-39 | RP-080094 | 0016 | | Addition of IMS-CC test case 8.2 to IMS_CC ATS V5.1.0 | В | 6.0.0 | 6.1.0 | R5s070543 |
| RP-39 | RP-080094 | 0017 | | Addition of IMS-CC test case 7.6 to IMS_CC ATS V5.1.0 | В | 6.0.0 | 6.1.0 | R5s070539 |
| RP-39 | RP-080094 | 0018 | | Addition of IMS-CC test case 7.4 to IMS_CC ATS V5.1.0 | В | 6.0.0 | 6.1.0 | R5s070537 |
| RP-39 | RP-080094 | 0019 | | Addition of IMS-CC test case 11.1 to IMS_CC ATS V5.1.0 | В | 6.0.0 | 6.1.0 | R5s070551 |
| RP-39 | RP-080094 | 0020 | | Addition of IMS-CC test case 14.1 to IMS_CC ATS V5.1.0 | В | 6.0.0 | 6.1.0 | R5s070555 |
| RP-39 | RP-080094 | 0021 | | Addition of IMS-CC test case 13.1 to IMS_CC ATS V5.1.0 | В | 6.0.0 | 6.1.0 | R5s070553 |
| RP-39 | RP-080094 | 0022 | | Addition of IMS-CC test case 8.4 to IMS_CC ATS V5.1.0 | В | 6.0.0 | 6.1.0 | R5s070547 |
| RP-39 | RP-080094 | 0023 | | Addition of IMS-CC test case 8.1 to IMS_CC ATS V5.1.0 | В | 6.0.0 | 6.1.0 | R5s070541 |
| RP-39 | RP-080094 | 0024 | | Addition of IMS-CC test case 7.1 to IMS_CC ATS V5.1.0 | В | 6.0.0 | 6.1.0 | R5s070491 |
| RP-39 | RP-080094 | 0025 | 1 | Common corrections to IMS-CC test cases | F | 6.0.0 | 6.1.0 | R5s070534 |
| RP-40 | RP-080369 | 0027 | | Correction to regular expressions in IMS | F | 6.1.0 | 7.0.0 | R5s080036 |
| RP-40 | RP-080369 | 0028 | | IMS ATS / handling of P-Access-Network-Info header over non secure ports | F | 6.1.0 | 7.0.0 | R5s080063 |
| RP-40 | RP-080369 | 0029 | | IMS ATS / test case 9.1 / handling of authorization header in Register messages | F | 6.1.0 | 7.0.0 | R5s080085 |
| RP-40 | RP-080376 | 0030 | | Extend test model supporting XCAP test | F | 6.1.0 | 7.0.0 | R5-081036 |
| RP-41 | RP-080654 | 0031 | | CR to 34.229-3: Add new verified and e-mail agreed TTCN test cases in the TC lists in 34.229-3 (prose), Annex A | F | 7.0.0 | 7.1.0 | - |
| RP-41 | RP-080615 | 0032 | | Addition of IMS-CC test case 9.2 to IMS_CC ATS v.7.0.0 | F | 7.0.0 | 7.1.0 | R5s080115 |
| RP-41 | RP-080615 | 0033 | | Addition of IMS-CC test case 7.3 to IMS_CC ATS | F | 7.0.0 | 7.1.0 | R5s080114 |

| RP-41 RP-080615 | Meet- ing | TSG doc | CR | Rev | Subject | Cat | Old vers | New vers | WG doc |
|--|--------------|-----------|------|-----------|---|-----|-------------|-------------|----------------|
| RP-48 | RP-41 | RP-080615 | 0034 | | | F | 7.0.0 | 7.1.0 | R5s080138 |
| RP-41 RP-080615 0036 Addition of IMS-CC test case 8.8 to IMS_CC ATS F 7.0.0 7.1.0 RS-080143 RP-41 RP-080615 0037 Addition of IMS-CC test case 7.5 to IMS_CC ATS F 7.0.0 7.1.0 RS-0808065 RP-41 RP-080740 0038 Update of TS 34.229.3 from Rel ⁶ to Rel ⁷ F 7.1.0 7.2.0 RS-080065 RP-42 RP-080989 0040 DHCP response messages P 7.1.0 7.2.0 RS-080016 RP-43 RP-0809210 0040 Minor correction of Route header template in the F 7.1.0 7.2.0 RS-080018 RP-43 RP-090210 0042 IMS CC ATS / Improvement: Stopping test case F 8.0.0 8.1.0 RS-090785 RP-43 RP-090210 0044 IMS CC ATS / Handring of non-default port number in F 8.0.0 8.1.0 RS-090018 RP-43 RP-090210 0044 IMS CC ATS / Handring of Contact Header F 8.0.0 8.1.0 RS-090018 RP-43 RP-090210 0046 IM | RP-41 | RP-080615 | 0035 | | Addition of IMS-CC test case 8.9 to IMS_CC ATS | F | 7.0.0 | 7.1.0 | R5s080145 |
| RP-41 RP-680615 0.037 Addition of IMS-CC test case 7.5 to IMS_CC ATS F 7.0.0 7.1.0 7.2.0 R56080151 RP-42 RP-680859 0.039 Correction of HW Type and HW Length fields in DHCP response messages F 7.1.0 7.2.0 R56080171 DHCP response messages DHCP response messages Minor correction of Route header template in the F F 7.1.0 7.2.0 R56080171 RP-43 RP-090210 0041 Update of TS 34.2293 from Rel-7 to Rel-8 F 7.2.0 R5.00076 R5.00076 RP-43 RP-090210 0043 IMS CC ATS I Fingerowernet: Stopping test case F 8.0.0 8.1.0 R56990078 RP-43 RP-090210 0044 IMS CC ATS I Findering of Contact Header F 8.0.0 8.1.0 R56990078 RP-43 RP-090210 0046 IMS CC ATS I Findering of Contact Header F 8.0.0 8.1.0 R56990078 RP-43 RP-909210 0046 IMS CC ATS I Findering of Contact Header F 8.0.0 8.1.0 R56990009 RP-43 | RP-41 | RP-080615 | 0036 | | Addition of IMS-CC test case 8.8 to IMS_CC ATS | F | 7.0.0 | 7.1.0 | R5s080143 |
| RP-44 RP-080959 0039 Update of TS 34;229-3 from Rel-8 to Rel-7 F 7,1.0 7,2.0 R5-080061 RP-42 RP-080959 0040 Observation of HW Type and HW Length fields in F 7,1.0 7,2.0 R5-080011 RP-43 RP-080210 0041 Mission Correction of Route header template in the initial Register message initial Register | RP-41 | RP-080615 | 0037 | | | F | 7.0.0 | 7.1.0 | R5s080151 |
| RP-42 RP-080959 | RP-41 | | | | | | | | |
| RP-498 RP-090950 0.040 Minor correction of Route header template in the initial Register message RP-43 RP-090210 0.041 Update of TS 34.229-3 from Rel-7 to Rel-8 F 7.2.0 8.0.0 R5-090765 RP-43 RP-090210 0.042 Update of TS 34.229-3 from Rel-7 to Rel-8 F 7.2.0 8.0.0 R5-090765 RRP-43 RP-090210 0.044 Mis CC ATS? Improvement: Stopping test case F 8.0.0 8.1.0 R56090019 RRP-43 RP-090210 0.044 Mis CC ATS? Handling of non-default port number in F 8.0.0 8.1.0 R56090016 RRP-43 RP-090210 0.045 Mis CC ATS? Handling of non-default port number in F 8.0.0 8.1.0 R56090005 RRP-43 RP-090210 0.046 Mis CC ATS? Handling of Contact Header F 8.0.0 8.1.0 R56090005 RRP-43 RP-090210 0.046 Mis CC ATS? Handling of Contact Header F 8.0.0 8.1.0 R56090005 RRP-43 RP-090210 0.046 Mis CC Addition of test case 11.2 to the IMS ATS F 8.0.0 8.1.0 R56090032 RRP-43 RP-090210 0.046 Mis CC Addition of test case 11.2 to the IMS ATS F 8.0.0 8.1.0 R56090032 RRP-43 RP-090210 0.046 R600016 Risk contact Header F 8.0.0 8.1.0 R56090032 RRP-43 RP-090210 0.046 R600016 Risk contact Header F 8.0.0 8.1.0 R56090032 RRP-43 RP-090210 0.046 R600016 Risk contact Header F 8.0.0 8.1.0 R56090032 RRP-43 RRP-090210 0.046 R600016 | RP-42 | RP-080959 | 0039 | | Correction of HW Type and HW Length fields in | F | 7.1.0 | 7.2.0 | R5s080171 |
| RP-43 RP-900210 0041 Update of TS 34.229-3 from Rel-7 to Rel-8 F 7.2.0 8.0.0 8.0.0 RS-9090765 RP-43 RP-900210 0043 IMS CC ATS / Handing of non-default port number in F 8.0.0 8.1.0 RS-9090718 RP-43 RP-900210 0044 IMS CC ATS / Handing of non-default port number in F 8.0.0 8.1.0 RS-9090709 RP-43 RP-900210 0044 IMS CC ATS / Handing of Contact Header F 8.0.0 8.1.0 RS-95090000 RP-43 RP-900210 0045 IMS CC ATS / Handing of Contact Header F 8.0.0 8.1.0 RS-9900000 RP-43 RP-900210 0047 IMS CC I Addition of test case 11.2 to the IMS ATS F 8.0.0 8.1.0 RS-9900303 RP-43 RP-900210 0048 Removal of an unused pixil and other routine updates F 8.0.0 8.1.0 RS-9000803 RP-43 RP-900175 0049 CR to 34.229-3 (prose) update to v820 F 8.0.0 8.1.0 RS-9000803 RP-43 RP-901140 005 | RP-42 | RP-080959 | 0040 | | Minor correction of Route header template in the | F | 7.1.0 | 7.2.0 | R5s080168 |
| RP-43 RP-090210 0042 MRS CC ATS / Improvement: Stopping test case F 8.0.0 8.1.0 R5c00019 execution once a PTC fails default port number in F 8.0.0 8.1.0 R5c00018 the Contact Header F 8.0.0 8.1.0 R5c090018 the Contact Header F 8.0.0 8.1.0 R5c090018 the Contact Header F 8.0.0 8.1.0 R5c090018 the Contact Header F 8.0.0 8.1.0 R5c090005 RP-43 RP-090210 0045 MRS CC ATS / Handling of Contact Header F 8.0.0 8.1.0 R5c090005 RP-43 RP-090210 0046 MRS CC ATS / Handling of Contact Header F 8.0.0 8.1.0 R5c090005 RP-43 RP-090210 0047 MRS CC / Moritor corrections on test 11.2 (re- F 8.0.0 8.1.0 R5c090031 MRS CC / Addition of test case 11.2 to the IMS ATS F 8.0.0 8.1.0 R5c090032 reconfigure IP Layer F 8. | RP-43 | RP-090210 | 0041 | | | F | 7.2.0 | 8.0.0 | R5-090765 |
| RP-43 RP-990210 0044 IMS CC ATS / Handling of non-default port number in F 8.0.0 8.1.0 R5s0900018 the Contact Header F 8.0.0 8.1.0 R5s090005 RP-43 RP-990210 0045 IMS CC ATS / Handling of Contact Header F 8.0.0 8.1.0 R5s090005 RP-43 RP-990210 0046 IMS CC / Minor corrections on test 11.2 (re- F 8.0.0 8.1.0 R5s090005 RP-43 RP-990210 0047 IMS CC (Addition of test case 11.2 to the IMS ATS F 8.0.0 8.1.0 R5s090031 RP-43 RP-990210 0047 IMS CC (Addition of the MS ATS F 8.0.0 8.1.0 R5s090032 reconfigure IP Layer RP-44 RP-990210 0048 Removal of an unused pixil and other routine updates F 8.0.0 8.1.0 R5s090032 RP-44 RP-901150 0049 CR to 34.229-3 (prose) update to v820 F 8.0.0 8.1.0 R5-090056 RP-47 RP-100146 0050 CR to 34.229-3 (prose) update to v820 F 8.2.0 8.3.0 R5-100087 RP-47 RP-100145 0051 Correction of IMS test model for XCAP-based SS test F 8.2.0 8.3.0 R5-100087 RP-48 RP-100154 0052 Add bearer information for E-UTRA F 8.2.0 8.3.0 R5-100087 RP-48 RP-100514 0055 CR to 34.229-3 (prose) update to v840 F 8.3.0 8.4.0 R5-103382 RP-50 RP-10146 0055 Routine maintenance of TS 34.229-3 F 8.4.0 8.5.0 8.6.0 R5-106088 RP-50 RP-10146 0055 Routine maintenance of TS 34.229-3 F 8.4.0 8.5.0 8.6.0 8.7.0 R5-106088 RP-51 RP-110165 0056 CR to 34.229-3 (prose) update to v860 F 8.6.0 8.6.0 8.6.0 R5-112648 RP-52 RP-110655 0056 CR to 34.229-3 (prose) update to v860 F 8.6.0 8.6.0 8.6.0 R5-112648 RP-52 RP-110650 0061 CR to 34.229-3 (prose) update to v860 F 8.6.0 8.6.0 8.6.0 R5-112648 RP-52 RP-110655 0061 CR to 34.229-3 (prose) update to v860 F 8.6.0 8.6.0 8.6.0 R5-112648 RP-52 RP-110655 0061 CR to 34.229-3 (prose) update to v860 F 8.6.0 8.6.0 8.6.0 R5-112648 RP-52 RP-110650 0061 CR to 34.229-3 (prose) update to v860 F 8.6.0 8 | | RP-090210 | | | IMS CC ATS / Improvement: Stopping test case | F | | | |
| RP-43 RP-090210 0044 IMS CC ATS / Handling of Contact Header F 8.0.0 8.1.0 RS0900004 RP-43 RP-090210 0045 IMS CC (Minor corrections on test 11.2 (re- authentication) 8.0.0 8.1.0 RS0900004 RP-43 RP-090210 0047 IMS CC (C Addition of test case 11.2 to the IMS ATS F 8.0.0 8.1.0 RS090005 RP-43 RP-090210 0048 IMS CC (C Addition of test case 11.2 to the IMS ATS F 8.0.0 8.1.0 RS090056 RP-43 RP-090210 0049 RE 050005 Removal of an unused pixt and other routine updates F 8.0.0 8.1.0 RS0-090056 RP-48 RP-100146 0050 C R to 34.229-3 (prose) update to v820 F 8.2.0 8.3.0 RS-090056 RP-47 RP-100146 0050 C R to 34.229-3 (prose) update to v820 F 8.2.0 8.3.0 RS-100087 RP-47 RP-100155 0051 Core to 34.229-3 (prose) update to v820 F 8.2.0 8.3.0 RS-100044 RP-43 RP-100511 0053 C R to 34.229-3 (pros | RP-43 | RP-090210 | 0043 | | IMS CC ATS / Handling of non-default port number in | F | 8.0.0 | 8.1.0 | R5s090018 |
| RP-43 RP-990210 0046 IMS CC / Minor corrections on test 11.2 (re- | RP-43 | RP-090210 | 0044 | | | F | 8.0.0 | 8.1.0 | R5s090005 |
| RP-943 RP-990210 0046 IMS CC / Addition of test case 11.2 to the IMS ATS F 8.0.0 8.1.0 RS-980313 RP-43 RP-990210 0047 IMS CC test model / Addition of new ASP to reconfigure IP Layer F 8.0.0 8.1.0 RS-990323 RP-46 RP-09156 0049 C R to 34.229-3 (prose) update to v820 F 8.1.0 8.2.0 8.3.0 - - RP-47 RP-100146 0050 C R to 34.229-3 (prose) update to v820 F 8.2.0 8.3.0 - < | | | 0045 | | IMS CC / Minor corrections on test 11.2 (re- | F | | | |
| RP-43 RP-090210 0048 Removal of an unused pixit and other routine updates F 8.0.0 8.1.0 R5-090056 RP-46 RP-091156 0049 CR to 34.229-3 (prose) update to v820 F 8.1.0 8.2.0 | RP-43 | RP-090210 | 0046 | | IMS CC / Addition of test case 11.2 to the IMS ATS | F | 8.0.0 | 8.1.0 | R5s080313 |
| RP-46 RP-091156 0049 CR to 34.229-3 (prose) update to v830 F 8.10 8.20 - RP-47 RP-100165 0050 CR to 34.229-3 (prose) update to v830 F 8.20 8.30 R5-100087 RP-47 RP-100165 0051 Correction of IMS test model for XCAP-based SS test F 8.20 8.30 R5-100081 RP-48 RP-100514 0053 CR to 34.229-3 (prose) update to v840 F 8.30 8.40 R5-100081 RP-48 RP-100511 0055 ROUTINE RESIDIATION (provided and provided state) (provided and provided and provi | RP-43 | | 0047 | | IMS CC test model / Addition of new ASP to reconfigure IP Layer | - | 8.0.0 | 8.1.0 | R5-090032 |
| RP-47 RP-100146 0050 Correction of IMS test model for XGAP-based SS test F 8.2.0 8.3.0 RP-47 RP-47 RP-100155 0051 Correction of IMS test model for XGAP-based SS test F 8.2.0 8.3.0 R5-100087 RP-48 RP-100511 0052 Add bearer information for E-UTRA F 8.2.0 8.3.0 R5-100414 RP-48 RP-100511 0054 Update IMS test model for ST, | | | | | | | | | R5-090056 |
| RP-47 RP-100145 0051 Correction of IMS test model for XCAP-based SS test F 8.2.0 8.3.0 R5-100087 RP-48 RP-100514 0052 Add bearer information for E-UTRA F 8.2.0 8.3.0 8.4.0 R-5100414 RP-48 RP-100511 0053 CR to 34.229-3 (prose) update to v840 F 8.3.0 8.4.0 R-5100382 RP-50 RP-101146 0055 Routine maintenance of TS 34.229-3 F 8.4.0 8.5.0 R8-100382 RP-50 RP-101150 0056 CR to 34.229-3 update to v850 F 8.4.0 8.5.0 R8-10608 RP-51 RP-101165 0057 Mapping of some PIXIT parameters to ISIM Efs – 3 F 8.5.0 8.6.0 R5-10608 RP-51 RP-101651 0059 Removal of technical content in 34.229-3 v8.6.0 and substitution with pointer to the next Release F 8.6.0 8.0.0 8.7.0 R5-112246 RP-52 RP-110651 0060 Routine maintenance F 8.6.0 9.0.0 R5-12246 RP-52 R | | | | - | | | | | - |
| RP-49 RP-100514 0052 | | RP-100146 | | - | | | | | - |
| RP-48 RP-100511 0054 CR to 34.229-3 (prose) update to v840 F 8.3.0 8.4.0 RS-107-100511 RP-50 RP-1001146 0055 - Routine maintenance of TS 34.229-3 F 8.4.0 8.5.0 R5-106088 RP-50 RP-101150 0056 - Routine maintenance of TS 34.229-3 F 8.4.0 8.5.0 R5-106088 RP-50 RP-101150 0056 - Routine maintenance of TS 34.229-3 F 8.4.0 8.5.0 R6.0 RP-51 RP-101050 0057 Mapping of some PIXIT parameters to ISIM Efs – 3 IS.5.0 8.6.0 R6.0 RP-51 RP-110651 0059 Removal of technical content in 34.229-3 w.6.0 and substitution with pointer to the next Release R6.0 8.0 8.7.0 R5-112246 RP-52 RP-110651 0060 Routine maintenance F 8.6.0 9.0 R5-112246 RP-52 RP-111584 0063 Routine maintenance and update to v870 F 8.6.0 9.0 R5-112246 RP-53 RP-111160 | | | | - | | | | | |
| RP-48 RP-100511 0054 Update IMS test model F 8.3.0 8.4.0 R5-10382 RP-50 RP-101150 0055 Routine maintenance of TS 34.229-3 F 8.4.0 8.5.0 R5-106088 RP-50 RP-101165 0057 Mapping of some PIXIT parameters to ISIM Efs – 3 F 8.5.0 8.6.0 R5-110694 RP-51 RP-110169 0058 CR to 34.229-3 (prose) update to v860 F 8.5.0 8.6.0 R5-110694 RP-52 RP-110651 0059 Removal of technical content in 34.229-3 v8.6.0 and substitution with pointer to the next Release 8.6.0 8.7.0 R5-112246 RP-52 RP-110651 0060 Routine maintenance R9-10060 R5-112246 | | | | - | | - | | | R5-100414 |
| RP-50 RP-101146 0055 Routine maintenance of TS 34 229-3 F 8.4.0 8.5.0 RS-10808 RP-51 RP-101150 0056 - CR to 34.229-3 update to v950 F 8.4.0 8.5.0 8.5.0 RP-51 RP-10165 0057 - Mapping of some PIXIT parameters to ISIM Efs - 3 F 8.5.0 8.6.0 R5-110694 RP-52 RP-101651 0059 - CR to 34.229-3 (prose) update to v860 F 8.5.0 8.6.0 - R5-112246 RP-52 RP-110651 0059 - Removal of technical content in 34.229-3 v8.6.0 and substitution with pointer to the next Release F 8.6.0 9.0.0 R5-112246 RP-52 RP-110651 0060 - Routine maintenance F 8.6.0 9.0.0 R5-112248 RP-53 RP-111684 0061 - CR to 34.229-3 (prose) update to v970 F 8.6.0 9.0.0 9.1.0 RP-53 RP-111684 0063 - Routine maintenance and updates to v970 F 9.0.0 9.1.0 R5-115670 RP-55 RP-120187 0064 < | | RP-100514 | | - | | | | | - R5-103382 |
| RP-50 RP-101165 0056 CR to 34.229-3 update to v850 F 8.40 8.5.0 - RP-51 RP-110165 0057 Mapping of some PIXIT parameters to ISIM Efs = 3 F 8.5.0 8.6.0 R5-110694 MPU RP-51 RP-110169 0058 CR to 34.229-3 (prose) update to v860 F 8.5.0 8.6.0 R5-110694 RP-52 RP-110651 0059 Removal of technical content in 34.229-3 v8.6.0 and substitution with pointer to the next Release F 8.6.0 9.0.0 R5-11246 RP-52 RP-110651 0060 Routine maintenance F 8.6.0 9.0.0 R5-112648 RP-52 RP-110655 0061 CR to 34.229-3 (prose) update to v870 F 8.6.0 9.0.0 RP-53 RP-111160 0062 CR to 34.229-3 (prose) update to v870 F 8.6.0 9.0.0 RP-53 RP-111160 0062 CR to 34.229-3 (prose) update to v870 F 9.1.0 9.2.0 R5-115670 RP-53 RP-11160 0063 Routine maintenance and updates for IMS ASP F 9.1.0 9.2.0 R5-115670 RP-55 RP-120149 0065 Routine maintenance and updates F 9.3.0 9.4.0 R5-121090 RP-56 RP-120802 0066 Correction to IMS CC test cases / Ipv6 address F 9.3.0 9.4.0 R5-121080 RP-57 RP-121103 0067 34229-3: Routine maintenance and updates F 9.4.0 9.5.0 R5-123085 RP-57 RP-121121 0069 Addition of GCF WI-031 IMS test case 8.10 F 9.4.0 9.5.0 R5-125037 RP-57 RP-121221 0070 Addition of GCF WI-031 IMS test case 8.13 F 9.4.0 9.5.0 R5-120537 RP-57 RP-121221 0072 Addition of GCF WI-031 IMS test case 8.13 F 9.4.0 9.5.0 R5-120537 RP-57 RP-121221 0073 Addition of GCF WI-031 IMS test case 8.13 F 9.4.0 9.5.0 R5-120549 RP-57 RP-121221 0074 Addition of GCF WI-031 IMS test case 8.13 F 9.4.0 9.5.0 R5-120549 RP-57 RP-121221 0075 Addition of GCF WI-031 IMS test case 8.13 F 9.4.0 9.5.0 R5-120549 RP-57 RP-121221 0075 Addition of GCF WI-031 IMS test case 8.15 F 9.4.0 9.5.0 R5-120549 RP-57 RP-121221 0075 Addition of GCF WI-031 IMS test case 18.1 F 9.4.0 9.5.0 R5-120549 RP-57 | | | | - | | • | | | |
| RP-51 RP-110165 0057 Mapping of some PIXIT parameters to ISIM Efs – 3 F 8.5.0 8.6.0 R5-110694 MPU RP-51 RP-110169 0058 CR to 34.229-3 (prose) update to v860 F 8.5.0 8.6.0 R5-110695 RP-52 RP-110651 0059 Removal of technical content in 34.229-3 v8.6.0 and substitution with pointer to the next Release F 8.6.0 8.7.0 R5-112246 RP-52 RP-110651 0060 Routine maintenance F 8.6.0 9.0.0 R5-112648 RP-52 RP-110655 0061 CR to 34.229-3 (prose) update to v870 F 8.6.0 9.0.0 - RF-54 RP-111584 0062 CR to 34.229-3 (prose) update to v870 F 8.6.0 9.0.0 - RF-54 RP-111584 0063 R04129-3 (prose) update to v970 F 9.0.0 9.1.0 - RF-55 RP-120187 0064 CR to 34.229-3 (prose) update to v970 F 9.0.0 9.1.0 - RF-55 RP-120187 0064 CR to 34.229-3 (prose) update to v970 F 9.0.0 9.1.0 - RF-56 RP-120802 0066 ROUTINE maintenance and updates for IMS ASP F 9.1.0 9.2.0 R5-115670 RP-56 RP-120802 0066 ROUTINE maintenance and updates F 9.3.0 9.4.0 R5-121090 RF-56 RP-120802 0066 ROUTINE maintenance and updates F 9.3.0 9.4.0 R5-121090 RF-57 RP-121103 0067 34229-3: Routine maintenance and updates F 9.4.0 9.5.0 R5-120085 RP-57 RP-121221 0069 Addition of GCF WI-031 IMS test case 8.10 F 9.4.0 9.5.0 R5-120087 RP-57 RP-121221 0070 Addition of GCF WI-031 IMS test case 8.11 F 9.4.0 9.5.0 R5-120537 RP-57 RP-121221 0071 Addition of GCF WI-031 IMS test case 8.13 F 9.4.0 9.5.0 R5-120547 RP-57 RP-121221 0072 Addition of GCF WI-031 IMS test case 8.13 F 9.4.0 9.5.0 R5-120547 RP-57 RP-121221 0073 Addition of GCF WI-103 IMS test case 8.13 F 9.4.0 9.5.0 R5-120547 RP-57 RP-121221 0074 Addition of GCF WI-103 IMS test case 8.15 F 9.4.0 9.5.0 R5-120547 RP-57 RP-121221 0075 Addition of GCF WI-103 IMS test case 16.2 F 9.4.0 9.5.0 R5-120549 RP-58 RP-121669 0079 Addition | | | | - | | | | | - |
| RP-51 RP-110169 0058 CR to 34,229-3 (prose) update to v860 F 8.5.0 8.6.0 RP-52 RP-10651 0059 Removal of technical content in 34,229-3 v8.6.0 and substitution with pointer to the next Release F 8.6.0 9.0.0 R5-11246 RP-52 RP-110655 0060 Routine maintenance F 8.6.0 9.0.0 R5-112648 RP-52 RP-110655 0061 CR to 34,229-3 (prose) update to v870 F 8.6.0 9.0.0 R5-112648 RP-53 RP-11160 0062 CR to 34,229-3 (prose) update to v970 F 8.6.0 9.0.0 9.1.0 RP-54 RP-111544 0063 Routine maintenance and updates for IMS ASP F 9.1.0 9.2.0 R5-115670 RP-54 RP-111544 0064 Routine maintenance and updates for IMS ASP F 9.1.0 9.2.0 R5-115670 RP-55 RP-120187 0064 Routine maintenance and updates F 9.3.0 9.4.0 R5-121090 RP-56 RP-120802 0066 Routine maintenance and updates F 9.3.0 9.4.0 R5-121090 RP-56 RP-120802 0066 Routine maintenance and updates F 9.3.0 9.4.0 R5-121090 RP-57 RP-121103 0067 34229-3: Routine maintenance and updates F 9.4.0 9.5.0 R5-123085 RP-57 RP-121221 0068 Addition of GCF WI-031 IMS test case 8.10 F 9.4.0 9.5.0 R5s120530 RP-57 RP-121221 0070 Addition of GCF WI-031 IMS test case 8.12 F 9.4.0 9.5.0 R5s120531 RP-57 RP-121221 0071 Addition of GCF WI-031 IMS test case 8.13 F 9.4.0 9.5.0 R5s120543 RP-57 RP-121221 0074 Addition of GCF WI-031 IMS test case 8.13 F 9.4.0 9.5.0 R5s120543 RP-57 RP-121221 0075 Addition of GCF WI-031 IMS test case 8.15 F 9.4.0 9.5.0 R5s120543 RP-57 RP-121221 0074 Addition of GCF WI-031 IMS test case 18.1 F 9.4.0 9.5.0 R5s120549 RP-57 RP-121221 0075 Addition of GCF WI-031 IMS test case 18.1 F 9.4.0 9.5.0 R5s120549 RP-57 RP-121669 0079 Addition of GCF WI-031 IMS test case 15.1 F 9.4.0 9.5.0 R5s | | | | - | Mapping of some PIXIT parameters to ISIM Efs – 3 | F | | | R5-110694 |
| Substitution with pointer to the next Release RP-52 RP-110655 0061 CR to 34.229-3 (prose) update to v870 F 8.6.0 9.0.0 S-112648 | RP-51 | RP-110169 | 0058 | - | | F | 8.5.0 | 8.6.0 | - |
| RP-52 RP-110655 0061 CR to 34.229-3 (prose) update to v870 F 8.6.0 9.0.0 - RP-53 RP-111160 0062 CR to 34.229-3 (prose) update to v910 F 9.0.0 9.1.0 9.2.0 R5-115670 RP-55 RP-120187 0064 CR to 34.229-3 (prose) update to v930 F 9.2.0 93.0 - RP-56 RP-120849 0065 Routine maintenance and updates F 9.3.0 9.4.0 R5-121090 RP-56 RP-120802 0066 Correction to IMS CC test cases / Ipv6 address F 9.3.0 9.4.0 R5-121090 RP-57 RP-121103 0067 - 34229-3: Routine maintenance and updates F 9.4.0 9.5.0 R5-123085 RP-57 RP-121221 0068 TTCN IMS correction F 9.4.0 9.5.0 R5-123085 RP-57 RP-121221 0070 Addition of GCF WI-031 IMS test case 8.10 F 9.4.0 9.5.0 R5s120539 RP-57 RP-121221 0071 Addition of GCF WI-031 IMS test case 8.12 | RP-52 | RP-110651 | 0059 | - | Removal of technical content in 34.229-3 v8.6.0 and | F | 8.6.0 | 8.7.0 | R5-112246 |
| RP-53 RP-111160 0062 - CR to 34.229-3 (prose) update to v910 F 9.0.0 9.1.0 - RP-54 RP-120187 0064 - CR to 34.229-3 (prose) update to v930 F 9.2.0 9.3.0 - RP-56 RP-120649 0065 - Routine maintenance and updates F 9.3.0 9.4.0 R5-121090 RP-56 RP-120802 0066 - Correction to IMS CC test cases / Ipv6 address F 9.3.0 9.4.0 R5-121090 RP-57 RP-12103 0067 - 34229-3: Routine maintenance and updates F 9.4.0 9.5.0 R5-123085 RP-57 RP-121221 0068 TTCN IMS correction F 9.4.0 9.5.0 R5-123085 RP-57 RP-121221 0069 Addition of GCF WI-031 IMS test case 8.10 F 9.4.0 9.5.0 R5-120537 RP-57 RP-121221 0070 Addition of GCF WI-031 IMS test case 8.12 F 9.4.0 9.5.0 R5s120539 RP-57 RP-121221 | RP-52 | RP-110651 | 0060 | - | Routine maintenance | F | 8.6.0 | 9.0.0 | R5-112648 |
| RP-54 RP-111584 0063 Routine maintenance and updates for IMS ASP F 9.1.0 9.2.0 R5-115670 RP-55 RP-120187 0064 CR to 34.229-3 (prose) update to v930 F 9.2.0 9.3.0 - RP-56 RP-120849 0065 Routine maintenance and updates F 9.3.0 9.4.0 R5-121090 RP-56 RP-120802 0066 Correction to IMS CC test cases / Ipv6 address F 9.3.0 9.4.0 R5-121090 RP-57 RP-121103 0067 34229-3: Routine maintenance and updates F 9.4.0 9.5.0 R5-123085 RP-57 RP-121120 0068 TTCN IMS correction F 9.4.0 9.5.0 R5-120850 RP-57 RP-121221 0069 Addition of GCF WI-031 IMS test case 8.10 F 9.4.0 9.5.0 R5s120530 RP-57 RP-121221 0071 Addition of GCF WI-031 IMS test case 8.12 F 9.4.0 9.5.0 R5s120539 RP-57 RP-121221 0071 Addition of GCF WI-031 IMS test case 18.1 | | | | - | | F | | | - |
| RP-55 RP-120187 0064 - CR to 34.229-3 (prose) update to v930 F 9.2.0 9.3.0 - RP-56 RP-120649 0065 Routine maintenance and updates F 9.3.0 9.4.0 R5-121090 RP-56 RP-120802 0066 - Correction to IMS CC test cases / Ipv6 address F 9.3.0 9.4.0 R5-12108 RP-57 RP-121103 0067 34229-3: Routine maintenance and updates F 9.4.0 9.5.0 R5-123085 RP-57 RP-121221 0069 Addition of GCF WI-031 IMS test case 8.10 F 9.4.0 9.5.0 R5s120530 RP-57 RP-121221 0070 Addition of GCF WI-031 IMS test case 8.12 F 9.4.0 9.5.0 R5s120537 RP-57 RP-121221 0070 Addition of GCF WI-031 IMS test case 8.12 F 9.4.0 9.5.0 R5s120537 RP-57 RP-121221 0071 Addition of GCF WI-031 IMS test case 8.12 F 9.4.0 9.5.0 R5s120530 RP-57 RP-121221 0073 Addition of GCF WI-128 IMS test case 18.1 F | | | | - | | | | | - |
| RP-56 RP-120649 0065 - Routine maintenance and updates F 9.3.0 9.4.0 R5-121090 RP-56 RP-120802 0066 - Correction to IMS CC test cases / Ipv6 address F 9.3.0 9.4.0 R5s120108 RP-57 RP-121103 0067 - 34229-3: Routine maintenance and updates F 9.4.0 9.5.0 R5-123085 RP-57 RP-121221 0068 - TTCN IMS correction F 9.4.0 9.5.0 R5s120530 RP-57 RP-121221 0069 - Addition of GCF WI-031 IMS test case 8.10 F 9.4.0 9.5.0 R5s120537 RP-57 RP-121221 0070 - Addition of GCF WI-031 IMS test case 8.12 F 9.4.0 9.5.0 R5s120539 RP-57 RP-121221 0071 - Addition of GCF WI-031 IMS test case 8.12 F 9.4.0 9.5.0 R5s120537 RP-57 RP-121221 0071 - Addition of GCF WI-128 IMS test case 8.13 F 9.4.0 9.5.0 R5s120541 RP-57 RP-121621 0074 - Addition of GCF WI-128 IM | | | | - | | | | | R5-115670 |
| RP-56 RP-120802 0066 Correction to IMS CC test cases / Ipv6 address F 9.3.0 9.4.0 RSs120108 RP-57 RP-121103 0067 - 34229-3: Routine maintenance and updates F 9.4.0 9.5.0 R5-123085 RP-57 RP-121221 0068 - TTCN IMS correction F 9.4.0 9.5.0 R5s120530 RP-57 RP-121221 0070 - Addition of GCF WI-031 IMS test case 8.10 F 9.4.0 9.5.0 R5s120537 RP-57 RP-121221 0070 - Addition of GCF WI-031 IMS test case 8.12 F 9.4.0 9.5.0 R5s120539 RP-57 RP-121221 0070 - Addition of GCF WI-031 IMS test case 8.13 F 9.4.0 9.5.0 R5s120549 RP-57 RP-121221 0072 - Addition of GCF WI-128 IMS test case 18.1 F 9.4.0 9.5.0 R5s120543 RP-57 RP-121221 0073 - Addition of GCF WI-103 IMS test case 18.2 F 9.4.0 9.5.0 R5s120549 | | | | - | | | | | - DE 121000 |
| RP-57 RP-121103 0067 - 34229-3: Routine maintenance and updates F 9.4.0 9.5.0 R5-123085 RP-57 RP-121221 0068 - TTCN IMS correction F 9.4.0 9.5.0 R5s120530 RP-57 RP-121221 0069 - Addition of GCF WI-031 IMS test case 8.10 F 9.4.0 9.5.0 R5s120537 RP-57 RP-121221 0070 - Addition of GCF WI-031 IMS test case 8.12 F 9.4.0 9.5.0 R5s120533 RP-57 RP-121221 0071 - Addition of GCF WI-031 IMS test case 8.13 F 9.4.0 9.5.0 R5s120541 RP-57 RP-121221 0072 - Addition of GCF WI-128 IMS test case 18.1 F 9.4.0 9.5.0 R5s120541 RP-57 RP-121221 0073 - Addition of GCF WI-128 IMS test case 18.1 F 9.4.0 9.5.0 R5s120545 RP-57 RP-121221 0073 - Addition of GCF WI-103 IMS test case 16.1 F 9.4.0 9.5.0 R5s1 | | | | - | Correction to IMS CC test cases / Ipv6 address | • | | | |
| RP-57 RP-121221 0068 - TTCN IMS correction F 9.4.0 9.5.0 R5s120530 RP-57 RP-121221 0069 - Addition of GCF WI-031 IMS test case 8.10 F 9.4.0 9.5.0 R5s120537 RP-57 RP-121221 0070 - Addition of GCF WI-031 IMS test case 8.12 F 9.4.0 9.5.0 R5s120539 RP-57 RP-121221 0071 - Addition of GCF WI-031 IMS test case 8.13 F 9.4.0 9.5.0 R5s120539 RP-57 RP-121221 0072 - Addition of GCF WI-128 IMS test case 18.1 F 9.4.0 9.5.0 R5s120543 RP-57 RP-121221 0073 - Addition of GCF WI-128 IMS test case 18.2 F 9.4.0 9.5.0 R5s120543 RP-57 RP-121221 0074 - Addition of GCF WI-103 IMS test case 18.2 F 9.4.0 9.5.0 R5s120545 RP-57 RP-121261 0075 - Addition of GCF WI-103 IMS test case 16.2 F 9.4.0 9.5.0 R5s | PD-57 | PD-121103 | 0067 | _ | | F | 0.4.0 | 950 | P5-123085 |
| RP-57 RP-121221 0069 - Addition of GCF WI-031 IMS test case 8.10 F 9.4.0 9.5.0 R5s120537 RP-57 RP-121221 0070 - Addition of GCF WI-031 IMS test case 8.12 F 9.4.0 9.5.0 R5s120539 RP-57 RP-121221 0071 - Addition of GCF WI-031 IMS test case 8.13 F 9.4.0 9.5.0 R5s120539 RP-57 RP-121221 0072 - Addition of GCF WI-128 IMS test case 18.1 F 9.4.0 9.5.0 R5s120543 RP-57 RP-121221 0073 - Addition of GCF WI-128 IMS test case 18.2 F 9.4.0 9.5.0 R5s120545 RP-57 RP-121221 0074 - Addition of GCF WI-103 IMS test case 16.1 F 9.4.0 9.5.0 R5s120547 RP-57 RP-121221 0075 - Addition of GCF WI-103 IMS test case 16.2 F 9.4.0 9.5.0 R5s120547 RP-57 RP-121601 0076 - CR to 34.229-3: Add new verified and e-mail agreed TTCN test cases in the TC lists in 34.229-3 (prose), Annex A F 9.4.0 9.5.0 9.5.0 - R5s120609 <td></td> <td></td> <td></td> <td>[</td> <td></td> <td></td> <td></td> <td></td> <td></td> | | | | [| | | | | |
| RP-57 RP-121221 0070 Addition of GCF WI-031 IMS test case 8.12 F 9.4.0 9.5.0 R5s120539 RP-57 RP-121221 0071 - Addition of GCF WI-031 IMS test case 8.13 F 9.4.0 9.5.0 R5s120541 RP-57 RP-121221 0072 - Addition of GCF WI-128 IMS test case 18.1 F 9.4.0 9.5.0 R5s120543 RP-57 RP-121221 0073 - Addition of GCF WI-128 IMS test case 18.2 F 9.4.0 9.5.0 R5s120545 RP-57 RP-121221 0074 - Addition of GCF WI-103 IMS test case 16.2 F 9.4.0 9.5.0 R5s120547 RP-57 RP-121221 0075 - Addition of GCF WI-103 IMS test case 16.2 F 9.4.0 9.5.0 R5s120549 RP-57 RP-121106 0076 - CR to 34.229-3: Add new verified and e-mail agreed TTCN test cases in the TC lists in 34.229-3 (prose), Annex A F 9.4.0 9.5.0 R5s120549 RP-58 RP-121669 0078 - Addition of GCF WI-103 IMS test case 12.12 | | | | - | | | | | |
| RP-57 RP-121221 0071 - Addition of GCF WI-031 IMS test case 8.13 F 9.4.0 9.5.0 R5s120541 RP-57 RP-121221 0072 - Addition of GCF WI-128 IMS test case 18.1 F 9.4.0 9.5.0 R5s120543 RP-57 RP-121221 0073 - Addition of GCF WI-128 IMS test case 16.1 F 9.4.0 9.5.0 R5s120547 RP-57 RP-121221 0074 - Addition of GCF WI-103 IMS test case 16.1 F 9.4.0 9.5.0 R5s120547 RP-57 RP-121221 0075 - Addition of GCF WI-103 IMS test case 16.2 F 9.4.0 9.5.0 R5s120547 RP-57 RP-121106 0076 - CR to 34.229-3: Add new verified and e-mail agreed TCN test cases in the TC lists in 34.229-3 (prose), Annex A F 9.4.0 9.5.0 - < | | RP-121221 | | E | Addition of GCF WI-031 IMS test case 8.12 | | | | R5s120539 |
| RP-57 RP-121221 0073 - Addition of GCF WI-128 IMS test case 18.2 F 9.4.0 9.5.0 R5s120545 RP-57 RP-121221 0074 - Addition of GCF WI-103 IMS test case 16.1 F 9.4.0 9.5.0 R5s120547 RP-57 RP-121221 0075 - Addition of GCF WI-103 IMS test case 16.2 F 9.4.0 9.5.0 R5s120549 RP-57 RP-121106 0076 - CR to 34.229-3: Add new verified and e-mail agreed TTCN test cases in the TC lists in 34.229-3 (prose), Annex A F 9.4.0 9.5.0 - RP-58 RP-121664 0077 - 34229-3: Routine maintenance and updates F 9.5.0 9.6.0 R5-125120 RP-58 RP-121669 0078 - Addition of GCF WI-103 IMS test case 12.12 B 9.5.0 9.6.0 R5s120605 RP-58 RP-121669 0080 - Addition of GCF WI-103 IMS test case 15.11 B 9.5.0 9.6.0 R5s120609 RP-58 RP-121669 0081 - Addition of GCF WI-103 IMS test case 15.1< | | RP-121221 | 0071 | - | Addition of GCF WI-031 IMS test case 8.13 | | 9.4.0 | 9.5.0 | R5s120541 |
| RP-57 RP-121221 0074 - Addition of GCF WI-103 IMS test case 16.1 F 9.4.0 9.5.0 R5s120547 RP-57 RP-121221 0075 - Addition of GCF WI-103 IMS test case 16.2 F 9.4.0 9.5.0 R5s120549 RP-57 RP-121106 0076 - CR to 34.229-3: Add new verified and e-mail agreed TTCN test cases in the TC lists in 34.229-3 (prose), Annex A F 9.4.0 9.5.0 - RP-58 RP-121664 0077 - 34229-3: Routine maintenance and updates F 9.5.0 9.6.0 R5-125120 RP-58 RP-121669 0078 - Addition of GCF WI-103 IMS test case 12.12 B 9.5.0 9.6.0 R5s120605 RP-58 RP-121669 0079 - Addition of GCF WI-103 IMS test case 12.13 B 9.5.0 9.6.0 R5s120607 RP-58 RP-121669 0080 - Addition of GCF WI-103 IMS test case 15.11 B 9.5.0 9.6.0 R5s120609 RP-58 RP-121669 0081 - IMS TTCN correction F <td></td> <td></td> <td></td> <td>-</td> <td></td> <td></td> <td></td> <td></td> <td></td> | | | | - | | | | | |
| RP-57 RP-121221 0075 - Addition of GCF WI-103 IMS test case 16.2 F 9.4.0 9.5.0 R5s120549 RP-57 RP-121106 0076 - CR to 34.229-3: Add new verified and e-mail agreed TTCN test cases in the TC lists in 34.229-3 (prose), Annex A F 9.4.0 9.5.0 - RP-58 RP-121664 0077 - 34229-3: Routine maintenance and updates F 9.5.0 9.6.0 R5-125120 RP-58 RP-121669 0078 - Addition of GCF WI-103 IMS test case 12.12 B 9.5.0 9.6.0 R5s120605 RP-58 RP-121669 0079 - Addition of GCF WI-103 IMS test case 12.13 B 9.5.0 9.6.0 R5s120607 RP-58 RP-121669 0080 - Addition of GCF WI-103 IMS test case 15.11 B 9.5.0 9.6.0 R5s120607 RP-58 RP-121669 0081 - IMS TTCN correction F 9.5.0 9.6.0 R5s120729 RP-58 RP-121669 0082 - Addition of GCF WI-103 IMS test case 15.12 B </td <td></td> <td></td> <td></td> <td>-</td> <td></td> <td></td> <td></td> <td></td> <td></td> | | | | - | | | | | |
| RP-57 RP-121106 0076 CR to 34.229-3: Add new verified and e-mail agreed TTCN test cases in the TC lists in 34.229-3 (prose), Annex A F 9.4.0 9.5.0 - RP-58 RP-121664 0077 - 34229-3: Routine maintenance and updates F 9.5.0 9.6.0 R5-125120 RP-58 RP-121669 0078 - Addition of GCF WI-103 IMS test case 12.12 B 9.5.0 9.6.0 R5s120605 RP-58 RP-121669 0079 - Addition of GCF WI-103 IMS test case 12.13 B 9.5.0 9.6.0 R5s120607 RP-58 RP-121669 0080 - Addition of GCF WI-103 IMS test case 15.11 B 9.5.0 9.6.0 R5s120609 RP-58 RP-121669 0081 - IMS TTCN correction F 9.5.0 9.6.0 R5s120729 RP-58 RP-121669 0082 - Addition of GCF WI-103 IMS test case 15.8 B 9.5.0 9.6.0 R5s120730 RP-58 RP-121669 0083 - Addition of GCF WI-103 IMS test case 15.27 B 9.5 | | | | - | | | | | |
| RP-58 RP-121664 0077 - 34229-3: Routine maintenance and updates F 9.5.0 9.6.0 R5-125120 RP-58 RP-121669 0078 - Addition of GCF WI-103 IMS test case 12.12 B 9.5.0 9.6.0 R5s120605 RP-58 RP-121669 0079 - Addition of GCF WI-103 IMS test case 12.13 B 9.5.0 9.6.0 R5s120607 RP-58 RP-121669 0080 - Addition of GCF WI-103 IMS test case 15.11 B 9.5.0 9.6.0 R5s120609 RP-58 RP-121669 0081 - IMS TTCN correction F 9.5.0 9.6.0 R5s120729 RP-58 RP-121669 0082 - Addition of GCF WI-103 IMS test case 15.8 B 9.5.0 9.6.0 R5s120730 RP-58 RP-121669 0083 - Addition of GCF WI-103 IMS test case 15.12 B 9.5.0 9.6.0 R5s120732 RP-58 RP-121669 0084 - Addition of GCF WI-103 IMS test case 15.27 B 9.5.0 9.6.0 <td< td=""><td></td><td></td><td></td><td>-</td><td>CR to 34.229-3: Add new verified and e-mail agreed TTCN test cases in the TC lists in 34.229-3 (prose),</td><td></td><td></td><td></td><td>-</td></td<> | | | | - | CR to 34.229-3: Add new verified and e-mail agreed TTCN test cases in the TC lists in 34.229-3 (prose), | | | | - |
| RP-58 RP-121669 0078 - Addition of GCF WI-103 IMS test case 12.12 B 9.5.0 9.6.0 R5s120605 RP-58 RP-121669 0079 - Addition of GCF WI-103 IMS test case 12.13 B 9.5.0 9.6.0 R5s120607 RP-58 RP-121669 0080 - Addition of GCF WI-103 IMS test case 15.11 B 9.5.0 9.6.0 R5s120609 RP-58 RP-121669 0081 - IMS TTCN correction F 9.5.0 9.6.0 R5s120729 RP-58 RP-121669 0082 - Addition of GCF WI-103 IMS test case 15.8 B 9.5.0 9.6.0 R5s120730 RP-58 RP-121669 0083 - Addition of GCF WI-103 IMS test case 15.12 B 9.5.0 9.6.0 R5s120732 RP-58 RP-121669 0084 - Addition of GCF WI-103 IMS test case 15.27 B 9.5.0 9.6.0 R5s120733 RP-58 RP-121669 0085 - Addition of GCF WI-103 IMS test case 15.28 B 9.5.0 9.6.0 < | DD 50 | DD 404004 | 0077 | | | _ | 0.5.0 | 0.6.0 | DE 405400 |
| RP-58 RP-121669 0079 - Addition of GCF WI-103 IMS test case 12.13 B 9.5.0 9.6.0 R5s120607 RP-58 RP-121669 0080 - Addition of GCF WI-103 IMS test case 15.11 B 9.5.0 9.6.0 R5s120609 RP-58 RP-121669 0081 - IMS TTCN correction F 9.5.0 9.6.0 R5s120729 RP-58 RP-121669 0082 - Addition of GCF WI-103 IMS test case 15.8 B 9.5.0 9.6.0 R5s120730 RP-58 RP-121669 0083 - Addition of GCF WI-103 IMS test case 15.12 B 9.5.0 9.6.0 R5s120732 RP-58 RP-121669 0084 - Addition of GCF WI-103 IMS test case 15.27 B 9.5.0 9.6.0 R5s120733 RP-58 RP-121669 0085 - Addition of GCF WI-103 IMS test case 15.28 B 9.5.0 9.6.0 R5s120736 RP-58 RP-121668 0086 - CR to 34.229-3: Add new verified and e-mail agreed TTCN test cases in the TC lists in 34.229-3 (prose), Annex A | | | | <u> </u> | | | | | |
| RP-58 RP-121669 0080 - Addition of GCF WI-103 IMS test case 15.11 B 9.5.0 9.6.0 R5s120609 RP-58 RP-121669 0081 - IMS TTCN correction F 9.5.0 9.6.0 R5s120729 RP-58 RP-121669 0082 - Addition of GCF WI-103 IMS test case 15.8 B 9.5.0 9.6.0 R5s120730 RP-58 RP-121669 0083 - Addition of GCF WI-103 IMS test case 15.12 B 9.5.0 9.6.0 R5s120732 RP-58 RP-121669 0084 - Addition of GCF WI-103 IMS test case 15.27 B 9.5.0 9.6.0 R5s120733 RP-58 RP-121669 0085 - Addition of GCF WI-103 IMS test case 15.28 B 9.5.0 9.6.0 R5s120736 RP-58 RP-121668 0086 - CR to 34.229-3: Add new verified and e-mail agreed TTCN test cases in the TC lists in 34.229-3 (prose), Annex A F 9.5.0 9.6.0 - RP-59 RP-130145 0087 - 34229-3: Routine maintenance and updates F </td <td></td> <td></td> <td></td> <td>Ε</td> <td></td> <td></td> <td></td> <td></td> <td></td> | | | | Ε | | | | | |
| RP-58 RP-121669 0081 - IMS TTCN correction F 9.5.0 9.6.0 R5s120729 RP-58 RP-121669 0082 - Addition of GCF WI-103 IMS test case 15.8 B 9.5.0 9.6.0 R5s120730 RP-58 RP-121669 0083 - Addition of GCF WI-103 IMS test case 15.12 B 9.5.0 9.6.0 R5s120732 RP-58 RP-121669 0084 - Addition of GCF WI-103 IMS test case 15.27 B 9.5.0 9.6.0 R5s120733 RP-58 RP-121669 0085 - Addition of GCF WI-103 IMS test case 15.28 B 9.5.0 9.6.0 R5s120736 RP-58 RP-121668 0086 - CR to 34.229-3: Add new verified and e-mail agreed TTCN test cases in the TC lists in 34.229-3 (prose), Annex A F 9.5.0 9.6.0 - RP-59 RP-130145 0087 - 34229-3: Routine maintenance and updates F 9.6.0 9.7.0 R5-130198 | | | | - | | | | | |
| RP-58 RP-121669 0082 - Addition of GCF WI-103 IMS test case 15.8 B 9.5.0 9.6.0 R5s120730 RP-58 RP-121669 0083 - Addition of GCF WI-103 IMS test case 15.12 B 9.5.0 9.6.0 R5s120732 RP-58 RP-121669 0084 - Addition of GCF WI-103 IMS test case 15.27 B 9.5.0 9.6.0 R5s120733 RP-58 RP-121669 0085 - Addition of GCF WI-103 IMS test case 15.28 B 9.5.0 9.6.0 R5s120736 RP-58 RP-121668 0086 - CR to 34.229-3: Add new verified and e-mail agreed TTCN test cases in the TC lists in 34.229-3 (prose), Annex A F 9.5.0 9.6.0 - RP-59 RP-130145 0087 - 34229-3: Routine maintenance and updates F 9.6.0 9.7.0 R5-130198 | | | | <u> -</u> | | | | | |
| RP-58 RP-121669 0083 - Addition of GCF WI-103 IMS test case 15.12 B 9.5.0 9.6.0 R5s120732 RP-58 RP-121669 0084 - Addition of GCF WI-103 IMS test case 15.27 B 9.5.0 9.6.0 R5s120733 RP-58 RP-121669 0085 - Addition of GCF WI-103 IMS test case 15.28 B 9.5.0 9.6.0 R5s120736 RP-58 RP-121668 0086 - CR to 34.229-3: Add new verified and e-mail agreed TTCN test cases in the TC lists in 34.229-3 (prose), Annex A F 9.5.0 9.6.0 - RP-59 RP-130145 0087 - 34229-3: Routine maintenance and updates F 9.6.0 9.7.0 R5-130198 | | RP-121669 | | - | | | | | |
| RP-58 RP-121669 0084 - Addition of GCF WI-103 IMS test case 15.27 B 9.5.0 9.6.0 R5s120733 RP-58 RP-121669 0085 - Addition of GCF WI-103 IMS test case 15.28 B 9.5.0 9.6.0 R5s120736 RP-58 RP-121668 0086 - CR to 34.229-3: Add new verified and e-mail agreed TTCN test cases in the TC lists in 34.229-3 (prose), Annex A F 9.5.0 9.6.0 - RP-59 RP-130145 0087 - 34229-3: Routine maintenance and updates F 9.6.0 9.7.0 R5-130198 | RP-58 | RP-121669 | 0083 | - | Addition of GCF WI-103 IMS test case 15.12 | | | 9.6.0 | |
| RP-58 RP-121668 0086 - CR to 34.229-3: Add new verified and e-mail agreed TTCN test cases in the TC lists in 34.229-3 (prose), Annex A F 9.5.0 9.6.0 - RP-59 RP-130145 0087 - 34229-3: Routine maintenance and updates F 9.6.0 9.7.0 R5-130198 | | RP-121669 | | - | Addition of GCF WI-103 IMS test case 15.27 | | | | R5s120733 |
| TTCN test cases in the TC lists in 34.229-3 (prose), Annex A RP-59 RP-130145 0087 - 34229-3: Routine maintenance and updates F 9.6.0 9.7.0 R5-130198 | | | | - | | | | | R5s120736 |
| RP-59 RP-130145 0087 - 34229-3: Routine maintenance and updates F 9.6.0 9.7.0 R5-130198 | RP-58 | RP-121668 | 0086 | - | TTCN test cases in the TC lists in 34.229-3 (prose), | F | 9.5.0 | 9.6.0 | - |
| | RP-59 | RP-130145 | 0087 | <u> -</u> | | F | 9.6.0 | 9.7.0 | R5-130198 |
| | | | | Ŀ | | | | | |

| Meet- ing | TSG doc | CR | Rev | Subject | Cat | Old vers | New vers | WG doc |
|--------------|-----------|------|-----|--|-----|-------------|-------------|-----------|
| | | | | LTE with 36.523-3 test model | | | | |
| RP-59 | RP-130150 | 0089 | - | Corrections for IMS test cases with 34.229-3 test model | F | 9.6.0 | 9.7.0 | R5s120907 |
| RP-59 | RP-130150 | 0090 | - | Re-verification of IMS Registration test case 8.4 over LTE with new 34.229-3 test model | F | 9.6.0 | 9.7.0 | R5s120945 |
| RP-59 | RP-130150 | 0091 | - | Re-verification of IMS Authentication test case 9.1 over LTE with the new 34.229-3 test model | F | 9.6.0 | 9.7.0 | R5s120947 |
| RP-59 | RP-130150 | 0092 | - | Corrections to IMS_36523_IWD_12wk48 test suite | F | 9.6.0 | 9.7.0 | R5s130011 |
| RP-59 | RP-130150 | 0093 | - | Corrections for IMS TC 8.1 regarding Ipv6 privacy | F | 9.6.0 | 9.7.0 | R5s130049 |
| RP-59 | RP-130149 | 0094 | - | CR to 34.229-3 (prose) update to v970 | F | 9.6.0 | 9.7.0 | - |
| RP-60 | RP-130611 | 0095 | - | 34229-3: Routine maintenance and updates | F | 9.7.0 | 9.8.0 | R5-131140 |
| RP-60 | RP-130617 | 0096 | - | Corrections to feature parameter in MT call invitation | F | 9.7.0 | 9.8.0 | R5s130109 |
| RP-60 | RP-130617 | 0097 | - | Re-verification of IMS Registration (IPSec) test case 8.1 over LTE with 36.523-3 test model | F | 9.7.0 | 9.8.0 | R5s130133 |
| RP-60 | RP-130617 | 0098 | - | Re-verification of IMS test case 8.3 over LTE with 36.523-3 test model | F | 9.7.0 | 9.8.0 | R5s130181 |
| RP-60 | RP-130617 | 0099 | - | Re-verification of IMS SMS test case 18.2 over LTE with 36.523-3 test model | F | 9.7.0 | 9.8.0 | R5s130183 |
| RP-60 | RP-130617 | 0100 | - | Corrections for IMS TC 8.1 | F | 9.7.0 | 9.8.0 | R5s130187 |
| RP-60 | RP-130617 | 0101 | - | Re-verification of IMS Registration test case 8.2 over LTE with 34.229-3 test model | F | 9.7.0 | 9.8.0 | R5s130233 |
| RP-60 | RP-130617 | 0102 | - | Re-verification of IMS SMS test case 18.1 over LTE with 34.229-3 test model | F | 9.7.0 | 9.8.0 | R5s130235 |
| RP-60 | RP-130617 | 0103 | - | Correction to SIP template cr_FromWithTag | F | 9.7.0 | 9.8.0 | R5s130256 |
| RP-60 | RP-130617 | 0104 | - | Re-verification of IMS Authentication test case 9.2 over LTE with 34.229-3 test model | F | 9.7.0 | 9.8.0 | R5s130264 |
| RP-60 | RP-130617 | 0105 | - | Re-verification of IMS Notification test case 11.2 over LTE with 34.229-3 test model | F | 9.7.0 | 9.8.0 | R5s130266 |
| RP-60 | RP-130617 | 0106 | - | Corrections for IMS Registration TC 8.3 over LTE with 34.229-3 test model | F | 9.7.0 | 9.8.0 | R5s130274 |
| RP-60 | RP-130617 | 0107 | - | Re-verification of IMS Subscription test case 10.1 over LTE with 34.229-3 test model | F | 9.7.0 | 9.8.0 | R5s130294 |
| RP-60 | RP-130617 | 0108 | - | Re-verification of IMS Registration test case 11.1 over LTE with 34.229-3 test model | F | 9.7.0 | 9.8.0 | R5s130296 |
| RP-60 | RP-130617 | 0109 | - | Re-verification of IMS Call Control test case 12.12 over LTE with 36.523-3 test model | F | 9.7.0 | 9.8.0 | R5s130333 |
| RP-61 | RP-131107 | 0111 | - | Correction to EPS ATTACH procedure to enable IMS Registration via NAS signalling | F | 9.8.0 | 9.9.0 | R5s130383 |
| RP-61 | RP-131107 | 0112 | - | Correction to IMS test cases 8.1, 8.2, 8.3 and 8.4 | F | 9.8.0 | 9.9.0 | R5s130454 |
| RP-61 | RP-131107 | 0113 | - | Correction to encoding rules to be used for Reginfo_Type | F | 9.8.0 | 9.9.0 | R5s130474 |
| RP-61 | RP-131107 | 0114 | - | Corrections for IMS call control test case 12.12 | F | 9.8.0 | 9.9.0 | R5s130497 |
| RP-61 | RP-131107 | 0115 | - | Addition of GCF WI-154/ee1 IMS Emergency Call over EPS test case 19.1.2 (using TS 36.523-3 test model) | В | 9.8.0 | 9.9.0 | R5s130508 |
| RP-61 | RP-131107 | 0116 | - | Re-verification for IMS TC 12.13 over LTE with 34.229-3 test model | F | 9.8.0 | 9.9.0 | R5s130510 |
| RP-61 | RP-131107 | 0117 | - | Corrections to GCF WI-128 SMS over IMS Testcase 18.1 | F | 9.8.0 | 9.9.0 | R5s130514 |
| RP-61 | RP-131107 | 0118 | - | Correction of IMS test case 9.2 over LTE with 34.229-3 test model | F | 9.8.0 | 9.9.0 | R5s130573 |

| Meet- | TSG doc | CR | Rev | Subject | Cat | Old vers | New vers | WG doc |
|-------|-----------|------|-----|---|-----|-------------|-------------|-----------|
| RP-61 | RP-131107 | 0119 | - | Verification for IMS test case 12.2 over LTE with 34.229-1 test model | В | 9.8.0 | 9.9.0 | R5s130580 |
| RP-61 | RP-131107 | 0120 | - | Correction of IMS test case 12.12 over LTE with 34.229-3 test model | F | 9.8.0 | 9.9.0 | R5s130586 |
| RP-61 | RP-131106 | 0121 | - | CR to 34.229-3: Add new verified and e-mail agreed TTCN test cases in the TC lists in 34.229-3 (prose), Annex A | F | 9.8.0 | 9.9.0 | RP-131106 |
| RP-61 | RP-131100 | 0110 | - | 34229-3: Routine maintenance and updates | F | 9.9.0 | 10.0.0 | R5-133632 |
| RP-62 | RP-131875 | 0122 | - | Splitting 34.229-3 | F | 10.0.0 | 10.1.0 | R5-134070 |
| RP-62 | RP-132006 | 0123 | - | 34229-3: Routine maintenance and updates for multitesters model | F | 10.0.0 | 10.1.0 | R5-134290 |
| RP-62 | RP-131868 | 0125 | - | Regression CR for IMS registration procedure in ATS_13wk35 | F | 10.0.0 | 10.1.0 | R5s130681 |
| RP-62 | RP-131868 | 0126 | - | Correction of IMS test case 12.2 over LTE with 34.229-3 test model | F | 10.0.0 | 10.1.0 | R5s130684 |
| RP-62 | RP-131868 | 0127 | - | Correction of IMS test case 12.13 over LTE with 34.229-3 test model | F | 10.0.0 | 10.1.0 | R5s130685 |
| RP-62 | RP-131868 | 0128 | - | Correction of IMS test case 8.1 over LTE with 34.229-3 test model | F | 10.0.0 | 10.1.0 | R5s130710 |
| RP-62 | RP-131868 | 0129 | - | Correction to usage of constant tsc_IMS_AcceptContactValue | F | 10.0.0 | 10.1.0 | R5s130738 |
| RP-62 | RP-131868 | 0130 | - | Correction to SMS over IMS test case 18.2 | F | 10.0.0 | 10.1.0 | R5s130739 |
| RP-62 | RP-131868 | 0131 | - | Corrections to IMS codec selection test case 16.1 and 16.2 | F | 10.0.0 | 10.1.0 | R5s130742 |
| RP-62 | RP-131868 | 0132 | - | Correction to IMS Call Control test case 12.13 | F | 10.0.0 | 10.1.0 | R5s130743 |
| RP-62 | RP-131868 | 0133 | - | Correction to GCF WI-154 IMS Emergency Call over EPS test case 19.1.2 | F | 10.0.0 | 10.1.0 | R5s130760 |
| RP-62 | RP-131868 | 0134 | - | Corrections to number of channels in SDP in 34.229-3 test model | F | 10.0.0 | 10.1.0 | R5s130798 |
| RP-62 | RP-131867 | 0135 | - | CR to 34.229-3 (prose) update to v10.1.0 | F | 10.0.0 | 10.1.0 | RP-131867 |
| RP-63 | R5-140319 | 0136 | - | Routine maintenance and updates | F | 10.1.0 | 10.2.0 | R5-140931 |
| RP-63 | RP-140313 | 0137 | - | Addition of GCF WI-171 MTSI MO speech call / SSAC test case 12.18 (using TS 36.523-3 test model) | В | 10.1.0 | 10.2.0 | R5s130766 |
| RP-63 | RP-140313 | 0138 | - | Addition of GCF WI-171 IMS Emergency call / SSAC test case 12.20 (using TS 36.523-3 test model) | В | 10.1.0 | 10.2.0 | R5s130768 |
| RP-63 | RP-140313 | 0139 | - | Re-verification of MTSI MT speech call test case 12.13 (using TS 36.523-3 test model) | F | 10.1.0 | 10.2.0 | R5s130770 |
| RP-63 | RP-140313 | 0140 | - | Re-verification of IMS test case 16.1 over LTE with 34.229-3 test model | F | 10.1.0 | 10.2.0 | R5s130808 |
| RP-63 | RP-140313 | 0141 | - | Re-verification of IMS test case 16.2 over LTE with 34.229-3 test model | F | 10.1.0 | 10.2.0 | R5s130810 |
| RP-63 | RP-140313 | 0142 | - | Correction of IMS test case 12.2 over LTE with 34.229-3 test model | F | 10.1.0 | 10.2.0 | R5s130885 |
| RP-63 | RP-140313 | 0143 | - | Correction of IMS test case 12.12 over LTE with 34.229-3 test model | F | 10.1.0 | 10.2.0 | R5s130894 |
| RP-63 | RP-140313 | 0144 | - | Corrections for common IMS functions | F | 10.1.0 | 10.2.0 | R5s130897 |
| RP-63 | RP-140313 | 0145 | - | Correction to GCF WI-103 IMS test case 11.2 with | F | 10.1.0 | 10.2.0 | R5s130900 |

| Meet- | TSG doc | CR | Rev | Subject | Cat | Old vers | New vers | WG doc |
|-------|-----------|------|-----|---|-----|-------------|-------------|-----------|
| 9 | | | | 36.523-3 Test Model | | 10.0 | 70.0 | |
| RP-63 | RP-140313 | 0146 | - | Correction to Postamble handling for IMS deregistration procedure | F | 10.1.0 | 10.2.0 | R5s130901 |
| RP-63 | RP-140313 | 0147 | - | Correction to fl_EUTRA_IPCAN_ActivateDedicatedEpsBearer_Spe echCall | F | 10.1.0 | 10.2.0 | R5s130916 |
| RP-63 | RP-140313 | 0148 | - | Correction of IMS test case 8.10 over LTE with 34.229-3 test model | F | 10.1.0 | 10.2.0 | R5s130925 |
| RP-63 | RP-140313 | 0149 | - | Addition of GCF WI-103 IMS MTSI test case 16.3 over 36.523-3 Test Model | В | 10.1.0 | 10.2.0 | R5s130956 |
| RP-63 | RP-140313 | 0150 | - | Addition of GCF WI-103 IMS MTSI test case 16.4 over 36.523-3 Test Model | В | 10.1.0 | 10.2.0 | R5s130958 |
| RP-63 | RP-140313 | 0151 | - | Correction to GCF WI-154 IMS Emergency Call over EPS test case 19.1.2 | F | 10.1.0 | 10.2.0 | R5s130978 |
| RP-63 | RP-140313 | 0152 | - | Correction to GCF WI-103 IMS MTSI test case 12.13 | F | 10.1.0 | 10.2.0 | R5s130985 |
| RP-63 | RP-140313 | 0153 | - | Addition of GCF WI-154 IMS Emergency Call over EPS test case 19.4.1 | В | 10.1.0 | 10.2.0 | R5s130990 |
| RP-63 | RP-140313 | 0154 | - | Correction to GCF WI-103 IMS MTSI test case 9.2 | F | 10.1.0 | 10.2.0 | R5s131004 |
| RP-63 | RP-140313 | 0155 | - | Correction to GCF WI-103 IMS MTSI test case 11.2 | F | 10.1.0 | 10.2.0 | R5s131040 |
| RP-63 | RP-140313 | 0156 | - | Correction of common altsteps in IMS PTC for test case 11.2 | F | 10.1.0 | 10.2.0 | R5s140003 |
| RP-63 | RP-140313 | 0157 | - | Correction for IMS common function f_IMS_InviteRequest_MessageHeaderRX() | F | 10.1.0 | 10.2.0 | R5s140005 |
| RP-63 | RP-140313 | 0158 | - | Re-verification of IMS test case 15.11 over LTE with 34.229-3 test model | F | 10.1.0 | 10.2.0 | R5s140017 |
| RP-63 | RP-140312 | 0159 | - | CR to 34.229-3: Add new verified and e-mail agreed TTCN test cases in the TC lists in 34.229-3 (prose), Annex A | F | 10.1.0 | 10.2.0 | RP-140312 |
| RP-64 | RP-140812 | 0160 | - | Routine maintenance and updates | F | 10.2.0 | 10.3.0 | R5-142961 |
| RP-64 | RP-140822 | 0161 | - | Addition of GCF WI-154 IMS Emergency Call over EPS test case 19.5.6 (with TS 36.523-3 test model) | F | 10.2.0 | 10.3.0 | R5s140037 |
| RP-64 | RP-140822 | 0162 | - | Addition of GCF WI-154 IMS Emergency Call over EPS test case 19.5.10 (with TS 36.523-3 test model) | F | 10.2.0 | 10.3.0 | R5s140039 |
| RP-64 | RP-140822 | 0163 | - | Addition of GCF WI-103 IMS MTSI Testcase 15.28 with 36.523-3 Test Model | F | 10.2.0 | 10.3.0 | R5s140092 |
| RP-64 | RP-140822 | 0164 | - | Re-verification of GCF WI-103 IMS MTSI Testcase 15.11 over 36.523-3 Test Model | F | 10.2.0 | 10.3.0 | R5s140121 |
| RP-64 | RP-140822 | 0165 | - | Addition of GCF WI-154 IMS Emergency Testcase 19.4.5 with 36.523-3 Test Model | F | 10.2.0 | 10.3.0 | R5s140123 |
| RP-64 | RP-140822 | 0166 | - | Correction of GCF WI-103 IMS MTSI Testcase 9.1 | F | 10.2.0 | 10.3.0 | R5s140136 |
| RP-64 | RP-140822 | 0167 | - | Correction to GCF WI-171 IMS SSAC testcase 12.20 | F | 10.2.0 | 10.3.0 | R5s140137 |
| RP-64 | RP-140822 | 0168 | - | Correction of P-Preferred-Service and P-Asserted- Service usage over LTE with 34.229-3 test model | F | 10.2.0 | 10.3.0 | R5s140141 |
| RP-64 | RP-140822 | 0169 | - | Addition of GCF WI-103 IMS MO Call test case 12.2a (with both TS 36.523-3 and TS 34.229-3 test model) | F | 10.2.0 | 10.3.0 | R5s140142 |
| RP-64 | RP-140822 | 0170 | - | Correction to GCF WI-171 SSAC testcase 12.20 | F | 10.2.0 | 10.3.0 | R5s140168 |

| Meet- ing | TSG doc | CR | Rev | Subject | Cat | Old vers | New vers | WG doc |
|--------------|-----------|------|-----|---|-----|-------------|-------------|-----------|
| RP-64 | RP-140822 | 0171 | - | Correction to GCF WI-154 IMS Emergency Call testcase 19.1.2 | F | 10.2.0 | 10.3.0 | R5s140171 |
| RP-64 | RP-140822 | 0172 | - | Correction to GCF WI-154 IMS Emergency Call testcase 19.5.6 | F | 10.2.0 | 10.3.0 | R5s140172 |
| RP-64 | RP-140822 | 0173 | - | Correction to IMS function f_IMS_Dialog_SetRemoteTag | F | 10.2.0 | 10.3.0 | R5s140173 |
| RP-64 | RP-140822 | 0174 | - | Correction of IMS function f_IMS_PTC_ImsInfo_DialogInit | F | 10.2.0 | 10.3.0 | R5s140174 |
| RP-64 | RP-140822 | 0175 | = | Correction to Postamble Procedure for IMS Testcases | F | 10.2.0 | 10.3.0 | R5s140175 |
| RP-64 | RP-140822 | 0176 | = | Correction to GCF WI-103 IMS MTSI Testcases 9.1 and 9.2 | F | 10.2.0 | 10.3.0 | R5s140176 |
| RP-64 | RP-140822 | 0177 | - | Correction of GCF WI-103 IMS MTSI Testcase 15.28 | F | 10.2.0 | 10.3.0 | R5s140178 |
| RP-64 | RP-140822 | 0178 | - | Correction to IMS Route header in ACK sent by SS | F | 10.2.0 | 10.3.0 | R5s140194 |
| RP-64 | RP-140822 | 0179 | - | Correction to 183 Session Progress Message | F | 10.2.0 | 10.3.0 | R5s140204 |
| RP-64 | RP-140822 | 0180 | - | Correction to TCP Connection Close procedure for IMS Testcases | F | 10.2.0 | 10.3.0 | R5s140219 |
| RP-64 | RP-140822 | 0181 | - | Correction to IMS Main PTC Function | F | 10.2.0 | 10.3.0 | R5s140243 |
| RP-64 | RP-140822 | 0182 | = | Correction of f_IMS_AckRequest_MessageHeaderRX() | F | 10.2.0 | 10.3.0 | R5s140264 |
| RP-64 | RP-140822 | 0183 | - | Correction of f_IPCAN_StartProcedure | F | 10.2.0 | 10.3.0 | R5s140265 |
| RP-64 | RP-140822 | 0184 | - | spi and port values | F | 10.2.0 | 10.3.0 | R5s140266 |
| RP-64 | RP-140822 | 0185 | = | Correction to GCF WI-103 IMS Call Control Test Case 11.2 | F | 10.2.0 | 10.3.0 | R5s140303 |
| RP-64 | RP-140822 | 0186 | - | Correction to SMS over IMS Test Case 18.1 | F | 10.2.0 | 10.3.0 | R5s140304 |
| RP-64 | RP-140822 | 0187 | - | Re-verification of IMS test case 15.27 over LTE with 34.229-3 test model | F | 10.2.0 | 10.3.0 | R5s140307 |
| RP-64 | RP-140822 | 0188 | = | Re-verification of IMS test case 15.12 over LTE with 34.229-3 test model | F | 10.2.0 | 10.3.0 | R5s140324 |
| RP-64 | RP-140822 | 0189 | = | Addition of GCF WI-154 IMS Emergency Call over EPS test case 19.5.9 with 36.523-3 test model | F | 10.2.0 | 10.3.0 | R5s140329 |
| RP-64 | RP-140822 | 0190 | - | Correction to GCF WI-171 IMS SSAC Testcase 12.18 | F | 10.2.0 | 10.3.0 | R5s140334 |
| RP-64 | RP-140822 | 0191 | - | Correction to WI-103 IMS MTSI Testcase 11.1 | F | 10.2.0 | 10.3.0 | R5s140342 |
| RP-64 | RP-140822 | 0192 | = | Correction for checking of via Header in IMS response messages | F | 10.2.0 | 10.3.0 | R5s140350 |
| RP-64 | RP-140822 | 0193 | - | Verification of IMS test case 8.11 over LTE with 34.229-3 test model | F | 10.2.0 | 10.3.0 | R5s140356 |
| RP-64 | RP-140822 | 0194 | - | Corrections for IMS MO call setup sequence with preconditions | F | 10.2.0 | 10.3.0 | R5s140359 |
| RP-64 | RP-140822 | 0195 | - | Corrections to de-registration procedure | F | 10.2.0 | 10.3.0 | R5s140428 |
| RP-64 | RP-140821 | 0196 | - | CR to 34.229-3: Add new verified and e-mail agreed TTCN test cases in the TC lists in 34.229-3 (prose), Annex A | F | 10.2.0 | 10.3.0 | RP-140821 |
| RP-65 | RP-141571 | 0197 | - | Routine maintenance and updates | F | 10.3.0 | 10.4.0 | R5-144747 |
| RP-65 | RP-141580 | 0217 | - | CR to 34.229-3: Add new verified and e-mail agreed TTCN test cases in the TC lists in 34.229-3 (prose), | F | 10.3.0 | 10.4.0 | - |

| Meet- | TSG doc | CR | Rev | Subject | Cat | Old vers | New vers | WG doc |
|-------|-----------|------|-----|---|-----|-------------|-------------|-----------|
| 9 | | | | Annex A | | 10.0 | 10.0 | |
| RP-65 | RP-141581 | 0198 | - | Addition of GCF WI-154 IMS Emergency Call test case 19.5.7 with TS 36.523-3 test model | В | 10.3.0 | 10.4.0 | R5s140338 |
| RP-65 | RP-141581 | 0199 | - | Correction for IMS Codec Selection test cases 16.3 and 16.4 | F | 10.3.0 | 10.4.0 | R5s140360 |
| RP-65 | RP-141581 | 0200 | - | IMS test case 18.1 for GIBA | F | 10.3.0 | 10.4.0 | R5s140469 |
| RP-65 | RP-141581 | 0201 | - | Addition of GCF WI-154 IMS Emergency Call test case 19.3.3 with TS 36.523-3 test model | В | 10.3.0 | 10.4.0 | R5s140490 |
| RP-65 | RP-141581 | 0202 | - | Correction to IMS function f_IMS_MTCallSetup_SendPRACK_ReceiveOK. | F | 10.3.0 | 10.4.0 | R5s140551 |
| RP-65 | RP-141581 | 0203 | - | Correction to GCF WI-103 IMS MTSI test case 11.2. | F | 10.3.0 | 10.4.0 | R5s140561 |
| RP-65 | RP-141581 | 0204 | - | Regression CR for IMS modules in ATS_14wk24 | F | 10.3.0 | 10.4.0 | R5s140565 |
| RP-65 | RP-141581 | 0205 | - | Corrections for IMS Codec Selection test cases 16.3 and 16.4 | F | 10.3.0 | 10.4.0 | R5s140567 |
| RP-65 | RP-141581 | 0206 | - | Correction to GCF WI-103 IMS test case 15.12 | F | 10.3.0 | 10.4.0 | R5s140571 |
| RP-65 | RP-141581 | 0207 | - | Correction of IMS SSAC Testcases 12.18, 12.19, 12.20, 12.18a, 12.19a and 12.20a | F | 10.3.0 | 10.4.0 | R5s140577 |
| RP-65 | RP-141581 | 0208 | - | Re-verification of GCF WI-103 IMS Codec Selecting test case 16.2 with 36.523-3 test model | F | 10.3.0 | 10.4.0 | R5s140580 |
| RP-65 | RP-141581 | 0209 | - | Corrections to IMS test case 15.11 | F | 10.3.0 | 10.4.0 | R5s140602 |
| RP-65 | RP-141581 | 0210 | - | Correction to IMS test case 15.27 | F | 10.3.0 | 10.4.0 | R5s140606 |
| RP-65 | RP-141581 | 0211 | - | Re-verification of IMS test case 15.8 over LTE with 34.229-3 test model | F | 10.3.0 | 10.4.0 | R5s140621 |
| RP-65 | RP-141581 | 0212 | - | Correction to IMS test case 16.2 | F | 10.3.0 | 10.4.0 | R5s140646 |
| RP-65 | RP-141581 | 0213 | - | Correction to GCF WI-154 IMS Emergency Call Testcase 19.5.7 | F | 10.3.0 | 10.4.0 | R5s140647 |
| RP-65 | RP-141581 | 0214 | - | Correction to ContactIE and UL Grant to IMS messages | F | 10.3.0 | 10.4.0 | R5s140676 |
| RP-65 | RP-141581 | 0215 | - | Bandwidth values for TCs 16.2, 16.3, and 16.4 | F | 10.3.0 | 10.4.0 | R5s140678 |
| RP-65 | RP-141581 | 0216 | - | Correction to Socket Handling during IMS registration procedure | F | 10.3.0 | 10.4.0 | R5s140713 |
| RP-66 | RP-142054 | 0218 | - | Routine maintenance and updates | F | 10.4.0 | 10.5.0 | R5-145191 |
| RP-66 | RP-142064 | 0219 | - | Correction of IMS test case 8.2 over LTE | F | 10.4.0 | 10.5.0 | R5s140779 |
| RP-66 | RP-142064 | 0220 | - | Correction of IMS test case 12.2a | F | 10.4.0 | 10.5.0 | R5s140780 |
| RP-66 | RP-142064 | 0221 | - | Correction to IMS Emergency Call test case 19.4.5 | F | 10.4.0 | 10.5.0 | R5s140786 |
| RP-66 | RP-142064 | 0222 | - | Addition of GCF WI-154 IMS emergency call testcase 19.1.3 over 36.523-3 Test Model | F | 10.4.0 | 10.5.0 | R5s140788 |
| RP-66 | RP-142064 | 0223 | - | Correction to IMS Emergency Call test case 19.5.7 | F | 10.4.0 | 10.5.0 | R5s140791 |
| RP-66 | RP-142064 | 0224 | - | Correction to GCF WI-103 IMS testcase 11.2 | F | 10.4.0 | 10.5.0 | R5s140801 |
| RP-66 | RP-142064 | 0225 | - | Correction to IMS test case 12.2a on branch parameter | F | 10.4.0 | 10.5.0 | R5s140802 |
| RP-66 | RP-142064 | 0226 | - | Correction to GCF WI-103 IMS test case 12.2a | F | 10.4.0 | 10.5.0 | R5s140856 |
| RP-66 | RP-142064 | 0227 | - | Correction to GCF WI-103 IMS test case 15.8 | F | 10.4.0 | 10.5.0 | R5s140905 |

| Meet- | TSG doc | CR | Rev | Subject | Cat | Old vers | New vers | WG doc |
|-------|-----------|------|-----|---|-----|-------------|-------------|-----------|
| RP-66 | RP-142064 | 0228 | - | Correction to WI-154 IMS Emergency Call Testcases 19.5.6 and 19.5.7 | F | 10.4.0 | 10.5.0 | R5s140909 |
| RP-66 | RP-142064 | 0229 | - | Correction of IMS test case 15.11 | F | 10.4.0 | 10.5.0 | R5s140919 |
| RP-66 | RP-142064 | 0230 | - | Corrections for Ipv6 address checking in common IMS functions | F | 10.4.0 | 10.5.0 | R5s140934 |
| RP-66 | RP-142064 | 0231 | - | Correction of IMS test case 18.1 | F | 10.4.0 | 10.5.0 | R5s140968 |
| RP-66 | RP-142064 | 0232 | - | Verification of IMS test case 15.5 | F | 10.4.0 | 10.5.0 | R5s140975 |
| RP-66 | RP-142064 | 0233 | - | Verification of IMS test case 15.7 | F | 10.4.0 | 10.5.0 | R5s140976 |
| RP-66 | RP-142064 | 0234 | - | Verification of IMS test case 15.9 | F | 10.4.0 | 10.5.0 | R5s140977 |
| RP-66 | RP-142064 | 0235 | - | Correction to IMS Emergency Call test case 19.3.3 | F | 10.4.0 | 10.5.0 | R5s140997 |
| RP-66 | RP-142064 | 0236 | - | Correction to GCF WI-103 IMS MTSI test case 15.11 | F | 10.4.0 | 10.5.0 | R5s141020 |
| RP-66 | RP-142064 | 0237 | - | Addition of GCF WI-103 IMS XCAP Supplementary Service Testcase 15.1 over 36.523-3 Test Model | F | 10.4.0 | 10.5.0 | R5s141051 |
| RP-66 | RP-142064 | 0238 | - | Addition of GCF WI-103 XCAP supplementary service Testcase 15.3 over 36.523-3 Test Model | F | 10.4.0 | 10.5.0 | R5s141053 |
| RP-66 | RP-142064 | 0239 | - | Addition of GCF WI-103 XCAP supplementary service Testcase 15.4 over 36.523-3 Test Model | F | 10.4.0 | 10.5.0 | R5s141055 |
| RP-66 | RP-142064 | 0240 | - | Addition of XCAP supplementary service Testcase 15.14 over 36.523-3 Test Model | F | 10.4.0 | 10.5.0 | R5s141113 |
| RP-66 | RP-142064 | 0241 | - | Addition of GCF WI-103 XCAP supplementary service Testcase 15.14a over 36.523-3 Test Model | F | 10.4.0 | 10.5.0 | R5s141115 |
| RP-66 | RP-142064 | 0242 | - | Addidtion of IMS over UTRAN testcase 6.3 to IMS Utran testsuite | F | 10.4.0 | 10.5.0 | R5s141125 |
| RP-66 | RP-142064 | 0243 | - | Re-Verification of IMS over UTRAN testcase 7.1 to IMS Utran testsuite | F | 10.4.0 | 10.5.0 | R5s141127 |
| RP-66 | RP-142064 | 0244 | - | Re-verification of GCF WI-103 IMS XCAP Supplementary Service Testcase 15.5 over 36.523-3 Test Model | F | 10.4.0 | 10.5.0 | R5s141130 |
| RP-66 | RP-142064 | 0245 | - | Re-verification of GCF WI-103 IMS XCAP Supplementary Service Testcase 15.7 over 36.523-3 Test Model | F | 10.4.0 | 10.5.0 | R5s141133 |
| RP-66 | RP-142064 | 0246 | - | Re-verification of GCF WI-103 IMS XCAP Supplementary Service Testcase 15.9 over 36.523-3 Test Model | F | 10.4.0 | 10.5.0 | R5s141135 |
| RP-66 | RP-142064 | 0247 | - | Changes to XML templates | F | 10.4.0 | 10.5.0 | R5s141138 |
| RP-66 | RP-142064 | 0248 | - | Verification of IMS test case 15.2 over LTE with 34.229-4 test model | F | 10.4.0 | 10.5.0 | R5s141140 |
| RP-66 | RP-142064 | 0249 | - | Verification of IMS test case 15.13 over LTE with 34.229-4 test model | F | 10.4.0 | 10.5.0 | R5s141142 |
| RP-66 | RP-142064 | 0250 | - | Correction to GCF WI-103 IMS call control test case 12.2a | F | 10.4.0 | 10.5.0 | R5s141154 |
| RP-66 | RP-142064 | 0251 | - | Addition of GCF WI-103 XCAP supplementary service Testcase 15.10a over 36.523-3 Test Model | F | 10.4.0 | 10.5.0 | R5s141162 |
| RP-66 | RP-142063 | 0252 | - | CR to 34.229-3: Add new verified and e-mail agreed TTCN test cases in the TC lists in 34.229-3 (prose), Annex A | F | 10.4.0 | 10.5.0 | RP-142063 |
| RP-67 | RP-150332 | 0253 | - | Routine maintenance for TS 34.229-3 | F | 10.5.0 | 10.6.0 | R5-150355 |

| Meet- ing | TSG doc | CR | Rev | Subject | Cat | Old vers | New vers | WG doc |
|--------------|-----------|------|-----|---|-----|-------------|-------------|-----------|
| RP-67 | RP-150332 | 0283 | - | CR to 34.229-3: Add new verified and e-mail agreed TTCN test cases in the TC lists in 34.229-3 (prose), Annex A | F | 10.5.0 | 10.6.0 | - |
| RP-67 | RP-150333 | 0254 | - | Addition of GCF WI-154 IMS emergency call testcase 19.3.1 over 36.523-3 Test Model | В | 10.5.0 | 10.6.0 | R5s141155 |
| RP-67 | RP-150333 | 0255 | - | Correction of IMS test case 8.1: sip-instance | F | 10.5.0 | 10.6.0 | R5s141212 |
| RP-67 | RP-150333 | 0256 | - | Addition of GCF WI-198 MO MTSI Video Call test case 12.21 (using 36.523-3 test model) | В | 10.5.0 | 10.6.0 | R5s141221 |
| RP-67 | RP-150333 | 0257 | - | Correction to IMS Emergency call test case 19.4.1 | F | 10.5.0 | 10.6.0 | R5s141232 |
| RP-67 | RP-150333 | 0258 | - | Addition of GCF WI-154 Emergency Call Testcase 19.3.4 over 36.523-3 Test Model | В | 10.5.0 | 10.6.0 | R5s141237 |
| RP-67 | RP-150333 | 0259 | - | Correction of o-lines in SDP bodies sent by SS | F | 10.5.0 | 10.6.0 | R5s141244 |
| RP-67 | RP-150333 | 0260 | - | Correction to GCF WI-171 IMS SSAC test case 12.18 | F | 10.5.0 | 10.6.0 | R5s141273 |
| RP-67 | RP-150333 | 0261 | - | Addition of GCF WI-154 IMS Emergency Call test case 19.1.5 | В | 10.5.0 | 10.6.0 | R5s141286 |
| RP-67 | RP-150333 | 0262 | - | Correction to IMS Registration Procedure | F | 10.5.0 | 10.6.0 | R5s141322 |
| RP-67 | RP-150333 | 0263 | - | Correction to GCF WI-103 IMS test case 11.2 | F | 10.5.0 | 10.6.0 | R5s141326 |
| RP-67 | RP-150333 | 0264 | - | Addition of GCF WI-198 MO MTSI Video Call test case 12.22 over 36.523-3 Test Model | В | 10.5.0 | 10.6.0 | R5s141329 |
| RP-67 | RP-150333 | 0265 | - | Correction to GCF WI-154 IMS emergency test case 19.5.6 and 19 5.7 | F | 10.5.0 | 10.6.0 | R5s141335 |
| RP-67 | RP-150333 | 0266 | - | Correction to GCF WI-198 IMS MO Video Call Testcase 12.21 | F | 10.5.0 | 10.6.0 | R5s141336 |
| RP-67 | RP-150333 | 0267 | - | Correction to GCF WI-154 IMS emergency test case 19.3.4 | F | 10.5.0 | 10.6.0 | R5s141337 |
| RP-67 | RP-150333 | 0268 | - | Addition of GCF WI-103 IMS Conference Call Testcase 15.17 over 36.523-3 Test Model | В | 10.5.0 | 10.6.0 | R5s141341 |
| RP-67 | RP-150333 | 0269 | - | Addition of GCF WI-103 IMS Conference Call Testcase 15.19 over 36.523-3 Test Model | В | 10.5.0 | 10.6.0 | R5s141343 |
| RP-67 | RP-150333 | 0270 | - | Correction of IMS TC 15.10a: not-registered condition | F | 10.5.0 | 10.6.0 | R5s141350 |
| RP-67 | RP-150333 | 0271 | - | Correction to GCF WI-103 IMS 15.x XCAP Testcases | F | 10.5.0 | 10.6.0 | R5s141351 |
| RP-67 | RP-150333 | 0272 | - | Correction of XCAP TCs on usage of str2oct | F | 10.5.0 | 10.6.0 | R5s141353 |
| RP-67 | RP-150333 | 0273 | - | Correction of IMS Emergency Call testcase 19.4.5 | F | 10.5.0 | 10.6.0 | R5s141370 |
| RP-67 | RP-150333 | 0274 | - | Correction of IMS SSAC Testcases 12.18, 12.19, 12.20, 12.18a, 12.19a and 12.20a | F | 10.5.0 | 10.6.0 | R5s141381 |
| RP-67 | RP-150333 | 0275 | - | Correction of prefix to XCAP Root Uri | F | 10.5.0 | 10.6.0 | R5s150030 |
| RP-67 | RP-150333 | 0276 | - | Correction to UPDATE message for IMS MT Call Testcases | F | 10.5.0 | 10.6.0 | R5s150035 |
| RP-67 | RP-150333 | 0277 | - | Correction for record-route header in IMS MT call scenarios | F | 10.5.0 | 10.6.0 | R5s150039 |
| RP-67 | RP-150333 | 0278 | - | Correction to cr_UE_RadioAccessCapability template for IMS UTRA test cases | F | 10.5.0 | 10.6.0 | R5s150054 |
| RP-67 | RP-150333 | 0279 | - | Correction to IMS Multiple PDN | F | 10.5.0 | 10.6.0 | R5s150055 |
| RP-67 | RP-150333 | 0280 | - | Correction to DNS Query procedure for IMS Testcases | F | 10.5.0 | 10.6.0 | R5s150085 |

| Meet- | TSG doc | CR | Rev | Subject | Cat | Old vers | New vers | WG doc |
|-------|-----------|------|-----|--|-----|-------------|-------------|-----------|
| RP-67 | RP-150333 | 0281 | - | Correction to SessionID in IMS signalling procedures | F | 10.5.0 | 10.6.0 | R5s150086 |
| RP-67 | RP-150333 | 0282 | - | Addition of GCF WI-171 MO MTSI Video Call test case 12.19 (using 36.523-3 test model) | В | 10.5.0 | 10.6.0 | R5s150115 |
| RP-68 | RP-150884 | 0284 | - | Routine maintenance for TS 34.229-3 | F | 10.6.0 | 10.7.0 | R5-151102 |
| RP-68 | RP-150894 | 0286 | - | Corrections to Emergency Services Over IMS test case 19.1.3 | F | 10.6.0 | 10.7.0 | R5s150061 |
| RP-68 | RP-150894 | 0287 | = | Corrections for Emergency Services over IMS test case 19.1.5 | F | 10.6.0 | 10.7.0 | R5s150091 |
| RP-68 | RP-150894 | 0288 | - | Correction to IMS XCAP Testcases | F | 10.6.0 | 10.7.0 | R5s150148 |
| RP-68 | RP-150894 | 0289 | - | Correction of RR and RS modifiers | F | 10.6.0 | 10.7.0 | R5s150153 |
| RP-68 | RP-150894 | 0290 | - | Correction to IMS Emergency Call testcase 19.4.5 | F | 10.6.0 | 10.7.0 | R5s150157 |
| RP-68 | RP-150894 | 0291 | - | Correction to IMS Emergency Call testcase 19.3.1 | F | 10.6.0 | 10.7.0 | R5s150158 |
| RP-68 | RP-150894 | 0292 | - | Correction of SPI matching error at runtime | F | 10.6.0 | 10.7.0 | R5s150174 |
| RP-68 | RP-150894 | 0293 | - | Correction for checking of video feature tag | F | 10.6.0 | 10.7.0 | R5s150180 |
| RP-68 | RP-150894 | 0294 | - | Correction to IMS Emergency Call testcase 19.3.1 | F | 10.6.0 | 10.7.0 | R5s150193 |
| RP-68 | RP-150894 | 0295 | = | Correction to GCF WI-154 IMS Emergency Call testcase 19.5.7 | F | 10.6.0 | 10.7.0 | R5s150195 |
| RP-68 | RP-150894 | 0296 | - | Correction regarding XCAP Root URI | F | 10.6.0 | 10.7.0 | R5s150202 |
| RP-68 | RP-150894 | 0297 | - | Correction to Annex Procedure C.28 | F | 10.6.0 | 10.7.0 | R5s150205 |
| RP-68 | RP-150894 | 0298 | - | Correction in IMS MTSI Video call test case 12.21 | F | 10.6.0 | 10.7.0 | R5s150236 |
| RP-68 | RP-150894 | 0299 | - | Correction of Require header in 200 OK | F | 10.6.0 | 10.7.0 | R5s150237 |
| RP-68 | RP-150894 | 0300 | - | Corrections for upper tester for IMS XCAP call forwarding test cases | F | 10.6.0 | 10.7.0 | R5s150244 |
| RP-68 | RP-150894 | 0301 | - | Corrections for Emergency Services over IMS test case 19.5.7 | F | 10.6.0 | 10.7.0 | R5s150245 |
| RP-68 | RP-150894 | 0302 | - | Addition of GCF WI-103 MTSI Message Waiting Indication test case 15.15 (using 36.523-3 and 34.229-4 test models) | В | 10.6.0 | 10.7.0 | R5s150259 |
| RP-68 | RP-150894 | 0303 | - | Correction of multi-PDN PCO handling | F | 10.6.0 | 10.7.0 | R5s150267 |
| RP-68 | RP-150894 | 0304 | - | Correction for inactivity timer in IMS XCAP test cases | F | 10.6.0 | 10.7.0 | R5s150269 |
| RP-68 | RP-150894 | 0305 | - | Corrections for TCP connection handling for IMS test cases | F | 10.6.0 | 10.7.0 | R5s150270 |
| RP-68 | RP-150894 | 0306 | = | Correction to IMS emergency services test case 19.1.3 | F | 10.6.0 | 10.7.0 | R5s150273 |
| RP-68 | RP-150894 | 0307 | - | Correction of Require header in 200 OK - continued | F | 10.6.0 | 10.7.0 | R5s150274 |
| RP-68 | RP-150894 | 0308 | - | Correction of IMS TC 15.19 | F | 10.6.0 | 10.7.0 | R5s150276 |
| RP-68 | RP-150894 | 0309 | - | Addition of GCF WI-103 IMS XCAP Testcase 15.10 over 36.523-3 Test Model | В | 10.6.0 | 10.7.0 | R5s150289 |
| RP-68 | RP-150894 | 0310 | - | Addition of GCF WI-154 IMS Emergency Call test case 19.4.2 (using 36.523-3 test model) | В | 10.6.0 | 10.7.0 | R5s150327 |
| RP-68 | RP-150894 | 0312 | _ | Correction to TC 8.2 on expiration values | F | 10.6.0 | 10.7.0 | R5s150342 |
| RP-68 | RP-150894 | 0313 | - | Addition of GCF WI-103 IMS Testcase 15.12a over 36.523-3 Test Model | В | 10.6.0 | 10.7.0 | R5s150371 |

| Meet- | TSG doc | CR | Rev | Subject | Cat | Old | New | WG doc |
|-------|-----------|------|-----|--|-----|--------|--------|-----------|
| ing | | | | | | vers | vers | |
| RP-68 | RP-150894 | 0314 | | Addition of GCF WI-198 IMS Testcase 15.19a over 36.523-3 Test Model | В | 10.6.0 | 10.7.0 | R5s150373 |
| RP-68 | RP-150894 | 0315 | | Addition of GCF WI-103 IMS Testcase 15.21a over 36.523-3 Test Model | В | 10.6.0 | 10.7.0 | R5s150382 |
| RP-68 | RP-150894 | 0316 | - | Correction to IMS Emergency Call test case 19.3.1 | F | 10.6.0 | 10.7.0 | R5s150414 |
| RP-68 | RP-150894 | 0317 | - | Correction of IMS TC 8.1 | F | 10.6.0 | 10.7.0 | R5s150446 |
| RP-70 | RP-151688 | 0332 | | Removal of technical content in 34.229-3 v10.7.0 and substitution with pointer to the next Release | F | 10.7.0 | 10.8.0 | R5-155034 |

History

| Document history | | |
|------------------|----------------|-------------|
| V10.0.0 | October 2013 | Publication |
| V10.1.0 | January 2014 | Publication |
| V10.2.0 | March 2014 | Publication |
| V10.3.0 | July 2014 | Publication |
| V10.4.0 | September 2014 | Publication |
| V10.5.0 | January 2015 | Publication |
| V10.6.0 | April 2015 | Publication |
| V10.7.0 | July 2015 | Publication |
| V10.8.0 | January 2016 | Publication |