ETSI TS 134 121-1 V10.8.0 (2013-10)



Universal Mobile Telecommunications System (UMTS);
User Equipment (UE) conformance specification;
Radio transmission and reception (FDD);
Part 1: Conformance specification
(3GPP TS 34.121-1 version 10.8.0 Release 10)



Reference RTS/TSGR-0534121-1va80 Keywords UMTS

ETSI

650 Route des Lucioles F-06921 Sophia Antipolis Cedex - FRANCE

Tel.: +33 4 92 94 42 00 Fax: +33 4 93 65 47 16

Siret N° 348 623 562 00017 - NAF 742 C Association à but non lucratif enregistrée à la Sous-Préfecture de Grasse (06) N° 7803/88

Important notice

Individual copies of the present document can be downloaded from: <u>http://www.etsi.org</u>

The present document may be made available in more than one electronic version or in print. In any case of existing or perceived difference in contents between such versions, the reference version is the Portable Document Format (PDF). In case of dispute, the reference shall be the printing on ETSI printers of the PDF version kept on a specific network drive within ETSI Secretariat.

Users of the present document should be aware that the document may be subject to revision or change of status.

Information on the current status of this and other ETSI documents is available at

http://portal.etsi.org/tb/status/status.asp

If you find errors in the present document, please send your comment to one of the following services: <u>http://portal.etsi.org/chaircor/ETSI_support.asp</u>

Copyright Notification

No part may be reproduced except as authorized by written permission. The copyright and the foregoing restriction extend to reproduction in all media.

© European Telecommunications Standards Institute 2013. All rights reserved.

DECTTM, **PLUGTESTS**TM, **UMTS**TM and the ETSI logo are Trade Marks of ETSI registered for the benefit of its Members. **3GPP**TM and **LTE**TM are Trade Marks of ETSI registered for the benefit of its Members and of the 3GPP Organizational Partners.

GSM® and the GSM logo are Trade Marks registered and owned by the GSM Association.

Intellectual Property Rights

IPRs essential or potentially essential to the present document may have been declared to ETSI. The information pertaining to these essential IPRs, if any, is publicly available for **ETSI members and non-members**, and can be found in ETSI SR 000 314: "Intellectual Property Rights (IPRs); Essential, or potentially Essential, IPRs notified to ETSI in respect of ETSI standards", which is available from the ETSI Secretariat. Latest updates are available on the ETSI Web server (http://ipr.etsi.org).

Pursuant to the ETSI IPR Policy, no investigation, including IPR searches, has been carried out by ETSI. No guarantee can be given as to the existence of other IPRs not referenced in ETSI SR 000 314 (or the updates on the ETSI Web server) which are, or may be, or may become, essential to the present document.

Foreword

This Technical Specification (TS) has been produced by ETSI 3rd Generation Partnership Project (3GPP).

The present document may refer to technical specifications or reports using their 3GPP identities, UMTS identities or GSM identities. These should be interpreted as being references to the corresponding ETSI deliverables.

The cross reference between GSM, UMTS, 3GPP and ETSI identities can be found under http://webapp.etsi.org/key/queryform.asp.

Contents

Intel	lectual Property Rights	2
	word	
	word	
	oduction	
	Scope	
	References	
3		
4 4.1	Frequency bands and channel arrangement	
5 to	11 Void	6
Ann	ex A to K: Void	7
	ex L (informative): Change history	
Hista		

Foreword

This Technical Specification has been produced by the 3rd Generation Partnership Project (3GPP).

The contents of the present document are subject to continuing work within the TSG and may change following formal TSG approval. Should the TSG modify the contents of the present document, it will be re-released by the TSG with an identifying change of release date and an increase in version number as follows:

Version x.y.z

where:

- x the first digit:
 - 1 presented to TSG for information;
 - 2 presented to TSG for approval;
 - 3 or greater indicates TSG approved document under change control.
- y the second digit is incremented for all changes of substance, i.e. technical enhancements, corrections, updates, etc.
- z the third digit is incremented when editorial only changes have been incorporated in the document.

Introduction

The present document is part 1 of a multi-parts TS:

3GPP TS 34.121-1: User Equipment (UE) conformance specification; Radio transmission and reception (FDD); Part 1: Conformance specification.

3GPP TS 34.121-2 [32]: User Equipment (UE) conformance specification; Radio transmission and reception (FDD); Part 2: Implementation Conformance Statement (ICS).

NOTE: TS 34.121 has been converted to multipart TS with version 7.0.0. Previous versions are a single part standard 34.121.

1 Scope

The present document specifies the UTRA measurement procedures for the conformance test of the user equipment (UE) that contain transmitting characteristics, receiving characteristics and performance requirements in addition to requirements for support of RRM (Radio Resource Management) in FDD mode. In addition it specifies conformance testing of RRM requirements for support of E-UTRA when the UE operates in UTRA mode.

NOTE: Conformance testing of RRM requirements for support of UTRA when the UE operates in E-UTRA mode are specified in TS 36.521-3 [38].

The requirements are listed in different clauses only if the corresponding parameters deviate. More generally, tests are only applicable to those mobiles that are intended to support the appropriate functionality. To indicate the circumstances in which tests apply, this is noted in the "definition and applicability" part of the test.

For example only Release 5 and later UE declared to support HSDPA shall be tested for this functionality. In the event that for some tests different conditions apply for different releases, this is indicated within the text of the test itself.

2 References

The following documents contain provisions which, through reference in this text, constitute provisions of the present document.

- References are either specific (identified by date of publication, edition number, version number, etc.) or non-specific.
- For a specific reference, subsequent revisions do not apply.
- For a non-specific reference, the latest version applies. In the case of a reference to a 3GPP document (including a GSM document), a non-specific reference implicitly refers to the latest version of that document.
 - For a Release 1999 UE, references to 3GPP documents are to version 3.x.y.
 - For a Release 4 UE, references to 3GPP documents are to version 4.x.y.
 - For a Release 5 UE, references to 3GPP documents are to version 5.x.y.
 - For a Release 6 UE, references to 3GPP documents are to version 6.x.y.
 - For a Release 7 UE, references to 3GPP documents are to version 7.x.y.
 - For a Release 8 UE, references to 3GPP documents are to version 8.x.y.
 - For a Release 9 UE, references to 3GPP documents are to version 9.x.y.

[1] to [38] (void)

[39] 3GPP TS 34.121-1 Release 11: "User Equipment (UE) conformance specification; Radio transmission and reception (FDD); Part 1: Conformance specification"

3 Definitions, symbols, abbreviations and equations

Void

4 Frequency bands and channel arrangement

4.1 General

The requirements of the present document are provided in 3GPP TS 34.121-1 Release 11 [39].

5 to 11 Void

Annex A to K:

Void

Annex L (informative): Change history

T Meeting	Doc-1 st -Level	CR	Rev	Subject	Cat	Version - Current	Version -New	Doc-2 nd -Level
TP-07				Approval of the specification		2.0.0	3.0.0	
				No change: replaces invalid zip file on server		3.0.0	3.0.1	
TP-08	TP-000090	001		Editorial corrections to clauses 2, 3, 4 and 5.1	D	3.0.1	3.1.0	T1-000059
TP-08	TP-000090	002		Modifications to clause 5.4 "Output Power Dynamics in the Uplink"	С	3.0.1	3.1.0	T1-000060
TP-08	TP-000090	003		Out-of-synchronisation handling of the UE	В	3.0.1	3.1.0	T1-000061
TP-08	TP-000090	004		Modifications to clauses 5.8, 5.9, 5.10 and 5.11	D	3.0.1	3.1.0	T1-000062
TP-08	TP-000090	005		Modifications to Chapter 6 "Receiver Characteristics"	F	3.0.1	3.1.0	T1-000063
TP-08	TP-000090	006		Modifications to Annex D, Annex E, Annex G and Annex H	F	3.0.1	3.1.0	T1-000067
TP-08	TP-000090	800		Modifications to clauses 5.5, 5.6 and 5.7	F	3.0.1	3.1.0	T1-000069
TP-08	TP-000090	009		Modifications to Chapter 7 "Performance requirements"	F	3.0.1	3.1.0	T1-000070
TP-08	TP-000090	010		Modifications to test power control in downlink	F	3.0.1	3.1.0	T1-000071
TP-08	TP-000090	011		Modifications to clause 5.13 "Transmit Modulation"	F	3.0.1	3.1.0	T1-000072
TP-08	TP-000090	012		Modifications to test for inner loop power control in the uplink	F	3.0.1	3.1.0	T1-000073
TP-08	TP-000090	013		Revision of Annex B: Global in-channel Tx test	F	3.0.1	3.1.0	T1-000074
TP-08	TP-000090	014		Blind transport format detection	В	3.0.1	3.1.0	T1-000075
TP-08	TP-000090	015		Removal of Annex I "Open Items"	D	3.0.1	3.1.0	T1-000077
TP-08	TP-000090	016		Modifications to Chapter 8 "Requirements for support of RRM"	С	3.0.1	3.1.0	T1-000117
TP-08	TP-000090	017		Modifications to Annex C "Measurement channels"	F	3.0.1	3.1.0	T1-000118
TP-08	TP-000090	018		Idle mode test cases (test of performance requirements)	F	3.0.1	3.1.0	T1-000119
TP-09	TP-000163	019		Editorial corrections for References and Frequency Stability (2, 5.2, 5.3)	F	3.1.0	3.2.0	T1-000131
TP-09	TP-000163	020		Corrections for Output Power Dynamics in the Uplink (5.4)	F	3.1.0	3.2.0	T1-000132
TP-09	TP-000163	021		Transients for uplink inner loop power control (5.4.2.4.2)	F	3.1.0	3.2.0	T1-000133
TP-09	TP-000163	022		Transmit On/Off power (5.5.2.4.2)	F	3.1.0	3.2.0	T1-000134
TP-09	TP-000163	023		Change of TFC (5.6.4.2)	F	3.1.0	3.2.0	T1-000135
TP-09	TP-000163	024		Clarification of the definition on Peak Code Domain Error (5.13.2.1)	F	3.1.0	3.2.0	T1-000139
TP-09	TP-000163	025		UE interfering signal definition (6.3, 6.4, 6.5, 6.7)	F	3.1.0	3.2.0	T1-000140
TP-09	TP-000163	026		Performance requirements (7.1, 7.2, 7.3, 7.4, 7.5)	F	3.1.0	3.2.0	T1-000143
TP-09	TP-000163	027		CR on clause 7.6 and 7.7 in TS34.121 (7.6, 7.7)	F	3.1.0	3.2.0	T1-000144
TP-09	TP-000163	028		Performance requirements (7.9, 7.10, 7.11)	F	3.1.0	3.2.0	T1-000146
TP-09	TP-000163	029		Corrections for Annex D (Annex-D)	F	3.1.0	3.2.0	T1-000147
TP-09	TP-000163	030		Corrections for Annex E (Annex-E)	F	3.1.0	3.2.0	T1-000148
TP-09	TP-000163	031		Corrections for Transmit ON/OFF Power, Change of TFC and Power setting in uplink compressed mode (5.5, 5.6, 5.7)	F	3.1.0	3.2.0	T1-000149
TP-09	TP-000163	032		Corrections for power setting in uplink compressed mode (5.7)	F	3.1.0	3.2.0	T1-000136
TP-09	TP-000163	033		CR for subclause 7.8: Power control in downlink (7.8)	В	3.1.0	3.2.0	T1-000145
TP-09	TP-000163	034		Corrections to clause 5.8, 5.9, 5.10, 5.11 and 5.12	F	3.1.0	3.2.0	T1-000137
TP-09	TP-000163	035		Corrections to EVM and PCDE formulae (B.2.7.1, B2.7.2)	F	3.1.0	3.2.0	T1-000138
TP-09	TP-000163	036		New initial conditions for Spurious emission test case (6.8.4.1)	F	3.1.0	3.2.0	T1-000141
TP-09	TP-000163	037			F	3.1.0	3.2.0	T1-000142
TP-10	TP-000216	038		Corrections to Chapter 3 "Definitions, symbols, abbreviations and equations"	D	3.2.0	3.3.0	T1-000247
TP-10	TP-000216	039	<u> </u>	Vocabulary Corrections	D	3.2.0	3.3.0	T1-000253
TP-10	TP-000216	040	1	Reference Measurement Channels in Annex C	F	3.2.0	3.3.0	T1-000238
TP-10	TP-000216	041		Inclusion of OCNS definition for performance tests	F	3.2.0	3.3.0	T1-000241
TP-10	TP-000216	042		Handling of measurement uncertainties in UE conformance testing (FDD)	F	3.2.0	3.3.0	T1-000250

T	Doc-1 st -Level	CR	Rev	Subject	Cat	Version		Doc-2 nd -Level
Meeting						Current	-New	
TP-10	TP-000216	043		Update of Idle mode test cases	F	3.2.0	3.3.0	T1-000252
TP-10	TP-000216	044		UE emission mask measurement filter definition correction	F	3.2.0	3.3.0	T1-000254
TP-10	TP-000216	045		New structure of TS 34.121	F	3.2.0	3.3.0	T1-000255
TP-10	TP-000216	046		Ü	F	3.2.0	3.3.0	T1-000239
TP-10	TP-000216	047		Corrections to power control tests	F	3.2.0	3.3.0	T1-000240
TP-10	TP-000216	048		Correction to Open Loop Power Control in Uplink	F	3.2.0	3.3.0	T1-000242
TP-10	TP-000216	049		Correction to Transmit ON/OFF Time mask	F	3.2.0	3.3.0	T1-000243r
TP-10	TP-000216	050		Correction to Spurious Emission test	F	3.2.0	3.3.0	T1-000244
TP-10	TP-000216	051		Correction of spurious emission measurement procedure	F	3.2.0	3.3.0	T1-000245
TP-10	TP-000216	052		Out-of-synchronization handling of output power	F	3.2.0	3.3.0	T1-000246
TP-10	TP-000216	053		Clarification of test procedure and test requirement for receiver blocking and spurious response.	F	3.2.0	3.3.0	T1-000248
TP-10	TP-000216	054		Subclause 7.8 Power control in downlink	F	3.2.0	3.3.0	T1-000249
TP-10	TP-000216	055		Downlink compressed mode	F	3.2.0	3.3.0	T1-000251
TP-11	TP-010019	056		CR on Test tolerance for 6.5 Blocking Characteristics	F	3.3.0	3.4.0	T1-010020
TP-11	TP-010019	057		CR on Test tolerance for 6.7 Intermodulation Characteristics	F	3.3.0	3.4.0	T1-010025
TP-11	TP-010019	058		CR on Test tolerance for 5.5.1 Test Tolerance for Transmit OFF power	F	3.3.0	3.4.0	T1-010027
TP-11	TP-010019	059		CR on Test tolerance for 6.6 Spurious Response	F	3.3.0	3.4.0	T1-010028
TP-11	TP-010019	060		CR on Test tolerance for 5.11 Test Tolerance for Transmit Spurious emissions	F	3.3.0	3.4.0	T1-010029
TP-11	TP-010019	061		CR on Test tolerance for Annex F TS34.121	F	3.3.0	3.4.0	T1-010030
TP-11	TP-010019	062		CR on Test tolerance for 5.2 Maximum output power	F	3.3.0	3.4.0	T1-010031
TP-11	TP-010019	063		CR on Test tolerance for 5.4.3 Minimum Output Power	F	3.3.0	3.4.0	T1-010032
TP-11	TP-010019	064		CR on Test tolerance for 5.9 Spectrum Emission Mask	F	3.3.0	3.4.0	T1-010033
TP-11	TP-010019	065		CR on Test tolerance for 5.10 ACLR	F	3.3.0	3.4.0	T1-010034
TP-11	TP-010019	066		CR on Test tolerance for 5.12 Transmit Intermodulation	F	3.3.0	3.4.0	T1-010035
TP-11	TP-010019	067		CR on Test tolerance for 6.2 Reference Sensitivity Level	F	3.3.0	3.4.0	T1-010036
TP-11	TP-010019	068		CR on Test tolerance for 5.3 Frequency Error	F	3.3.0	3.4.0	T1-010037
TP-11	TP-010019	069		CR on Test tolerance for 5.8 Occupied Bandwidth	F	3.3.0	3.4.0	T1-010038
TP-11	TP-010019	070		CR on Test tolerance for 5.13.1 EVM	F	3.3.0	3.4.0	T1-010039
TP-11	TP-010019	071		CR on Test tolerance for 5.13.2 PCDE	F	3.3.0	3.4.0	T1-010040
TP-11	TP-010019	072		CR on Test tolerance for 5.4.4 Out of Synchronisation transmit power	F	3.3.0	3.4.0	T1-010041
TP-11	TP-010019	073		CR on Test tolerance for 6.4 ACS	F	3.3.0	3.4.0	T1-010042
	TP-010019	074		CR on Test tolerance for 6.8 RX Spurious Emissions		3.3.0	3.4.0	T1-010108
TP-11	TP-010019	075		CR on corrections to DL compressed mode	F	3.3.0	3.4.0	T1-010021
TP-11	TP-010019	076		CR on Corrections to DL 384kbps and BTFD measurement channels	F	3.3.0	3.4.0	T1-010022
TP-11	TP-010019	077		CR on Corrections to Maximum output power	F	3.3.0	3.4.0	T1-010023
TP-11	TP-010019	078		CR on RX spurious emissions	F	3.3.0	3.4.0	T1-010024
TP-11	TP-010019	079		CR on Editorial correction to channel number	D	3.3.0	3.4.0	T1-010026
TP-11	TP-010019	080		CR Correction of Annex-E and reference information to Annex E	F	3.3.0	3.4.0	T1-010043
TP-11	TP-010019	081		Editorial corrections	D	3.3.0	3.4.0	T1-010044
TP-11	TP-010076	082	1	Regional requirements on Test Tolerance	F	3.3.0	3.4.0	Presented directly to TP- 11
TP-12	TP-010119	083		CR: Addition of Test System uncertainties and Test Tolerances	F	3.4.0	3.5.0	T1-010139
TP-12	TP-010119	084		CR: Measurement accuracy of CPICH RSCP	F	3.4.0	3.5.0	T1-010140
TP-12	TP-010119	085		CR: Measurement accuracy of CPICH Ec/lo	F.	3.4.0	3.5.0	T1-010141
TP-12	TP-010119	086			F	3.4.0	3.5.0	T1-010142
TP-12	TP-010119	087		Maintenance CR: Propagation condition 250 km/h	F	3.4.0	3.5.0	T1-010143
TP-12	TP-010119	088		Maintenance CR: Removal of square brackets	F	3.4.0	3.5.0	T1-010144
TP-12	TP-010119	089		Maintenance CR: Tx power for Rx characteristics	F	3.4.0	3.5.0	T1-010145
TP-12	TP-010119	090		measurement Maintenance CR: Correction of Definition of multi-	F	3.4.0	3.5.0	T1-010146
TP-12	TP-010119	090		code OCNS signal Maintenance CR: Conformance requirement to	D D	3.4.0	3.5.0	T1-010147
11 -12	11 -010119	031		Minimum requirement		3.4.0	J.J.U	11-010147

T Meeting	Doc-1 st -Level	CR	Rev	Subject	Cat	Version - Current	Version -New	Doc-2 nd -Level
TP-12	TP-010119	092		Maintenance CR: Test conditions for TS 34.121	F	3.4.0	3.5.0	T1-010148
TP-12	TP-010119	093		Maintenance CR: Editorial correction 34.121	D	3.4.0	3.5.0	T1-010149
TP-12	TP-010119	094		Maintenance CR: closed loop power control close to the limits	С	3.4.0	3.5.0	T1-010150
TP-12	TP-010119	095		Maintenance CR: removal of annex I	D	3.4.0	3.5.0	T1-010151
TP-12	TP-010119	096		Maintenance CR: correction to annex E	F	3.4.0	3.5.0	T1-010152
TP-12	TP-010119	097		Maintenance CR: corrections to TS34.121	F	3.4.0	3.5.0	T1-010153
TP-13	TP-010184	098		Annex F Measurement uncertainty	F	3.5.0	3.6.0	T1-010342
TP-13	TP-010184	099		RX Spurious emissions	F	3.5.0	3.6.0	T1-010364
TP-13	TP-010184	100		Structure of RRM test cases	F	3.5.0	3.6.0	T1-010356
TP-13 TP-13	TP-010184 TP-010184	101 102		Clause 8.2, Idle mode cell reselection delay tests Proposal for measuring method of Random Access	F F	3.5.0 3.5.0	3.6.0 3.6.0	T1-010361 T1-010362
TP-13	TP-010184	103		Modification to OCNS code channels to allow for 384 kbps allocation	F	3.5.0	3.6.0	T1-010382
TP-13	TP-010184	104		Clarification of AWGN definition	F	3.5.0	3.6.0	T1-010340
TP-13	TP-010184	105		Correction to test for inner loop power control in the uplink (FDD)	F	3.5.0	3.6.0	T1-010341
TP-13	TP-010184	106		Core specification change for uplink inner loop power control	F	3.5.0	3.6.0	T1-010355
TP-13	TP-010184	107		Power Control mode in downlink	F	3.5.0	3.6.0	T1-010357
TP-13	TP-010184	108		Correction of frequency range for receiver spurious emission requirements	F	3.5.0	3.6.0	T1-010360
TP-13	TP-010184	109		Test numbering of multi-path fading propagation tests	F	3.5.0	3.6.0	T1-010363
TP-13	TP-010184	110		Measurement of the ON/OFF power during the PRACH preamble	F	3.5.0	3.6.0	T1-010370
TP-14	TP-010259	111		Improvement of test description: CPICH RSCP test case	F	3.6.0	3.7.0	T1-010489
TP-14	TP-010259	112		Improvement of test description: CPICH Ec/lo test case	F	3.6.0	3.7.0	T1-010490
TP-14	TP-010259	113		UTRA Carrier RSSI test case	F	3.6.0	3.7.0	T1-010491
TP-14	TP-010259	114		Corrections and improvements for TS 34.121 subclauses 5, 6 and Annex E	F	3.6.0	3.7.0	T1-010492
TP-14	TP-010259	115		Clarification of test requirements for Transmit ON/OFF time mask	F	3.6.0	3.7.0	T1-010493
TP-14 TP-14	TP-010259 TP-010259	116 117		Clarification of procedure for Out-of-synchronisation handling of output power UE Rx-Tx time difference type 1	F	3.6.0	3.7.0	T1-010494 T1-010495
TP-14 TP-14	TP-010259 TP-010259	117		UE Transmit Timing	F	3.6.0	3.7.0	T1-010495
TP-14	TP-010259	119		Changes to blocking characteristics and spurious response test cases	F	3.6.0	3.7.0	T1-010496
TP-14	TP-010259	120		Clarification in Spectrum emission mask section	F	3.6.0	3.7.0	T1-010498
TP-14	TP-010259	121		DL Power Control Step Size in performance requirements	F	3.6.0	3.7.0	T1-010499
TP-14	TP-010259	122		DL Compressed mode, correction of pattern	F	3.6.0	3.7.0	T1-010500
TP-14	TP-010259	123		BER/BLER testing based on statistical approach	F	3.6.0	3.7.0	T1-010517
TP-14	TP-010259	124		Deletion of OFF power measurement on "Power setting in uplink compressed mode" Test	F	3.6.0	3.7.0	T1-010520
TP-14	TP-010259	125		Cell reselection delay tests in idle mode	F	3.6.0	3.7.0	T1-010521
TP-14	TP-010259	126		CR for Transmit OFF power measurement	F	3.6.0	3.7.0	T1-010522
TP-15 TP-15	TP-020039 TP-020039	127 128		Correction of power terms and definitions Creation of common default messages for RRM test cases in Annex I	F F	3.7.0 3.7.0	3.8.0	T1-020133 T1-020134
TP-15	TP-020039	129		Transmit ON/OFF time mask, Change of TFC and Power setting in uplink compressed mode	F	3.7.0	3.8.0	T1-020135
TP-15	TP-020039	130		Maintenance of Annex B	F	3.7.0	3.8.0	T1-020136
TP-15	TP-020039	131		Correction of minimum test times under fading	F	3.7.0	3.8.0	T1-020137
TP-15	TP-020039	132		Addition of test case description for SFN-CFN observed time difference	F	3.7.0	3.8.0	T1-020138
TP-15	TP-020039	133		Addition of test case description for SFN-SFN observed time difference type 1	F	3.7.0	3.8.0	T1-020139
TP-15	TP-020039	134		Corrections for TS 34.121 subclause 8.7.6	F	3.7.0	3.8.0	T1-020140
TP-15	TP-020039	135		Correction changes in clause 8.7	F	3.7.0	3.8.0	T1-020141
TP-15	TP-020039	136		Update of RRM Cell reselection delay tests in idle mode	F	3.7.0	3.8.0	T1-020142
TP-15	TP-020039	137		Implementation of test tolerances to test cases in subclause 7	F	3.7.0	3.8.0	T1-020143
TP-15	TP-020039	138		RRM Annex F	F	3.7.0	3.8.0	T1-020144
TP-15	TP-020039	139		Connection Diagrams for RRM tests cell re-selection in idle mode		3.7.0	3.8.0	T1-020145
TP-15	TP-020039	140		Statistical testing of RRM delay performance	F	3.7.0	3.8.0	T1-020146

T Meeting	Doc-1 st -Level	CR	Rev	Subject	Cat	Version - Current	Version -New	Doc-2 nd -Level
TP-15	TP-020039	141		RRM Hard handover test cases	F	3.7.0	3.8.0	T1-020147
TP-15	TP-020039	142		System Simulator and Test System definition	F	3.7.0	3.8.0	T1-020148
TP-15	TP-020039	143		WCDMA 1800 and 1900 additions	F	3.7.0	3.8.0	T1-020170
TP-15	TP-020039	144		Correction of power spectral density	F	3.7.0	3.8.0	T1-020171
TP-16	TP-020139	145		Spectrum emission mask test case: Change to frequencies to be tested	F	3.8.0	3.9.0	T1-020220
TP-16	TP-020139	146		Power control in downlink, initial convergence	F	3.8.0	3.9.0	T1-020221
TP-16	TP-020139	147		Event triggered reporting in AWGN propagation conditions	F	3.8.0	3.9.0	T1-020222
TP-16	TP-020139	148		Event triggered reporting of multiple neighbours in AWGN propagation conditions	F	3.8.0	3.9.0	T1-020223
TP-16	TP-020139	149		Event triggered reporting of two detectable neighbours in AWGN propagation conditions	F	3.8.0	3.9.0	T1-020224
TP-16	TP-020139	150		Correct reporting of neighbours in fading propagation conditions	F	3.8.0	3.9.0	T1-020226
TP-16	TP-020139	151		Removal of "AFC On" reference from clause 5.3 Frequency Error test	F	3.8.0	3.9.0	T1-020227
TP-16	TP-020139	152		Correct reporting of neighbours in AWGN propagation conditions - inter frequency case	F	3.8.0	3.9.0	T1-020235
TP-16	TP-020139	153		Deletion of test case description 'Correct reporting of neighbours in Fading propagation conditions - Inter frequency case	F	3.8.0	3.9.0	T1-020236
TP-16	TP-020139	154		Correction of UE Tx Timing adjustment rate	F	3.8.0	3.9.0	T1-020237
TP-16	TP-020139	155		Correction of Units of side conditions and test parameters	F	3.8.0	3.9.0	T1-020238
TP-16	TP-020139	156		Structure of subclause 8	F	3.8.0	3.9.0	T1-020239
TP-16	TP-020139	157		Inter-system Handover from UTRAN FDD to GSM	F	3.8.0	3.9.0	T1-020240
TP-16	TP-020139	158		UTRAN to GSM Cell Re-Selection: Change of minimum requirements	F	3.8.0	3.9.0	T1-020241
TP-16	TP-020139	159		Cell reselection in idle mode: CR for testcase	F	3.8.0	3.9.0	T1-020242
TP-16	TP-020139	160		Cell reselection in idle mode: CR for annex F.4	F	3.8.0	3.9.0	T1-020243
TP-16	TP-020139	161		UTRAN to GSM cell reselection: CR for testcase	F	3.8.0	3.9.0	T1-020244
TP-16	TP-020139	162		UTRAN to GSM cell reselection: CR for annex F.4	F	3.8.0	3.9.0	T1-020245
TP-16	TP-020139	163		Test parameters of FDD/FDD Hard Handover test case	F	3.8.0	3.9.0	T1-020246
TP-16	TP-020139	164		Addition of details for RRM test cases in 8.3.7.1 and 8.3.7.2 (Cell Re-selection in URA_PCH)	F	3.8.0	3.9.0	T1-020247
TP-16	TP-020139	165		Addition of details for RRM test cases in 8.4.1 (RRC Re-establishment delay)	F	3.8.0	3.9.0	T1-020248
TP-16	TP-020139	166		Addition of details for RRM test case 8.3.1	F	3.8.0	3.9.0	T1-020249
TP-16	TP-020139	167		Addition of details for RRM test case 8.3.5.1	F	3.8.0	3.9.0	T1-020250
TP-16	TP-020139	168		Addition of details for RRM test case 8.3.5.2	F	3.8.0	3.9.0	T1-020251
TP-16	TP-020139	169		UE RX TX time difference: CR for testcase	F	3.8.0	3.9.0	T1-020252
TP-16	TP-020139	170		UE RX TX time difference: CR for annex	F	3.8.0	3.9.0	T1-020253
TP-16	TP-020139	171		Correction for SSDT test parameters and UL DPCCH slot format for performance	F	3.8.0	3.9.0	T1-020265
TP-16	TP-020139	172		Correction of UE FDD EVM definition	F F	3.8.0	3.9.0	T1-020266
TP-16 TP-16	TP-020139 TP-020139	173 174		Clarification of Meaning of FDR Modification to the test case for RX spurious	F	3.8.0	3.9.0 3.9.0	T1-020267 T1-020268
TP-16	TP-020139	175			F	3.8.0	3.9.0	T1-020422
TP-16	TP-020139	176		Transmit ON/OFF Time mask in TS34.121 Corrections to ACLR in TS34.121	F	3.8.0	3.9.0	T1-020423
TP-17	TP-020185	177	-	Addition of sub clause 8.7.6.2 – UE Rx-Tx time	F	3.9.0	3.10.0	T1-020453
TP-17	TP-020185	178	-	Addition of test case Cell reselection in CELL_PCH	F	3.9.0	3.10.0	T1-020454
TP-17	TP-020185	179	-	Addition of test case Transport format combination	F	3.9.0	3.10.0	T1-020455
TP-17	TP-020185	180	-	Maintenance of Re-selection and handover test	F	3.9.0	3.10.0	T1-020456
TP-17	TP-020185	181	-	Correction of test parameters of Handover to inter-	F	3.9.0	3.10.0	T1-020457
TP-17	TP-020185	182	-	Addition of details for RRM test case 8.7.3C (UE	F	3.9.0	3.10.0	T1-020458
TP-17	TP-020185	183	-	Corrections to clause 6 and 7 for editorial errors	F	3.9.0	3.10.0	T1-020459
TP-17	TP-020185	184	-	Correction to clause 8.2.2 Cell Re-Selection	F	3.9.0	3.10.0	T1-020460
TP-17	TP-020185	185	-	Correction to clause 8.3.1 FDD/FDD Soft Handover	F	3.9.0	3.10.0	T1-020461
TP-17	TP-020185	187	-	Correction to clause 8.6.1.1 Event triggered	F	3.9.0	3.10.0	T1-020463
TP-17	TP-020185	188	<u> </u>	Correction to clause 8.6.1.2 Event triggered	F	3.9.0	3.10.0	T1-020463
TP-17	TP-020185	189	<u> </u>		F	3.9.0	3.10.0	T1-020464
TP-17	TP-020185	190	-	Correction to clause 8.6.1.3 Event triggered Correction to clause 8.6.1.4 Correct reporting of	F	3.9.0	3.10.0	T1-020465
TP-17	TP-020185	191	-	Correction to clause 8.6.2.1 Correct reporting of	r F	3.9.0	3.10.0	T1-020467
TP-17	TP-020185	192	-	Correction to clause 8.7.1 CPICH RSCP	r F	3.9.0	3.10.0	T1-020467
L,	520100	.52	İ	2525	l '	5.5.0	3 0.0	525-50

T	Doc-1 st -Level	CR	Rev	Subject	Cat	Version	Version	Doc-2 nd -Level
Meeting				ŕ		- Current	-New	
TP-17	TP-020185	193	-	Correction to clause 8.7.2 CPICH Ec/Io	F	3.9.0	3.10.0	T1-020469
TP-17	TP-020185	194	-	Correction of test case 'Rx-Tx time difference type	F	3.9.0	3.10.0	T1-020470
TP-17	TP-020185	195	-	FDD/TDD Handover Test Case	F	3.9.0	3.10.0	T1-020471
TP-17	TP-020185	196	-	Test Requirements for Cell Re-Selection in	F	3.9.0	3.10.0	T1-020474
TP-17	TP-020185	197	-	Correction to clause 8.3.7 Cell Re-selection in	F	3.9.0	3.10.0	T1-020475
TP-17	TP-020185	198	-	Segmented Measurement to be allowed for Inner	F	3.9.0	3.10.0	T1-020476
TP-17	TP-020185	199	-	Correction to clause 8.4.1 RRC Re-establishment	F	3.9.0	3.10.0	T1-020477
TP-17	TP-020185	200	-	Correction to clause 8.7.3 UTRA Carrier RSSI	F	3.9.0	3.10.0	T1-020478
TP-17	TP-020185	201	_	Correction to clause 8.7.4 and 8.7.5 SFN-CFN/SFN	F	3.9.0	3.10.0	T1-020479
TP-17	TP-020185	202	_	Addition of a set of Compressed mode reference	F	3.9.0	3.10.0	T1-020480
TP-17	TP-020185	203	_	Correction of Compressed Mode Performance	F	3.9.0	3.10.0	T1-020481
TP-17	TP-020185	204	<u> </u>	Tx Power level control during Rx testing	F	3.9.0	3.10.0	T1-020482
TP-17	TP-020185	205		Deletion of some subclauses from F.6.1 Statistical	F.	3.9.0	3.10.0	T1-020483
TP-17	TP-020185	206	-	Correction to clause 8.3.5 Cell Re-selection in	F	3.9.0	3.10.0	T1-020484
TP-17	TP-020185	207	-		F			T1-020484
			_	Test Requirements for Cell Re-Selection in CELL-		3.9.0	3.10.0	
TP-17	TP-020185	208	-	Calculation of Test Requirements for Cell Re-	F	3.9.0	3.10.0	T1-020486
TP-17	TP-020185	209	-	Clarification of the definition of 90 % success rate	F	3.9.0	3.10.0	T1-020491
TP-17	TP-020185	210	-	Update of test requirement derivation of Downlink	F	3.9.0	3.10.0	T1-020492
TP-17	TP-020192	211	-	Correction of regional note in Annex J.1	F	3.9.0	3.10.0	-
TP-18	TP-020294	212	-	Correction of table titles of Demodulation of DCH in	F	3.10.0	3.11.0	T1-020631
TP-18	TP-020294	213	1	closed loop transmit diversity mode test case Maintenance of FDD/TDD Cell Re-selection test	F	3.10.0	3.11.0	T1-020632
17-10	17-020294	213	ļ ⁻	case	Г	3.10.0	3.11.0	11-020032
TP-18	TP-020294	214	-	Maintenance of UE Transmit Timing test case	F	3.10.0	3.11.0	T1-020633
TP-18	TP-020294	215	-	Correction of ACLR absolute power limit	F	3.10.0	3.11.0	T1-020634
TP-18	TP-020294	216	-	Correction to clause 8.3.6 Cell Re-selection in	F	3.10.0	3.11.0	T1-020636
TP-18	TP-020294	217	1	CELL_PCH Maintenance of 8.4.2.4 Correct behaviour when	F	3.10.0	3.11.0	T1-020637
17-10	17-020294	217	ļ ⁻	reaching maximum transit power	Г	3.10.0	3.11.0	11-020037
TP-18	TP-020294	218	-	Correction of table numbers	F	3.10.0	3.11.0	T1-020639
TP-18	TP-020294	219	-	Correction of message parameter	F	3.10.0	3.11.0	T1-020640
TP-18	TP-020294	220	-	Correction of test parameter in 8.4.2.3 Correct	F	3.10.0	3.11.0	T1-020641
TP-18	TP-020294	221	-	behaviour when Time-out Modification of the Random Access Test 8.4.2.1,	F	3.10.0	3.11.0	T1-020651
11 -10	11 -020294	221	_	Correct behaviour when receiving an ACK.	'	3.10.0	3.11.0	11-020031
TP-18	TP-020294	222	-	Modifications to the test case for Inner Loop Power	F	3.10.0	3.11.0	T1-020642
				Control in the Uplink in TS34.121				
TP-18	TP-020294	223	-	Correction of SCH side conditions and other	F	3.10.0	3.11.0	T1-020750
TP-18	TP-020294	224	_	Corrections of test for power setting in uplink	F	3.10.0	3.11.0	T1-020751
11 10	11 020204			compressed mode		0.10.0	0.11.0	11 020701
TP-18	TP-020294	225	-	Text for annex F.6.2 Statistical testing of RRM delay	F	3.10.0	3.11.0	T1-020752
TD 40	TD 000004	000		performance	_	0.40.0	0.44.0	T4 000750
TP-18	TP-020294	226	-	Maintenance of annex F.6.1 Statistical testing of BER BLER performance	F	3.10.0	3.11.0	T1-020753
TP-18	TP-020294	227	_	Dual limit BLER tests	F	3.10.0	3.11.0	T1-020754
TP-18	TP-020294	228	-	Correction of test method: Out-of-synchronisation	F	3.10.0	3.11.0	T1-020755
				handling of output power				
TP-18	TP-020294	229	-	Correction of table and subclause references	F	3.10.0	3.11.0	T1-020756
TP-18	TP-020294	230	-	Revision of table titles in Sec 8. to provide unique and unambiguous descriptions	F	3.10.0	3.11.0	T1-020757
TP-18	TP-020294	231	_	Correction to clause 8.3.2 FDD/FDD Hard Handover	F	3.10.0	3.11.0	T1-020758
TP-18	TP-020294	232	-	Correction to PHYSICAL CHANNEL	F	3.10.0	3.11.0	T1-020759
				RECONFIGURATION message that activates				
TD 40	TD 000004	000		compressed mode	_	0.40.0	0.44.0	T4 000700
TP-18	TP-020294	233	-	Introduction of test tolerances in Cell Reselection multi carrier test cases	F	3.10.0	3.11.0	T1-020769
TP-18	TP-020294	234	<u> </u>	Correction of UL reference measurement channel	F	3.10.0	3.11.0	T1-020889
TP-19	TP-030045	235	-	P-CCPCH RSCP test case for FDD to TDD	F	3.11.0	3.12.0	T1-030171
TP-19	TP-030045	236	-	Correct reporting of TDD inter-frequency neighbours	F	3.11.0	3.12.0	T1-030172
TP-19	TP-030045	237	<u> </u>	Correction for minimum requirement of UE	F	3.11.0	3.12.0	T1-030173
TP-19	TP-030045	238	 	Removal of 34.123-1 Annex A reference	F	3.11.0	3.12.0	T1-030173
TP-19	TP-030045	239	L		F	3.11.0	3.12.0	T1-030174
TP-19			-	Correction of OE parameter for Correct behaviour at	F			
	TP-030045	240	Ε	Removal of uplink dummy DCCH transmission		3.11.0	3.12.0	T1-030178
TP-19	TP-030045	241	<u> </u>	Nemoval of uplink duffing DCCH transmission	F	3.11.0	3.12.0	T1-030179

T Meeting	Doc-1 st -Level	CR	Rev	Subject	Cat	Version - Current	Version -New	Doc-2 nd -Level
TP-19	TP-030045	242	-	Correction for Combining of TPC commands from	F	3.11.0	3.12.0	T1-030186
TP-20	TP-030099	243	-	Modifications to the test cases for Transmit diversity modes in TS34.121	F	3.12.0	3.13.0	T1-030323
TP-20	TP-030099	244	-	Correction for Cell Re-selection in CELL_FACH state test case	F	3.12.0	3.13.0	T1-030324
	TP-030099	245	-	Correction for Random Access test case	F	3.12.0	3.13.0	T1-030325
	TP-030099	246	-	Correction for downlink compressed mode test case	F	3.12.0	3.13.0	T1-030326
TP-20	TP-030099	247	-	CR to 34.121 R99; Correction to Activation Time in Hard Handover RRM Test Cases	F	3.12.0	3.13.0	T1-030343
TP-20	TP-030099	249	-	CR to 34.121 R99; Correction to Inner Loop Power Control in the Uplink	F	3.12.0	3.13.0	T1-030348
TP-20	- TD 000000	-	-	Upgrade to Rel-4	-	3.13.0	4.0.0	- T4 000700
TP-20	TP-030099	250	-	Addition of clarification for modulation accuracy requirement	F	4.0.0	5.0.0	T1-030732
TP-21	TP-030189	251	-	Creation of a merged release for 34.121 which incorporates R99 and Rel-4	F	5.0.0	5.1.0	T1-030796
TP-21	TP-030189	253	-	CR to 34.121 R99; Addition of test case details for RRM test case 8.3.5.3 (Cell Reselection to GSM in Cell_FACH)	F	3.13.0	5.1.0	T1-030814
TP-21	TP-030189	254	-	CR to 34.121 REL-4; Addition of test case details for RRM test case 8.3.5.3 (Cell Reselection to GSM in Cell_FACH)	Α	4.0.0	5.1.0	T1-030815
TP-21	TP-030189	255	-	CR to 34.121 REL-5; Addition of test case details for RRM test case 8.3.5.3 (Cell Reselection to GSM in Cell_FACH)	Α	5.0.0	5.1.0	T1-030816
TP-21	TP-030189	256	-	Correction of SSDT performance test case (R99)	F	3.13.0	5.1.0	T1-030817
	TP-030189	257	-	Correction of SSDT performance test case (Rel-4)	Α	4.0.0	5.1.0	T1-030818
	TP-030189	258	-	Correction of SSDT performance test case (Rel-5)	Α	5.0.0	5.1.0	T1-030819
TP-21	TP-030189	261	-	Test Requirements for RRM CPICH RSCP Inter Frequency Measurement	F	3.13.0	5.1.0	T1-030841
TP-21	TP-030189	262	-	Test Requirements for RRM CPICH RSCP Inter Frequency Measurement	Α	4.0.0	5.1.0	T1-030842
TP-21	TP-030189	263	-	Test Requirements for RRM CPICH RSCP Inter Frequency Measurement	Α	5.0.0	5.1.0	T1-030843
TP-21	TP-030189	264	-	Test Requirements for RRM CPICH RSCP Intra Frequency Measurement	F	3.13.0	5.1.0	T1-030859
TP-21	TP-030189	265	-	Test Requirements for RRM CPICH RSCP Intra Frequency Measurement	Α	4.0.0	5.1.0	T1-030860
TP-21	TP-030189	266	-	Test Requirements for RRM CPICH RSCP Intra Frequency Measurement	Α	5.0.0	5.1.0	T1-030861
TP-21	TP-030189	267	-	Correction to RRC Re-establishment delay test case (R99)		3.13.0	5.1.0	T1-030862
TP-21	TP-030189	268	-	Correction to RRC Re-establishment delay test case (Rel-4)		4.0.0	5.1.0	T1-030863
TP-21	TP-030189	269	-	Correction to RRC Re-establishment delay test case (Rel-5)	Α	5.0.0	5.1.0	T1-030864
TP-21	TP-030189	270	-	CR to 34.121 R99; Correction to SFN-SFN observed time difference type 1	F	3.13.0	5.1.0	T1-030865
TP-21	TP-030189	271	-	CR to 34.121 Rel-4; Correction to SFN-SFN observed time difference type 1	Α	4.0.0	5.1.0	T1-030866
TP-21	TP-030189	272	-	CR to 34.121 Rel-5; Correction to SFN-SFN observed time difference type 1	Α	5.0.0	5.1.0	T1-030867
TP-21	TP-030189	277	-	CR to 34.121 R99; Correction to CPICH Ec/lo in correct reporting of neighbours in AWGN propagation condition test case	F	3.13.0	5.1.0	T1-031108
TP-21	TP-030189	278	-	CR to 34.121 Rel-4; Correction to CPICH Ec/lo in correct reporting of neighbours in AWGN propagation condition test case	4	4.0.0	5.1.0	T1-031109
TP-21	TP-030189	279	-	CR to 34.121 Rel-5; Correction to CPICH Ec/lo in correct reporting of neighbours in AWGN propagation condition test case	Α	5.0.0	5.1.0	T1-031110
TP-21	TP-030189	280	-	Test Requirements for RRM CPICH Ec/lo Intra Frequency Measurement	F	3.13.0	5.1.0	T1-031182
TP-21	TP-030189	281	-	Test Requirements for RRM CPICH Ec/lo Intra Frequency Measurement	Α	4.0.0	5.1.0	T1-031183
TP-21	TP-030189	282	-	CR Rel 5 Test requirements for RRM CPICH_Ec/lo Intra Frequency Measurement	Α	5.0.0	5.1.0	T1-031184
TP-21	TP-030189	283	-	Test Requirements for RRM CPICH Ec/lo Inter Frequency Measurement	F	3.13.0	5.1.0	T1-031188
TP-21	TP-030189	284	1_	Test Requirements for RRM CPICH Ec/lo Inter	Α	4.0.0	5.1.0	T1-031189

T Meeting	Doc-1 st -Level	CR	Rev	Subject	Cat	Version - Current	Version -New	Doc-2 nd -Level
TP-21	TP-030189	285	-	Test Requirements for RRM CPICH Ec/lo Inter Frequency Measurement	А	5.0.0	5.1.0	T1-031190
TP-21	TP-030189	286	-	Test requirements for RRM Random Access tests	F	3.13.0	5.1.0	T1-031191
TP-21	TP-030189	287	-	Test requirements for RRM Random Access Test	A	4.0.0	5.1.0	T1-031192
TP-21	TP-030189	288	-	Test requirements for RRM Random Access Test	Α	5.0.0	5.1.0	T1-031193
TP-21	TP-030189	289	-	Completion of Annex F	F	3.13.0	5.1.0	T1-031229
TP-21	TP-030189	290	-	Completion of Annex F	Α	4.0.0	5.1.0	T1-031230
TP-21	TP-030189	291	-	Completion of Annex F	Α	5.0.0	5.1.0	T1-031231
TP-21	TP-030189	252	-	CR to 34.121 R99; Correction to Inter-system Handover from UTRAN FDD to GSM	F	3.13.0	5.1.0	T1-030800
TP-21	TP-030189	273	-	CR to 34.121 Rel-99; Correction to CRC bit for reference measurement channel using RLc-TM for DTCH, transport channel parameters	F	3.13.0	5.1.0	T1-030870
TP-21	TP-030189	274	-	Introduction of Test Tolerances to Cell Reselection in CELL_FACH tests 8.3.5.1 & 8.3.5.2	F	3.13.0	5.1.0	T1-030873
TP-21	TP-030189	259	-	Introduction of Test Tolerances to Cell Reselection	F	4.0.0	5.1.0	T1-030832
TP-21	TP-030189	260	-	in CELL_FACH tests 8.3.5.1 & 8.3.5.2 Introduction of Test Tolerances to Cell Reselection	F	5.0.0	5.1.0	T1-030833
TP-21	TP-030189	275	-	in CELL_FACH tests 8.3.5.1 & 8.3.5.2 CR to 34.121 Rel-4; Correction to Inter-system	F	4.0.0	5.1.0	T1-031103
TP-21	TP-030189	276	-	Handover from UTRAN FDD to GSM CR to 34.121 Rel-5; Correction to Inter-system	F	5.0.0	5.1.0	T1-031104
TP-21	TP-030189	292	-	Handover from UTRAN FDD to GSM CR to 34.121 Rel-4; Correction to CRC bit for	F	4.0.0	5.1.0	T1-030871
		202		reference measurement channel using RLc-TM for DTCH, transport channel parameters		1.0.0	0.1.0	11 000071
TP-21	TP-030189	293	=	CR to 34.121 Rel-5; Correction to CRC bit for reference measurement channel using RLc-TM for DTCH, transport channel parameters	F	5.0.0	5.1.0	T1-030872
TP-21	TP-030189	296	-	Introduction of the phase discontinuity test (Specific to Rel-5)	F	5.0.0	5.1.0	T1-031277
TD 00	TD 000000			Complete CR266 implementation		5.1.0	5.1.1	T
TP-22		298		CR to 34.121: Correction to Inter-system Handover from UTRAN FDD to GSM	F	5.1.1	5.2.0	T1-031356
TP-22	TP-030280	299		CR to 34.121: Correction to Power control in DL, initial convergence test case	F	5.1.1	5.2.0	T1-031357
TP-22	TP-030280	319		Correction to RRM test case 8.3.2.1	F	5.1.1	5.2.0	T1-031445
TP-22		314	1	Correction of clause 4.2 Frequency bands	В	5.1.1	5.2.0	T1-031551
TP-22	TP-030280	315	1	Clause 4.4 Channel arrangement for DS-CDMA Introduction in the 800 MHz Band	В	5.1.1	5.2.0	T1-031552
TP-22	TP-030280	316	1	DS-CDMA Introduction in the 800 MHz Band	В	5.1.1	5.2.0	T1-031553
TP-22	TP-030280	317	1	Correction and maintenance of Annex H and DS- CDMA Introduction in the 800 MHz Band	В	5.1.1	5.2.0	T1-031556
TP-22	TP-030280	300	1	Introduction of reference to RRM test tolerances TR	F	5.1.1	5.2.0	T1-031561
TP-22	TP-030280	301	1	Introduction of Test Tolerances to Cell Reselection tests 8.2.2.1 & 8.2.2.2	F	5.1.1	5.2.0	T1-031562
TP-22	TP-030280	302	1	Introduction of Test Tolerances to Cell Re-selection in CELL_PCH tests 8.3.6.1 & 8.3.6.2	F	5.1.1	5.2.0	T1-031563
TP-22	TP-030280	329		Introduction of Test Tolerances to Cell Re-selection	F	5.1.1	5.2.0	T1-031564
TP-22	TP-030280	303	1	in URA_PCH tests 8.3.7.1 & 8.3.7.2 Clarification of Downlink Physical Channel in table	F	5.1.1	5.2.0	T1-031565
TP-22	TP-030280	309	1	E.3.1 FDD inter-frequency cell identification and	F	5.1.1	5.2.0	T1-031566
TP-22	TP-030280	310	1	measurement reporting test case Changes to section 8.4.3, TFC selection	F	5.1.1	5.2.0	T1-031567
TP-22	TP-030280	327	1	requirements for codec mode switch Test requirements for RRM CPICH RSCP Intra	F	5.1.1	5.2.0	T1-031568
TP-22	TP-030280	328	1	Frequency Measurement Test requirements for RRM CPICH RSCP Inter	F	5.1.1	5.2.0	T1-031569
TP-22		324	1	Frequency Measurement Test requirements for RRM CPICH_Ec/lo Intra	F	5.1.1	5.2.0	T1-031570
TP-22		B25	<u> </u>	Frequency Measurement Test requirements for RRM CPICH_Ec/lo Inter	F	5.1.1	5.2.0	T1-031570
			<u> </u>	Frequency Measurement	F			
TP-22		318		Correction of clause 8.7.3C UE transmitted power		5.1.1	5.2.0	T1-031604
TP-22		304	1	CR to 34.121: Correction to FDD/FDD Soft Handover test case	F	5.1.1	5.2.0	T1-031605
TP-22		308	1	Correction to RRM test case 8.3.5.3	F	5.1.1	5.2.0	T1-031606
TP-22	TP-030280	321	<u>r</u>	12.2 kbit/s RMC is insufficient for BLER testing	F	5.1.1	5.2.0	T1-031611
TP-22	TP-030280	320	<u>[l</u>	Update of initial conditions for RF test cases	F	5.1.1	5.2.0	T1-031612

P-22 TP-030280 807 2 Addition of two new test cases: 7.11 (Demodulation of paging channel (PCH)) and 7.12 (Detection of acquisition indicator (All))		Doc-1 st -Level	CR	Rev	Subject	Cat	Version		Doc-2 nd -Level
Pr-22	Meeting						- Current	-New	
Promotion Prom	FP-22	TP-030280	307	2	of paging channel (PCH)) and 7.12 (Detection of	F	5.1.1	5.2.0	T1-031613
DSCH (fixed reference channel) single link performance performance	P-22	TP-030280	311	1		F	5.1.1	5.2.0	T1-031624
Channel Quality Indicator (CQI) AWGN propagation conditions Conditions	P-22	TP-030280	312	1	DSCH (fixed reference channel) single link performance	F	5.1.1	5.2.0	T1-031625
RRM	P-22	TP-030280	313	1	Channel Quality Indicator (CQI) AWGN propagation conditions	F	5.1.1	5.2.0	T1-031626
Definition Def	P-22	TP-030280	306	1		F	5.1.1	5.2.0	T1-031627
TP-22 TP-030280 332	P-22	TP-030280	331			F	5.1.1	5.2.0	T1-031652
tests to Releases	TP-22	TP-030280	330	1			5.1.1	5.2.0	T1-031692
Level test 6.3	TP-22	TP-030280	332			F	5.1.1	5.2.0	T1-031694
TP-23 TP-040038 333 Correction to the measurement control message in F 5.2.0 5.3.0 T1-040	ГР-23	TP-040038	332	-		F	5.2.0	5.3.0	T1-040099
TP-23 TP-040038 334 S.72 S.72 TP-040038 335 Correction to the measurement control message in F 5.2.0 5.3.0 T1-040 ГР-23	TP-040038	333	-	CPICH_Ec/lo Inter frequency relative accuracy	F	5.2.0	5.3.0	T1-040165	
TP-23 TP-040038 335 Correction of the TGD value for single gap F 5.2.0 5.3.0 T1-040	ГР-23	TP-040038	334	-	Correction to the measurement control message in	F	5.2.0	5.3.0	T1-040288
TP-23 TP-040038 336 Screetion to the Measurement Control message in F 5.2.0 5.3.0 T1-040	ГР-23	TP-040038	335	-	Correction of the TGD value for single gap	F	5.2.0	5.3.0	T1-040289
TP-23 TP-040038 337 Introduction of correct reporting of GSM neighbours F 5.2.0 5.3.0 T1-040	ГР-23	TP-040038	336	-	Correction to the Measurement Control message in	F	5.2.0	5.3.0	T1-040292
TP-23 TP-040038 338 Correction to 8.6.2.1 Correct reporting of neighbours F 5.2.0 5.3.0 T1-040	ГР-23	TP-040038	337	-	Introduction of correct reporting of GSM neighbours	F	5.2.0	5.3.0	T1-040341
TP-23 TP-040038 339 Correction to RRC connection control test 1 and 2 F 5.2.0 5.3.0 T1-040	ΓP-23	TP-040038	338	-	Correction to 8.6.2.1 Correct reporting of neighbours	F	5.2.0	5.3.0	T1-040345
TP-23	ГР-23 ·	TP-040038	339	_	Correction to RRC connection control test 1 and 2	F	5.2.0	5.3.0	T1-040354
TP-23 TP-040038 342 - Removal of square brackets in Annex F.6 F 5.2.0 5.3.0 T1-040				-		F			T1-040100
Definition									
TP-23 TP-040038 344 - Define TBD message parameters for FDD/FDD F 5.2.0 5.3.0 T1-040	P-23	TP-040038	341	-	definition	F	5.2.0	5.3.0	T1-040190
TP-23 TP-040038 344 - Define TBD message parameters for FDD/FDD F 5.2.0 5.3.0 T1-040 TP-23 TP-040038 345 - Introduction of Test Tolerances to FDD/FDD Hard Handover to intra-frequency cell, test 8.3.2.1 F 5.2.0 5.3.0 T1-040 TP-23 TP-040038 346 - Introduction of Test Tolerances to FDD/FDD Hard Handover to inter-frequency cell, test 8.3.2.2 F 5.2.0 5.3.0 T1-040 TP-23 TP-040038 347 - Introduction of PRACH preamble tests B 5.2.0 5.3.0 T1-040 TP-23 TP-040038 348 - Correction of requirements of HSDPA CQI reporting in AWGN propagation conditions F 5.2.0 5.3.0 T1-040 TP-23 TP-040038 349 - Annex A for HSDPA F 5.2.0 5.3.0 T1-040 TP-23 TP-040038 351 - Correction of DL channelisation code value in DL F 5.2.0 5.3.0 T1-040 TP-23 TP-040038 352 - Correction				-					T1-040248
Hard Handover test cases				-					T1-040279
Handover to intra-frequency cell, test 8.3.2.1				-	Hard Handover test cases				T1-040281
Handover to inter-frequency cell, test 8.3.2.2 Fr.23 TP-040038 348 Correction of PRACH preamble tests B 5.2.0 5.3.0 T1-040 T1-040038 T1-04				-	Handover to intra-frequency cell, test 8.3.2.1				T1-040282
TP-23 TP-040038 348 - Correction of requirements of HSDPA CQI reporting in AWGN propagation conditions F 5.2.0 5.3.0 T1-040 in AWGN propagation conditions TP-23 TP-040038 349 - Annex A for HSDPA F 5.2.0 5.3.0 T1-040 T				-	Handover to inter-frequency cell, test 8.3.2.2	F			T1-040284
In AWGN propagation conditions				-					T1-040330
TP-23 TP-040038 349 - Annex A for HSDPA F 5.2.0 5.3.0 T1-040 TP-23 TP-040038 350 - Annex F.1 for HSDPA F 5.2.0 5.3.0 T1-040 TP-23 TP-040038 351 - Correction of DL channelisation code value in DL radio resources F 5.2.0 5.3.0 T1-040 TP-23 TP-040038 352 - Correction to F.4.1 F 5.2.0 5.3.0 T1-040 TP-23 TP-040038 353 - Links to Annex F.6.2 in RRM test cases F 5.2.0 5.3.0 T1-040 TP-23 TP-040038 354 - Clarify measurement control for FDD/FDD Interfequency Hard Handover test case F 5.2.0 5.3.0 T1-040 TP-23 - - Correction on implementation of CR 333 on CPICH_EC/lo Inter frequency relative accuracy requirements for reported values on Table R.7.2.2.2.3 5.3.1 5.3.0 5.3.1 5.4.0 T1-040 TP-24 TP-040113 355 - Introduction of Test Tolerances to Event trigger	P-23	TP-040038	348	-		F	5.2.0	5.3.0	T1-040333
TP-23 TP-040038 350 - Annex F.1 for HSDPA F 5.2.0 5.3.0 T1-040 TP-23 TP-040038 351 - Correction of DL channelisation code value in DL radio resources F 5.2.0 5.3.0 T1-040 TP-23 TP-040038 352 - Correction to F.4.1 F 5.2.0 5.3.0 T1-040 TP-23 TP-040038 353 - Links to Annex F.6.2 in RRM test cases F 5.2.0 5.3.0 T1-040 TP-23 TP-040038 354 - Clarify measurement control for FDD/FDD Interfrequency Hard Handover test case F 5.2.0 5.3.0 T1-040 TP-23 - - Correction on implementation of CR 333 on CPICH_Ec/lo Inter frequency requirements for reported values on Table F 5.3.0 5.3.1 - TP-24 TP-040113 355 - Introduction of Test Tolerances to Event triggered reporting in AWGN propagation conditions, test F 5.3.1 5.4.0 T1-040 TP-24 TP-040113 356 - Corrections to CPICH RSCP tes	ГР-23 ·	TP-040038	349	_		F	5.2.0	5.3.0	T1-040337
TP-23 TP-040038 351 - Correction of DL channelisation code value in DL radio resources F 5.2.0 5.3.0 T1-040 TP-23 TP-040038 352 - Correction to F.4.1 F 5.2.0 5.3.0 T1-040 TP-23 TP-040038 353 - Links to Annex F.6.2 in RRM test cases F 5.2.0 5.3.0 T1-040 TP-23 TP-040038 354 - Clarify measurement control for FDD/FDD Interfrequency Hard Handover test case F 5.2.0 5.3.0 T1-040 TP-23 - - Correction on implementation of CR 333 on CPICH_Ec/lo Inter frequency relative accuracy requirements for reported values on Table 8.7.2.2.2.3 F 5.3.0 5.3.1 - TP-24 TP-040113 355 - Introduction of Test Tolerances to Event triggered reporting in AWGN propagation conditions, test 8.6.1.1 F 5.3.1 5.4.0 T1-040 TP-24 TP-040113 356 - Corrections to CPICH RSCP test cases F 5.3.1 5.4.0 T1-040 TP-24 TP-040113 358				-				5.3.0	T1-040338
TP-23 TP-040038 353 - Links to Annex F.6.2 in RRM test cases F 5.2.0 5.3.0 T1-040 TP-23 TP-040038 354 - Clarify measurement control for FDD/FDD Interfrequency Hard Handover test case F 5.2.0 5.3.0 T1-040 TP-23 - - - Correction on implementation of CR 333 on CPICH_Ec/lo Inter frequency relative accuracy requirements for reported values on Table 8.7.2.2.2.3 F 5.3.0 5.3.1 - TP-24 TP-040113 355 - Introduction of Test Tolerances to Event triggered reporting in AWGN propagation conditions, test 8.6.1.1 F 5.3.1 5.4.0 T1-040 TP-24 TP-040113 356 - Corrections to CPICH RSCP test cases F 5.3.1 5.4.0 T1-040 TP-24 TP-040113 358 - Correction to 8.4.1.1 RRC connection control test 1 F 5.3.1 5.4.0 T1-040 TP-24 TP-040113 359 - Correction to MEASUREMENT CONTROL and MEASUREMENT CONTROL and MEASUREMENT REPORT messages F 5.3.1 5.4.0 T1-040				-	Correction of DL channelisation code value in DL				T1-040339
TP-23 TP-040038 353 - Links to Annex F.6.2 in RRM test cases F 5.2.0 5.3.0 T1-040 TP-23 TP-040038 354 - Clarify measurement control for FDD/FDD Interfrequency Hard Handover test case F 5.2.0 5.3.0 T1-040 TP-23 - - - Correction on implementation of CR 333 on CPICH_Ec/lo Inter frequency relative accuracy requirements for reported values on Table 8.7.2.2.2.3 F 5.3.0 5.3.1 - TP-24 TP-040113 355 - Introduction of Test Tolerances to Event triggered reporting in AWGN propagation conditions, test 8.6.1.1 F 5.3.1 5.4.0 T1-040 TP-24 TP-040113 356 - Corrections to CPICH RSCP test cases F 5.3.1 5.4.0 T1-040 TP-24 TP-040113 358 - Correction to 8.4.1.1 RRC connection control test 1 F 5.3.1 5.4.0 T1-040 TP-24 TP-040113 359 - Correction to MEASUREMENT CONTROL and MEASUREMENT CONTROL and MEASUREMENT REPORT messages F 5.3.1 5.4.0 T1-040	TP-23	TP-040038	352	[5.2.0	5.3.0	T1-040393
TP-23 - Correction on implementation of CR 333 on CPICH_Ec/lo Inter frequency relative accuracy requirements for reported values on Table 8.7.2.2.2.3 Introduction of Test Tolerances to Event triggered reporting in AWGN propagation conditions, test 8.6.1.1 Example 1.5.3.1 Example 2.5.3.1 ΓP-23 ⁻			-				5.3.0	T1-040139	
TP-23 - - Correction on implementation of CR 333 on CPICH_Ec/lo Inter frequency relative accuracy requirements for reported values on Table 8.7.2.2.2.3 F 5.3.0 5.3.1 - TP-24 TP-040113 355 - Introduction of Test Tolerances to Event triggered reporting in AWGN propagation conditions, test 8.6.1.1 F 5.3.1 5.4.0 T1-040 TP-24 TP-040113 356 - Corrections to CPICH RSCP test cases F 5.3.1 5.4.0 T1-040 TP-24 TP-040113 357 - Corrections to CPICH Ec/lo test cases F 5.3.1 5.4.0 T1-040 TP-24 TP-040113 358 - Correction to 8.4.1.1 RRC connection control test 1 F 5.3.1 5.4.0 T1-040 TP-24 TP-040113 359 - Correction to MEASUREMENT CONTROL and MEASUREMENT CONTROL and MEASUREMENT REPORT messages F 5.3.1 5.4.0 T1-040 TP-24 TP-040113 360 - Addition of unit for OCNS_Ec/lor in RRM tests F 5.3.1 5.4.0 T1-040		TP-040038	354	-	frequency Hard Handover test case				T1-040252
TP-24 TP-040113 355 - Introduction of Test Tolerances to Event triggered reporting in AWGN propagation conditions, test 8.6.1.1 F 5.3.1 5.4.0 T1-040 TP-24 TP-040113 356 - Corrections to CPICH RSCP test cases F 5.3.1 5.4.0 T1-040 TP-24 TP-040113 357 - Corrections to CPICH Ec/lo test cases F 5.3.1 5.4.0 T1-040 TP-24 TP-040113 358 - Correction to 8.4.1.1 RRC connection control test 1 F 5.3.1 5.4.0 T1-040 TP-24 TP-040113 359 - Correction to MEASUREMENT CONTROL and MEASUREMENT REPORT messages F 5.3.1 5.4.0 T1-040 TP-24 TP-040113 360 - Addition of unit for OCNS_Ec/lor in RRM tests F 5.3.1 5.4.0 T1-040	P-23 -	-	-	-	Correction on implementation of CR 333 on CPICH_Ec/lo Inter frequency relative accuracy requirements for reported values on Table	F	5.3.0	5.3.1	-
TP-24 TP-040113 357 - Corrections to CPICH Ec/lo test cases F 5.3.1 5.4.0 T1-040 TP-24 TP-040113 358 - Correction to 8.4.1.1 RRC connection control test 1 F 5.3.1 5.4.0 T1-040 TP-24 TP-040113 359 - Correction to MEASUREMENT CONTROL and MEASUREMENT REPORT messages F 5.3.1 5.4.0 T1-040 TP-24 TP-040113 360 - Addition of unit for OCNS_Ec/lor in RRM tests F 5.3.1 5.4.0 T1-040				-	Introduction of Test Tolerances to Event triggered reporting in AWGN propagation conditions, test 8.6.1.1				T1-040524
TP-24 TP-040113 358 - Correction to 8.4.1.1 RRC connection control test 1 F 5.3.1 5.4.0 T1-040 TP-24 TP-040113 359 - Correction to MEASUREMENT CONTROL and MEASUREMENT REPORT messages F 5.3.1 5.4.0 T1-040 TP-24 TP-040113 360 - Addition of unit for OCNS_Ec/lor in RRM tests F 5.3.1 5.4.0 T1-040				-					T1-040533
TP-24 TP-040113 359 - Correction to MEASUREMENT CONTROL and MEASUREMENT REPORT messages F 5.3.1 5.4.0 T1-040 TP-24 TP-040113 360 - Addition of unit for OCNS_Ec/lor in RRM tests F 5.3.1 5.4.0 T1-040				-					T1-040534
MEASUREMENT REPORT messages TP-24 TP-040113 360 - Addition of unit for OCNS_Ec/lor in RRM tests F 5.3.1 5.4.0 T1-040				-					T1-040864 T1-040541
				<u> </u>	MEASUREMENT REPORT messages				
11P-24 TTP-040113 T361 I- Correction to default messages in Annex Lof 34 121 TF T5 3.1 T5 4.0 TT1-040		TP-040113	361	-		F	5.3.1	5.4.0	T1-040542
				1-					T1-040695

T Meeting	Doc-1 st -Level	CR	Rev	Subject	Cat	Version - Current	Version -New	Doc-2 nd -Level
TP-24	TP-040113	363	-	Correction of Spurious Emissions for UMTS800(band VI)	F	5.3.1	5.4.0	<u>T1-040700</u>
TP-24	TP-040113	364	-	Removal of [] for UE transmit power test case 8.7.3C	F	5.3.1	5.4.0	T1-040720
	TP-040113	365	-	Correction to 8.7.6 UE Rx-Tx time difference	F	5.3.1	5.4.0	T1-040728
	TP-040113	366	1-	Inter system handover	F	5.3.1	5.4.0	T1-040805
	TP-040113	367	-	Correction to BTFD test case 7.10	F	5.3.1	5.4.0	T1-040815
TP-24	TP-040113	368	1_	Addition of details for RRM test case for GSM carrier		5.3.1	5.4.0	T1-040816
	TP-040113	369	<u> </u>	RSSI Correction of FDD intra frequency measurements ,	r F	5.3.1	5.4.0	T1-040817
			-	wrong IEs				
	TP-040113	370	-	Correction of FDD inter frequency measurements, wrong IEs	F	5.3.1	5.4.0	<u>T1-040818</u>
TP-24	TP-040113	371	-	Correction to Transmit Off Power	F	5.3.1	5.4.0	T1-040824
	TP-040113	372	-	Corrections to UTRA Carrier RSSI test cases	F	5.3.1	5.4.0	T1-040825
	TP-040113	373	-	Corrections to FDD/FDD Soft Handover test cases	F	5.3.1	5.4.0	T1-040826
TP-24	TP-040113	374	-	Correction to the pathloss indicator in measurement control messages	F	5.3.1	5.4.0	T1-040827
TP-24	TP-040113	375	-	Corrections to SFN-CFN observed time difference test cases	F	5.3.1	5.4.0	<u>T1-040831</u>
TP-24	TP-040113	376	-	Corrections to SFN-SFN type 1 measurement test cases	F	5.3.1	5.4.0	T1-040832
TP-24	TP-040113	377	-	Correction to URA identity for reselection in Cell	F	5.3.1	5.4.0	<u>T1-040834</u>
TP-24	TP-040113	378	-	Proposed addition of downlink code allocation table	F	5.3.1	5.4.0	<u>T1-040838</u>
TP-24	TP-040113	379	-	to 34.121 Annex Correction of channel number for UMTS800(band VI)	F	5.3.1	5.4.0	<u>T1-040839</u>
TP-24	TP-040113	380	-	Correction to the pathloss indicator in measurement	F	5.3.1	5.4.0	<u>T1-040840</u>
				control messages				
	TP-040113	381	=	HSDPA test 9.3.1	F	5.3.1	5.4.0	T1-040842
TP-24	TP-040113	382	-	HSDPA test 9.3.2	F	5.3.1	5.4.0	T1-040843
TP-24	TP-040113	383	-	New test case for 9.2.2 Open Loop Diversity Performance	F	5.3.1	5.4.0	<u>T1-040844</u>
	TP-040113	385	-	Statistical approach for HSDPA tests	F	5.3.1	5.4.0	T1-040854
	TP-040113	386	-	Correction to GSM neighbour reporting in 8.6.4.1	F	5.3.1	5.4.0	T1-040856
	TP-040113	387	-	Correction to measurement report in 8.3.2	F	5.3.1	5.4.0	T1-040857
TP-24	TP-040113	388	-	Corrections to UE Rx-Tx time difference type 1 test cases	F	5.3.1	5.4.0	<u>T1-040859</u>
TP-24	TP-040113	389	-	Addition of MEASUREMENT CONTROL message and ACTIVESET UPDATE message in 8.5.1	F	5.3.1	5.4.0	<u>T1-040863</u>
TP-24	TP-040113	391	-	HSDPA test: 9.2.1	F	5.3.1	5.4.0	T1-040871
TP-24	TP-040113	392	-	New test case for 9.4 HS-SCCH Detection Performance	F	5.3.1	5.4.0	T1-040872
TP-24	TP-040113	393	1_	New TPC combining in SHO	F	5.3.1	5.4.0	T1-040873
	TP-040113	394	-	New test case for 9.2.3 Closed Loop Diversity	F	5.3.1	5.4.0	T1-040874
TP-24	TP-040113	395	-	Performance Addition of CELL_UPDATE CONFIRM Message and	F	5.3.1	5.4.0	<u>T1-040866</u>
TP-24	TP-040113	396	-		F	5.3.1	5.4.0	<u>T1-040855</u>
TP-25	TP-040158	395	-	(PCH)) Addition of a new case to Adjacent Channel	F	5.4.0	5.5.0	T1-041017
TP-25	TP-040158	396	-	Selectivity test Removal of [] for test case 8.3.5.3 'Cell Reselection	D	5.4.0	5.5.0	T1-041034
			1	to GSM'				
TP-25	TP-040158	397	-	Addition of the integrity protection in messages	F	5.4.0	5.5.0	T1-041058
TP-25	TP-040158	398	-	Correction to Cell Re-selection in CELL_PCH and URA_PCH test cases	F	5.4.0	5.5.0	T1-041076
TP-25	TP-040158	399	[-	Addition of test tolerances to TC 8.4.3	F	5.4.0	5.5.0	T1-041093
TP-25	TP-040158	400	-	Revision of Test Tolerances to Event triggered reporting in AWGN propagation conditions, test	F	5.4.0	5.5.0	T1-041098
TP-25	TP-040158	401	-	8.6.1.1 Correction of RRM test case 8.7.3A (GSM carrier	F	5.4.0	5.5.0	T1-041176
TP-25	TP-040158	402	-	RSSI) Completion of Annex F.6.3 Statistical Testing of	F	5.4.0	5.5.0	T1-041201
TP-25	TP-040158	403	-	HSDPA Receiver Performance Correction to the Measurement Control message in	F	5.4.0	5.5.0	T1-041203
TP-25	TP-040158	404	-	8.7.6 UE Rx-Tx time difference	F	5.4.0	5.5.0	T1-041204
TP-25	TP-040158	405	<u> </u>	control messages Correction to test uncertainty definition of Inner Loop		5.4.0	5.5.0	T1-041307
20	010100			Power Control in the Uplink test case	<u> </u>	3	3.0.0	. 1 0 11007

T Meeting	Doc-1 st -Level	CR	Rev	Subject	Cat	Version - Current	Version -New	Doc-2 nd -Level
TP-25	TP-040158	406	-	Addition of the integrity protection in 5.7 Power setting in uplink compressed mode	F	5.4.0	5.5.0	T1-041308
TP-25	TP-040158	407	-	Corrections to Demodulation of DCH in Inter-Cell Soft Handover	В	5.4.0	5.5.0	T1-041311
TP-25	TP-040158	408	-	Correction to 7.7.3: Combining of reliable TPC commands from radio links of different radio link sets	F	5.4.0	5.5.0	T1-041314
TP-25	TP-040158	409	-	Addition of TPC error rate accuracy to TC 7.7.3	F	5.4.0	5.5.0	T1-041316
TP-25	TP-040158	410	-	Test system uncertainties update for test case 8.3.5.3	F	5.4.0	5.5.0	T1-041319
TP-25	TP-040158	411	-		F	5.4.0	5.5.0	T1-041325
TP-25	TP-040158	412	-	DPCH and S-CCPCH	F	5.4.0	5.5.0	T1-041326
TP-25	TP-040158	413	-	in Annex I	F	5.4.0	5.5.0	T1-041328
TP-25	TP-040158	414	-	Correction to 5.5.2: Transmit ON/OFF Time mask test case	F	5.4.0	5.5.0	T1-041333
TP-25	TP-040158	415	-	Cell configuration mapping	F	5.4.0	5.5.0	T1-041341
TP-25	TP-040158	416	-	Test tolerances in 8.4.1 RRC Re-establishment delay	F	5.4.0	5.5.0	T1-041344
TP-25	TP-040158	417	-	Completion of Transmitter Intermodulation test 5.12	F	5.4.0	5.5.0	T1-041345
TP-25	TP-040158	418	-	Correction of reference to generic setup procedure in TS 34.108 for Cell_FACH	F	5.4.0	5.5.0	T1-041348
TP-25	TP-040158	419	-	Correction to TC 7.8.3, Power control in the downlink, wind up effects	F	5.4.0	5.5.0	T1-041349
TP-25	TP-040158	420	-	Revision of Receiver Spurious Emissions Test 6.8	F	5.4.0	5.5.0	T1-041353
TP-25	TP-040158	421	-	Correction to BTFD test case 7.10 and DL dummy DCCH	F	5.4.0	5.5.0	T1-041358
TP-25	TP-040158	422	-	Correction to measurement control message in 8.6.1.2	F	5.4.0	5.5.0	T1-041360
TP-25	TP-040158	423	-	Correction to test case 8.2.3 'UTRAN to GSM Cell Re-Selection'	F	5.4.0	5.5.0	T1-041362
TP-25	TP-040158	425	-	Corrections to Annex F.2.4 and F.4.4	F	5.4.0	5.5.0	T1-041322
TP-25	TP-040158	426	-	Introduction of Test Tolerances to Event triggered reporting of multiple neighbours in AWGN propagation condition, test 8.6.1.2	F	5.4.0	5.5.0	T1-041329
TP-25	TP-040158	427	-	Correction to 8.6.1.1	F	5.4.0	5.5.0	T1-041361
TP-25	TP-040158	429	-	Proposed addition of HSDPA downlink code allocation to 34.121 Annex	F	5.4.0	5.5.0	T1-041372
TP-25	TP-040158	430	-	Maximum Input Level for HSDPA	F	5.4.0	5.5.0	T1-041375
TP-25	TP-040158	431	-	Correction to test procedure for test cases using Cell_PCH or URA_PCH state	F	5.4.0	5.5.0	T1-041347r2
TP-25	TP-040158	432	-	Clarification of OCNS power control	F	5.4.0	5.5.0	T1-041318r4
TP-26	TP-040234	433	-	Addition of UMTS-850 Band V to chapter 5	F	5.5.0	5.6.0	T1-041524
TP-26	TP-040234	434	-	parameters	F	5.5.0	5.6.0	T1-041567
TP-26	TP-040234	435	-	Corrections to TC 8.7.3C UE transmitted power	F	5.5.0	5.6.0	T1-041577
TP-26	TP-040234	436	-	Addition of test tolerances to TC 8.3.4	F	5.5.0	5.6.0	T1-041579
TP-26	TP-040234	437	-	New clause for reference conditions	F	5.5.0	5.6.0	T1-041648
TP-26 TP-26	TP-040234 TP-040234	438 439	-	Alignment of HSDPA OCNS with TS 25.101 Correction to Handover to GSM TC 8.3.4	F F	5.5.0 5.5.0	5.6.0 5.6.0	T1-041650 T1-041653
TP-26	TP-040234	440	-	Correction to test procedure in 7.12	F	5.5.0	5.6.0	T1-041661
TP-26	TP-040234	441	-	Correction to 8.7.6.1 UE Rx-Tx time difference type	F	5.5.0	5.6.0	T1-041662
TP-26	TP-040234	442	-	Corrections to RRM test cases 8.6.1.2 Event triggered reporting	F	5.5.0	5.6.0	T1-041667
TP-26	TP-040234	443	1-	Update of references to GSM core specifications	F	5.5.0	5.6.0	T1-041684
TP-26	TP-040234	444		Corrections to HSDPA test 9.4 (HS-SCCH detection)	F	5.5.0	5.6.0	T1-041749
TP-26	TP-040234	445	-	Clarification of HS-PDSCH and HS-SCCH signal structure	F	5.5.0	5.6.0	T1-041790
TP-26	TP-040234	446	-	CR to 34.121 Rel 5: Editorial corrections to test 8.7.3		5.5.0	5.6.0	T1-041810
TP-26	TP-040234	447	-	Corrections to BTFD test case	F	5.5.0	5.6.0	T1-041813
TP-26	TP-040234	448		Corrections to RRM test cases 8.3.2.1 and 8.3.2.2 Correction to the test procedure of FDD/FDD Hard Handover test cases	F	5.5.0	5.6.0	T1-041818
TP-26	TP-040234	449	-	Corrections to TC 8.6.4.1	F	5.5.0	5.6.0	T1-041822
TP-26	TP-040234	450	1-	Correction to pathloss indicator	F	5.5.0	5.6.0	T1-041824
TP-26	TP-040234	451	-	Corrections to RRM test case 8.5.1 UE Transmit	F	5.5.0	5.6.0	T1-041830
TP-26	TP-040234	452	-	Timing Corrections and additions to Release 5 RRM test	F	5.5.0	5.6.0	T1-041831
TP-26	TP-040234	453		case 8.6.2.2 Measurement Channel for BLER measurement in	F	5.5.0	5.6.0	T1-041832
11 - 20	11 040204	-100		8.3.1 FDD/FDD Soft Handover.	•	0.0.0	0.0.0	11041002

T Meeting	Doc-1 st -Level	CR	Rev	Subject	Cat	Version - Current	Version -New	Doc-2 nd -Level
TP-26	TP-040234	454	-	Correction to SFN-SFN observed time difference type 1 measurement test case	F	5.5.0	5.6.0	T1-041834
TP-26	TP-040234	455	-	Corrections to HSDPA test 6.3A (max input power)	F	5.5.0	5.6.0	T1-041838
TP-26	TP-040234	456	-	CM configuration in FDD inter frequency measurements in TC 8.6.2.1	F	5.5.0	5.6.0	T1-041841
TP-26	TP-040234	457	=	Addition of the scheduling information for Cell Re- Selection test cases	F	5.5.0	5.6.0	T1-041843
TP-26	TP-040234	458	-	Correction to 8.3.1 UE FDD/FDD Soft Handover	F	5.5.0	5.6.0	T1-041844
TP-26	TP-040234	459	-	Correction to 8.7.1.1 CPICH RSCP Intra frequency measurements accuracy	F	5.5.0	5.6.0	T1-041845
TP-26	TP-040234	460	-	Corrections to HSDPA test 9.3 (CQI reporting)	F	5.5.0	5.6.0	T1-041852
TP-26	TP-040234	461	-	Correction to measurement configurations in section 7	F	5.5.0	5.6.0	T1-041858
TP-26	TP-040234	462	-	Change of notes position in TS34.121 Annex E.3	F	5.5.0	5.6.0	T1-041859
TP-26	TP-040234	463	-	BLER testing for UEs with asymmetrical UL/DL data rates	F	5.5.0	5.6.0	T1-041860
TP-26	TP-040234	464	-	Invalid MAC header for downlink dummy DCCH	F	5.5.0	5.6.0	T1-041861
TP-26	TP-040234	465	-	Addition of test tolerances and corrections for 8.6.2.1 Correct reporting of neighbours in AWGN propagation condition (34.121)	F	5.5.0	5.6.0	T1-041865
TP-26	TP-040234	466	-	Correction to Correct reporting of neighbours in fading propagation condition test case	F	5.5.0	5.6.0	T1-041866
TP-26	TP-040234	467	-	Correction to Event triggered reporting of two detectable neighbours in AWGN propagation condition test cases	F	5.5.0	5.6.0	T1-041867
TP-26	TP-040234	468	-		F	5.5.0	5.6.0	T1-041868
TP-26	TP-040234	469	-	Corrections to TC 8.2.3.1 and 8.2.3.2	F	5.5.0	5.6.0	T1-041869
TP-26	TP-040234	470	-	Correction to MEASUREMENT CONTROL Message for 8.6.2.1: Correct reporting of neighbours in AWGN propagation condition and 8.3.2.2: FDD/FDD Hard Handover to inter-frequency cell test cases	F	5.5.0	5.6.0	T1-041870
TP-26	TP-040234	471	-	Corrections to HSDPA test 9.2 (Demod of HS-DSCH)	F	5.5.0	5.6.0	T1-041872
TP-26	TP-040234	472	-	Addition of UMTS-850 Band V to chapter 6	F	5.5.0	5.6.0	T1-041873
TP-26	TP-040234	473	=	Correction of time to receive system information in RRM test cases	F	5.5.0	5.6.0	T1-041877
TP-26	TP-040234	474	-	CR to 34.121: Changing the BLER target for the DCCH in test 7.8	D	5.5.0	5.6.0	T1-041878
TP-26	TP-040234	475	-	Corrections to Information elements for Monitored Cells in Annex I.	F	5.5.0	5.6.0	T1-041881
TP-26	TP-040234	476	-	Introduction of UMTS-850 MHz band V	F	5.5.0	5.6.0	T1-041882
TP-26	TP-040234	477	-	Introduction of Test Tolerances to Event triggered reporting of multiple neighbours in AWGN propagation condition (Rel-4 and later), test 8.6.1.2A	F	5.5.0	5.6.0	T1-041507
TP-26	TP-040234	478	-	Addition of UMTS-850 Band V to chapter 4.	F	5.5.0	5.6.0	T1-041523
TP-27	TP-050033	479		Change of test method and test time optimization in TC 8.7.3A	F	5.6.0	6.0.0	T1-050080
TP-27	TP-050033	480		Corrections to RRM test case 8.4.3.1 "Transport format combination selection in UE"	F	5.6.0	6.0.0	T1-050122
TP-27	TP-050033	481		Ior value correction for RRM test case, 8.6.2.1	F	5.6.0	6.0.0	T1-050124
TP-27	TP-050033	482		Removal of editorial notes from TC 8.7.3C	F	5.6.0	6.0.0	T1-050186
TP-27	TP-050033	483		Invalid MAC header for downlink dummy DCCH (mandatory)	F	5.6.0	6.0.0	T1-050215
TP-27	TP-050033	484		Correction to RRC CONNECTION SETUP and RB SETUP messages for TX diversity	F	5.6.0	6.0.0	T1-050217
TP-27	TP-050033	485		Correction to CPICH_Ec/lo in 8.6.1.3	F	5.6.0	6.0.0	T1-050219
TP-27	TP-050033	486		Correction to "Read SFN indicator" in Measurement Control Messages	F	5.6.0	6.0.0	T1-050221
TP-27	TP-050033	487		Table E.3.4 Correction	D	5.6.0	6.0.0	T1-050233
TP-27	TP-050033	488		Addition of 25.212 to reference list	D	5.6.0	6.0.0	T1-050234
TP-27	TP-050033	489		Addition of fading case 8 for HSDPA testing	D F	5.6.0	6.0.0	T1-050235
TP-27 TP-27	TP-050033 TP-050033	490 491		Measurement configuration setup information Addition of uncertainties and test tolerances to TC	F	5.6.0 5.6.0	6.0.0	T1-050308 T1-050309
TP-27	TP-050033	492		7.7.3 Omission of test points in 6.5. Blocking Characteristics	F	5.6.0	6.0.0	T1-050311
TP-27	TP-050033	493		CR to 34.121: Changes to 7.12: Detection of Acquisition Indicator	F	5.6.0	6.0.0	T1-050313
TP-27	TP-050033	494		CR to 34.121: Changes to 8.6.1.2 Event triggered reporting of multiple neighbours in AWGN propagation condition (R99)	F	5.6.0	6.0.0	T1-050315

T Meeting	Doc-1 st -Level	CR	Rev	Subject	Cat	Version -	Version -New	Doc-2 nd -Level
TP-27	TP-050033	495		Deletion of Target quality value on DTCH in Clause	F	Current 5.6.0	6.0.0	T1-050316
TP-27	TP-050033	496		8.7.3C UE transmitted power Clarification of reference value for T Reconfirm Abort	F	5.6.0	6.0.0	T1-050319
TD 07	TD 050000	407		Parameter in Inter-Rat Test Case 8.3.4	_	5.00	0.00	T4 050204
TP-27 TP-27	TP-050033 TP-050033	497 498		Clarification of RRM TC 8.2.3 Correction to "Reporting cell status" in Measurement	F	5.6.0 5.6.0	6.0.0	T1-050321 T1-050322
17-27	11-000000	490		Control Messages			6.0.0	11-050322
TP-27	TP-050033	499		Correction to 8.3.1	F	5.6.0	6.0.0	T1-050324
TP-27	TP-050033	500		Correction to MEASUREMENT REPORT message in Annex I	F	5.6.0	6.0.0	T1-050326
TP-27	TP-050033	501		Removal of Rel-5 specific reference to TS 25.101	F	5.6.0	6.0.0	T1-050329
TP-27	TP-050033	502		Test tolerances for Test 9.2.2 Open loop diversity performance and 9.2.3 Closed loop diversity performance	F	5.6.0	6.0.0	T1-050338
TP-27	TP-050033	503		CR to 34.121: Changes to Annex D and Annex H to introduce UMTS 850 Band	В	5.6.0	6.0.0	T1-050347
TP-27	TP-050033	504		Correction of 34.121 Power vs. Time diagrams	F	5.6.0	6.0.0	T1-050351
TP-27	TP-050033	505		Clarification for Test Case 7.9	F	5.6.0	6.0.0	T1-050352
TP-27	TP-050033	506		Correction to OCNS value in 8.7.2.2	F	5.6.0	6.0.0	T1-050356
TP-27	TP-050033	508		Level Definition HS_SCCH_1 and DPCH for Test 9.2.2 Open loop diversity performance And Test 9.2.3 Closed loop diversity performance	F	5.6.0	6.0.0	T1-050362
TP-27	TP-050033	509		Changes to Annex I to harmonise System Information scheduling for RRM test cases.	F	5.6.0	6.0.0	<u>T1-050366</u>
TP-27	TP-050033	510		Level Definition HS_SCCH_1 and DPCH for Test 9.2.1 Single link performance	F	5.6.0	6.0.0	T1-050368
TP-27	TP-050033	511		Correction to TS34.121 TC 8.4.2	D	5.6.0	6.0.0	T1-050370
TP-27	TP-050033	512		Correction to the event triggered reporting test cases	F	5.6.0	6.0.0	T1-050371
TP-27	TP-050033	513		Corrections to reporting of CQI	F	5.6.0	6.0.0	T1-050373
TP-27	TP-050033	514		Correction to H Set-4/5 pattern length	F	5.6.0	6.0.0	T1-050374
TP-27	TP-050033	515		Corrections to detection of HS-SCCH	F	5.6.0	6.0.0	T1-050375
TP-27	TP-050033	516		CR to 34.121 section 5: Introduction of test case for Adjacent Channel Leakage Power Ratio with HS-DPCCH	В	5.6.0	6.0.0	<u>T1-050376</u>
TP-27	TP-050033	517		CR to 34.121 section 5: Introduction of new test case for HSDPA: UE max output power with HS-DPCCH	В	5.6.0	6.0.0	<u>T1-050377</u>
TP-27	TP-050033	518		CR to 34.121 section 5: Introduction of new test case for Error Vector Magnitude with HS-DPCCH	В	5.6.0	6.0.0	<u>T1-050378</u>
TP-27	TP-050033	519		CR to 34.121 section 5: Introduction of a new test case for spectrum emission mask with HS-DPCCH	В	5.6.0	6.0.0	<u>T1-050379</u>
TP-27	TP-050033	520		CR to 34.121: Changes to RRM test cases for introduction of UMTS 850 Band	В	5.6.0	6.0.0	<u>T1-050381</u>
TP-27	TP-050033	521			F	5.6.0	6.0.0	<u>T1-050382</u>
TP-27	TP-050033	522		Corrections to TC 8.5.1 UE transmit timing	F	5.6.0	6.0.0	T1-050318r3
TP-27	TP-050033	523	1	Corrections to demodulation of HS-DSCH	F	5.6.0	6.0.0	T1-05031813
RP-28	RP-050269	525	-	CR to 34.121: Correction to operating conditions for TCs: 5.13.1, 5.13A.1 & 5.13.2	F	6.0.0	6.1.0	R5-050671
RP-28	RP-050269	526	<u> </u> -	Removal of TGPL2	F	6.0.0	6.1.0	R5-050842
RP-28	RP-050269	527	-	Clarification of the interfering signal in 6.5 Blocking Characteristics and 6.7 Intermodulation Characteristics	F	6.0.0	6.1.0	R5-050816
RP-28	RP-050269	528	ļ	Addition of test tolerances to TC 7.11	F	6.0.0	6.1.0	R5-050615
RP-28	RP-050269	529		Correction to 7.7.2 Combining of TPC commands from radio links of different radio link sets	F	6.0.0	6.1.0	R5-050820
RP-28	RP-050269	530	-	Clarification of TS34.121 Closed Loop Transmit Diversity test cases	F	6.0.0	6.1.0	R5-050833
RP-28	RP-050269	531	-	CR to 34.121: Clarification of Annex C.6 for BLER measurement configurations	F	6.0.0	6.1.0	R5-050843
RP-28	RP-050269	532	-	Change of 34.121 test case 7.8.2	F	6.0.0	6.1.0	R5-050850
RP-28	RP-050269	533	-	Correction to TS34.121 TC 8.6.1.2	F	6.0.0	6.1.0	R5-050571
RP-28	RP-050269	534	-	Corrections to TS34.121 TC 8.7.6.1	F	6.0.0	6.1.0	R5-050573
RP-28 RP-28	RP-050269 RP-050269	535 536	 -	Corrections to test cases having power control ON. Correction to TS34.121 TC 8.6.1.3	F F	6.0.0	6.1.0 6.1.0	R5-050652 R5-050822
RP-28	RP-050269	537	-	Modification of call setup procedure for inter-RAT	F	6.0.0	6.1.0	R5-050823
RP-28	RP-050269	538	-	Connected state RRM tests Addition of test tolerances and corrections for 8.6.2.2 Correct reporting of neighbours in fading propagation condition	F	6.0.0	6.1.0	R5-050825
RP-28	RP-050269	539	<u> -</u>	CR to 34.121: GSM band corrections	F	6.0.0	6.1.0	R5-050829
RP-28	RP-050269	540	t	Statistical approach for 8.7.3A GSM Carrier RSSI	F.	6.0.0	6.1.0	R5-050837

T Meeting	Doc-1 st -Level	CR	Rev	Subject	Cat	Version - Current	Version -New	Doc-2 nd -Level
RP-28	RP-050269	541	-	CR to 34.121 Rel-6; Update of the MEASUREMENT REPORT message to RRC release 5	F	6.0.0	6.1.0	R5-050821
RP-28	RP-050269	542	-	CR to 34.121: Corrections to Annex C and Annex E	F	6.0.0	6.1.0	R5-050830
	RP-050269	543	-	CR to TC 5.9 Spectrum emission mask	F	6.0.0	6.1.0	R5-050814
	RP-050269	544	-	Clarifications of TS34.121 section 9.1	F	6.0.0	6.1.0	R5-050575
	RP-050270	545	-	Editorial correction to TS34.121 TC 9.3.2	D	6.0.0	6.1.0	R5-050718
RP-28	RP-050270	546	-	CR to 34.121: Addition of a new annex section for uplink Reference Measurement Channel for testing of UE Transmitter Characteristics with HS-DPCCH.	F	6.0.0	6.1.0	R5-050841
	RP-050270	547	-	CR to 34.121: New test case for HS-DPCCH.	F	6.0.0	6.1.0	R5-050860
RP-28	RP-050270	548	-	Correction to 9.2.1 Single Link Performance in 9.2 Demodulation of HS-DSCH	F	6.0.0	6.1.0	R5-050864
RP-28	RP-050270	549	-	Corrections to TC 7.12, detection of acquisition indicator (AI)	F	6.0.0	6.1.0	R5-050819
RP-28	RP-050270	550	-	Corrections to test tolerances in TC 7.8.2	F	6.0.0	6.1.0	R5-050847
RP-28	RP-050270	551	-	OCNS for TX diversity	F	6.0.0	6.1.0	R5-050859
RP-28	RP-050270	552	-	Correction to "Read SFN indicator" in Measurement Control Messages in 8.3.2.2	F	6.0.0	6.1.0	R5-050863
RP-28	RP-050270	553	-	Corrections to TC 5.4.1 and 5.5.2 due to too low S-CCPCH level	F	6.0.0	6.1.0	R5-050614
RP-28	RP-050270	554	-	Changes to 8.3.1 FDD/FDD Soft Handover.	F	6.0.0	6.1.0	R5-050877
RP-29	RP-050517	555	-	Addition of test tolerances to open loop power control tolerance	F	6.1.0	6.2.0	R5-051155
	RP-050517	556	-	Correction to 5.13.3	F	6.1.0	6.2.0	R5-051282
RP-29 RP-29	RP-050517 RP-050517	557 558	-	Correction of Transmit ON/OFF Test Case 5.5.2 Clarification to TX OFF power Test Tolerance in TC	F F	6.1.0 6.1.0	6.2.0 6.2.0	R5-051405 R5-051406
RP-29	RP-050517	559		5.5.2 Correction to 5.6	F	6.1.0	6.2.0	R5-051408
RP-29	RP-050517 RP-050517	560	-	Correction to 34.121 for test case: 5.7 Power setting	F	6.1.0	6.2.0	R5-051406 R5-051412
RP-29	RP-050517	561		in uplink compressed mode Correction to 5.3 Frequency Error	F	6.1.0	6.2.0	R5-051440
RP-29	RP-050517	562	-	Output power control in the uplink procedure changes (TC5.4.1)	F	6.1.0	6.2.0	R5-051441
RP-29	RP-050517	563	_	Correction to 5.4.1and 5.5.2	F	6.1.0	6.2.0	R5-051442
RP-29	RP-050517	564	-	Correction to 5.11	F.	6.1.0	6.2.0	R5-051453
RP-29	RP-050517	565	-	CR to 34.121: Correction to TC 7.11 PCH detection regarding SIB5	F	6.1.0	6.2.0	R5-051117
RP-29	RP-050517	566	-	Corrections to Procedure and Test System Uncertainty for TC7.7.3	F	6.1.0	6.2.0	R5-051444
RP-29	RP-050517	567	-	Correction to UE parameters for AI test	F	6.1.0	6.2.0	R5-051452
RP-29	RP-050517	568	-	CR on 34.121: Correction to TC 8.3.3	F	6.1.0	6.2.0	R5-051099
RP-29	RP-050517	569	-	Removal of TC 8.6.1.4 Correct reporting of neighbours in fading propagation condition	F	6.1.0	6.2.0	R5-051159
	RP-050517	570	-		F	6.1.0	6.2.0	R5-051160
RP-29	RP-050517	571	-	CR to 34.121: Correction to RXLEV in test requirements for cell re-selection to GSM test cases	F	6.1.0	6.2.0	R5-051193
RP-29	RP-050517	572	-	Correction to 8.3.5.2	F	6.1.0	6.2.0	R5-051275
RP-29	RP-050517	573	-	Correction to "Reporting cell status" in Measurement Control Messages		6.1.0	6.2.0	R5-051276
RP-29	RP-050517	574	-	TX type 2 measurement requirements	F	6.1.0	6.2.0	R5-051417
RP-29	RP-050518	575	-	Correction to procedure for RRM test case 8.3.5.3	F	6.1.0	6.2.0	R5-051418
RP-29 RP-29	RP-050518 RP-050518	576 577	-	Update of Annex I and K Correction / Clarification to Annex E Transmit	F F	6.1.0 6.1.0	6.2.0 6.2.0	R5-051421 R5-051416
DD 00	DD 050510	570		Diversity	_	0.4.0	0.00	DE 054072
RP-29 RP-29	RP-050518 RP-050518	578 579	-	Feature Clean Up: Removal of Closed Loop mode 2 Feature Clean Up: Removal of DRAC from TS	F F	6.1.0 6.1.0	6.2.0 6.2.0	R5-051072 R5-051422
RP-29	RP-050518	580	-	34.121 Feature Clean Up: Removal of Observed Time	F	6.1.0	6.2.0	R5-051423
RP-29	RP-050518	581	-	Difference to GSM cell from TS 34.121 Feature Clean Up: Removal of SSDT from TS	F	6.1.0	6.2.0	R5-051424
RP-29	RP-050518	582	-	34.121 Feature Clean Up: Removal of compressed mode by	F	6.1.0	6.2.0	R5-051425
RP-29	RP-050518	583	 	puncturing Feature Clean Up: Removal of DSCH	F	6.1.0	6.2.0	R5-051426
RP-29	RP-050518	584	-	Feature Clean Up to 34.121: Removal of CPCH	F	6.1.0	6.2.0	R5-051426
RP-29	RP-050518	585	-	Correction to Annex F for 6.3A Maximum Input Level for HS-PDSCH Reception	F	6.1.0	6.2.0	R5-051278
RP-29	RP-050518	586	-	Correction to 9.2.3 Closed Loop Diversity Performance	F	6.1.0	6.2.0	R5-051279

T	Doc-1 st -Level	CR	Rev	Subject	Cat	Version		Doc-2 nd -Level
Meeting						- Current	-New	
RP-29	RP-050518	587	-	Correction to 5.9A Spectrum Emission Mask with HS-DPCCH	F	6.1.0	6.2.0	R5-051429
RP-29	RP-050513	588	-	Correction to 34.121 for HSDPA test case: Maximum Output Power with HS-DPCCH and addition of Uplink Reference Measurement Channel	F	6.1.0	6.2.0	R5-051431
RP-29	RP-050518	589		for testing Table C.8.1.5 Correction	F	6.1.0	6.2.0	R5-051433
RP-29	RP-050518	590	- -	Correction to 5.10A ACLR with HS-DPCCH	F	6.1.0	6.2.0	R5-051433
RP-29	RP-050513	591	-	Correction to 34.121 for HSDPA test case 5.7A: HS-	F	6.1.0	6.2.0	R5-051449
RP-29	RP-050518	592	_	DPCCH Removal of 1st BLER measurement in TC 7.8.1 and		6.1.0	6.2.0	R5-051438
				7.9.1				
RP-29	RP-050518	593	-	Corrections and Clarification of TC8.6.4.1	F	6.1.0	6.2.0	R5-051589
RP-29	RP-050518	594	- -	Corrections to Inter-system handover TC 8.3.4 Correction to 34.121 for HSDPA test case 5.7A: HS-	F F	6.1.0	6.2.0	R5-051590
	RP-050767	595	-	DPCCH		6.2.0	6.3.0	R5-051921
RP-30	RP-050767	596	-	Correction to 34.121: UE Capabilities for HSDPA testing	F	6.2.0	6.3.0	R5-052341
RP-30	RP-050767	597	-	Correction to power step size for HSDPA test case 5.7A: HS-DPCCH	F	6.2.0	6.3.0	R5-051927
RP-30	RP-050716	598	-	Addition of reference measurement channel for E- DCH RF testing	F	6.2.0	6.3.0	R5-052327
RP-30	RP-050719	599	-	Restructuring of chapter 9.4 (HS-SCCH detection performance)	F	6.2.0	6.3.0	R5-052333
RP-30	RP-050719	600	-	Addition of HSDPA Enhanced performance requirements plus splitting of Test Cases in Sections 9.2.1, 9.2.2 and 9.2.3	В	6.2.0	6.3.0	R5-052343
RP-30	RP-050767	601	-	Addition of Open and Closed loop diversity Rel-6 test cases for CQI reporting in section 9.3 and calculation of BLER during CQI reporting tests	В	6.2.0	6.3.0	R5-052318
RP-30	RP-050770	602	-	Modification of the protection band for PHS	F	6.2.0	6.3.0	R5-051994
RP-30	RP-050770	603	-	Revision of additional receiver spurious emissions requirements on 800MHz band in Japan	F	6.2.0	6.3.0	R5-051995
RP-30	RP-050770	604	-	Clarification of UE measurement reference point	F	6.2.0	6.3.0	R5-052305
RP-30	RP-050770	605	-	Addition of test tolerance to Change of TFC Test Case	F	6.2.0	6.3.0	R5-051843
RP-30	RP-050770	606	-	Addition of test tolerance to Power setting in Uplink compressed mode Test Case	F	6.2.0	6.3.0	R5-052303
RP-30	RP-050770	607	-	Correction to TC5.4.1 and 5.5.2 <reflor> and levels</reflor>	F	6.2.0	6.3.0	R5-052304
RP-30	RP-050770	608	-	Correction to TS34.121 TC7.7.3	F	6.2.0	6.3.0	R5-051844
RP-30	RP-050770	609	-	Correction to Measurement Configuration in TS34.121 Chapter 7	F	6.2.0	6.3.0	R5-052309
RP-30	RP-050770	610	-	Clarification on TFCS size for DCH demodulation	F	6.2.0	6.3.0	R5-051934
RP-30	RP-050770	611	<u> </u>	requirements Correction to TC7.7.2 statistical requirements	F	6.2.0	6.3.0	R5-052306
	RP-050776	612	-	Test time optimization for test cases 7.11 and 7.12	F	6.2.0	6.3.0	R5-052022
RP-30	RP-050770	613	-	Modification of BLER target in RRM hard handover test cases	F	6.2.0	6.3.0	R5-051853
RP-30	RP-050770	614	-	Removal of some event 1C reporting which may fill	F	6.2.0	6.3.0	R5-052310
RP-30	RP-050770	615	-	RLC buffer in RRM test cases 8.6.1.2 and 8.6.1.2A Correction to 8.2.3.1 and 8.2.3.2 Monitored cell list	F	6.2.0	6.3.0	R5-052338
DD 20	DD 050770	040		information added	_	0.0.0	0.0.0	DE 050040
RP-30 RP-30	RP-050770 RP-050770	616 617	-	Correction to 8.3.1 Test procedure	F F	6.2.0	6.3.0	R5-052312
RP-30	RP-050770	618	1-	Clarification of monitored cell list Correction to 8.3.7 Cell Re-selection in URA_PCH	F	6.2.0	6.3.0 6.3.0	R5-052336 R5-052007
RP-30	RP-050770	619	-	Addition of integrity check info in MEASUREMENT CONTROL messages	F	6.2.0	6.3.0	R5-052314
RP-30	RP-050777	620	1_	Correction to SIB 11 of 8.6.2.2 in Annex I	F	6.2.0	6.3.0	R5-052315
RP-30	RP-050777	621	1-	New test scenario: 8.2.3.3 Scenario 3: HCS with	F	6.2.0	6.3.0	R5-052347
RP-30	RP-050779	622		only UTRA level changed. Introduction of PRACH timing accuracy test	r F	6.2.0	6.3.0	R5-052337
	RP-050779	623	 -	Correction to Measurement Report messages	F	6.2.0	6.3.0	R5-052337
RP-30	RP-050770	624	1-	Corrections to Annex F for Change of TFC	F	6.2.0	6.3.0	R5-052344 R5-052316
RP-30	RP-050770	625	-	Removal of temporary BLER measurement configuration	F	6.2.0	6.3.0	R5-051935
RP-30	RP-050780	626	 -	Introduction of UMTS1700 for TS34.121	В	6.2.0	6.3.0	R5-052334
RP-31	RP-060144	627	-	Introduction of OW151700 for 1334.121 Introduction of test case 5.9B Spectrum Emission Mask with E-DCH	F	6.3.0	6.4.0	R5-060465
RP-31	RP-060155	628	-	Allowance of alternative DL power control response	D	6.3.0	6.4.0	R5-060466
DD 04	DD 000450	000		time	_	0.00	0.40	DE 000 407
RP-31	RP-060153	629	<u> -</u>	Introduction of Band VII and Band VIII to Chapter 5	F	6.3.0	6.4.0	R5-060427

T Meeting	Doc-1 st -Level	CR	Rev	Subject	Cat	-	Version -New	Doc-2 nd -Level
RP-31	RP-060155	630	-	Allowance of DL power control response time in TC 7.8.2	F	6.3.0	6.4.0	R5-060114
RP-31	RP-060155	631	=	Correction to SIB11 signalling for inter frequency test cases	F	6.3.0	6.4.0	R5-060464
RP-31	RP-060144	632	-	Introduction of test case 5.10B Adjacent Channel Leakage Ratio (ACLR) with E-DCH	F	6.3.0	6.4.0	R5-060456
RP-31	RP-060155	633	-	Correction to tolerance of setting -20 dBm output power in tests 5.13.1 and 5.13.2	F	6.3.0	6.4.0	R5-060458
RP-31	RP-060155	634	-	Correction to spurious emissions requirements in TC 5.11	F	6.3.0	6.4.0	R5-060461
RP-31	RP-060155	635	-	Clarification of Connection Diagrams in Annex A	F	6.3.0	6.4.0	R5-060452
RP-31	RP-060166	636	-	New Rel-6 RRM test case for combined inter-	F	6.3.0	6.4.0	R5-060460
				frequency and GSM measurements				
RP-31	RP-060155	637	-	Alignment of 34.121 and 25.133 for TC 8.4.1.2	F	6.3.0	6.4.0	R5-060421
RP-31	RP-060153	638	-	Introduction of UMTS band VII and VIII test cases	F	6.3.0	6.4.0	R5-060428
RP-31	RP-060146	639	-		F	6.3.0	6.4.0	R5-060243
RP-31	RP-060146	640		in Clause 9 Correction to 34.121 for HSDPA: UE max output	F	6.3.0	6.4.0	R5-060426
			-	power with HS-DPCCH				
RP-31	RP-060151	641	-	Correction to Annex F Statistical Requirements for HSDPA tests	F	6.3.0	6.4.0	R5-060425
RP-31	RP-060146	642	-	Correction to TRANSPORT CHANNEL RECONFIGURATION message for test cases with HSDPA	F	6.3.0	6.4.0	R5-060423
RP-31	RP-060146	643	-	Missing references and definitions for performance requirements for HSDPA	F	6.3.0	6.4.0	R5-060417
RP-31	RP-060146	644	-	Definition of downlink power level for HSDPA RF transmitter test cases	F	6.3.0	6.4.0	R5-060416
RP-31	RP-060146	645	-	Addition of Test System Uncertainties for 9.3.x	F	6.3.0	6.4.0	R5-060411
RP-31	RP-060155	646	-	Correction to monitored cell lists	F	6.3.0	6.4.0	R5-060420
RP-31	RP-060155	647	-	Clarification of CN domain for BLER measurements	F	6.3.0	6.4.0	R5-060261
RP-31	RP-060164	648	-	Editorial errors and missing changes in Section 9 and related annexes	F	6.3.0	6.4.0	R5-060409
RP-31	RP-060155	649	-	Correction to 7.7.3 Combining of reliable TPC commands from radio links of different radio link sets	F	6.3.0	6.4.0	R5-060246
RP-31	RP-060155	650	l_	Correction to TC7.7.2 power step threshold	F	6.3.0	6.4.0	R5-060407
RP-31	RP-060155	651	-	Editorial errors in Clause 5	D	6.3.0	6.4.0	R5-060403
RP-31	RP-060155	652	-	Band IX additions to tables 5.4.1.3 and 5.5.2.3	F	6.3.0	6.4.0	R5-060408
RP-31	RP-060144	653	-	Code allocation for EDCH testing	F	6.3.0	6.4.0	R5-060437
RP-31	RP-060163	654	-	Correction to 34.121: FDD/TDD Cell Re-selection, TDD measurements and P-CCPCH RSCP test cases	F	6.3.0	6.4.0	R5-060441
RP-31	RP-060155	655	-		F	6.3.0	6.4.0	R5-060418
RP-31	RP-060152	656	-	Introduction of Band VII and Band VIII to Chapter 6	F	6.3.0	6.4.0	R5-060040
RP-31	RP-060152	657	-		F	6.3.0	6.4.0	R5-060038
RP-31	RP-060146	658	-	Correction to HSDPA call setup levels in 34.121	F	6.3.0	6.4.0	R5-060297
RP-31	RP-060155	659	-	Corrections to downlink code allocation tables in Annex E.6	F	6.3.0	6.4.0	R5-060046
RP-31	RP-060163	660	-	Clarifications to TC 8.6.1.4A	F	6.3.0	6.4.0	R5-060288
RP-31	RP-060155	661	-	Correction to 8.7.4.2 Inter frequency measurement	F	6.3.0	6.4.0	R5-060242
RP-31	RP-060163	662	-	requirement Correction to MEASUREMENT CONTROL message	F	6.3.0	6.4.0	R5-060241
RP-31	RP-060155	663	-	in 8.6.1.2A Correction to 8.3.2.2 FDD/FDD Hard Handover to	F	6.3.0	6.4.0	R5-060240
RP-31	RP-060155	664	=	inter-frequency cell Change to the statistical analysis of multiple events	F	6.3.0	6.4.0	R5-060047
RP-31	RP-060163	665	<u> </u>	in 8.6.x.x. tests Correction to 7.12	F	6.3.0	6.4.0	R5-060239
RP-31	RP-060165	666	 -	Correction to 7.8.2	F	6.3.0	6.4.0	R5-060239
RP-31	RP-060155	667	-	Correction of TGD parameter for compressed mode tests	F	6.3.0	6.4.0	R5-060237
RP-31	RP-060155	668	1-	Correction to Frequency Error	F	6.3.0	6.4.0	R5-060235
RP-31	RP-060155	669	-	Correction to the operating conditions in TS34.121	F	6.3.0	6.4.0	R5-060043
DD 0:	DD 000411	070		5.13.1 and 5.13.1A			0.4.0	DE 000 100
RP-31	RP-060144	670	=	Correction to 34.121: HSDPA and E-DCH beta configurations	F	6.3.0	6.4.0	R5-060468
RP-31	RP-060146	671	-	Correction of HSDPA EVM test case 5.13.1A	F	6.3.0	6.4.0	R5-060590
RP-31	RP-060164	672	-	New Test Case Introduction to 34.121: Power control in the downlink, different transport formats	F	6.3.0	6.4.0	R5-060588

T Meeting	Doc-1 st -Level	CR	Rev	Subject	Cat	Version - Current	Version -New	Doc-2 nd -Level
RP-31	RP-060166	673	-	Replace the content of 34.121 with reference pointer to Version 7.0.0	F	6.3.0	6.4.0	R5-060557
RP-31	RP-060167	674	-	Convert 34.121 to a multipart specification; 34.121-1 modification	F	6.3.0	7.0.0	R5-060574
RP-32	RP-060322	675	-	Correction to test system uncertainty in 5.11	F	7.0.0	7.1.0	R5-061402
RP-32	RP-060322	676	-	Correction to spurious emissions requirements applicability for TC 5.11	F	7.0.0	7.1.0	R5-061209
RP-32	RP-060329	677	-	Correction to 5.13.3	F	7.0.0	7.1.0	R5-061456
RP-32	RP-060322	678	-	Clarification to TC7.8.2	F	7.0.0	7.1.0	R5-061404
RP-32	RP-060322	679	-	Correction to TC7.9	F	7.0.0	7.1.0	R5-061405
RP-32	RP-060322	680	-	Correction to 7.8.1 and 7.9.1 test cases	F	7.0.0	7.1.0	R5-061406
RP-32	RP-060329	681	-	Correction to 34.121-1 Test Case 7.8.4: Power control in the downlink, different transport formats	F	7.0.0	7.1.0	R5-061407
RP-32	RP-060328	682	-	Missing lor/loc field in 7.12 test requirements	F	7.0.0	7.1.0	R5-061408
RP-32	RP-060331	683	=	Modifications to 8.6.5 Combined Inter frequency and GSM measurements		7.0.0	7.1.0	R5-061409
RP-32	RP-060329	684	=	Correction to Measurement Control Message in 8.6.2.2	F	7.0.0	7.1.0	R5-061411
RP-32	RP-060322	685	-	correction to Tc 8.7.3.a	F	7.0.0	7.1.0	R5-061412
RP-32	RP-060322	686	-	Tc 8.7.3a - Move Sib 11 exceptions to Annex I	F	7.0.0	7.1.0	R5-061413
RP-32	RP-060322	687	-	Tc 8.3.5.3 - Addition of 2quater parameters to the test parameters	F	7.0.0	7.1.0	R5-061414
RP-32	RP-060322	688	-	for Band III/IX UE	F	7.0.0	7.1.0	R5-061416
RP-32	RP-060322	689	-	Correction to the contents of Tables of the section of F.4 of 3GPP TS 34.121-1		7.0.0	7.1.0	R5-061457
RP-32	RP-060322	690	-	Correction to Annex F.6.1.10 Dual limit BLER tests	F	7.0.0	7.1.0	R5-061458
RP-32	RP-060328	691	-	Addition of downlink physical channels power definition for performance tests without a dedicated connection	F	7.0.0	7.1.0	R5-061423
RP-32	RP-060337	692	-	Clarification to H-SET 1 used in Tx HSDPA tests	F	7.0.0	7.1.0	R5-061428
RP-32	RP-060337	693	-	Number of HARQ processes in HS-SCCH performance tests	F	7.0.0	7.1.0	R5-061049
RP-32	RP-060337	694	-	Clarification of HS-SCCH performance requirements	F	7.0.0	7.1.0	R5-061076
RP-32	RP-060337	695	-	Beta values for HSDPA RF test 5.7A	F	7.0.0	7.1.0	R5-061436
RP-32	RP-060337	696	-	Correction to 5.2A	F	7.0.0	7.1.0	R5-061437
RP-32 RP-32	RP-060337 RP-060337	697 698	-	Annex F HSET data rate clarification and corrections Addition of MAC-d PDU size and HARQ process in	F F	7.0.0	7.1.0 7.1.0	R5-061422 R5-061467
		699		9.3 and 9.4 and Annex C.8.1	F			R5-061471
RP-32 RP-32	RP-060337 RP-060337	700	-	Correction to 5.7A and 5.13.1A waveform patterns Correction to 5.13.1A minimum power setting	F	7.0.0	7.1.0 7.1.0	R5-061471
RP-32	RP-060337	701	-	E-HICH test	F	7.0.0	7.1.0	R5-061433
RP-32	RP-060332	702	1_	E-RGCH test	F	7.0.0	7.1.0	R5-061462
RP-32	RP-060332	703	l_		F	7.0.0	7.1.0	R5-061090
RP-32	RP-060332	704	-	Definition of serving cell for E-DCH RF transmitter test cases	F	7.0.0	7.1.0	R5-061463
RP-32	RP-060332	705	-	Correction to 34.121-1: HSDPA and E-DCH beta configurations	F	7.0.0	7.1.0	R5-061459
RP-32	RP-060332	706	-	Addition to 34.121-1 for HSUPA: UE max output power with HS-DPCCH and E-DCH and HS-DPCCH only release 6 and later	F	7.0.0	7.1.0	R5-061461
RP-32	RP-060332	707	-	Introduction of the demodulation of E-AGCH test case	F	7.0.0	7.1.0	R5-061445
RP-32	RP-060335	708	-	CR to 34.121-1: Introduction of improvement of performance requirements of HSDPA receiver (type 3) for UE categories 7 & 8	F	7.0.0	7.1.0	R5-061472
RP-32	RP-060334	709	1-	Introduction of Band IV to 34.121-1 Chapter 4	F	7.0.0	7.1.0	R5-061072
RP-32	RP-060334	710	-	Introduction of Band IV to 34.121-1 Chapter 5	F	7.0.0	7.1.0	R5-061073
RP-32	RP-060334	711	<u> </u>	Introduction of Band IV to 34.121 Chapter 6	F	7.0.0	7.1.0	R5-061465
RP-32	RP-060334	712	=	CR to 34.121-1: Changes to Annex D to introduce UMTS 1.7/2.1 GHz (Band IV)	F	7.0.0	7.1.0	R5-061452
RP-32	RP-060334	713	=	CR to 34.121-1: Changes to chapter 8 to introduce UMTS 1.7/2.1 GHz (Band IV)	F	7.0.0	7.1.0	R5-061466
RP-32	RP-060322	714	<u> </u>	Correction of UE Transmit timing 8.5.1	F	7.0.0	7.1.0	R5-061475r3
RP-33	RP-060549	715	=	Correction to the formula of CPICH_RSCP of Table 5.5.2.3	F	7.1.0	7.2.0	R5-062423
RP-33	RP-060553	716		Correction to 5.13.3 UE phase discontinuity	F	7.1.0	7.2.0	R5-062220
RP-33	RP-060553	717	<u> -</u>	Correction to 5.13.4 PRACH preamble quality	F	7.1.0	7.2.0	R5-062406
RP-33	RP-060549	718	-	Split of 34.121-1 test case 6.4 to 6.4 and 6.4A	F	7.1.0	7.2.0	R5-062407
RP-33	RP-060553	719	-	BLER test limit for TC 7.8.4 Power control in DL,	F	7.1.0	7.2.0	R5-062129
		<u> </u>		different transport formats	<u> </u>			

T Meeting	Doc-1 st -Level	CR	Rev	Subject	Cat	Version -	Version -New	Doc-2 nd -Level
RP-33	RP-060552	720	-	Correction to test case 7.11 Demodulation of Paging	F	7.1.0	7.2.0	R5-062450
RP-33	RP-060549	721	-	Channel (PCH) Correction to 7.8.2 Power control in the downlink, initial convergence	F	7.1.0	7.2.0	R5-062409
RP-33	RP-060549	722	-		F	7.1.0	7.2.0	R5-062400
RP-33	RP-060549	723	-	Correction to the RRM Test cases 8.6.1.1 and 8.6.1.1A	F	7.1.0	7.2.0	R5-062411
RP-33	RP-060549	724	-	Correction to ARFCN of GSM target cell in test case 8.2.3.3	F	7.1.0	7.2.0	R5-062203
RP-33	RP-060549	725	-	Clarification to GSM target cell in test case 8.3.5.3	F	7.1.0	7.2.0	R5-062204
RP-33	RP-060549	726	-	Correction to 8.5.1 UE Transmit Timing	F	7.1.0	7.2.0	R5-062222
RP-33	RP-060560	727	-	Correction to 8.6.5.1 Correct reporting of neighbours in AWGN propagation condition		7.1.0	7.2.0	R5-062413
RP-33	RP-060549	728	=	Correction to Annex C.6.2 Channel combinations for BLER measurements		7.1.0	7.2.0	R5-062426
RP-33	RP-060567 RP-060567	729	-	Beta values for HSDPA RF tests	F F	7.1.0	7.2.0	R5-062060
RP-33 RP-33	RP-060567	730 731	-	Correction to beta values to be used in test 5.13.1A Correction of reference to connection diagram in	F	7.1.0 7.1.0	7.2.0 7.2.0	R5-062420 R5-062421
RP-33	RP-060567	732	-	9.3.1 MAC header transmission on HS-DSCH	F	7.1.0		
RP-33	RP-060567	732	-		F	7.1.0	7.2.0 7.2.0	R5-062439 R5-062422
			_	cell change				
RP-33	RP-060567	734	-	Changes to annex of 34.121-1 for the test case "Serving HS-DSCH cell change"	F	7.1.0	7.2.0	R5-062231
RP-33	RP-060567	735	-	Correction of beta factors during the measurement period for test cases in 5.xA tests	F	7.1.0	7.2.0	R5-062441
RP-33	RP-060562	736	-	New HSUPA Test Case to 34.121-1: E-TFC restriction in UE	F	7.1.0	7.2.0	R5-062452
RP-33	RP-060562	737	-	New HSUPA Test Case to 34.121-1: Detection Inter- Cell Handover conditions for E-HICH for RLS not containing the Serving E-DCH cell and containing the Serving E-DCH cell	F	7.1.0	7.2.0	R5-062448
RP-33	RP-060562	738	-	New HSUPA Test Case to 34.121-1: Detection Inter- Cell Handover conditions for E-RGCH	F	7.1.0	7.2.0	R5-062449
RP-33	RP-060562	739	-	Clarification on the loopback test mode for E-DCH RF test cases	F	7.1.0	7.2.0	R5-062433
RP-33	RP-060562	740	-		F	7.1.0	7.2.0	R5-062434
RP-33	RP-060562	741	-	Test tolerance for E-AGCH test case.	F	7.1.0	7.2.0	R5-062211
RP-33	RP-060549	742	-	Correction to 5.11 and 6.5.2.2	F	7.1.0	7.2.0	R5-062436
RP-33	RP-060560	743	-	Addition of phase discontinuity to HSDPA EVM test	F	7.1.0	7.2.0	R5-062444r2
RP-33	RP-060562	744	-	Beta values for E-DCH RF tests	F	7.1.0	7.2.0	R5-062447r2
	RP-060731	745	-	Correction to call setup procedure	F	7.2.0	7.3.0	R5-063403
RP-34	RP-060731	746	=	Correction to PHYSICAL CHANNEL RECONFIGURATION messages	F	7.2.0	7.3.0	R5-063404
RP-34	RP-060735	747	-	Corrections to Annex C table references	F	7.2.0	7.3.0	R5-063405
RP-34	RP-060735	748	-	Clarification to HSDPA EVM and phase discontinuity timing diagrams	F	7.2.0	7.3.0	R5-063406
RP-34	RP-060735	749	-	Clarification on the MAC headers for HSDPA test cases	F	7.2.0	7.3.0	R5-063230
RP-34	RP-060731	750	-	Correction to transmit diversity test cases	F	7.2.0	7.3.0	R5-063447
RP-34	RP-060731	751	-	Correction to SHO test cases	F	7.2.0	7.3.0	R5-063408
RP-34 RP-34	RP-060731 RP-060739	752 753	-	Correction to TC 7.8.2 Correction to RRM Test Case to 34.121-1: Band VI	F F	7.2.0 7.2.0	7.3.0 7.3.0	R5-063453 R5-063461
RP-34	RP-060731	754	<u> </u>	Inter-Frequency Band test cases interference issue. Correction to the RRM Test case 8.3.5.3	F	7.2.0	7.3.0	R5-063410
	RP-060731	755	 -	Correction to RRM Test case 8.5.1.2A	F	7.2.0	7.3.0	R5-063410
RP-34	RP-060731	756	1-	Correction to 8.3.4	F	7.2.0	7.3.0	R5-063411
RP-34	RP-060731	757	1-	Correction to 8.3.5	F	7.2.0	7.3.0	R5-063413
RP-34	RP-060731	758	<u> -</u>	Correction to 8.4.1	F	7.2.0	7.3.0	R5-063414
RP-34	RP-060731	759	-	Correction to MEASUREMENT CONTROL messages in 8.7.2.1.1 and 8.7.6.1	F	7.2.0	7.3.0	R5-063415
RP-34	RP-060731	760	<u> -</u>	Update of Annex I	F	7.2.0	7.3.0	R5-063416
RP-34	RP-060731	761	-	Correction to MEASUREMENT CONTROL messages in RRM	F	7.2.0	7.3.0	R5-063417
RP-34	RP-060732	762	-	Correction to UARFCN frequency offset for Band VII	F	7.2.0	7.3.0	R5-063070
RP-34	RP-060735	763	-	Corrections to CQI tests	F	7.2.0	7.3.0	R5-063418
RP-34	RP-060739	764	-	Correction of reference to connection diagram in 9.3.3 and 9.3.5	F	7.2.0	7.3.0	R5-063419
RP-34	RP-060735	765	-	Correction to Downlink Physical Channels for HSDPA Closed Loop Transmit Diversity	F	7.2.0	7.3.0	R5-063422

T Meeting	Doc-1 st -Level	CR	Rev	Subject	Cat	Version - Current	Version -New	Doc-2 nd -Level
RP-34	RP-060735	766	_	Correction to Annex F.6.1.8 and F.6.3.4	F	7.2.0	7.3.0	R5-063420
RP-34	RP-060739	767	-	New test case - UE Relative code domain power accuracy	F	7.2.0	7.3.0	R5-063452
RP-34	RP-060743	768	-	Correction to TC 10.2.1 E-HICH test, single link	F	7.2.0	7.3.0	R5-063456
RP-34	RP-060743	769	-	Correction to TC 10.3.1 E-RGCH , single link	F	7.2.0	7.3.0	R5-063457
RP-34	RP-060743	770	-	Correction to HSUPA Test Case to 34.121-1: Detection Inter-Cell Handover conditions for E-HICH for RLS not containing the Serving E-DCH cell and containing the Serving E-DCH cell	F	7.2.0	7.3.0	R5-063468
RP-34	RP-060743	771	-	Correction of test case: Detection in Inter-Cell Handover conditions for E-RGCH.	F	7.2.0	7.3.0	R5-063464
RP-34	RP-060743	772	-	Correction to HSUPA Test Case to 34.121-1: E-TFC restriction in UE 10ms TTI test case and addition of 2ms TTI test case	F	7.2.0	7.3.0	R5-063465
RP-34	RP-060743	773	-	Additions to HSUPA Test Case to 34.121-1: Test Tolerances for E-TFC restriction in UE 10ms TTI test case and 2ms TTI test case	F	7.2.0	7.3.0	R5-063438
RP-34	RP-060743	774	-	Adding the notice to Sub-test 3 in E-DCH Test cases	F	7.2.0	7.3.0	R5-063439
RP-34	RP-060743	775	-	Adding downlink channel and power definition for E-	F	7.2.0	7.3.0	R5-063469
RP-34	RP-060743	776	-	DCH tests Clarification on the MAC headers for E-DCH test	F	7.2.0	7.3.0	R5-063232
RP-34	RP-060743	777		cases Clarification on the beta values for the E-AGCH test	F	7.2.0	7.3.0	R5-063466
RP-34	RP-060743	778	- -	UE Transmission Power Headroom test	F	7.2.0	7.3.0	R5-063470
RP-34	RP-060743	779	-	Addition of statistical testing of RRM delay performance for test case 8.4.4 for 10 ms TTI E-DCH E-TFC restriction and 2 ms TTI E-DCH E-TFC restriction	F	7.2.0	7.3.0	R5-063449
RP-34	RP-060735	780	-	Corrections to test case 5.7A HS-DPCCH power time template	F	7.2.0	7.3.0	R5-063462r1
RP-34	RP-060743	781	-	Correction to set UE to maximum output power	F	7.2.0	7.3.0	R5-063434r1
RP-35	RP-070101	782	-	Correction to 34.121-1 test case for: Change of TFC	F	7.3.0	7.4.0	R5-070501
RP-35	RP-070105	783	-	Correction to 34.121-1 test case for: Change to peak code domain error applicability		7.3.0	7.4.0	R5-070173
RP-35	RP-070101	784	-	7.7.2.	F	7.3.0	7.4.0	R5-070216
RP-35	RP-070101	785	-	Correction to test requirements in section 8.4.2.4 and F.4.4	F	7.3.0	7.4.0	R5-070502
RP-35 RP-35	RP-070101 RP-070101	786 787	-	Correction to Table 8.3.7.2.1 and Table F.4.1 Correction to the content of Measurement Control message in RRM Test cases 8.3.2.2, 8.6.2.1 and 8.6.2.2	F F	7.3.0 7.3.0	7.4.0 7.4.0	R5-070555 R5-070503
RP-35	RP-070101	788	-	Correction of the definition of known cell	F	7.3.0	7.4.0	R5-070218
	RP-070101	789	-	·	F	7.3.0	7.4.0	R5-070256
RP-35 RP-35	RP-070111	790 791	-	Correction to SIB11for 8.6.5.1 in Annex I	F F	7.3.0	7.4.0	R5-070257
RP-35	RP-070111 RP-070101	792	- -	Correction to 8.3.8 Default Qrxlevmin value for RRM Test cases	F	7.3.0 7.3.0	7.4.0 7.4.0	R5-070504 R5-070505
RP-35	RP-070101	793	-		F	7.3.0	7.4.0	R5-070506
RP-35	RP-070105	794	-	Correction to reference TFC in Annex I	F	7.3.0	7.4.0	R5-070219
RP-35	RP-070105	795	-	E-DCH performance tests	F	7.3.0	7.4.0	R5-070220
RP-35	RP-070105	796	-	Removal of the fixed MAC-hs header option for HSDPA test cases	F	7.3.0	7.4.0	R5-070290
RP-35	RP-070105	797	-	Correction to HSDPA Performance test cases	F	7.3.0	7.4.0	R5-070583
RP-35 RP-35	RP-070105 RP-070111	798 799	 -	Clarification of CQI test cases Introduction of Relative Code Domain Error	F F	7.3.0 7.3.0	7.4.0 7.4.0	R5-070584 R5-070557
RP-35	RP-070111	800	 -	E-TFC selection for E-DCH maximum power tests	F	7.3.0	7.4.0	R5-070557
RP-35	RP-070096	801	-	Corrections to method of test and limits for E-DCH RRM test 8.4.4.1	F	7.3.0	7.4.0	R5-070582
RP-35	RP-070096	802	-	Correction to HSUPA Test Case to 34.121-1: E-TFC restriction in UE 10ms TTI test case and 2ms TTI test case	F	7.3.0	7.4.0	R5-070576
RP-35	RP-070096	803	-	Reduction of lower limits in TC 5.2B	F	7.3.0	7.4.0	R5-070223
RP-35	RP-070096	804	-	Addition of test system uncertainties and test tolerances for inter cell E-DCH tests	F	7.3.0	7.4.0	R5-070524
RP-35	RP-070096	805	-	Correction to E-AGCH test case	F	7.3.0	7.4.0	R5-070520
RP-35	RP-070096	806	-	Removal of the 2ms test from 10.2.1(E-HICH, Single link performance)		7.3.0	7.4.0	R5-070562
RP-35	RP-070096	807	-	Separation of the 2ms test from 10.2.1(E-HICH, Single link performance)	F	7.3.0	7.4.0	R5-070563
RP-35	RP-070096	808	-	Removal of the 2ms test from 10.2.2.1(E-HICH, SHO, RLS not cont)	F	7.3.0	7.4.0	R5-070577

T Meeting	Doc-1 st -Level	CR	Rev	Subject	Cat	Version - Current	Version -New	Doc-2 nd -Level
RP-35	RP-070096	809	-	Separation of the 2ms test from 10.2.2.1(E-HICH, SHO, RLS not cont)	F	7.3.0	7.4.0	R5-070578
RP-35	RP-070096	810	-	Removal of the 2ms test from 10.2.2.2(E-HICH, SHO, RLS containing)	F	7.3.0	7.4.0	R5-070579
RP-35	RP-070096	811	-	Separation of the 2ms test from 10.2.2.2(E-HICH, SHO, RLS containing)	F	7.3.0	7.4.0	R5-070567
RP-35	RP-070096	812	-	Removal of the 2ms test from 10.3.1(E-RGCH, Single link performance)	F	7.3.0	7.4.0	R5-070568
RP-35	RP-070096	813	-	Separation of the 2ms test from 10.3.1(E-RGCH, single link)	F	7.3.0	7.4.0	R5-070569
	RP-070097	814	-	Correction to 10.3.2(E-RGCH, SHO)	F	7.3.0	7.4.0	R5-070570
	RP-070097	815	-	Statistical annex for E-DCH performance tests	F	7.3.0	7.4.0	R5-070561
	RP-070097	816	-	Statistical requirements for test cases 8.4.4	F	7.3.0	7.4.0	R5-070515
RP-35	RP-070090	817	=	New test case: Demodulation of MTCH and cell identification – RLC SDU Error Rate	F	7.3.0	7.4.0	R5-070580
RP-35	RP-070090	818	-	Addition of reference measurement channel, downlink physical channels configuration and VA3 fading condition for MBMS RF testing	F	7.3.0	7.4.0	R5-070546
RP-35	RP-070090	819	-	Introduction of the new demodulation of MTCH test case	F	7.3.0	7.4.0	R5-070547
RP-35	RP-070094	820	-	CR to 34.121-1: Introduction of FDD Mode Test frequencies for Operating Band X (Extended 1.7/2.1 GHz) to Chapter 4	F	7.3.0	7.4.0	R5-070162
RP-35	RP-070094	821	-	CR to 34.121-1: Introduction of FDD Band X (Extended UMTS 1.7/2.1 GHz) to Chapter 5	F	7.3.0	7.4.0	R5-070536
RP-35	RP-070094	822	-	CR to 34.121-1: Introduction of FDD Band X (Extended UMTS 1.7/2.1 GHz) to Chapter 6	F	7.3.0	7.4.0	R5-070537
RP-35	RP-070094	823	=	CR to 34.121-1: Introduction of FDD Band X (Extended UMTS 1.7/2.1 GHz) to Annex D	F	7.3.0	7.4.0	R5-070165
RP-35	RP-070094	824	-	CR to 34.121-1: Introduction of FDD Band X (Extended UMTS 1.7/2.1 GHz) to Annex F	F	7.3.0	7.4.0	R5-070166
RP-35	RP-070101	825	-	Test time reduction to event trigger tests	F	7.3.0	7.4.0	R5-070560
RP-35	RP-070090	826	-	New test case: Cell re-selection during an MBMS session, one UTRAN inter-frequency and 2 GSM cells present in the neighbour list	F	7.3.0	7.4.0	R5-070573
RP-36	RP-070357	827	-	Uncertainties for E-TFC restriction test cases 8.4.4.1 and 8.4.4.2.	F	7.4.0	7.5.0	R5-071064
RP-36	RP-070368	828	-	CR to 34.121-1: Introduction of FDD Band X (Extended UMTS 1.7/2.1 GHz) to Chapter 8	F	7.4.0	7.5.0	R5-071080
RP-36	RP-070368	829	-	CR to 34.121-1: Introduction of FDD Band X (Extended UMTS 1.7/2.1 GHz) to Annex F for RRM test cases	F	7.4.0	7.5.0	R5-071081
RP-36	RP-070344	830	-	TC 8.3.4 - addition of physical channel reconfiguration message	F	7.4.0	7.5.0	R5-071103
RP-36	RP-070356	831	-	Correction to connection diagram to use for test 9.2.1G	F	7.4.0	7.5.0	R5-071151
RP-36	RP-070354	832	-	Addition of settings for the serving cell in test case 5.2AA	F	7.4.0	7.5.0	R5-071153
RP-36 RP-36	RP-070349 RP-070350	833 834	-	Adding the AICH power level to TC 7.11 TC 7.8.4 and RRC CONNECTION SETUP message in Annex I	F F	7.4.0 7.4.0	7.5.0 7.5.0	R5-071179 R5-071180
RP-36 RP-36	RP-070357 RP-070357	835 836	-	Corrections to test procedure of test case 5.2B Removing tables C.11.1.1 and C.11.1.2 from Annex	F	7.4.0 7.4.0	7.5.0 7.5.0	R5-071182 R5-071183
RP-36	RP-070350	837	-	C Clarification to DL DTCH for HSDPA test cases and	r F	7.4.0	7.5.0	R5-071203
RP-36	RP-070363	838	-	E-DCH test cases in section 5. Connection diagram for three cells tests with	F	7.4.0	7.5.0	R5-071207
RP-36	RP-070344	839	-	multipath fading propagation is missing Correction to Measurement report message in	F	7.4.0	7.5.0	R5-071217
	RP-070357	840	=	Annex I for Inter RAT tests Correction to RB setup in 5.2B	F	7.4.0	7.5.0	R5-071222
	RP-070357	841	-	Correction to missed down procedure in 10.3.2	F	7.4.0	7.5.0	R5-071226
	RP-070357	842	-	Correction of procedure for 10.3.1.1	F	7.4.0	7.5.0	R5-071228
RP-36 RP-36	RP-070363 RP-070344	843 844	-	Correction to the demodulation of MTCH test case Applicability change of vibration condition to 34.121-	F F	7.4.0 7.4.0	7.5.0 7.5.0	R5-071255 R5-071323
RP-36	RP-070344	845	<u> </u>	1 test case 5.3 Correction to 5.13.1	F	7.4.0	750	R5-071324
RP-36	RP-070344 RP-070350	846	-	Correction to 5.13.1 Correction of test parameter 'Available signature Start Index and Available signature End Index' for TC 5.13.4 in TS 34.121-1	F	7.4.0	7.5.0 7.5.0	R5-071325
İ				1 O O. 10.7 III 1 O OT. 1 4 1 T	1		i	i .
RP-36	RP-070350	847	-	Correction to 6.3A	F	7.4.0	7.5.0	R5-071326

Т	Doc-1 st -Level	CR	Rev	Subject	Cat	Version	Version	Doc-2 nd -Level
Meeting	DOC-1 -Level	CK	Kev	Subject	Cat	- Current	-New	DOC-2 -Level
RP-36	RP-070350	849	-	Correction to 7.8.4	F	7.4.0	7.5.0	R5-071328
RP-36	RP-070354	850	-	UTRA Carrier RSSI relative accuracy	F	7.4.0	7.5.0	R5-071330
RP-36	RP-070363	851	=	Tc 8.3.6.3 - modification of table 8.3.6.3.1 and addition of SIB11	F	7.4.0	7.5.0	R5-071332
RP-36	RP-070354	852	-	Correction to 8.3.8	F	7.4.0	7.5.0	R5-071334
RP-36	RP-070344	853	-	Correction to Annex K - ' cell configuration mapping' table	F	7.4.0	7.5.0	R5-071336
RP-36	RP-070350	854	-	Correction to 34.121-1 test case for: UE Transmitted Power test tolerances to Annex F		7.4.0	7.5.0	R5-071339
RP-36	RP-070354	855	-	Applicability of DL power tables	F	7.4.0	7.5.0	R5-071340
RP-36	RP-070350	856	-	Clarification to fading conditions for Enhanced Performance Requirements Type 3 and Transmit Diversity	F	7.4.0	7.5.0	R5-071341
RP-36	RP-070350	857	-	MAC-d PDU size for UE Categories 7 and above in 9.3	F	7.4.0	7.5.0	R5-071342
RP-36	RP-070354	858	-	Correction to performance TCs for HS-SCCH detection	F	7.4.0	7.5.0	R5-071343
RP-36	RP-070350	859	-	CR to 34.121-1:Introduction of test cases for multipath fading intra-frequency cell identification	F	7.4.0	7.5.0	R5-071345
RP-36	RP-070350	860	-	CR to 34.121-1:Introduction of test tolerances for multi-path fading intra-frequency cell identification RRM test cases	F	7.4.0	7.5.0	R5-071346
RP-36	RP-070350	861	-	CR to 34.121-1:Introduction of default message contents for multi-path fading intra-frequency cell identification RRM test cases	F	7.4.0	7.5.0	R5-071347
RP-36	RP-070357	862	-	Corrections to E-TFCI restriction test cases 8.4.4.1 and 8.4.4.2	F	7.4.0	7.5.0	R5-071349
RP-36	RP-070357	863	-	Correction to E-DCH Power Setting	F	7.4.0	7.5.0	R5-071355
RP-36	RP-070357	864	-	Corrections to HSUPA test case 8.4.4.1	F	7.4.0	7.5.0	R5-071356
RP-36	RP-070363	865	-	Correction to Annex E.5B	F	7.4.0	7.5.0	R5-071357
RP-36	RP-070350	866	-	Correction of parameter for TC 5.13.4 in TS 34.121-	F	7.4.0	7.5.0	R5-071362
RP-36	RP-070350	867	-	Correction to 34.121-1 test case for: UE transmitted power	F	7.4.0	7.5.0	R5-071363
RP-36	RP-070344	868	-	TC 8.6.4.1 test 1 and 2 - addition of physical channel reconfiguration messages		7.4.0	7.5.0	R5-071364
RP-36	RP-070354	869	-	Corrections to TC 8.6.5.1Correct reporting of neighbours	F	7.4.0	7.5.0	R5-071366
RP-36	RP-070363	870	-	Typo correction on Tc 8.3.6.3.	F	7.4.0	7.5.0	R5-071367
RP-36	RP-070357	871	-	Introduction of Relative Code Domain Power Accuracy for HS-DPCCH and E-DCH	F	7.4.0	7.5.0	R5-071369
RP-36	RP-070357	872	-	Introduction of Relative Code Domain Error with HS-DPCCH and E-DCH		7.4.0	7.5.0	R5-071370
RP-36 RP-36	RP-070357	873	-	RLC SDU size for E-DCH test cases in Annex C	F F	7.4.0 7.4.0	7.5.0	R5-071371
	RP-070357	874	_	Statistical requirements for 8.7.9 UE Transmission Power Headroom	-		7.5.0	R5-071372
RP-36 RP-36	RP-070363 RP-070363	875 876	-	Statistical Requirements for TC 8.3.6.3 MBMS New test case: Cell Reselection during an MBMS session, one frequency present in neighbour	F F	7.4.0 7.4.0	7.5.0 7.5.0	R5-071373 R5-071374
DD 00	DD 070057	077		list	_	7.40	7.5.0	DE 074075
RP-36 RP-36	RP-070357 RP-070357	877 878	<u> </u>	Correction to E-TFC restriction in UE RLC SDU size for E-DCH test cases	F F	7.4.0 7.4.0	7.5.0 7.5.0	R5-071375 R5-071376
RP-36	RP-070357	879	 -	Corrections to HSUPA test case 8.4.4.2	F	7.4.0	7.5.0	R5-071376
RP-36	RP-070344	880	-	Correction of test case 8.3.4 for Inter-system Handover from UTRAN FDD to GSM	F	7.4.0	7.5.0	R5-071249
RP-36	RP-070344	881	-	Corrections to RRM test case 8.7.3.A when run in FDD Band V and VI	F	7.4.0	7.5.0	R5-071379r1
RP-37	RP-070588	882	1-	Correction to call setup procedure	F	7.5.0	7.6.0	R5-072256
RP-37	RP-070588	883	-	Correction to ACTIVESET UPDATE message in Annex I	F	7.5.0	7.6.0	R5-072257
RP-37	RP-070596	884	-	CR to 34.121-1: New Requirements for Fast L1 Synchronization	F	7.5.0	7.6.0	R5-072134
RP-37	RP-070593	885	-	Correction to cell configurations of 8.7.3.2 and 8.7.3D in Annex K	F	7.5.0	7.6.0	R5-072258
RP-37	RP-070588	886	<u> </u>	Clarification of Transmission gap pattern sequence	F	7.5.0	7.6.0	R5-072260
RP-37	RP-070596	887	-	Correction to Annex I	F	7.5.0	7.6.0	R5-072262
RP-37	RP-070588	888	-	Removing test procedure for event trigger tests	F	7.5.0	7.6.0	R5-072263
RP-37	RP-070596	889	-	Correction to MEASUREMENT CONTROL message (Intra Frequency) in 8.6.5.1		7.5.0	7.6.0	R5-072575
RP-37	RP-070596	890	-	CR to 34.121-1: New FDD UE receiver performance requirements for Release 6 test tolerances to Annex F	F	7.5.0	7.6.0	R5-072129

T Meeting	Doc-1 st -Level	CR	Rev	Subject	Cat	Version - Current	Version -New	Doc-2 nd -Level
RP-37	RP-070596	891	-	CR to 34.121-1: Introduction of new compressed mode reference pattern in Annex C	F	7.5.0	7.6.0	R5-072130
	RP-070596	892	-	CR to 34.121-1: Introduction of test case for correct reporting of neighbours in fading propagation condition using TGL1=14 RRM test tolerances	F	7.5.0	7.6.0	R5-072132
	RP-070596	893	-	Correction to channel power of T0 in 8.3.8	F	7.5.0	7.6.0	R5-072265
	RP-070596	894	-	CR to 34.121-1: Correction to the Inter Frequency Cell Identification test cases test tolerances	F	7.5.0	7.6.0	R5-072406
	RP-070601	895	-	Scheduling info Power offset for E-DCH E-TFC restriction TCs	F	7.5.0	7.6.0	R5-072055
	RP-070601	896	-	Correction of the maximum channelisation codes allowed in test cases 8.4.4.1 and 8.4.4.2.	F	7.5.0	7.6.0	R5-072056
	RP-070601	897	-	Correction to reference for E-DCH Test Case	F	7.5.0	7.6.0	R5-072060
	RP-070601	898	-	Correction to E-DCH 2 cell TCs	F	7.5.0	7.6.0	R5-072071
	RP-070601	899	-	Correction to E-DCH Active set update message	F	7.5.0	7.6.0	R5-072072
	RP-070601	900	-	Corrections to Table C.11.3.1 in Annex C	F	7.5.0	7.6.0	R5-072243
	RP-070601	901	-	Correction to HS-PDSCH power in section 10 test cases	F	7.5.0	7.6.0	R5-072269
RP-37	RP-070608	902	-	Addition of test tolerances for MBMS RF and RRM test cases	F	7.5.0	7.6.0	R5-072342
RP-37	RP-070615	903	-	Introduction of continuous packet connectivity (CPC) to "Out-of-synchronization handling of output power"	F	7.5.0	7.6.0	R5-072179
RP-37	RP-070596	907	-	Add test tolerance and test frequencies for 5.13.2A and 5.13.2B UE Relative Code Domain Error.	F	7.5.0	7.6.0	R5-072353
RP-37	RP-070596	908	-	Replace tentative test tolerances for UE Relative Code Domain Power Accuracy tests 5.2C and 5.2D.	F	7.5.0	7.6.0	R5-072354
RP-37	RP-070596	909	-	Add frequency range 4 to 6.5 Blocking Characteristics	F	7.5.0	7.6.0	R5-072355
RP-37	RP-070596	910	-		F	7.5.0	7.6.0	R5-072356
RP-37	RP-070588	911	-	CR to 34.121-1: Correction to FDD/FDD Soft Handover test cases	F	7.5.0	7.6.0	R5-072357
RP-37	RP-070596	912	-	CR to 34.121-1: Introduction of test case for correct reporting of neighbours in fading propagation	F	7.5.0	7.6.0	R5-072358
RP-37	RP-070593	913	-	condition using TGL1=14 RRM test case Correction to measurement control message in 8.7.3D	F	7.5.0	7.6.0	R5-072363
RP-37	RP-070596	914	-	Correction to frequency separation in 8.7.3.2	F	7.5.0	7.6.0	R5-072364
	RP-070593	915	_	Correction to HSDPA diversity performance TCs	F	7.5.0	7.6.0	R5-072366
_	RP-070601	916	-	Corrections to E-DCH UE Power Headroom TC	F	7.5.0	7.6.0	R5-072370
	RP-070601	917	-	Definition of uncertainties for E-DCH UE Power Headroom TC	F	7.5.0	7.6.0	R5-072371
RP-37	RP-070601	918	-	Corrections to E-DCH E-TFC restriction Test Cases	F	7.5.0	7.6.0	R5-072372
	RP-070601	919	-	Correction to 5.2D UE Relative Code Domain Power Accuracy for HS-DPCCH and E-DCH			7.6.0	R5-072375
RP-37	RP-070601	920	-	Corrections to Section 10	F	7.5.0	7.6.0	R5-072377
	RP-070608	921	-	Downlink physical channels code allocation for MBMS test cases	F	7.5.0	7.6.0	R5-072381
RP-37	RP-070615	922	-	Introduction of continuous packet connectivity (CPC) to E-TFC restriction	F	7.5.0	7.6.0	R5-072384
RP-37	RP-070618	923	-		F	7.5.0	7.6.0	R5-072388
RP-37	RP-070618	924	-		F	7.5.0	7.6.0	R5-072389
RP-37	RP-070618	925	-	New E-DCH TC: RLS containing the Serving E-DCH cell (10ms TTI, Type 1)	F	7.5.0	7.6.0	R5-072390
RP-37	RP-070618	926	-	New E-DCH TC: RLS containing the Serving E-DCH cell (2ms TTI, Type 1)	F	7.5.0	7.6.0	R5-072391
RP-37	RP-070618	927	-	New E-DCH TC: E-RGCH single link performance (10ms TTI, Type 1)	F	7.5.0	7.6.0	R5-072392
RP-37	RP-070618	928	-	New E-DCH TC: E-RGCH single link performance (2ms TTI, Type 1)	F	7.5.0	7.6.0	R5-072393
RP-37	RP-070618	929	-	New E-DCH TC: Detection in Inter-Cell Handover conditions (Type 1)	F	7.5.0	7.6.0	R5-072394
RP-37	RP-070618	930	-	New E-DCH TC: E-AGCH single link performance (Type 1)	F	7.5.0	7.6.0	R5-072395
RP-37	RP-070618	931	-	Measurement uncertainties for E-DCH RX diversity (Type 1) tests	F	7.5.0	7.6.0	R5-072396
RP-37	RP-070618	932	-		F	7.5.0	7.6.0	R5-072397
RP-37	RP-070618	933	-	New E-DCH Connection Diagram: 2 cells/Fading/RX-diversity	F	7.5.0	7.6.0	R5-072343

T Meeting	Doc-1 st -Level	CR	Rev	Subject	Cat	Version - Current	Version -New	Doc-2 nd -Level
RP-37	RP-070617	934	-	New test case for demodulation of MTCH and enhanced performance requirement 1	F	7.5.0	7.6.0	R5-072385
RP-37	RP-070600	935	1-	UE performance requirements for high speed train	F	7.5.0	7.6.0	R5-072413
RP-37	RP-070596	936	-	CR to 34.121-1: Correction to the Inter Frequency Cell Identification test cases	F	7.5.0	7.6.0	R5-072405
RP-37	RP-070592	937	-	Correction to 8.6.1.2A – invalid IE for event 1C	F	7.5.0	7.6.0	R5-072410
RP-37	RP-070596	938	-	CR to 34.121-1: Correction for testing receiver diversity UEs	F	7.5.0	7.6.0	R5-072402
RP-37	RP-070601	939	-	Correction to E-DCH AG detection TC	F	7.5.0	7.6.0	R5-072403
RP-37	RP-070601	940	-	Correction to 10.4 (E-AGCH)	F F	7.5.0	7.6.0	R5-072400
RP-37	RP-070618	941	-	New E-DCH TC: E-HICH single link performance (10ms TTI, Type 1)		7.5.0	7.6.0	R5-072414
RP-37	RP-070618	942	-	New E-DCH TC: E-HICH single link performance (2ms TTI, Type 1)	F	7.5.0	7.6.0	R5-072415
RP-37	RP-070601	943	-	Corrections to section 5.2B maximum output power with HS-DPCCH and E-DCH procedure	F	7.5.0	7.6.0	R5-072417
RP-37	RP-070601	944	-	Correction to signalling pattern on the E-RGCH in 10.3.1 and 10.3.2	F	7.5.0	7.6.0	R5-072418
RP-37	RP-070600	945	-	Production of 34.121-1 Rel-7 pointer version to point to Rel-8 of the spec		7.5.0	7.6.0	R5-072591
RP-37	RP-070599	904	-	Introduction of UMTS1500(Band XI) requirements to Chapter 4, 5 and 6		7.5.0	8.0.0	R5-072274
RP-37	RP-070599	905	-	Introduction of UMTS1500(Band XI) requirements to Chapter 8		7.5.0	8.0.0	R5-072275
RP-37	RP-070599	906	-	Introduction of UMTS1500(Band XI) requirements to Annex D and F	F	7.5.0	8.0.0	R5-072276
RP-38	RP-070858	946	-	CR to 34.121-1: Correction to TFC and Compressed Mode Time Mask Diagrams	F	8.0.0	8.1.0	R5-073065
RP-38	RP-070858	947	-	CR to 34.121-1: Correction to Spectrum Emission Mask Limits for Band V (UMTS 850)	F	8.0.0	8.1.0	R5-073067
RP-38	RP-070871	948	-	Clarification to section 5.2B when no E-TFCI is present	F	8.0.0	8.1.0	R5-073363
RP-38	RP-070876	949	-		F	8.0.0	8.1.0	R5-073082
RP-38	RP-070871	950	-	CR to 34.121-1: Correction to Downlink Compressed Mode Layer 1 Requirements	F	8.0.0	8.1.0	R5-073397
RP-38	RP-070858	951	-	CR to 34.121-1: Correction to test case CPICH RSCP intra frequency measurements absolute	F	8.0.0	8.1.0	R5-073068
RP-38	RP-070858	952	-	accuracy minimum requirements CR to 34.121-1: Correction to test case CPICH	F	8.0.0	8.1.0	R5-073314
RP-38	RP-070871	953	-	RSCP intra frequency test parameters CR to 34.121-1: Correction to the UE Rx-Tx Time Difference Type 1 test case	F	8.0.0	8.1.0	R5-073365
RP-38	RP-070858	954	-	CR to 34.121-1: Test time reduction for Cell Reselection in CELL_FACH State for one and two	F	8.0.0	8.1.0	R5-073071
RP-38	RP-070858	955	-	frequency present in neighbour list CR to 34.121-1: Test time reduction for RRM delay	F	8.0.0	8.1.0	R5-073316
RP-38	RP-070871	956	-	tests CR to 34.121-1: Correction to test case combined inter frequency and GSM measurements correct reporting of neighbours in AWGN propagation condition	F	8.0.0	8.1.0	R5-073080
RP-38	RP-070871	957	-	CR to 34.121-1: Correction to test case FDD/FDD Hard Handover to inter-frequency cell minimum requirements	F	8.0.0	8.1.0	R5-073317
RP-38	RP-070871	958	-	Test Case 8.3.8 – Correction to Measurement Report	F	8.0.0	8.1.0	R5-073318
RP-38	RP-070871	959	-		F	8.0.0	8.1.0	R5-073319
RP-38	RP-070871	960	1-	Correction to RRM test case 8.7.9	F	8.0.0	8.1.0	R5-073367
RP-38	RP-070858	961	-	Correction to the test case 8.6.2.1 – compressed mode	F	8.0.0	8.1.0	R5-073379
RP-38	RP-070871	962	-	Correction to the test case 8.6.2.1A – compressed mode	F	8.0.0	8.1.0	R5-073380
RP-38	RP-070869	963	-	Correction to the test cases 8.6.2.2 – compressed mode	F	8.0.0	8.1.0	R5-073381
RP-38	RP-070871	964	-	Correction to the test cases 8.6.2.2A – compressed mode	F	8.0.0	8.1.0	R5-073382
RP-38	RP-070858	965	 -	Correction to test case 8.6.4.1 – compressed mode	F	8.0.0	8.1.0	R5-073393
RP-38	RP-070858	966	1-	Correction to the test case 8.7.1.2.1 – compressed	F	8.0.0	8.1.0	R5-073384
				mode				

T Meeting	Doc-1 st -Level	CR	Rev	Subject	Cat	Version -	Version -New	Doc-2 nd -Level
RP-38	RP-070858	967	-	Correction to the test case 8.7.2.2.2 – compressed	F	Current 8.0.0	8.1.0	R5-073385
RP-38	RP-070858	968	 -	mode Correction to the test case 8.7.3.1 – compressed	F	8.0.0	8.1.0	R5-073394
				mode				
RP-38	RP-070858	969	-	Correction to test case 8.7.4.2 – compressed mode	F	8.0.0	8.1.0	R5-073387
RP-38	RP-070858	970	-	Corrections to test cases 8.6.1.3 and 8.6.1.3A	F	8.0.0	8.1.0	R5-073179
	RP-070858	971	-	Correction to Qhyst parameter in 8.3.5	F	8.0.0	8.1.0	R5-073207
RP-38	RP-070859	972	-	Addition of specific reference messages for 8.4.3	F	8.0.0	8.1.0	R5-073208
RP-38	RP-070859	973	-	Correction to system uncertainty of RRM test cases	F	8.0.0	8.1.0	R5-073209
	RP-070859	974	-	Correction to RRM test case 8.7.3.A	F	8.0.0	8.1.0	R5-073210
RP-38	RP-070859	975	-	Corrections to the BCCH ARFCN for RRM TCs	F	8.0.0	8.1.0	R5-073211
RP-38	RP-070859	976	-	Correction to Primary CPICH Tx Power in Measurement Control message for RRM TCs	F	8.0.0	8.1.0	R5-073324
RP-38	RP-070859	977	-	Correction to IE Reporting interval in RRM event triggered tests	F	8.0.0	8.1.0	R5-073213
RP-38	RP-070859	978	-	Correction to Annex I	F	8.0.0	8.1.0	R5-073215
RP-38	RP-070871	979	-	Corrections to TC 9.2.1G Enhanced Performance Requirements Type 3	F	8.0.0	8.1.0	R5-073052
RP-38	RP-070859	980	-	CR to 34.121-1: Correction to UARFCN for Band V and Band VI	F	8.0.0	8.1.0	R5-073064
RP-38	RP-070871	981	<u> </u>	Correction to 10.2.2.2.1of 34.121-1	F	8.0.0	8.1.0	R5-073087
	RP-070871	982	1_	Correction to fading configuration in 9.3.4 and 9.3.6	F	8.0.0	8.1.0	R5-073090
RP-38	RP-070871	983	1_	Correction to hading configuration in 9.3.4 and 9.3.6 Correction to number of tests in 9.4.1A and 9.4.2A	F	8.0.0	8.1.0	R5-073090
RP-38	RP-070871	984	+	Clarification on the behaviour of the SS in 10.3.2	F	8.0.0	8.1.0	R5-073092
RP-38	RP-070859	985	-	Correction to extreme condition voltages for Lithium	F	8.0.0	8.1.0	R5-073092
			-	batteries				
RP-38	RP-070876	986	-	Correction to 34.121-1 applicability of HSDPA tests testing Enhanced performance type 3 terminals	F	8.0.0	8.1.0	R5-073328
RP-38	RP-070859	987	-	Addition of new TCs to Annex K - cell configuration mapping table	F	8.0.0	8.1.0	R5-073127
RP-38	RP-070869	988	-	Corrections to Annex K - cell configuration mapping table	F	8.0.0	8.1.0	R5-073329
RP-38	RP-070876	989	-	Correction to test conditions in F5.3	F	8.0.0	8.1.0	R5-073190
RP-38	RP-070859	990	-	Correction of Table F.6.2.8 (statistical testing)	F	8.0.0	8.1.0	R5-073222
RP-38	RP-070872	991	-	CR to 34.121-1: Introduction of new Constant BLER Target Requirements using DL reference measurement channel 2 (64 kbps)	F	8.0.0	8.1.0	R5-073368
RP-38	RP-070872	992	-	CR to 34.121-1: Introduction of test tolerances for new Constant BLER Target using DL reference measurement channel 2 (64 kbps) test case	F	8.0.0	8.1.0	R5-073369
RP-38	RP-070872	993	-	CR to 34.121-1: Introduction of new Power Control in the Downlink for F-DPCH Requirements	F	8.0.0	8.1.0	R5-073335
RP-38	RP-070872	994	-	CR to 34.121-1: Introduction of new Power Control in the Downlink, Wind Up Effects (Release 6 and later) Requirements	F	8.0.0	8.1.0	R5-073370
RP-38	RP-070872	995	-	CR to 34.121-1: Introduction of test tolerances for new Power Control in the Downlink, Wind Up Effects (Release 6 and later) test case	F	8.0.0	8.1.0	R5-073337
RP-38	RP-070877	996	-	Clarification of the invalid MAC header for MBMS RF/RRM testing	F	8.0.0	8.1.0	R5-073175
RP-38	RP-070877	997	-	Clarification of power level for MBMS RF/RRM	F	8.0.0	8.1.0	R5-073346
RP-38	RP-070877	998	-	Test tolerances for TC 11.2 MTCH demodulation test	F	8.0.0	8.1.0	R5-073347
RP-38	RP-070877	999	-	Addition of test system uncertainties and test tolerance for 8.3.5.4 and 8.3.6.3	F	8.0.0	8.1.0	R5-073344
RP-38	RP-070877	1000	1-	Correction to Test Procedures of 8.3.5.4 and 8.3.6.3	F	8.0.0	8.1.0	R5-073345
RP-38	RP-070877	1001	-	Clarification of test procedure in 11.2, 11.2A and 11.3	F	8.0.0	8.1.0	R5-073343
RP-38	RP-070884	1002	-	Introduction of HSDPA performance requirements for 64QAM	F	8.0.0	8.1.0	R5-073348
RP-38	RP-070884	1003	-	New 64QAM Test Case: Maximum Input Level for HS-PDSCH Reception (64QAM)	F	8.0.0	8.1.0	R5-073373
RP-38	RP-070883	1004	-	CR to 34.121-1: Introduction of UE Transmitter	F	8.0.0	8.1.0	R5-073366
RP-38	RP-070885	1005	-	Requirements for 16-QAM test cases Introduction of HS-SCCH-less demodulation	F	8.0.0	8.1.0	R5-073352
RP-38	RP-070881	1006	-	requirements for CPC New MIMO Test Case: Demodulation of HS-DSCH (Fixed Reference Channel): MIMO Performance	F	8.0.0	8.1.0	R5-073396
RP-38	RP-070881	1007	-	New MIMO Test Case: Reporting of Channel Quality	F	8.0.0	8.1.0	R5-073375
KP-36				Indicator: MIMO Performance				

Т	Doc-1 st -Level	CR	Rev	Subject	Cat	Version	Version	Doc-2 nd -Level
Meeting						-	-New	
						Current		
RP-38	RP-070881	1009	I	MIMO Fading scenarios and MIMO changes for 34.121-1 Annex	F	8.0.0	8.1.0	R5-073395
RP-38	RP-070888	1010	I	Addition of test tolerances for TC 11.2A demodulation of MTCH enhanced perf req 1	F	8.0.0	8.1.0	R5-073357

From v8.1.0, the history table is generated automatically from the Specs Status database (form "2008-04-01_apprvd-CRs-for-spec_form").

T Meeting	Doc-1 st -Level		Rev	Subject	Cat	- Current	-New	Doc-2 nd -Level
RP-39	RP-080091	1011	-	Correction to Spectrum emission mask	F	8.1.0	8.2.0	R5-080419
RP-39	RP-080095	1012	-	Correction to Test Procedure in 5.2B	F	8.1.0	8.2.0	R5-080381
RP-39	RP-080091	1013	-	Correction to test case 6.5 for Band V operation	F	8.1.0	8.2.0	R5-080141
RP-39	RP-080095	1014	-	CR to 34.121-1: Correction to test case power control in the downlink, wind up effects	F	8.1.0	8.2.0	R5-080425
RP-39	RP-080095	1015	-	Correction to DL RMC for Channel2(64kbps)	F	8.1.0	8.2.0	R5-080421
RP-39	RP-080091	1016	-	Correction to SHO messages	F	8.1.0	8.2.0	R5-080240
RP-39	RP-080095	1017	-	Correction to target quality on DCCH	F	8.1.0	8.2.0	R5-080383
RP-39	RP-080095	1018	-	Correction to TC 7.8.5 (F-DPCH power control test case)	F	8.1.0	8.2.0	R5-080385
RP-39	RP-080095	1019	-	Correction to Table F6.1.10.3 for Power control in the downlink, constant BLER target	F	8.1.0	8.2.0	R5-080386
RP-39	RP-080095	1020	-	Correction to test case 8.7.9 UE Transmission Power Headroom	F	8.1.0	8.2.0	R5-080174
RP-39	RP-080091	1021	<u> </u>	Correction to system uncertainty of RRM test cases	F	8.1.0	8.2.0	R5-080243
RP-39	RP-080095	1022	-	Correction to MEASUREMENT REPORT message in 8.7.6.1A	F	8.1.0	8.2.0	R5-080422
RP-39	RP-080095	1023		Correction to 8.6.5.1	F	8.1.0	8.2.0	R5-080245
RP-39	RP-080095	1023	+	Correction to RRM test cases 8.4.4.1 and 8.4.4.2	F	8.1.0	8.2.0	R5-080245
RP-39	RP-080093	1024	+	TC 8.3.2.1 û Correction to Measurement Report	F	8.1.0	8.2.0	R5-080249
RP-39	RP-080091	1025	-	Uniform application of Annex F.6.2.8 (statistical	F	8.1.0	8.2.0	R5-080319
RP-39	RP-080091	1027	-	annex) to all tests in clause 8.7 Completion and correction of Annex F.6.2.8 (Statistical testing)	F	8.1.0	8.2.0	R5-080403
RP-39	RP-080095	1028	-	Correction to table F.1.5 for test case 8.6.2.1A	F	8.1.0	8.2.0	R5-080139
RP-39	RP-080095	1029	-	Correction to 9.4.2 and 9.4.2A channel levels	F	8.1.0	8.2.0	R5-080140
RP-39	RP-080095	1030	-	Correction to 34.121-1 HSDPA test applicabilities for Enhanced Performance type 1 and type 3 terminals.		8.1.0	8.2.0	R5-080242
RP-39	RP-080093	1031	-	Corrections to applicability of CQI test cases 9.3.1 to 9.3.6	F	8.1.0	8.2.0	R5-080250
RP-39	RP-080103	1032	-	PICH power level for MBMS performance test	F	8.1.0	8.2.0	R5-080418
RP-39	RP-080103	1033	-	Clarification on MBMS MTCH reference channel for TC 11.3	F	8.1.0	8.2.0	R5-080147
RP-39	RP-080103	1034	-	Correction to TC 8.3.6.3	F	8.1.0	8.2.0	R5-080391
RP-39	RP-080103	1035	-	Correction to test procedure in 8.3.5.4 and 8.3.6.3	F	8.1.0	8.2.0	R5-080392
RP-39	RP-080103	1036	<u> </u>	Addition the message exceptions to 8.3.6.3	F	8.1.0	8.2.0	R5-080224
RP-39	RP-080103	1037	-	Correction to the time for sending valid MAC headers and RLS SDUs in 11.2 and 11.2A	F	8.1.0	8.2.0	R5-080225
RP-39	RP-080103	1038	-	Correction to cell update procedure in the transition from CELL_PCH to CELL_FACH.	F	8.1.0	8.2.0	R5-080227
RP-39	RP-080103	1039	t <u>-</u>	Correction to the BCCH ARFCN for 8.3.6.3	F	8.1.0	8.2.0	R5-080228
RP-39	RP-080103	1040	1-	Correction to MBMS test case 11.3	F.	8.1.0	8.2.0	R5-080393
RP-39	RP-080103	1041	 	Correction to 11.2 and 11.2A	F	8.1.0	8.2.0	R5-080428
RP-39	RP-080107	1042	-	Addition of downlink physical channels power definition for 64QAM performance tests	F	8.1.0	8.2.0	R5-080394
RP-39	RP-080107	1043	<u> </u>	Correction of table captions in Annex F.6.3.4	F	8.1.0	8.2.0	R5-080265
RP-39	RP-080107	1044	<u> </u>	Correction to Maximum input level 64QAM test case	F	8.1.0	8.2.0	R5-080426
RP-39	RP-080108	1045	-	CR to 34.121-1: Correction to UE Transmitter 16- QAM test cases	F	8.1.0	8.2.0	R5-080395
RP-39	RP-080108	1046	-	CR to 34.121-1: Introduction of test tolerances for UE Transmitter 16-QAM test cases	F	8.1.0	8.2.0	R5-080417
RP-39	RP-080111	1047	-	Introduction of continuous packet connectivity (CPC) to intra frequency CPICH measurement requirements	F	8.1.0	8.2.0	R5-080414
RP-39	RP-080105	1048	-	Adding test tolerances for test case 9.2.4A: MIMO Performance û Fixed Reference Channel (FRC) H-Set 9	F	8.1.0	8.2.0	R5-080398
RP-39	RP-080105	1049	-	Adding test tolerances in the annex for MIMO test cases	F	8.1.0	8.2.0	R5-080427

RP-38 RP-080105 1050 - Adding test procedure for MIMO CQI reporting test F 8.1.0 8.2.0 R5-080 cases 9.3.7 and 93.78 degree 93.78 degre	Doc-2 nd -Level	-New	Version - Current	Cat	Subject	Rev	CR	Doc-1 st -Level	T Meeting
RP-39 RP-080105 1051 - New MIMOT Test cases: HS-SCCH Detection F 8.1.0 8.2.0 R5-080	R5-080399			F		-	1050	RP-080105	RP-39
RP-39 RP-080103 1052 Corde allocation for HSDPA test cases F 8,1.0 8,2.0 RS-080 RS-980 RP-39 RP-080372 1054 Correction to TC 8,3.5.4 F 8,1.0 8,2.0 RS-080 RP-080372 1054 Correction to TC 8,3.5.4 F 8,1.0 8,2.0 RS-080 RP-080372 1055 CR to 34,121-1: Correction to UE Transmitter 16- F 8,2.1 8,3.0 RS-081 RP-40 RP-080372 1055 CR to 34,121-1: Correction to UE Transmitter 16- F 8,2.1 8,3.0 RS-081 RP-40 RP-080372 1056 Introduction of new Test. Relative Carrier Leakage F 8,2.1 8,3.0 RS-081 RP-40 RP-080372 1057 CR to 34,121-1: Introduction of test tolerances for F 8,2.1 8,3.0 RS-081 RP-40 RP-080372 1058 Correction to UE Transmitter 16-OAM test cases F 8,2.1 8,3.0 RS-081 RP-40 RP-080373 1059 CR to 34,121-1: Introduction of fest tolerances for F 8,2.1 8,3.0 RS-081 RP-40 RP-080373 1059 CR to 34,121-1: Introduction of Bands XII XIII and F 8,2.1 8,3.0 RS-081 RP-40 RP-080370 1060 CR to 34,121-1: Introduction of Bands XII XIII and F 8,2.1 8,3.0 RS-081 RP-40 RP-080370 1061 CR to 34,121-1: Introduction of Bands XII XIII and F 8,2.1 8,3.0 RS-081 RP-40 RP-080370 1061 CR to 34,121-1: Introduction of Bands XII XIII and F 8,2.1 8,3.0 RS-081 RP-40 RP-080370 1062 CR to 34,121-1: Introduction of Bands XII XIII and F 8,2.1 8,3.0 RS-081 RP-40 RP-080370 1062 CR to 34,121-1: Introduction of Bands XII XIII and F 8,2.1 8,3.0 RS-081 RP-40 RP-080370 1063 CR to 34,121-1: Introduction of Bands XII XIII and F 8,2.1 8,3.0 RS-081 RP-40 RP-080370 1064 CR to 34,121-1: Introduction of Bands XII XIII and F 8,2.1 8,3.0 RS-081 RP-40 RP-080384 1066 CR to 34,121-1: Introduction of Bands XII XIII and F 8,2.1 8,3.0 RS-081 RP-40 RP-080384 1066 CR to 34,121-1: Introduction of Bands XII XIII and F 8,2.1 8,3.0 RS-081 RP-40 RP-080384 1070 CR to 34,121-1: Introduction	R5-080401	8.2.0	8.1.0	F	New MIMO Test case: HS-SCCH Detection	-	1051	RP-080105	RP-39
RP-39 RP-080103 1053 Correction to TC 8.3.5.4 F 8.1.0 8.2.0 RS-080 Completion of history table entries 8.2.0 R.2.1 RP-40 RP-080372 1054 CR to 34.121-1: Correction to UE Transmitter 16-	R5-080423	8.2.0	8.1.0	F		-	1052	RP-080105	RP-39
RP-40 RP-080372 1054 CR to 34.121-1: Correction to UE Transmitter 16-	R5-080307	8.2.0	8.1.0	F	Correction to TC 8.3.5.4	-	1053	RP-080103	RP-39
RP-40 RP-080372 1055 CR to 34.121-1: Addition of UE reference measurement channel for E-DCH tests with 160AM R-080372 1056 Introduction of new Test: Relative Carrier Leakage R-20 R			8.2.0		Completion of history table entries				
RP-40	R5-081424	8.3.0	8.2.1	F		-	1054	RP-080372	RP-40
Power (IQ offset)	R5-081446				measurement channel for E-DCH tests with 16QAM	-			
RP-40 RP-080372 1058 Correction to UE Transmitter 16-OAM test cases F 8.2.1 8.3.0 RS-081 RP-40 RP-080373 1059 CR to 34.121-1: Correction to Transmit ON/OFF F 8.2.1 8.3.0 RS-081 RP-40 RP-080370 1060 CR to 34.121-1: Introduction of Bands XII XIII and F 8.2.1 8.3.0 RS-081 RP-40 RP-080370 1061 CR to 34.121-1: Introduction of Bands XII XIII and F 8.2.1 8.3.0 RS-081 RP-40 RP-080370 1061 CR to 34.121-1: Introduction of Bands XII XIII and F 8.2.1 8.3.0 RS-081 RP-40 RP-080370 1062 CR to 34.121-1: Introduction of Bands XII XIII and F 8.2.1 8.3.0 RS-081 RP-40 RP-080370 1062 CR to 34.121-1: Introduction of Bands XII XIII and F 8.2.1 8.3.0 RS-081 XIV (UMTS700 MHz) to section 6 RP-40 RP-080370 1063 CR to 34.121-1: Introduction of Bands XII XIII and F 8.2.1 8.3.0 RS-081 XIV (UMTS700 MHz) to section 8 RP-40 RP-080370 1064 CR to 34.121-1: Introduction of Bands XII XIII and F 8.2.1 8.3.0 RS-081 XIV (UMTS700 MHz) to section 8 RP-40 RP-080370 1065 CR to 34.121-1: Introduction of Bands XII XIII and F 8.2.1 8.3.0 RS-081 XIV (UMTS700 MHz) to Annex D RS-081 R5-081422	8.3.0	8.2.1	F		-	1056	RP-080372	RP-40	
RP-40 RP-080373 1059 CR to 34.121-1: Correction to Transmit ON/OFF F 8.2.1 8.3.0 R5-081 RP-40 RP-080370 1060 CR to 34.121-1: Introduction of Bands XII XIII and F 8.2.1 8.3.0 R5-081 RP-40 RP-080370 1061 CR to 34.121-1: Introduction of Bands XII XIII and F 8.2.1 8.3.0 R5-081 RP-40 RP-080370 1062 CR to 34.121-1: Introduction of Bands XII XIII and F R.2.1 R.3.0 R5-081 RP-40 RP-080370 1062 CR to 34.121-1: Introduction of Bands XII XIII and F R.2.1 R.3.0 R5-081 RP-40 RP-080370 1063 CR to 34.121-1: Introduction of Bands XII XIII and F R.2.1 R.3.0 R5-081 RP-40 RP-080370 1063 CR to 34.121-1: Introduction of Bands XII XIII and F R.2.1 R.3.0 R5-081 RP-40 RP-080370 1064 CR to 34.121-1: Introduction of Bands XII XIII and F R.2.1 R.3.0 R5-081 RP-40 RP-080370 1065 CR to 34.121-1: Introduction of Bands XII XIII and F R.2.1 R.3.0 R5-081 RP-40 RP-080370 1065 CR to 34.121-1: Introduction of Bands XII XIII and F R.2.1 R.3.0 R5-081 RP-40 RP-080384 1066 Carrection to test requirements of TC 5.2B F R.2.1 R.3.0 R5-081 RP-40 RP-080385 1068 Carrection to test requirements of TC 5.2B F R.2.1 R.3.0 R5-081 RP-40 RP-080385 1068 Carrection to DL reference channel for 6.3B F R.2.1 R.3.0 R5-081 RP-40 RP-080386 1069 Carrection to DL reference channel for 6.3B F R.2.1 R.3.0 R5-081 RP-40 RP-080386 1070 Carrection to test procedure in 7.8.5 of 34.121-1 R.2.1 R.3.0 R5-081 RP-40 RP-080386 1070 Carrection to test procedure in 7.8.5 of 34.121-1 R.2.1 R.3.0 R5-081 RP-40 RP-080386 1073 Carrection to 10.1 Reference channel for 6.3B F R.2.1 R.3.0 R5-081 RP-40 RP-080386 1073 Carrection to 10.1 Reference channel for 6.3B F R.2.1 R.3.0 R5-081 RP-40 RP-080386 1070 Carrection to 10.1 Reference channel for 6.3B F R.2.1 R.3.0 R5-081 RP-40 RP-080386 1077	R5-081425	8.3.0	8.2.1	F		-	1057	RP-080372	RP-40
Power test cases for CPC requirements	R5-081275		8.2.1			-			
RP-40 RP-080370 1061 CR to 34.121-1: Introduction of Bands XII XIII and F 8.2.1 8.3.0 R5-081 XIV (UMTS700 MHz) to section 5 RP-40 RP-080370 1062 CR to 34.121-1: Introduction of Bands XII XIII and F 8.2.1 8.3.0 R5-081 XIV (UMTS700 MHz) to section 5 RP-40 RP-080370 1063 CR to 34.121-1: Introduction of Bands XII XIII and F 8.2.1 8.3.0 R5-081 XIV (UMTS700 MHz) to section 6 RP-40 RP-080370 1064 CR to 34.121-1: Introduction of Bands XII XIII and F 8.2.1 8.3.0 R5-081 XIV (UMTS700 MHz) to section 8 RP-40 RP-080370 1065 CR to 34.121-1: Introduction of Bands XII XIII and F 8.2.1 8.3.0 R5-081 XIV (UMTS700 MHz) to Annex D XIV (UMTS700 MHz) to Annex F RP-40 RP-080364 1066 Correction to test requirements of TC 5.2B F 8.2.1 8.3.0 R5-081 RP-40 RP-080364 1066 Correction to test requirements of TC 5.2B F 8.2.1 8.3.0 R5-081 RP-40 RP-080364 1066 Correction to Annex C.3.5 and C.6.2 for 7.8.1A F 8.2.1 8.3.0 R5-081 RP-40 RP-080364 1070 Correction to Annex C.3.5 and C.6.2 for 7.8.1A F 8.2.1 8.3.0 R5-081 RP-40 RP-080364 1070 Correction to Annex C.3.5 and C.6.2 for 7.8.1A F 8.2.1 8.3.0 R5-081 RP-40 RP-080363 1071 8.6.2 for 18.6 and 8.6.2 for 7.8.1A F 8.2.1 8.3.0 R5-081 RP-40 RP-080364 1070 Correction to test procedure in 7.8.5 of 34.121-1 F 8.2.1 8.3.0 R5-081 RP-40 RP-080364 1073 Correction to 8.3.6.3 R5-081 RP-40 RP-080364 1073 Correction to 8.3.6.3 R5-081 RP-40 RP-080364 1075 Correction to R0 R0 R0 R0 R0 R0 R0 R0 R0 R0 R0 R0 R0	R5-081427					-			
RP-40 RP-080370 1062 - CR to 34.121-1: Introduction of Bands XII XIII and F 8.2.1 8.3.0 R5-081 RP-40 RP-080370 1063 - CR to 34.121-1: Introduction of Bands XII XIII and F 8.2.1 8.3.0 R5-081 RP-40 RP-080370 1064 - CR to 34.121-1: Introduction of Bands XII XIII and F 8.2.1 8.3.0 R5-081 RP-40 RP-080370 1064 - CR to 34.121-1: Introduction of Bands XII XIII and F 8.2.1 8.3.0 R5-081 RP-40 RP-080370 1065 - CR to 34.121-1: Introduction of Bands XII XIII and F 8.2.1 8.3.0 R5-081 RP-40 RP-080364 1066 - Correction to Intest requirements of TC 5.2B F 8.2.1 8.3.0 R5-081 RP-40 RP-080364 1066 - Correction to test requirements of TC 5.2B F 8.2.1 8.3.0 R5-081 RP-40 RP-080365 1068 - Correction to test requirements of TC 5.7A F 8.2.1 8.3.0 R5-081 RP-40 RP-080365 1068 - Correction to DL reference channel for 6.3B F 8.2.1 8.3.0 R5-081 RP-40 RP-080364 1069 - Correction to Annex C.3.5 and C.6.2 for 7.8.1A F 8.2.1 8.3.0 R5-081 RP-40 RP-080364 1070 - Correction to test procedure in 7.8.5 of 34.121-1 F 8.2.1 8.3.0 R5-081 RP-40 RP-080363 1071 - S.6.2 1 and 8.6.2 1A: Correction to Measurement RP-40 RP-080364 1070 - Correction to B.3.6.3 R5-081 RP-40 RP-080364 1073 - Correction to B.3.6.3 F 8.2.1 8.3.0 R5-081 RP-40 RP-080364 1073 - Correction to 8.3.6.3 F 8.2.1 8.3.0 R5-081 RP-40 RP-080364 1075 - Correction to 8.3.6.3 F 8.2.1 8.3.0 R5-081 RP-40 RP-080364 1075 - Correction to 8.3.6.3 F 8.2.1 8.3.0 R5-081 RP-40 RP-080364 1075 - Correction to 34.121-1 HSDPA tests' applicabilities RP-40 RP-080364 1075 - Correction to 24.121-1 HSDPA tests' applicabilities RP-40 RP-080364 1075 - Correction to Cell power in Section 11 Test Cases F 8.2.1 8.3.0 R5-081 RP-40 RP-080364 1078 - Correction to RRM test cases F 8.2.1 8.3.0 R5-081 RP-40 RP-080364 1078 -	R5-081428	8.3.0	8.2.1			-	1060	RP-080370	RP-40
RP-40	R5-081429	8.3.0	8.2.1	F	XIV (UMTS700 MHz) to section 5	_	1061	RP-080370	RP-40
RP-40 RP-080370 1064 CR to 34.121-1: Introduction of Bands XII XIII and XIV (UMTS700 MHz) to Annex D RP-40 RP-080370 1065 CR to 34.121-1: Introduction of Bands XII XIII and XIV (UMTS700 MHz) to Annex D RP-40 RP-080364 1066 Correction to test requirements of TC 5.2B F 8.2.1 8.3.0 R5-081 RP-40 RP-080364 1066 Correction to test requirements of TC 5.2B F 8.2.1 8.3.0 R5-081 RP-40 RP-080364 1067 Removal of two test points from TC 5.7A F 8.2.1 8.3.0 R5-081 RP-40 RP-080365 1068 Correction to Let ference channel for 6.3B F 8.2.1 8.3.0 R5-081 RP-40 RP-080364 1069 Correction to Let ference channel for 6.3B F 8.2.1 8.3.0 R5-081 RP-40 RP-080364 1070 Correction to Annex C.3.5 and C.6.2 for 7.8.1A F 8.2.1 8.3.0 R5-081 RP-40 RP-080364 1070 Correction to test procedure in 7.8.5 of 34.121-1 F 8.2.1 8.3.0 R5-081 RP-40 RP-080363 1071 S.6.2.1 and 8.6.2.1A; correction to Measurement F 8.2.1 8.3.0 R5-081 RP-40 RP-080364 1073 Correction to 8.7.1.1 and 8.7.3A F 8.2.1 8.3.0 R5-081 RP-40 RP-080364 1073 Correction to 8.7.1.1 and 8.7.3A F 8.2.1 8.3.0 R5-081 RP-40 RP-080364 1073 Correction to 8.3.6.3 F 8.2.1 8.3.0 R5-081 RP-40 RP-080364 1075 Correction to 8.1.21-1 HSDPA tests' applicabilities F 8.2.1 8.3.0 R5-081 RP-40 RP-080364 1076 Statistical requirements for Clause 11 (MBMS) F 8.2.1 8.3.0 R5-081 RP-40 RP-080364 1076 Statistical requirements for Clause 11 (MBMS) F 8.2.1 8.3.0 R5-081 RP-40 RP-080364 1078 Correction to TC 8.3.5.4 F 8.2.1 8.3.0 R5-081 RP-40 RP-080364 1079 Correction to TC 8.3.5.4 F 8.2.1 8.3.0 R5-081 RP-40 RP-080364 1078 Correction to TC 8.3.5.4 F 8.2.1 8.3.0 R5-081 RP-40 RP-080364 1078 Correction to TC 8.3.5.4 F 8.2.1 8.3.0 R5-081 RP-40 RP-080364 1078 Correction to RDM tests cases F 8.2.1 8.3.0 R5-081 RP-	R5-081430	8.3.0	8.2.1	F		-	1062	RP-080370	RP-40
RP-40 RP-080370 1065 CR to 34.121-1: Introduction of Bands XII XIII and XIV (UMTS700 MHz) to Annex F RP-40 RP-080364 1066 Correction to test requirements of TC 5.2B F 8.2.1 8.3.0 R5-081 RP-40 RP-080427 1067 Removal of two test points from TC 5.7A F 8.2.1 8.3.0 R5-081 RP-40 RP-080364 1069 Correction to D. reference channel for 6.3B F 8.2.1 8.3.0 R5-081 RP-40 RP-080364 1070 Correction to Annex C.3.5 and C.6.2 for 7.8.1A F 8.2.1 8.3.0 R5-081 RP-40 RP-080364 1070 Correction to Annex C.3.5 and C.6.2 for 7.8.1A F 8.2.1 8.3.0 R5-081 RP-40 RP-080363 1071 RP-40 RP-080363 1071 RP-40 RP-080363 1072 Correction to test procedure in 7.8.5 of 34.121-1 F 8.2.1 8.3.0 R5-081 RP-40 RP-080364 1073 Correction to 8.7.1.1 and 8.7.3A F 8.2.1 8.3.0 R5-081 RP-40 RP-080364 1073 Correction to 8.3.6.3 F 8.2.1 8.3.0 R5-081 RP-40 RP-080364 1073 Correction to test procedure of RRM test cases F 8.2.1 8.3.0 R5-081 RP-40 RP-080364 1075 Correction to test procedure of RRM test cases F 8.2.1 8.3.0 R5-081 RP-40 RP-080364 1075 Correction to test procedure of RRM test cases F 8.2.1 8.3.0 R5-081 RP-40 RP-080364 1076 Statistical requirements for Clause 11 (MBMS) F 8.2.1 8.3.0 R5-081 RP-40 RP-080364 1078 Correction to Cell power in Section 11 Test Cases F 8.2.1 8.3.0 R5-081 RP-40 RP-080364 1078 Correction to TC 8.3.5.4 F 8.2.1 8.3.0 R5-081 RP-40 RP-080364 1078 Correction to TC 8.3.5.4 F 8.2.1 8.3.0 R5-081 RP-40 RP-080364 1078 Correction to TC 8.3.5.4 F 8.2.1 8.3.0 R5-081 RP-40 RP-080364 1081 Correction to TC 8.3.5.4 F 8.2.1 8.3.0 R5-081 RP-40 RP-080364 1081 Correction to TC 8.3.5.4 F 8.2.1 8.3.0 R5-081 RP-40 RP-080364 1085 Correction to TC 8.3.5.4 F 8.2.1 8.3.0 R5-081 RP-40 RP-080364 1085 Correction to RRM tests cases in clause	R5-081431	8.3.0	8.2.1	F		-	1063	RP-080370	RP-40
RP-40	R5-081432	8.3.0	8.2.1	F		-	1064	RP-080370	RP-40
RP-40 RP-080365 1068 -	R5-081433	8.3.0		F	CR to 34.121-1: Introduction of Bands XII XIII and XIV (UMTS700 MHz) to Annex F	-			RP-40
RP-40 RP-080365 1068 Correction to DL reference channel for 6.3B F 8.2.1 8.3.0 R5-081 RP-40 RP-080364 1069 Correction to Annex C.3.5 and C.6.2 for 7.8.1A F 8.2.1 8.3.0 R5-081 RP-40 RP-080364 1070 Correction to test procedure in 7.8.5 of 34.121-1 F 8.2.1 8.3.0 R5-081 RP-40 RP-080363 1071 8.6.2.1 and 8.6.2.1A: correction to Measurement Control message F 8.2.1 8.3.0 R5-081 RP-40 RP-080363 1072 Correction to 8.7.1.1 and 8.7.3A F 8.2.1 8.3.0 R5-081 RP-40 RP-080427 1074 Correction to set procedure of RRM test cases F 8.2.1 8.3.0 R5-081 RP-40 RP-080364 1075 Correction to test procedure of RRM test cases F 8.2.1 8.3.0 R5-081 RP-40 RP-080364 1075 Correction to Call power in Section 11 Test Cases F 8.2.1 8.3.0 R5-081 RP-40 RP-080364 1078	R5-081174					-			
RP-40 RP-080364 1069 Correction to Annex C.3.5 and C.6.2 for 7.8.1A F 8.2.1 8.3.0 R5-081 RP-40 RP-080364 1070 Correction to test procedure in 7.8.5 of 34.121-1 F 8.2.1 8.3.0 R5-081 RP-40 RP-080363 1071 - 8.6.2.1 and 8.6.2.16: correction to Measurement Control message F 8.2.1 8.3.0 R5-081 RP-40 RP-080363 1072 - Correction to 8.7.1.1 and 8.7.3A F 8.2.1 8.3.0 R5-081 RP-40 RP-080364 1073 - Correction to 8.3.6.3 F 8.2.1 8.3.0 R5-081 RP-40 RP-080364 1075 - Correction to test procedure of RRM test cases for Enhanced Performance type 1 type 2 and type 3 terminals F 8.2.1 8.3.0 R5-081 RP-40 RP-080364 1076 - Statistical requirements for Clause 11 (MBMS) F 8.2.1 8.3.0 R5-081 RP-40 RP-080364 1077 - Correction to cell power in Section 11 Test Cases F 8.2	R5-081437					-			
RP-40 RP-080364 1070 - Correction to test procedure in 7.8.5 of 34.121-1 F 8.2.1 8.3.0 R5-081 RP-40 RP-080363 1071 - 8.6.2.1 and 8.6.2.1 k: correction to Measurement F 8.2.1 8.3.0 R5-081 RP-40 RP-080363 1072 - Correction to 8.7.1.1 and 8.7.3A F 8.2.1 8.3.0 R5-081 RP-40 RP-080364 1073 - Correction to 8.3.6.3 F 8.2.1 8.3.0 R5-081 RP-40 RP-080427 1074 - Correction to test procedure of RRM test cases F 8.2.1 8.3.0 R5-081 RP-40 RP-080364 1075 - Correction to 34.121-1 HSDPA tests' applicabilities for Enhanced Performance type 1 type 2 and type 3 terminals F 8.2.1 8.3.0 R5-081 RP-40 RP-080364 1076 - Statistical requirements for Clause 11 (MBMS) F 8.2.1 8.3.0 R5-081 RP-40 RP-080364 1077 - Correction to cell power in Section 11 Test Cases	R5-081440		_			-			
RP-40 RP-080363 1071 - 8.6.2.1 and 8.6.2.1A: correction to Measurement Control message F 8.2.1 8.3.0 R5-081 RP-40 RP-080363 1072 - Correction to 8.7.1.1 and 8.7.3A F 8.2.1 8.3.0 R5-081 RP-40 RP-080364 1073 - Correction to 8.3.6.3 F 8.2.1 8.3.0 R5-081 RP-40 RP-080427 1074 - Correction to test procedure of RRM test cases B.6.1.5 F 8.2.1 8.3.0 R5-081 RP-40 RP-080364 1075 - Correction to 24.121-1 HSDPA tests' applicabilities for Enhanced Performance type 1 type 2 and type 3 terminals R5-081 RP-40 RP-080364 1076 - Statistical requirements for Clause 11 (MBMS) F 8.2.1 8.3.0 R5-081 RP-40 RP-080364 1077 - Correction to cell power in Section 11 Test Cases F 8.2.1 8.3.0 R5-081 RP-40 RP-080364 1079 - Correction to TC 8.3.5.4 F 8.2.1 8.3.0	R5-081441					-			
RP-40 RP-080363 1072 - Correction to 8.7.1.1 and 8.7.3A F 8.2.1 8.3.0 R5-081 RP-40 RP-080364 1073 - Correction to 8.3.6.3 F 8.2.1 8.3.0 R5-081 RP-40 RP-080427 1074 - Correction to test procedure of RRM test cases F 8.2.1 8.3.0 R5-081 RP-40 RP-080364 1075 - Correction to 34.121-1 HSDPA tests' applicabilities for Enhanced Performance type 1 type 2 and type 3 terminals F 8.2.1 8.3.0 R5-081 RP-40 RP-080364 1076 - Statistical requirements for Clause 11 (MBMS) F 8.2.1 8.3.0 R5-081 RP-40 RP-080364 1077 - Correction to cell power in Section 11 Test Cases F 8.2.1 8.3.0 R5-081 RP-40 RP-080364 1078 - Correction to Cell power in Section 11 Test Cases F 8.2.1 8.3.0 R5-081 RP-40 RP-080364 1079 - Corrections to TBS size for MBMS test cases <td< td=""><td>R5-081271 R5-081442</td><td></td><td></td><td></td><td>8.6.2.1 and 8.6.2.1A: correction to Measurement</td><td>-</td><td></td><td></td><td></td></td<>	R5-081271 R5-081442				8.6.2.1 and 8.6.2.1A: correction to Measurement	-			
RP-40 RP-080364 1073 Correction to 8.3.6.3 F 8.2.1 8.3.0 R5-081 RP-40 RP-080427 1074 Correction to test procedure of RRM test cases F 8.2.1 8.3.0 R5-081 RP-40 RP-080364 1075 Correction to 34.121-1 HSDPA tests' applicabilities for Enhanced Performance type 1 type 2 and type 3 terminals F 8.2.1 8.3.0 R5-081 RP-40 RP-080364 1076 Statistical requirements for Clause 11 (MBMS) F 8.2.1 8.3.0 R5-081 RP-40 RP-080364 1077 Correction to cell power in Section 11 Test Cases F 8.2.1 8.3.0 R5-081 RP-40 RP-080364 1078 Correction to TC 8.3.5.4 F 8.2.1 8.3.0 R5-081 RP-40 RP-080364 1079 Correction to TS size for MBMS test cases F 8.2.1 8.3.0 R5-081 RP-40 RP-080365 1080 Correction to Annex B F 8.2.1 8.3.0 R5-081 RP-41 RP-080555 1082 Correctio	D5 091272	020	0 2 1	_			1072	DD 080363	DD 40
RP-40 RP-080427 1074 Correction to test procedure of RRM test cases 8.6.1.5 and 8.6.1.6 F 8.2.1 8.3.0 R5-081 RP-40 RP-080364 1075 Correction to 34.121-1 HSDPA tests' applicabilities for Enhanced Performance type 1 type 2 and type 3 terminals F 8.2.1 8.3.0 R5-081 RP-40 RP-080364 1076 Statistical requirements for Clause 11 (MBMS) F 8.2.1 8.3.0 R5-081 RP-40 RP-080364 1077 Correction to cell power in Section 11 Test Cases F 8.2.1 8.3.0 R5-081 RP-40 RP-080364 1078 Correction to TC 8.3.5.4 F 8.2.1 8.3.0 R5-081 RP-40 RP-080364 1079 Corrections to TBS size for MBMS test cases F 8.2.1 8.3.0 R5-081 RP-40 RP-080365 1080 Correction to Annex B F 8.2.1 8.3.0 R5-081 RP-41 RP-080364 1081 Correction to system uncertainty and test tolerance of 8.3.6.3 F 8.3.0 8.4.0 R5-083 RP-41			_			- -			
RP-40 RP-080364 1075 Correction to 34.121-1 HSDPA tests' applicabilities for Enhanced Performance type 1 type 2 and type 3 terminals RP-40 RP-080364 1076 Statistical requirements for Clause 11 (MBMS) F 8.2.1 8.3.0 R5-081 RP-40 RP-080364 1077 Correction to cell power in Section 11 Test Cases F 8.2.1 8.3.0 R5-081 RP-40 RP-080364 1078 Correction to TC 8.3.5.4 F 8.2.1 8.3.0 R5-081 RP-40 RP-080364 1079 Corrections to TBS size for MBMS test cases F 8.2.1 8.3.0 R5-081 RP-40 RP-080365 1080 Corrections to TBS size for MBMS test cases F 8.2.1 8.3.0 R5-081 RP-40 RP-080365 1080 Correction to Annex B F 8.2.1 8.3.0 R5-081 RP-40 RP-080365 1081 Correction to system uncertainty and test tolerance of 8.3.6.3 R5-081 RP-41 RP-080555 1082 Corrections to cross references in EVM tests F 8.3.0 8.4.0 R5-083 RP-41 RP-080740 1084 Correction to RRM tests cases in clause 8.2.3 F 8.3.0 8.4.0 R5-083 RP-41 RP-080740 1085 Correction to 8.3.5.4 and 8.3.6.3 F 8.3.0 8.4.0 R5-083 RP-41 RP-080740 1086 Addition the message exceptions to 11.2, 11.2A, and 8.3.0 R5-083 RP-41 RP-080740 1086 Addition the message exceptions to 11.2, 11.2A, and 8.3.0 R5-083 RP-41 RP-080740 1087 Correction to 7.8.5 F 8.3.0 8.4.0 R5-083 R5-083 RP-41 RP-080740 1087 Correction to 7.8.5 F 8.3.0 8.4.0 R5-083 RP-41 RP-080740 1087 Correction to 7.8.5 F 8.3.0 8.4.0 R5-083 RP-41 RP-080740 1087 Correction to 7.8.5 F 8.3.0 R5-083 R5-08	R5-081352				Correction to test procedure of RRM test cases	-			
RP-40 RP-080364 1076 Statistical requirements for Clause 11 (MBMS) F 8.2.1 8.3.0 R5-081 RP-40 RP-080364 1077 Correction to cell power in Section 11 Test Cases F 8.2.1 8.3.0 R5-081 RP-40 RP-080364 1078 Correction to TC 8.3.5.4 F 8.2.1 8.3.0 R5-081 RP-40 RP-080364 1079 Corrections to TBS size for MBMS test cases F 8.2.1 8.3.0 R5-081 RP-40 RP-080365 1080 Correction to Annex B F 8.2.1 8.3.0 R5-081 RP-40 RP-080364 1081 Correction to system uncertainty and test tolerance of 8.3.6 F 8.2.1 8.3.0 R5-081 RP-41 RP-080555 1082 Corrections to cross references in EVM tests F 8.3.0 8.4.0 R5-083 RP-41 RP-080554 1083 Correction to RRM tests cases in clause 8.2.3 F 8.3.0 8.4.0 R5-083 RP-41 RP-080740 1084 Correction to RSLPA Tx test case <td>R5-081221</td> <td>8.3.0</td> <td>8.2.1</td> <td>F</td> <td>Correction to 34.121-1 HSDPA tests' applicabilities for Enhanced Performance type 1 type 2 and type 3</td> <td>-</td> <td>1075</td> <td>RP-080364</td> <td>RP-40</td>	R5-081221	8.3.0	8.2.1	F	Correction to 34.121-1 HSDPA tests' applicabilities for Enhanced Performance type 1 type 2 and type 3	-	1075	RP-080364	RP-40
RP-40 RP-080364 1077 Correction to cell power in Section 11 Test Cases F 8.2.1 8.3.0 R5-081 RP-40 RP-080364 1078 Correction to TC 8.3.5.4 F 8.2.1 8.3.0 R5-081 RP-40 RP-080364 1079 Corrections to TBS size for MBMS test cases F 8.2.1 8.3.0 R5-081 RP-40 RP-080365 1080 Correction to Annex B F 8.2.1 8.3.0 R5-081 RP-40 RP-080364 1081 Correction to system uncertainty and test tolerance of 8.3.0 R5-081 RP-41 RP-080555 1082 Corrections to cross references in EVM tests F 8.3.0 8.4.0 R5-083 RP-41 RP-080554 1083 Correction to RRM tests cases in clause 8.2.3 F 8.3.0 8.4.0 R5-083 RP-41 RP-080740 1084 Correction to HSUPA Tx test case F 8.3.0 8.4.0 R5-083 RP-41 RP-080740 1085 Correction to 8.3.5.4 and 8.3.6.3 F 8.3.0 8.4.0 <t< td=""><td>R5-081444</td><td>8.3.0</td><td>8.2.1</td><td>F</td><td></td><td>-</td><td>1076</td><td>RP-080364</td><td>RP-40</td></t<>	R5-081444	8.3.0	8.2.1	F		-	1076	RP-080364	RP-40
RP-40 RP-080364 1079 Corrections to TBS size for MBMS test cases F 8.2.1 8.3.0 R5-081 RP-40 RP-080365 1080 Correction to Annex B F 8.2.1 8.3.0 R5-081 RP-40 RP-080364 1081 Correction to system uncertainty and test tolerance of 8.3.6.3 F 8.2.1 8.3.0 R5-081 RP-41 RP-080555 1082 Corrections to cross references in EVM tests F 8.3.0 8.4.0 R5-083 RP-41 RP-080554 1083 Correction to RRM tests cases in clause 8.2.3 F 8.3.0 8.4.0 R5-083 RP-41 RP-080740 1084 Correction to HSUPA Tx test case F 8.3.0 8.4.0 R5-083 RP-41 RP-080740 1085 Correction to 8.3.5.4 and 8.3.6.3 F 8.3.0 8.4.0 R5-083 RP-41 RP-080740 1086 Addition the message exceptions to 11.2, 11.2A, and 11.3 R 8.3.0 8.4.0 R5-083 RP-41 RP-080740 1087 Correction to 7.8.5	R5-081445			F	Correction to cell power in Section 11 Test Cases	-	1077		
RP-40 RP-080365 1080 - Correction to Annex B F 8.2.1 8.3.0 R5-081 RP-40 RP-080364 1081 - Correction to system uncertainty and test tolerance of 8.3.6.3 F 8.2.1 8.3.0 R5-081 RP-41 RP-080555 1082 - Corrections to cross references in EVM tests F 8.3.0 8.4.0 R5-083 RP-41 RP-080554 1083 - Correction to RRM tests cases in clause 8.2.3 F 8.3.0 8.4.0 R5-083 RP-41 RP080740 1084 - Correction to HSUPA Tx test case F 8.3.0 8.4.0 R5-083 RP-41 RP080740 1085 - Correction to 8.3.5.4 and 8.3.6.3 F 8.3.0 8.4.0 R5-083 RP-41 RP080740 1086 - Addition the message exceptions to 11.2, 11.2A, and 11.3 R1.2 R5-083 RP-41 RP080740 1087 - Correction to 7.8.5 F 8.3.0 8.4.0 R5-083	R5-081286					-			
RP-40 RP-080364 1081 - Correction to system uncertainty and test tolerance of 8.3.6.3 F 8.2.1 8.3.0 R5-081 RP-41 RP-080555 1082 - Corrections to cross references in EVM tests F 8.3.0 8.4.0 R5-083 RP-41 RP-080554 1083 - Correction to RRM tests cases in clause 8.2.3 F 8.3.0 8.4.0 R5-083 RP-41 RP080740 1084 - Correction to HSUPA Tx test case F 8.3.0 8.4.0 R5-083 RP-41 RP080740 1085 - Correction to 8.3.5.4 and 8.3.6.3 F 8.3.0 8.4.0 R5-083 RP-41 RP080740 1086 - Addition the message exceptions to 11.2, 11.2A, and 11.3 F 8.3.0 8.4.0 R5-083 RP-41 RP080740 1087 - Correction to 7.8.5 F 8.3.0 8.4.0 R5-083	R5-081449					-			
RP-41 RP-080555 1082 - Corrections to cross references in EVM tests F 8.3.0 8.4.0 R5-083 RP-41 RP-080554 1083 - Correction to RRM tests cases in clause 8.2.3 F 8.3.0 8.4.0 R5-083 RP-41 RP080740 1084 - Correction to HSUPA Tx test case F 8.3.0 8.4.0 R5-083 RP-41 RP080740 1085 - Correction to 8.3.5.4 and 8.3.6.3 F 8.3.0 8.4.0 R5-083 RP-41 RP080740 1086 - Addition the message exceptions to 11.2, 11.2A, and 11.3 F 8.3.0 8.4.0 R5-083 RP-41 RP080740 1087 - Correction to 7.8.5 F 8.3.0 8.4.0 R5-083	R5-081426					-			
RP-41 RP-080554 1083 - Correction to RRM tests cases in clause 8.2.3 F 8.3.0 8.4.0 R5-083 RP-41 RP-080740 1084 - Correction to HSUPA Tx test case F 8.3.0 8.4.0 R5-083 RP-41 RP-080740 1085 - Correction to 8.3.5.4 and 8.3.6.3 F 8.3.0 8.4.0 R5-083 RP-41 RP-080740 1086 - Addition the message exceptions to 11.2, 11.2A, and 11.3 F 8.3.0 8.4.0 R5-083 RP-41 RP-080740 1087 - Correction to 7.8.5 F 8.3.0 8.4.0 R5-083	R5-081261	8.3.0	8.2.1	F		-	1081	RP-080364	RP-40
RP-41 RP-080554 1083 - Correction to RRM tests cases in clause 8.2.3 F 8.3.0 8.4.0 R5-083 RP-41 RP-080740 1084 - Correction to HSUPA Tx test case F 8.3.0 8.4.0 R5-083 RP-41 RP-080740 1085 - Correction to 8.3.5.4 and 8.3.6.3 F 8.3.0 8.4.0 R5-083 RP-41 RP-080740 1086 - Addition the message exceptions to 11.2, 11.2A, and 11.3 F 8.3.0 8.4.0 R5-083 RP-41 RP-080740 1087 - Correction to 7.8.5 F 8.3.0 8.4.0 R5-083	R5-083190	8.4.0	8.3.0		Corrections to cross references in EVM tests	-	1082	RP-080555	RP-41
RP-41 RP080740 1085 - Correction to 8.3.5.4 and 8.3.6.3 F 8.3.0 8.4.0 R5-083 RP-41 RP080740 1086 - Addition the message exceptions to 11.2, 11.2A, and 11.3 F 8.3.0 8.4.0 R5-083 RP-41 RP080740 1087 - Correction to 7.8.5 F 8.3.0 8.4.0 R5-083	R5-083219					-			
RP-41 RP080740 1086 - Addition the message exceptions to 11.2, 11.2A, and 11.3 F 8.3.0 8.4.0 R5-083 RP-41 RP080740 1087 - Correction to 7.8.5 F 8.3.0 8.4.0 R5-083	R5-083326					-			
and 11.3	R5-083328	8.4.0				-			
	R5-083329				and 11.3	-			
IDD 44 IDD 000FF7 14000	R5-083330					-			
	R5-083335					-			
RP-41 RP-080554 1090 - Correction to RRM test case 8.6.5.1 - compressed F 8.3.0 8.4.0 R5-083	R5-083343 R5-083349				Correction to RRM test case 8.6.5.1 – compressed	-			
mode and Measurement report	R5-083373	8.4.0	8.3.0	F		-	1091	RP080740	RP-41
	R5-083374				Performance tests for UE with RX-diversity:	-			
	R5-083376	8.4.0	8.3.0	F		-	1093	RP080740	RP-41
	R5-083381					-			
	R5-083384				Correction to Annex E.5.3 with respect to TC 9.2.1G	-			
RP-41 RP-080554 1096 - Typo in 6.5.2 F 8.3.0 8.4.0 R5-083	R5-083385	8.4.0	8.3.0	F	Typo in 6.5.2	-	1096	RP-080554	RP-41

						- Current	-New	Doc-2 nd -Level
RP-41	RP080740	1097	-	Maximum Channelisation Codes for CAT6 UE in 2ms case	F	8.3.0	8.4.0	R5-083388
	RP-080554	1098	-	Correction to for the DL reference measurement channel 2 for 64 kbps	F	8.3.0	8.4.0	R5-083389
RP-41	RP-080557	1099	-	Correction to MIMO propagation conditions, Annex D2.9	F	8.3.0	8.4.0	R5-083390
RP-41	RP080740	1100	-		F	8.3.0	8.4.0	R5-083454
RP-41	RP-080702	1101	-	New Fixed Reference Channel H-Set10 for 15 codes reception	F	8.3.0	8.4.0	R5-083462
RP-41	RP-080557	1102	-	Proposal on the testing specification of Transmitter Characteristics for TS 36.521-1	F	8.3.0	8.4.0	R5-083818
RP-41	RP-080702	1103	-	UE categories for 15 codes HSDPA reception to chapter 9.2 and applicability changes to existing tests.	F	8.3.0	8.4.0	R5-083819
RP-41	RP-080702	1104	-	UE categories for HSDPA 15 codes reception, applicability in existing tests.	F	8.3.0	8.4.0	R5-083820
RP-41	RP-080554	1105	-	Correction to the reference table of test case 6.8	F	8.3.0	8.4.0	R5-083827
RP-41	RP-080557	1106	-	Correction to 9.5.1 and 9.5.1A	F	8.3.0	8.4.0	R5-083832
	RP-080554	1107	-	Missing AWGN in connection A.13 and A.18	F	8.3.0	8.4.0	R5-083833
	RP-080560	1108	-	CR to 34.121 for SEM test cases	F	8.3.0	8.4.0	R5-083841
	RP-080554	1109	-	Correction to WI-10 RRM test case 8.3.5.3	F	8.3.0	8.4.0	R5-083846
	RP-080557	1110	-	TT for TC5.13.1AAA (EVM and IQ offset	F	8.3.0	8.4.0	R5-083847
	RP-080557	1111	-	CR to 34.121 for E-DCH 16QAM test cases	F	8.3.0	8.4.0	R5-083850
	RP-080954	1112	-	CR to 34.121-1 for 5.13.2B test case	F	8.4.0	8.5.0	R5-085074
	RP-080955	1113	-	CR to 34.121-1 Update of table F.6.3.5.1A	F	8.4.0	8.5.0	R5-085075
	RP-080963	1114	-	New HSDPA performance test cases for UEs supporting 15 HS-PDSCH codes	F	8.4.0	8.5.0	R5-085161
	RP-080955	1115	-	Clarification of title for MIMO clause 9.3.7	F	8.4.0	8.5.0	R5-085171
	RP-080955	1116	-	Correction to 5.2E, 5.13.1AAA and 5.13.2C	F	8.4.0	8.5.0	R5-085224
	RP-080956	1117	-	Correction to system uncertainty and test tolerance for 6.3B and 9.2.1	F	8.4.0	8.5.0	R5-085225
	RP-080954	1118	-	Correction to 9.2.1H, 9.2.1I and 9.2.4A	F	8.4.0	8.5.0	R5-085227
	RP-080954	1119	-	Correction to 6.3B, 9.2.1H and 9.2.1I	F	8.4.0	8.5.0	R5-085229
	RP-080954	1120	-	Correction to test time in 11.2 and 11.2A	F	8.4.0	8.5.0	R5-085234
	RP-080956 RP-080963	1121 1122	-	TT for TC 5.13.1AAA (EVM and IQ offset) Statistical testing for new HSDPA performance test	F F	8.4.0 8.4.0	8.5.0 8.5.0	R5-085318 R5-085724
RP-42	RP-080963	1123	-	cases (15 codes) Changes to Annex for UEs supporting 15 HS-PDSCH codes	F	8.4.0	8.5.0	R5-085725
RP-42	RP-080955	1124	-	CR to 34.121-1 for 5.13.2C test case editorial change	F	8.4.0	8.5.0	R5-085728
RP-42	RP-080953	1125	_		F	8.4.0	8.5.0	R5-085729
	RP-080956	1126	_	Applicability changes in Demodulation of HS-DSCH		8.4.0	8.5.0	R5-085730
	RP-080956	1127		single link tests.	F	8.4.0	8.5.0	R5-085731
	RP-080956	1128		Tx diversity tests. Wrong minimum requirements in test case 9.2.3C	· F	8.4.0	8.5.0	R5-085732
	RP-080953	1129	-	Addition of references for UE's supporting a release-		8.4.0	8.5.0	R5-083830
				independent frequency band				
	RP-090203	1130	-	Modifications to CQI test cases in annexes	F	8.5.0	8.6.0	R5-090094
	RP-090218	1132	-	New TC9.3.7D MIMO Dual Stream Static Orthogonal Conditions UE categories 15-20	F	8.5.0	8.6.0	R5-090242
RP-43	RP-090218	1133	-	New TC9.3.7E MIMO Dual Stream Static Orthogonal Conditions UE categories 19-20	F	8.5.0	8.6.0	R5-090244
RP-43	RP-090200	1134	1-	Correction to 8.7.1 and 8.7.2	F	8.5.0	8.6.0	R5-090305
RP-43	RP-090200	1135	-	Statistical requirements for TC 7.8.5 (Power control in the downlink for F-DPCH)	F	8.5.0	8.6.0	R5-090378
RP-43	RP-090203	1136	-	Correction to minimum test time for 9.5.1 and 9.5.1A	F	8.5.0	8.6.0	R5-090397
	RP-090218	1137	-	Fixed reference channel FRC H-Set 11 for 64QAM + MIMO		8.5.0	8.6.0	R5-090491
RP-43	RP-090200	1138	-		F	8.5.0	8.6.0	R5-091037
RP-43	RP-090202	1139	-	Correction to RRM E-TFC restriction test cases 8.4.4.1 and 8.4.4.2	F	8.5.0	8.6.0	R5-091062
RP-43	RP-090202	1140	 	Correction to 8.4.4.1 and 8.4.4.2	F	8.5.0	8.6.0	R5-091065
	RP-090202	1141	1-	Correction of table 8.7.1.1.1.5 the reported value	F	8.5.0	8.6.0	R5-091066
				requirements for 8.7.1.1.1				
RP-43	RP-090203	1142	[Extensions to CQI tests	F	8.5.0	8.6.0	R5-091067
	RP-090203	1143	-	Correction to minimum requirement table for 9.2.1 and 9.2.4	F	8.5.0	8.6.0	R5-091069
	RP-090203	1144	-		F	8.5.0	8.6.0	R5-091074

RP-43 F RP-43 F RP-43 F RP-43 F RP-44 F RP-44 F	RP-090203 RP-090218 RP-090218 RP-090202 RP-090201 RP-090201	1145 1146 1147 1148	-	control operation with discontinuous UL DPCCH transmission operation & changes to section 7 Introduction of requirements for UE UL power control operation with discontinuous UL DPCCH transmission operation & changes to Annexes	F	8.5.0	8.6.0	R5-091075
RP-43 F RP-43 F RP-43 F RP-43 F RP-44 F RP-44 F	RP-090218 RP-090218 RP-090202 RP-090201	1146	-	transmission operation & changes to section 7 Introduction of requirements for UE UL power control operation with discontinuous UL DPCCH	F	8.5.0	960	P5-001075
RP-43 F RP-43 F RP-43 F RP-43 F RP-44 F RP-44 F	RP-090218 RP-090218 RP-090202 RP-090201	1146	-	control operation with discontinuous UL DPCCH	F	8.5.0	960	P5-001075
RP-43 F RP-43 F RP-43 F RP-44 F RP-44 F	RP-090218 RP-090202 RP-090201	1147	-				0.0.0	179-091079
RP-43 F RP-43 F RP-43 F RP-44 F RP-44 F	RP-090218 RP-090202 RP-090201	1147	-	Itransmission operation & changes to Annexes				
RP-43 F RP-43 F RP-43 F RP-44 F RP-44 F	RP-090218 RP-090202 RP-090201	1147	-	Nov. TCO 2.7C MIMO Duel Chrome Fording	_	0.5.0	0.00	DE 004000
RP-43 F RP-43 F RP-44 F RP-44 F	RP-090202 RP-090201			New TC9.3.7C MIMO Dual Stream Fading	F	8.5.0	8.6.0	R5-091093
RP-43 F RP-43 F RP-44 F RP-44 F	RP-090202 RP-090201		-	Conditions & UE categories 19-20 Adding test tolerances and MIMO propagation	F	8.5.0	8.6.0	R5-091094
RP-43 F RP-43 F RP-44 F RP-44 F	RP-090201	1148		conditions in the annex for New MIMO test cases	'	0.5.0	0.0.0	100001004
RP-43 F RP-44 F RP-44 F			-	Statistical requirements for TC 9.2.3C	F	8.5.0	8.6.0	R5-091098
RP-44 F	RP-090218	1149	-	Clarification on compressed mode DL frame type	F	8.5.0	8.6.0	R5-091103
RP-44		1150	-	Mandatory support of enhanced receiver for 64QAM	F	8.5.0	8.6.0	R5-091104
RP-44				or MIMO capable UEs				
	RP-090445	1151	-	Statistical annex: HSDPA in CELL_FACH	F	8.6.0	8.7.0	R5-092134
DD_44 r	RP-090432	1152	-	Correction to TRANSPORT CHANNEL	F	8.6.0	8.7.0	R5-092145
	RP-090444	1150		RECONFIGURATION message in Annex I	F	0.6.0	0.7.0	R5-092175
117-44	RP-090444	1153	-	Addition of 64QAM + MIMO test case in annex of 34.121-1	F	8.6.0	8.7.0	R5-092175
RP-44 F	RP-090433	1154	_	Correction to 64QAM TCs of 6.3B, 9.2.1H, and	F	8.6.0	8.7.0	R5-092368
1 44	11 000-100	1104		9.2.11	•	0.0.0	0.7.0	110 002000
RP-44 F	RP-090444	1155	-	New HSDPA demodulation test for MIMO + 64QAM	F	8.6.0	8.7.0	R5-092631
				into 34.121-1				
RP-44	RP-090442	1156	-	Update of Annexure A and Annexure E.	F	8.6.0	8.7.0	R5-092634
	RP-090432	1157	-	Clarification about Rx Diversity in RRM tests	F	8.6.0	8.7.0	R5-092650
RP-44 F	RP-090442	1158	-	New TC9.2.1L Single Link Performance -	F	8.6.0	8.7.0	R5-092654
				Enhanced Performance Requirements Type 3i -				
DD 44	DD 000 100	1150		QPSK, Fixed Reference Channel (FRC) H-Set 6	_	0.00	0.7.0	DE 0000E0
	RP-090432	1159	-	Correction to HSUPA TC 5.2D and 5.13.2B	F	8.6.0	8.7.0	R5-092659
	RP-090432 RP-090598	1160 1162	-	CR to 34.121-1: Addition of band XIX to RRM test	F F	8.6.0 8.6.0	8.7.0 8.7.0	R5-092662 R5-092438
KP-44	KP-090596	1102	-	cases	Г	0.0.0	0.7.0	K5-092436
RP-44 F	RP-090598	1163	_	Introduction of Extended UMTS800 for TRx	F	8.6.0	8.7.0	R5-092462
	11 000000	1100		requirements	•	0.0.0	0.7.0	110 002402
RP-44 F	RP-090598	1164	-	Update of Annex for Extended UMTS 800	F	8.6.0	8.7.0	R5-092463
RP-44 F	RP-090432	0088	2	Improved stability of TC7.8.5 Power control in the	F	8.6.0	8.7.0	R5-092652
				downlink for F-DPCH				
	RP-090805	1165	-	Inclusion of DC-HSDPA into Annexes	F	8.7.0	8.8.0	R5-094236
	RP-090793	1166	-	Changes to applicabilities of CQI test cases	F	8.7.0	8.8.0	R5-094238
	RP-090794	1167	-	Corrections to Test Case 9.3.1A	F	8.7.0	8.8.0	R5-094239
	RP-090794	1168	-	Correction to FRC H-Set 8 Definition	F	8.7.0	8.8.0	R5-094240
	RP-090794 RP-090801	1169 1171	-	Correction to Table E.5.5A CR to 34.121-1: Addition of UTRA FDD-E-UTRA	F F	8.7.0 8.7.0	8.8.0 8.8.0	R5-094241 R5-094251
KP-45	KP-090601	1171	-	FDD cell reselection test case (E-UTRA is of higher Priority)	Г	0.7.0	0.0.0	R5-094251
RP-45 F	RP-090801	1172	-	CR to 34.121-1: Addition of UTRA FDD-E-UTRA	F	8.7.0	8.8.0	R5-094252
				FDD cell reselection test case (E-UTRA is of lower				
				Priority)				
RP-45	RP-090801	1173	-	CR to 34.121-1: Addition of UTRA FDD - E-UTRA	F	8.7.0	8.8.0	R5-094255
DD 45	DD 000004	4474		FDD cell search (fading) test case	_	0.7.0	0.0.0	DE 004050
RP-45	RP-090801	1174	-	CR to 34.121-1: Addition of UTRA FDD - E-UTRA FDD HO delay test case	F	8.7.0	8.8.0	R5-094256
		1175	_	-	_	_	_	_
RP-45 F	RP-090807	1176	_	Statistics for Test 9.2.1L (HSDPA type 3i)	F	8.7.0	8.8.0	R5-094383
	RP-090810	1177	-	CR to 34.121-1: Addition of band XIX requirement to		8.7.0	8.8.0	R5-094531
				6.8 test case	-			
RP-45 F	RP-090807	1178	-	Update to the Applicability sections under	F	8.7.0	8.8.0	R5-094553
				Performance requirements for HSDPA clause of				
				34.121-1				
		1179	-	-	-	-	-	-
RP-45 F	RP-090791	1180 1181	-	Adding reference to the new test sees 0.005 and	- F	8.7.0	8.8.0	- R5-094828
KP-45	RP-090791	1181	-	Adding reference to the new test cases 9.2.2E and 9.2.3E in annex	F	8.7.0	8.8.0	R5-094828
RP-45 F	RP-090800	1182	1_	Update to MIMO Performance - Reporting of	F	8.7.0	8.8.0	R5-094947
10	555550	2		Channel Quality Indicator test cases	ľ	3.1.0	3.3.0	
RP-45 F	RP-090805	1183	1-		F	8.7.0	8.8.0	R5-094948
-				34.121-1				
RP-45 F	RP-090805	1184	-	Inclusion of DC-HSDPA into section 6 of TS 34.121-	F	8.7.0	8.8.0	R5-094949
				1				
RP-45	RP-090805	1185	-	Reporting CQI test cases for DC-HSDPA Single Link Performance - AWGN and fading Propagation Conditions	F	8.7.0	8.8.0	R5-094950
RP-45 F	RP-090805	1186	<u> </u>	Inclusion of DC-HSDPA into sections 9.2 of TS	F	8.7.0	8.8.0	R5-094951

T Meeting	Doc-1 st -Level	CR	Rev	Subject	Cat	Version - Current	Version -New	Doc-2 nd -Level
				34.121-1				
RP-45	RP-090801	1187	-	UTRA FDD to E-UTRA TDD handover test case	F	8.7.0	8.8.0	R5-094955
RP-45 RP-45	RP-090801 RP-090793	1188 1189	-	UTRA FDD to E-UTRA TDD Cell Search test case Corrections to Annex C.11 for E-DCH test cases	F F	8.7.0 8.7.0	8.8.0	R5-094956 R5-094962
KF -45	KF-090793	1190			_	0.7.0	0.0.0	K3-094902
RP-45	RP-090809	1191	_	New test cases: HS-DSCH and HS-SCCH in	F	8.7.0	8.8.0	R5-094985
RP-45	RP-090793	1192	_	CR to 34.121-1: Correction to 5.2B test case	F.	8.7.0	8.8.0	R5-094992
RP-45	RP-090793	1193	_	CR to 34.121-1: Correction to 5.9B and 5.10B test	F	8.7.0	8.8.0	R5-094993
RP-46	RP-091121	1194	_	CR to 34.121-1: Update to UTRA FDD - E-UTRA	F	8.8.0	8.9.0	R5-095870
RP-46	RP-091121	1195	_	CR to 34.121-1: Update to UTRA FDD - E-UTRA	F	8.8.0	8.9.0	R5-095871
RP-46	RP-091121	1196	-	CR to 34.121-1: Addition of UTRA FDD - E-UTRA	F	8.8.0	8.9.0	R5-095872
RP-46	RP-091124	1197	-	Addition of Connection Diagrams for DC-HSDPA	F	8.8.0	8.9.0	R5-095918
RP-46	RP-091124	1198	-	Addition of DC-HSDPA receiver test cases to annex	F	8.8.0	8.9.0	R5-095920
RP-46	RP-091124	1199	-	Adding test tolerances and connection diagram	F	8.8.0	8.9.0	R5-095921
RP-46	RP-091117	1200	-	Correction to 9.2.3D for supported UE categories	F	8.8.0	8.9.0	R5-096050
RP-46	RP-091126	1201	-	Introduction of Type 3i test case uncertainties and	F	8.8.0	8.9.0	R5-096051
RP-46	RP-091124	1202	-	Update to DC-HSDPA related sections 9.2 of TS	F	8.8.0	8.9.0	R5-096282
RP-46	RP-091124	1203	-	Update to Reporting CQI test cases for DC-HSDPA	F	8.8.0	8.9.0	R5-096283
RP-46	RP-091124	1204	-	Updates to Annexure A to Annexure F. in 34.121-1	F	8.8.0	8.9.0	R5-096284
RP-46	RP-091124	1205	-	Addition of AWGN definition for DC-HSDPA tests	F	8.8.0	8.9.0	R5-096286
RP-46	RP-091117	1206	-	Clarification for Maximum Output Power with HS-	F	8.8.0	8.9.0	R5-096288
RP-46	RP-091118	1207	2	Update of tests 9.6.1 and 9.6.2 (HS-DSCH and HS-	F	8.8.0	8.9.0	R5-096290
RP-47	RP-100149	1208	-	Amendments to DC-HSDPA receiver test cases	F	8.9.0	8.10.0	R5-100138
RP-47	RP-100159	1209	-	Introduction of enhanced serving HS-DSCH cell	F	8.9.0	8.10.0	R5-100141
RP-47	RP-100139	1210	-	Addition of UE Power Class 3bis to all bands	F	8.9.0	8.10.0	R5-100143
RP-47	RP-100137	1211	-	Clarification to testing of RRM test cases with	F	8.9.0	8.10.0	R5-100144
RP-47	RP-100139	1212	-	Correction TC 7.8.5	F	8.9.0	8.10.0	R5-100145
RP-47	RP-100138	1213	-	Correction to power setting with HS-DPCCH	F	8.9.0	8.10.0	R5-100146
RP-47	RP-100139	1214	-	Title change for test case in TC 8.3.5.4 in section 8	F	8.9.0	8.10.0	R5-100148
RP-47	RP-100139	1215	-	Title change for test case in TC 8.3.5.4 in annexes	F	8.9.0	8.10.0	R5-100149
RP-47	RP-100142	1216	-	Addition of new test case TC 8.3.4d (UTRA FDD to	F	8.9.0	8.10.0	R5-100157
RP-47	RP-100149	1217	-	Updates to DC-HSDPA performance test cases	F	8.9.0	8.10.0	R5-100165
RP-47	RP-100149	1218	-	Updates to Annexure of 34.121-1 due to addition of	F	8.9.0	8.10.0	R5-100166
RP-47	RP-100149	1219	-	Updates to DC-HSDPA CQI reporting test cases	F	8.9.0	8.10.0	R5-100213
RP-47	RP-100142	1220	-	CR to 34.121-1: Update to UTRA FDD - E-UTRA	F	8.9.0	8.10.0	R5-100549
RP-47	RP-100142	1221	-	CR to 34.121-1: Update to UTRA FDD - E-UTRA	F	8.9.0	8.10.0	R5-100550
RP-47	RP-100142	1222	-	CR to 34.121-1: Update to UTRA FDD - E-UTRA	F	8.9.0	8.10.0	R5-100551
RP-47	RP-100142	1223	-	CR to 34.121-1: Update to UTRA - E-UTRA cell search (fading) test cases	F	8.9.0	8.10.0	R5-100552
RP-47	RP-100142	1224	-	CR to 34.121-1: Addition of Combined UTRA FDD - UTRA FDD - E-UTRA FDD cell search test case	F	8.9.0	8.10.0	R5-100553
RP-47	RP-100142	1225	-	E-UTRA RRMs test cases	F	8.9.0	8.10.0	R5-100554
RP-47	RP-100154	1226	-	CR to 34.121-1: Introduction of Extended UMTS1500MHz for RRM requirements	F	8.9.0	8.10.0	R5-100557
RP-47	RP-100139	1227	-	CR to 34.121-1: Correction to 5.2B, 5.9B and 5.10B test cases	F	8.9.0	8.10.0	R5-100564
RP-47	RP-100142	1229	-	Addition of new test case TC 8.6.7.2 (Combined Inter frequency and E-UTRAN measurements) to TS 34.121-1	F	8.9.0	8.10.0	R5-100867
RP-47	RP-100142	1230	-	Compressed mode reference pattern parameter updates to Annex C.5 to 34.121-1	F	8.9.0	8.10.0	R5-100868
RP-47	RP-100142	1231	-	Update of 9.3.1A Channel Code Power	F	8.9.0	8.10.0	R5-100869
RP-47	RP-100142	1232	-	CR to 34.121-1: Introduction of Extended	F	8.9.0	8.10.0	R5-100874
RP-47	RP-100149	1233	-	UMTS1500MHz for TRx requirements Addition of statistical tables for DC-HSDPA receiver tests	F	8.9.0	8.10.0	R5-100876
RP-47	RP-100149	1234	-		F	8.9.0	8.10.0	R5-100877

Т	Doc-1 st -Level	CR	Rev	Subject	Cat	Version	Version	Doc-2 nd -Level
Meeting				·		- Current	-New	
RP-47	RP-100159	1235	-	Introduction of enhanced serving HS-DSCH cell change test case into section 8	F	8.9.0	8.10.0	R5-100878
RP-47	RP-100141	1236	-	New CQI test case for Periodically Varying Radio	F	8.9.0	8.10.0	R5-100882
RP-47	RP-100142	1237	-	UTRAN FDD - E-UTRAN TDD RSRP Measurement	F	8.9.0	8.10.0	R5-100902
RP-47	RP-100142	1238	-		F	8.9.0	8.10.0	R5-100903
RP-47	-	_	_	Accuracy Tests Moved to v9.0.0 with no change	_	8.10.0	9.0.0	-
RP-48	RP-100521	1239	-	Band20 test requirement additions to Inter/Intra Frequency measurement accuracy related test cases in Chapter 8(8.7.x)	F	9.0.0	9.1.0	R5-103166
RP-48	RP-100521	1240	-	Addition of Band20 Test Tolerance for section 8.7.3.2 in 34.121-1 Annex F	F	9.0.0	9.1.0	R5-103168
RP-48	RP-100519	1241	-		F	9.0.0	9.1.0	R5-103502
RP-48	RP-100519	1242	-		F	9.0.0	9.1.0	R5-103503
RP-48	RP-100508	1243	-	Replacing the HS-SCCH Type M with HS-SCCH Type 3	F	9.0.0	9.1.0	R5-103505
RP-48	RP-100508	1244	-	Small corrections to TC 9.2.4B	F	9.0.0	9.1.0	R5-103506
RP-48	RP-100507	1245	-	Clarifications to TC 5.2C and 5.2D applicabilities	F	9.0.0	9.1.0	R5-103507
RP-48	RP-100508	1246	-	Correction to reference to Figure D.2.9.3	F	9.0.0	9.1.0	R5-103509
RP-48	RP-100507	1247	-	Correction to test procedure of RRM test 8.3.8	F	9.0.0	9.1.0	R5-103554
RP-48	RP-100521	1248	-	Support for UMTS/LTE 800MHz for Europe in	F	9.0.0	9.1.0	R5-103557
RP-48	RP-100521	1249	-	Band20 test requirement additions to sections	F	9.0.0	9.1.0	R5-103723
RP-48	RP-100509	1250	-	CR to 34.121-1: Update to UTRA FDD - E-UTRA	F	9.0.0	9.1.0	R5-103762
RP-48	RP-100517	1251	-	Removing the square brackets from the values	F	9.0.0	9.1.0	R5-103765
RP-48	RP-100521	1253	-	CR to 34.121-1: Addition of UE RF requirements for	F	9.0.0	9.1.0	R5-103767
RP-48	RP-100509	1252	-	UTRAN FDD to E-UTRA FDD RSRQ absolute	F	9.0.0	9.1.0	R5-103774
RP-48	RP-100509	1254	-	UTRAN FDD to E-UTRA FDD RSRP absolute accuracy	F	9.0.0	9.1.0	R5-103775
RP-48	RP-100507	1255	-	Correction to missing parameters in Table E.5.8C and Table F.6.1.10.4	F	9.0.0	9.1.0	R5-103787
RP-49	RP-100812	1257	-	CR to 34.121-1: Update to Inter-system Handover from UTRAN FDD to E-UTRAN FDD test case	F	9.1.0	9.2.0	R5-104187
RP-49	RP-100810	1258	-	Clarifications to applicabilities of TC 5.13.2A and TC 5.13.2B	F	9.1.0	9.2.0	R5-104373
RP-49	RP-100811	1259	-	Addition of CQI fading test case for 64QAM UEs	F	9.1.0	9.2.0	R5-104376
RP-49	RP-100811	1260	-	Addition of CQI fading test case for 64QAM UEs into annexes	F	9.1.0	9.2.0	R5-104379
RP-49	RP-100809	1261	-		F	9.1.0	9.2.0	R5-104382
RP-49	RP-100811	1262	-	Modification of MIMO CQI fading test case and propagation condition names	F	9.1.0	9.2.0	R5-104384
RP-49	RP-100812	1263	-	UTRA testing	F	9.1.0	9.2.0	R5-104530
RP-49	RP-100812	1264	-	testing	F	9.1.0	9.2.0	R5-104531
RP-49	RP-100985	1265	-	Simplified connection for type 3i performance tests	F	9.1.0	9.2.0	R5-104592
RP-49 RP-49	RP-100985	1266 1267	-	Further simplification for type 3i performance tests	F F	9.1.0	9.2.0	R5-104593
RP-49	RP-100812 RP-100811	1267	-	34.121-1: Annex K update Removing editors notes in HS in CELL_FACH test	F	9.1.0	9.2.0	R5-104615 R5-104651
RP-49	RP-100808	1269	-	cases 34.121-1_TC9.2.1HA_Definition and applicability correction	F	9.1.0	9.2.0	R5-104831
RP-49	RP-100808	1270	-	34.121-1 Correction parameters of Chapter 9	F	9.1.0	9.2.0	R5-104832
RP-49	RP-100811	1271	-	Correction in Initial Settings references correlating to		9.1.0	9.2.0	R5-104833
RP-49	RP-100811	1272	-	Test Requirements Tables for test case 10.2.1.1A Correction in Initial Settings references correlating to		9.1.0	9.2.0	R5-104834
RP-49	RP-100809	1273	-	Test Requirements Tables for test case 10.4.1A Correction in Annex E.2.1 to refer Downlink Physical		9.1.0	9.2.0	R5-104835
RP-49	RP-100811	1274	-	Channels settings for test case 5.13.4 Adding RX diversity further to TC 5.4.4 (out of synch		9.1.0	9.2.0	R5-104836
RP-49	RP-100811	1275	-	handling) TT and uncertainties for TC 5.4.4A (out of synch	F	9.1.0	9.2.0	R5-104837
RP-50	RP-101137	1276	-	handling / RX diversity) Correction in Procedure Settings for test case	F	9.2.0	9.3.0	R5-106159
				9.2.1G and corresponding Annex F.6.3				

T Meeting	Doc-1 st -Level	CR	Rev	Subject	Cat	Version - Current	Version -New	Doc-2 nd -Level
RP-50	RP-101136	1277	-	Correction to RCDP E-DCH 16QAM	F	9.2.0	9.3.0	R5-106199
RP-50	RP-101138	1278	-	CR to 34.121-1: Correction to UTRA FDD - E-UTRA FDD cell re-selection (UTRA higher priority) test case	F	9.2.0	9.3.0	R5-106251
RP-50	RP-101137	1279	-	Correction to UE Relative Code Domain Power Accuracy requirements	F	9.2.0	9.3.0	R5-106409
RP-50	RP-101134	1280	-	Correction to references in out-of-sync tests 5.4.4 and 5.4.4A	F	9.2.0	9.3.0	R5-106411
RP-50	RP-101134	1281	-	Adding Band XII, XIII and XIV operation info into out- of-band blocking test case	F	9.2.0	9.3.0	R5-106412
RP-50	RP-101146	1282	-	Addition of cell mapping table to Type 3i tests	F	9.2.0	9.3.0	R5-106413
RP-50	RP-101146	1283	-	Applicability change to TC 9.3.7A and 9.3.7B in TS 34.121-1	F	9.2.0	9.3.0	R5-106414
RP-50	RP-101137	1284	-	Correction to MIMO propagation conditions	F	9.2.0	9.3.0	R5-106416
RP-50	RP-101134	1285	-	Removal of lower limit for humidity in normal conditions	F	9.2.0	9.3.0	R5-106417
RP-50	RP-101147	1286	-	Maintenance of Band 20 for UTRAN RRM test cases	F	9.2.0	9.3.0	R5-106436
RP-50	RP-101138	1287	-	Annex K update	F	9.2.0	9.3.0	R5-106485
RP-50	RP-101138	1288	-	CR to 34.121-1: Correction to UTRA FDD - E-UTRA FDD cell re-selection (UTRA lower priority) test case	F	9.2.0	9.3.0	R5-106813
RP-50	RP-101160	1289	-	Update of legacy HSDPA performance test cases for UE HS-DSCH Physical Layer category 25 to 28	F	9.2.0	9.3.0	R5-106837
RP-50	RP-101146	1290	-	Introduction of Test tolerances for 9.3.1C (Periodically Varying Radio Conditions)	F	9.2.0	9.3.0	R5-106839
RP-50	RP-101147	1291	-	Correction to Downlink Physical Channels in DC- HSDPA Tests	F	9.2.0	9.3.0	R5-106861
RP-51	RP-110155	1292	-	Corrections to Annex F.6.3 and 9.2.4A	F	9.3.0	9.4.0	R5-110242
RP-51	RP-110155	1293	-	Corrections to Annex C.11 for E-DCH test cases	F	9.3.0	9.4.0	R5-110301
RP-51	RP-110156	1294	-	Correction in Clause 5.2E.4.1 to co-relate as per Annex C.8.1.1, Table C.8.1.1	F	9.3.0	9.4.0	R5-110326
RP-51	RP-110156	1295	-	Correction in Clause 5.13.2C.4.1 to co-relate as per Annex C.8.1.1, Table C.8.1.1	F	9.3.0	9.4.0	R5-110327
RP-51	RP-110152	1296	-	Correction to Notes in Tx Spurious Emissions	F	9.3.0	9.4.0	R5-110425
RP-51	RP-110155	1297	-	Correction to table references in minimum requirements	F	9.3.0	9.4.0	R5-110426
RP-51	RP-110155	1298	-	Clarification of CQI reporting requirement applicability	F	9.3.0	9.4.0	R5-110464
RP-51	RP-110156	1299	-	Addition of Level Set 7 into Table E.5.9	F	9.3.0	9.4.0	R5-110467
RP-51	RP-110177	1300	-	New TC 9.2.4 - MIMO Performance - Fixed Reference Channel (FRC) H-SET 9A and TC 9.2.4D - MIMO Performance - Fixed Reference Channel (FRC) H-SET 11A	F	9.3.0	9.4.0	R5-110934
RP-51	RP-110177	1301	-	Update of Annexure A to Annexure F	F	9.3.0	9.4.0	R5-110935
RP-51	RP-110157	1302	-	Update to test case 8.3.4d	F	9.3.0	9.4.0	R5-110936
RP-51	RP-110166	1303	-	Corrections to Band XII frequency range	F	9.3.0	9.4.0	R5-110976

T Meeting	Doc-1 st -Level	CR	Rev	Subject	Cat	Version - Current	Version -New	Doc-2 nd -Level
RP-52	RP-110652	1304	-	Correction of OOBB interferer frequency ranges for Band XII in 34.121-1	F	9.4.0	9.5.0	R5-112133
RP-52	RP-110651	1305	_	Correction to DC-HSDPA RX TCs	F	9.4.0	9.5.0	R5-112425
RP-52	RP-110651	1306	-	Correction to DC-HSDPA Performance TCs	F	9.4.0	9.5.0	R5-112427
RP-52	RP-110663	1307	-	DC+MIMO Performance Test Case Update	F	9.4.0	9.5.0	R5-112472
RP-52	RP-110667	1308	-	DB-DC-HSDPA in test case 6.2	F	9.4.0	9.5.0	R5-112490
RP-52	RP-110643	1309	-	Uncertainties and Test Tolerances for RRM test case 8.2.5.2 in 34.121-1	F	9.4.0	9.5.0	R5-112564
RP-52	RP-110643	1310	-	Uncertainties and Test Tolerances for RRM test case 8.3.4c in 34.121-1	F	9.4.0	9.5.0	R5-112805
RP-52	RP-110651	1311	-	Corrections to test case 10.3.2	F	9.4.0	9.5.0	R5-112806
RP-52	RP-110663	1312	-	Connection Diagram for DC+MIMO Performance tests	F	9.4.0	9.5.0	R5-112822
RP-52	RP-110652	1313	-	Correction to the content of 'Definition and applicability' of the test case 5.4.4	F	9.4.0	9.5.0	R5-112823
RP-52	RP-110641	1314	-	Correction to the initial condition of the test case 7.8.5 of TS 34.121-1	F	9.4.0	9.5.0	R5-112824
RP-52	RP-110642	1315	-	Update to TC 9.2.4A	F	9.4.0	9.5.0	R5-112825
RP-52	RP-110651	1316	-	Update to TC 9.2.4B	F	9.4.0	9.5.0	R5-112826
RP-52	RP-110642	1317	-	Update to TC 9.4.3	F	9.4.0	9.5.0	R5-112827
RP-52	RP-110652	1318	-	Update to TC 9.2.4C and 9.2.4D	F	9.4.0	9.5.0	R5-112828
RP-52	RP-110638	1319	-	Spurious Emission requirement extension due to EN spec change	F	9.4.0	9.5.0	R5-112836
RP-52	RP-110667	1320	-	Addition of DB-DC-HSDPA into common sections of 34.121-1	F	9.4.0	9.5.0	R5-112841
RP-52	RP-110667	1321	-	New test case 6.2B for DB-DC-HSDPA, RF sensitivity	F	9.4.0	9.5.0	R5-112842
RP-52	RP-110667	1322	-	New test case 6.3E for DB-DC-HSDPA, Maximum Input Level	F	9.4.0	9.5.0	R5-112843
RP-52	RP-110667	1323	-	New test case 6.4C for DB-DC-HSDPA, Adjacent Channel Selectivity	F	9.4.0	9.5.0	R5-112844
RP-52	RP-110667	1324	-	New test case 6.5B for DB-DC-HSDPA blocking	F	9.4.0	9.5.0	R5-112845
RP-52	RP-110667	1325	-	New test case 6.6B for DB-DC-HSDPA, spurious response	F	9.4.0	9.5.0	R5-112846
RP-52	RP-110667	1326	-	New test case 6.7B for DB-DC-HSDPA, Intermodulation	F	9.4.0	9.5.0	R5-112847
RP-52	RP-110643	1327	-	Correction to UTRAN to E-UTRAN Cell Reselection	F	9.4.0	9.5.0	R5-112856
RP-52	RP-110667	1328	_	Addition of DB-DC-HSDPA into Annex	F	9.4.0	9.5.0	R5-112867
RP-53	RP-111150	1329	-	Adding connection diagram for DC-HSUPA basic Tx tests	F	9.5.0	9.6.0	R5-113079
RP-53	RP-111133	1330	-	UE Relative Code Domain Power Accuracy for E- DCH	F	9.5.0	9.6.0	R5-113235
RP-53	RP-111150	1331	-	Introduction of Annex C.11A to include DC-HSUPA parameters	F	9.5.0	9.6.0	R5-113265

T Meeting	Doc-1 st -Level	CR	Rev	Subject	Cat	Version - Current	Version -New	Doc-2 nd -Level
RP-53	RP-111150	1332	-	Addition of DC-HSUPA max power and RCDP tests to Annex F	F	9.5.0	9.6.0	R5-113266
RP-53	RP-111134	1333	-	Correction to 8.6.6 E-UTRAN Measurement	F	9.5.0	9.6.0	R5-113470
RP-53	RP-111142	1334	-	Correction to Frequency ranges in Blocking TCs	F	9.5.0	9.6.0	R5-113474
RP-53	RP-111134	1335	-	Correction to DC-HSDPA Perf TCs	F	9.5.0	9.6.0	R5-113475
RP-53	RP-111146	1359	-	Introduction of system information acquisition for CSG cell test cases into annex	F	9.5.0	9.6.0	R5-113510
RP-53	RP-111134	1336	-	Correction to Inter-system Handover TCs	F	9.5.0	9.6.0	R5-114035
RP-53	RP-111142	1337	-	Update to DC HSDPA connection diagram	F	9.5.0	9.6.0	R5-114036
RP-53	RP-111134	1338	-	Uncertainties and Test Tolerances for UTRA to E- UTRA reselection test case 8.2.5.1	F	9.5.0	9.6.0	R5-114052
RP-53	RP-111134	1339	-	Uncertainties and Test Tolerances for Inter-system Handover from UTRAN FDD to E-UTRAN FDD/TDD test cases 8.3.4a+8.3.4b	F	9.5.0	9.6.0	R5-114054
RP-53	RP-111134	1340	-	Test Tolerances for TC 8.6.6.1 and 8.6.6.2	F	9.5.0	9.6.0	R5-114064
RP-53	RP-111134	1341	-	Update of Annex I	F	9.5.0	9.6.0	R5-114065
RP-53	RP-111146	1357	-	Addition of new Rel-9 RRM test case 8.3.10.1: Intrafrequency System information acquisition for CSG cell	F	9.5.0	9.6.0	R5-114075
RP-53	RP-111146	1358	-	Addition of new Rel-9 RRM test case 8.3.10.2: Inter frequency System information acquisition for CSG cell	F	9.5.0	9.6.0	R5-114076
RP-53	RP-111150	1342	-	New test case 5.4.2A, for DC-HSUPA, inner loop power control	F	9.5.0	9.6.0	R5-114078
RP-53	RP-111150	1343	-	New test case 5.4.1A, for DC-HSUPA, open loop power control	F	9.5.0	9.6.0	R5-114079
RP-53	RP-111150	1344	-	CR: New FDD Receiver TCs for Dual-Cell HSUPA	F	9.5.0	9.6.0	R5-114080
RP-53	RP-111150	1345	-	Introduction of new test case for DC-HSUPA maximum output power	F	9.5.0	9.6.0	R5-114081
RP-53	RP-111150	1346	-	Introduction of new test case for DC-HSUPA relative code domain power	F	9.5.0	9.6.0	R5-114082
RP-53	RP-111154	1347	-	Addition measurement uncertainties and test tolerances for HS-SCCH Type 3 performance single stream restriction test in Annex	F	9.5.0	9.6.0	R5-114085
RP-53	RP-111134	1352	-	Correction to 8.2.5.2	F	9.5.0	9.6.0	R5-114092
RP-53	RP-111143	1353	-	Harmonic Signal Exceptions in UTRA FDD Spurious Emissions	F	9.5.0	9.6.0	R5-114093
RP-53	RP-111143	1354	-	Clarify uncertainty values for multi-carrier HSDPA	F	9.5.0	9.6.0	R5-114094
RP-53	RP-111149	1356	-	Update to TC 9.2.1FA , 9.2.1HA and TC 9.2.1JA	F	9.5.0	9.6.0	R5-114109
RP-53	RP-111154	1348	-	Introduction of New Test case 9.2.4E	F	9.6.0	10.0.0	R5-114086
RP-53	RP-111154	1349	-	Introduction of New Test case 9.2.4F	F	9.6.0	10.0.0	R5-114087
RP-53	RP-111154	1350	-	Introduction of New Test case 9.2.4G and 9.2.4H	F	9.6.0	10.0.0	R5-114088
RP-53	RP-111154	1351	-	Update to 34.121-1 Annex	F	9.6.0	10.0.0	R5-114089
RP-53	RP-111154	1355	-	Introduction of new test case verifying HS-SCCH performance under symmetric CPICH conditions	F	9.6.0	10.0.0	R5-114098

T Meeting	Doc-1 st -Level	CR	Rev	Subject	Cat	Version - Current	Version -New	Doc-2 nd -Level
RP-54	RP-111595	1361	-	Annex changes for new ACLR test case for DC-HSUPA	F	10.0.0	10.1.0	R5-115152
RP-54	RP-111594	1362	-	Introduction of new DB-DC-HSDPA test cases 9.2.1GB, 9.2.1IB and 9.2.1KB	F	10.0.0	10.1.0	R5-115154
RP-54	RP-111594	1363	-	Annex changes for new DB-DC-HSDPA test cases 9.2.1GB, 9.2.1IB and 9.2.1KB	F	10.0.0	10.1.0	R5-115155
RP-54	RP-111595	1364	-	Transmit Intermodulation for DC-HSUPA - uncertainties and tolerances	F	10.0.0	10.1.0	R5-115160
RP-54	RP-111575	1365	-	Update of RRM 8.2.5 UTRAN to E-UTRA Cell Re- Selection	F	10.0.0	10.1.0	R5-115377
RP-54	RP-111594	1366	-	Annex changes for DB-DC-HSDPA test cases 9.2.1FB, 9.2.1HB and 9.2.1JB	F	10.0.0	10.1.0	R5-115411
RP-54	RP-111595	1368	-	Transmit Intermodulation for DC-HSUPA (new tc)	F	10.0.0	10.1.0	R5-115805
RP-54	RP-111573	1369	-	Correction to test applicability in 8.6.2.2	F	10.0.0	10.1.0	R5-115806
RP-54	RP-111595	1370	-	Connection diagram for transmit intermodulation for DC-HSUPA	F	10.0.0	10.1.0	R5-115807
RP-54	RP-111575	1371	-	Correction to 8.6.6.1 and 8.6.6.2	F	10.0.0	10.1.0	R5-115808
RP-54	RP-111597	1372	-	Adding band XXII (3500MHz) to 34.121-1 chapter 4	F	10.0.0	10.1.0	R5-115810
RP-54	RP-111575	1373	-	Uncertainties and Test Tolerances for RRM test case 8.6.7.1 and 8.6.7.2 in 34.121-1	F	10.0.0	10.1.0	R5-115829
RP-54	RP-111575	1374	-	Correction to Table F.4.4 for TC 8.6.6.1	F	10.0.0	10.1.0	R5-115849
RP-54	RP-111598	1375	-	CR New TCs for MIMO Operation with Non-MIMO Coexistence in HSDPA Type3 perf	F	10.0.0	10.1.0	R5-115851
RP-54	RP-111598	1376	-	New Test Case 9.3.7F - MIMO Single Stream Fading Conditions - Asymmetric CPICHs	F	10.0.0	10.1.0	R5-115852
RP-54	RP-111598	1377	-	New Test Case 9.3.7G - MIMO Dual Stream Fading Conditions - Asymmetric CPICHs	F	10.0.0	10.1.0	R5-115853
RP-54	RP-111598	1378	-	New Test Case 9.3.7H - MIMO Dual Stream Fading Conditions - UE categories 19-20 - Asymmetric CPICHs	F	10.0.0	10.1.0	R5-115854
RP-54	RP-111598	1379	-	New Test Case 9.3.7I and 9.3.7J	F	10.0.0	10.1.0	R5-115855
RP-54	RP-111598	1380	-	Update to 34.121-1 Annex	F	10.0.0	10.1.0	R5-115856
RP-54	RP-111598	1381	-	Introduction of new test case verifying HS-SCCH Type 3 performance single stream restriction-STTD disabled-asymmetric CPICHs	F	10.0.0	10.1.0	R5-115857
RP-54	RP-111598	1382	-	Addition measurement uncertainties and test tolerances for HS-SCCH Type 3 performance SS restriction-STTD disabled-asymmetric CPICHs test in Annex	F	10.0.0	10.1.0	R5-115858
RP-54	RP-111598	1383	-	Introduction of new test case verifying HS-SCCH Type 3 performance single stream restriction-STTD enabled-asymmetric CPICHs	F	10.0.0	10.1.0	R5-115859
RP-54	RP-111598	1384	-	Addition measurement uncertainties and test tolerances for HS-SCCH Type 3 performance SS restriction-STTD enabled-asymmetric CPICHs test in Annex	F	10.0.0	10.1.0	R5-115860
RP-54	RP-111594	1385	-	CR Test cases update for DB-DC-HSDPA CQI reporting	F	10.0.0	10.1.0	R5-115863

T Meeting	Doc-1 st -Level	CR	Rev	Subject	Cat	Version - Current	Version -New	Doc-2 nd -Level
RP-54	RP-111595	1386	-	Introduction of new ACLR test case for DC-HSUPA	F	10.0.0	10.1.0	R5-115866
RP-54	RP-111595	1387	-	CR New FDD transmitter TCs for Dual-Cell HSUPA	F	10.0.0	10.1.0	R5-115867
RP-54	RP-111595	1388	-	CR update FDD Receiver TCs for Dual-Cell HSUPA	F	10.0.0	10.1.0	R5-115868
RP-54	RP-111595	1389	-	New test case 5.9C, for DC-HSUPA spectrum emission	F	10.0.0	10.1.0	R5-115869
RP-54	RP-111595	1390	-	New test case 5.3A, for DC-HSUPA frequency error	F	10.0.0	10.1.0	R5-115870
RP-54	RP-111595	1391	-	Updates to annex of 34.121-1 to include DC-HSUPA	F	10.0.0	10.1.0	R5-115871
RP-54	RP-111575	1392	-	Update for Inter HO in 8.3.4x	F	10.0.0	10.1.0	R5-115876
RP-55	RP-120175	1393	-	HS-SCCH and DPCH codes and power level missing in Annex E.5E.1 tables	F	10.1.0	10.2.0	R5-120082
RP-55	RP-120194	1394	-	DC-HSUPA : Correction the Note content in tables for test cases 6.5C and 6.7C.	F	10.1.0	10.2.0	R5-120102
RP-55	RP-120175	1395	-	TC 9.6.2 - Contradiction in NOTE on how often DL transmission blocks are sent	F	10.1.0	10.2.0	R5-120258
RP-55	RP-120194	1396	-	DC-HSUPA RF - Correction to 5.4.3A and 5.8A applicabilities	F	10.1.0	10.2.0	R5-120290
RP-55	RP-120194	1397	-	CR update FDD Receiver TCs 6.5C & 6.7C for Dual-Cell HSUPA	F	10.1.0	10.2.0	R5-120296
RP-55	RP-120175	1398	-	Update of cell configuration mapping in Annex k	F	10.1.0	10.2.0	R5-120331
RP-55	RP-120194	1399	-	Introduction of new spurious emissions test case for DC-HSUPA	F	10.1.0	10.2.0	R5-120345
RP-55	RP-120194	1400	-	Changes to annexes for the new spurious emissions test case for DC-HSUPA	F	10.1.0	10.2.0	R5-120347
RP-55	RP-120197	1401	-	Test System uncertainties for frequencies between 3000MHz to 4200MHz in 34.121-1	F	10.1.0	10.2.0	R5-120396
RP-55	RP-120175	1402	-	Clarification of threshold other system values in measurement control messages	F	10.1.0	10.2.0	R5-120813
RP-55	RP-120194	1403	-	test case, In-band emission for DC-HSUPA	F	10.1.0	10.2.0	R5-120824
RP-55	RP-120198	1404	-	Annexure changes for Test case 9.4.4A, 9.4.4C, and 9.4.4E	F	10.1.0	10.2.0	R5-120834
RP-55	RP-120197	1405	-	Adding band XXII (3500MHz) to 34.121-1	F	10.1.0	10.2.0	R5-120857
RP-55	RP-120198	1406	-	New Test case 9.4.4A, 9.4.4C, and 9.4.4E	F	10.1.0	10.2.0	R5-120858
RP-55	RP-120193	1407	-	New test case 9.2.1LB (HSDPA, type 3i, Dual Band Dual Cell)	F	10.1.0	10.2.0	R5-120859
RP-55	RP-120194	1408	-	Correcting downlink physical channels for DC-HSUPA in annex E	F	10.1.0	10.2.0	R5-120860
RP-55	RP-120194	1409	-	New test case 5.13.2BA, Relative Code Domain Error with HS-DPCCH and E-DCH for DC-HSUPA	F	10.1.0	10.2.0	R5-120861
RP-55	RP-120201	1410	-	New Test case 9.2.1FC and 9.2.1FD	F	10.1.0	10.2.0	R5-120863
RP-55	RP-120198	1411	-	Corrections to the HS-SCCH Type 3 Performance for MIMO only with single-stream restriction-STTD disabled-asymmetric CPICH test	F	10.1.0	10.2.0	R5-120886
RP-55	RP-120198	1412	-	Corrections to HS-SCCH Type 3 Performance for MIMO only with single-stream restriction	F	10.1.0	10.2.0	R5-120888

T Meeting	Doc-1 st -Level	CR	Rev	Subject	Cat	Version - Current	Version -New	Doc-2 nd -Level
RP-55	RP-120198	1413	-	Corrections to the HS-SCCH Type 3 Performance for MIMO only with single-stream restriction-STTD enabled-asymmetric CPICH test	F	10.1.0	10.2.0	R5-120890
RP-55	RP-120184	1414	-	Correction to TC 9.2.1LA (HSDPA, type 3i, Dual Cell) and connection diagram	F	10.1.0	10.2.0	R5-120896
RP-56	RP-120656	1415	-	Addition of a new section 6.1A:Reference input power adjustment for a dual band device	F	10.2.0	10.3.0	R5-121149
RP-56	RP-120656	1416	-	Correction to the Notes of Tables of the test cases 6.5C and 6.7C.	F	10.2.0	10.3.0	R5-121150
RP-56	RP-120649	1417	-	Correction to the content of test case 6.5B	F	10.2.0	10.3.0	R5-121151
RP-56	RP-120648	1418	-	Addition the definition of enhance performance type 3i to TS 34.121-1	F	10.2.0	10.3.0	R5-121152
RP-56	RP-120648	1419	-	Error in initial CQI value TC 9.3.7C,E,H,J MIMO Dual Stream/64QAM configured	F	10.2.0	10.3.0	R5-121230
RP-56	RP-120639	1420	-	Error in initial CQI valueTC 9.3.7B,D,G,I MIMO Dual Stream/64QAM not configured	F	10.2.0	10.3.0	R5-121231
RP-56	RP-120648	1421	-	3G RRM: Corrections to test procedures of TC 8.6.6.1	F	10.2.0	10.3.0	R5-121252
RP-56	RP-120635	1422	-	Correction of Maximum Test System Uncertainty in Annex F.1.2 Table F.1.2	F	10.2.0	10.3.0	R5-121303
RP-56	RP-120640	1423	-	Correction to Inter-system Handover	F	10.2.0	10.3.0	R5-121533
RP-56	RP-120640	1424	-	Correction to 8.6.6.1	F	10.2.0	10.3.0	R5-121534
RP-56	RP-120639	1425	-	Correction to 5.4.4A	F	10.2.0	10.3.0	R5-121539
RP-56	RP-120648	1426	-	Correction to test time for HSDPA Rx TCs	F	10.2.0	10.3.0	R5-121540
RP-56	RP-120656	1427	-	Corrections to TC 5.4.1A (Open Loop Power Control for DC-HSUPA)	F	10.2.0	10.3.0	R5-121587
RP-56	RP-120656	1428	-	Adding DC-HSDPA configuration into DC-HSUPA section 5 test cases	F	10.2.0	10.3.0	R5-121590
RP-56	RP-120656	1429	-	Adding DC-HSDPA configuration into Annex C.11A	F	10.2.0	10.3.0	R5-121593
RP-56	RP-120638	1430	-	Removing a Note 3 from Table C.11.3.1	F	10.2.0	10.3.0	R5-121594
RP-56	RP-120640	1431	-	Correction to the test frequency references in FDD with E-UTRA tests	F	10.2.0	10.3.0	R5-121621
RP-56	RP-120659	1432	-	Adding band XXII (3500MHz) to 34.121-1 (RRM test cases)	F	10.2.0	10.3.0	R5-121642
RP-56	RP-120649	1433	-	Update to 34.121-1 for TCs 9.3.1BA & 9.3.2AA for DB-DC-HSDPA CQI reporting	F	10.2.0	10.3.0	R5-121916
RP-56	RP-120660	1434	-	Adding band XXV (1900MHz) to 34.121-1 Rx Blocking test cases	F	10.2.0	10.3.0	R5-121968
RP-56	RP-120664	1435	-	New test cases 9.2.1IC and 9.2.1ID	F	10.2.0	10.3.0	R5-121970
RP-56	RP-120664	1436	-	New test cases 9.2.1JC and 9.2.1JD	F	10.2.0	10.3.0	R5-121971
RP-56	RP-120664	1437	-	4C HSDPA related Updates to 34.121-1 Annex	F	10.2.0	10.3.0	R5-121972
RP-56	RP-120664	1438	-	New Test case 9.2.1HC and 9.2.1HD	F	10.2.0	10.3.0	R5-121973
RP-56	RP-120648	1439	-	3G RRM: Corrections to test procedures of TC 8.2.5.1 and 8.2.5.2	F	10.2.0	10.3.0	R5-121974

T Meeting	Doc-1 st -Level	CR	Rev	Subject	Cat	Version - Current	Version -New	Doc-2 nd -Level
RP-56	RP-120638	1440	-	Total DL power defined in TC 7.8.5 and Annex E.5C.1 tables greater than unity	F	10.2.0	10.3.0	R5-121975
RP-56	RP-120660	1441	-	Adding band XXV (1900MHz) to 34.121-1	F	10.2.0	10.3.0	R5-122005
RP-57	RP-121102	1442	-	Annex E.5 - Correction to numbers of HS-SCCH for DC-HSDPA	F	10.3.0	10.4.0	R5-123238
RP-57	RP-121115	1443	-	New test cases 9.2.1KC and 9.2.1KD	F	10.3.0	10.4.0	R5-123241
RP-57	RP-121094	1444	-	Changes associated with PHS band operation change for WCDMA	F	10.3.0	10.4.0	R5-123271
RP-57	RP-121094	1445	-	Update of Annex I	F	10.3.0	10.4.0	R5-123337
RP-57	RP-121094	1447	_	Alignment of test procedure steps in cell reselection tests	F	10.3.0	10.4.0	R5-123339
RP-57	RP-121091	1448	-	Correction on Rx test cases	F	10.3.0	10.4.0	R5-123344
RP-57	RP-121094	1449	-	Correction to test applicability in FDD/E-UTRAN test cases	F	10.3.0	10.4.0	R5-123380
RP-57	RP-121120	1450	-	Adding band XXVI (850MHz) to 34.121-1 (RRM test cases)	F	10.3.0	10.4.0	R5-123577
RP-57	RP-121094	1446	-	Correction to 8.6.7	F	10.3.0	10.4.0	R5-123786
RP-57	RP-121094	1453	-	Uncertainties and Test Tolerances for E-UTRAN RSRQ Test cases 8.7.12 and 8.7.13	F	10.3.0	10.4.0	R5-123796
RP-57	RP-121109	1456	-	Updating incomplete DC-HSUPA test cases in 34.121-1	F	10.3.0	10.4.0	R5-123797
RP-57	RP-121120	1451	-	Introduction of E850 Upper Band (Band 26) into sections 4 and 5 of 34.121-1	F	10.3.0	10.4.0	R5-123918
RP-57	RP-121094	1452	_	Uncertainties and Test Tolerances for E-UTRAN RSRP Test cases 8.7.10 and 8.7.11	F	10.3.0	10.4.0	R5-123929
RP-57	RP-121115	1454	-	New Test case 9.2.1LC and 9.2.1LD	F	10.3.0	10.4.0	R5-123967
RP-57	RP-121109	1455	-	Adding new RMCs into annexes for DC-HSUPA tests	F	10.3.0	10.4.0	R5-123971
RP-57	RP-121109	1457	-	New test case, Relative Code Domain Error with HS-DPCCH and E-DCH with 16QAM for DC-HSUPA	F	10.3.0	10.4.0	R5-123973
RP-57	RP-121089	1459	-	Adding band XXII in spurious emission test cases in 34.121-1	F	10.3.0	10.4.0	R5-123975
RP-58	RP-121673	1460	-	Introduction of new UE Relative Code Domain Power Accuracy test case for DC-HSUPA with 16QAM	F	10.4.0	10.5.0	R5-125249
RP-58	RP-121654	1461	-	Correction to UE output power level during relative CDP measurement in TC 5.2E	F	10.4.0	10.5.0	R5-125250
RP-58	RP-121680	1462	-	Adding connection diagram for 4C-HSDPA tests	F	10.4.0	10.5.0	R5-125255
RP-58	RP-121680	1463	-	Test system uncertainties, test tolerances and statistical testing for 4C-HSDPA tests	F	10.4.0	10.5.0	R5-125256
RP-58	RP-121680	1464	-	Corrections to many 4C-HSDPA performance tests in section 9	F	10.4.0	10.5.0	R5-125258
RP-58	RP-121655	1465	-	Addition of Band 26 in RSRP/RSRQ accuracy requirements in 34.121-1	F	10.4.0	10.5.0	R5-125387
RP-58	RP-121655	1466	-	Correction to exception messages in RRM 8.7.12 in 34.121-1	F	10.4.0	10.5.0	R5-125389

T Meeting	Doc-1 st -Level	CR	Rev	Subject	Cat	Version -	Version -New	Doc-2 nd -Level
RP-58	RP-121655	1467	-	Correction to Inter-system Handover in 34.121-1	F	10.4.0	10.5.0	R5-125392
RP-58	RP-121663	1468	-	Addition of message exceptions in 9.2.1J/9.2.1K/9.2.1L	F	10.4.0	10.5.0	R5-125401
RP-58	RP-121680	1469	-	4C-HSDPA related updates to Annexure	F	10.4.0	10.5.0	R5-125639
RP-58	RP-121655	1470	-	Correction to exception messages in RRM 8.7.10 in 34.121-1	F	10.4.0	10.5.0	R5-125822
RP-58	RP-121655	1471	-	Correction to RRM 8.6.7.2/8.6.7.2 in 34.121-1	F	10.4.0	10.5.0	R5-125823
RP-58	RP-121655	1472	-	Update of Annex K	F	10.4.0	10.5.0	R5-125824
RP-58	RP-121688	1473	-	Introduction of Band 27 to TS 34.121-1	F	10.4.0	10.5.0	R5-125834
RP-58	RP-121680	1474	-	Addition of new test cases 9.2.1GC and 9.2.1GD	F	10.4.0	10.5.0	R5-125840
RP-58	RP-121680	1475	-	New 4C-HSDPA Blocking test cases	F	10.4.0	10.5.0	R5-125841
RP-58	RP-121680	1476	-	New 4C-HSDPA Reference Sensitivity test cases	F	10.4.0	10.5.0	R5-125842
RP-58	RP-121680	1477	-	New 4C-HSDPA Maximum input level test cases	F	10.4.0	10.5.0	R5-125843
RP-58	RP-121680	1478	-	New 4C-HSDPA Spurious response test cases	F	10.4.0	10.5.0	R5-125844
RP-58	RP-121680	1479	-	New 4C-HSDPA intermodulation characteristics test cases	F	10.4.0	10.5.0	R5-125845
RP-58	RP-121680	1480	-	4C HSDPA related updates to General sections of 34.121-1	F	10.4.0	10.5.0	R5-125846
RP-58	RP-121655	1481	-	Correction to test applicability of inter-RAT measurement related TCs(TS34.121-1)	F	10.4.0	10.5.0	R5-125864
RP-58	RP-121655	1489	-	Completing TC8.3.4b, Handover from UTRAN FDD to E-UTRAN TDD	F	10.4.0	10.5.0	R5-125904
RP-58	RP-121655	1482	-	Completing TC8.3.4d, Handover from UTRAN FDD to E-UTRAN TDD unknown cell	F	10.4.0	10.5.0	R5-125905
RP-58	RP-121705	1485	-	Introduction of new RRM Test Case 8.4.3.1A	F	10.4.0	10.5.0	R5-125914
RP-58	RP-121680	1486	-	New 4C HSDPA - CQI reporting TC	F	10.4.0	10.5.0	R5-125918
RP-58	RP-121654	1487	-	Removing redundant testing for Type3/Type3i UEs (34.121-1)	F	10.4.0	10.5.0	R5-125926
RP-58	RP-121655	1488	-	Alignment of UE antenna connection in HSDPA and E-DCH performance tests	F	10.4.0	10.5.0	R5-125927
RP-58	RP-121673	1483	-	Updating incomplete DC-HSUPA test cases in 34.121-1	F	10.4.0	10.5.0	R5-126061
RP-58	RP-121673	1484	-	Splitting DC-HSUPA test case 5.2BA, 5.9C and 5.10C.	F	10.4.0	10.5.0	R5-126062
RP-59	RP-130155	1490	-	Updation of 4C-HSDPA Chapter 9 test cases	F	10.5.0	10.6.0	R5-130922
RP-59	RP-130155	1491	-	Addition of connection diagram for Receiver tests	F	10.5.0	10.6.0	R5-130923
RP-59	RP-130155	1492	-	Updating Chapter 6 receiver test cases for 4C_HSDPA	F	10.5.0	10.6.0	R5-130974
RP-59	RP-130155	1493	-	Annexure update to test tolerance and statistical testing for 4C-HSDPA	F	10.5.0	10.6.0	R5-130975
RP-59	RP-130611	1495	-	Adding definition of UE maximum output power for DC-HSUPA	F	10.6.0	10.7.0	R5-131211
RP-59	RP-130611	1496	-	Clarification of center frequency offset for additional SEM for DC-HSUPA	F	10.6.0	10.7.0	R5-131213

T Meeting	Doc-1 st -Level	CR	Rev	Subject	Cat	Version - Current	Version -New	Doc-2 nd -Level
RP-59	RP-130625	1497	-	Editors note for test cases where Test Requirement not valid above 3GHz	F	10.6.0	10.7.0	R5-131272
RP-59	RP-130607	1498	-	Applicability of test frequency ranges as per UE releases	F	10.6.0	10.7.0	R5-131547
RP-59	RP-130621	1500	-	Correction to the content of the test case 9.3.2AC	F	10.6.0	10.7.0	R5-131678
RP-59	RP-130625	1503	-	Update to test procedure for WCDMA to LTE Scenarios in absence of a configured PDP Context.	F	10.6.0	10.7.0	R5-131968
RP-59	RP-130621	1504	-	Annexure update to test tolerance and statistical testing for newly added 4C-HSDPA test cases	F	10.6.0	10.7.0	R5-131988
RP-59	RP-130608	1505	-	Changes to uplink 16QAM test case parameters and test procedures	F	10.6.0	10.7.0	R5-131989
RP-59	RP-130611	1506	-	Correction to relative Tx power difference between carriers in DC-HSUPA	F	10.6.0	10.7.0	R5-131991
RP-59	RP-130621	1507	-	Adding Chapter 6 test cases for 3C-HSDPA as part of 4C-HSDPA WP	F	10.6.0	10.7.0	R5-132108
RP-61	RP-131114	1509	-	Removal of technical content in 34.121-1 v10.7.0 and substitution with pointer to the next Release	F	10.7.0	10.8.0	R5-133236

History

Document history						
V10.1.0	March 2012	Publication				
V10.2.1	April 2012	Publication				
V10.3.0	August 2012	Publication				
V10.4.0	October 2012	Publication				
V10.5.0	February 2013	Publication				
V10.6.0	May 2013	Publication				
V10.7.0	July 2013	Publication				
V10.8.0	October 2013	Publication				