

П	А	В	С	D	E	F	G	н	J	К	\Box
0											0
1											1
2											2
3					vcc						3
4					DOUT 0 1 2	1 4 3 DIN					4
5					C1 100n X7R	52812B					5
6					÷	÷					6
7											7
8											8
9										DATE: 10/08/2016 DOX\Projects_BR_F\ngineering\v V:@REV TIME: 09:20:53	9 wooder
Image: Control of the control of th	Α	В	С	D	Е	F	G	н	J	К	工