Second Extruder Modifications

May 12, 2022 • Ranulf Urquhart-Gilmore

Rewiring second extruder:

- Second extruder has been rewired as it is pushing filament out instead of feeding it through.
 - o A bridge was made using a H14 4 way connector so it could be easily rewired.



o H14 Connector links:

https://uk.farnell.com/amp-te-connectivity/281838-4/housing-crimp-receptacle-2-54mm/dp/429594 https://uk.farnell.com/amp-te-connectivity/281695-4/header-tht-vert-2-54mm-1row-4way/dp/1205984?MER=sy-me-pd-mi-acce

- To invert the extruder direction we swapped red with green and blue with black.
 - Wiring Diagram:

