
Nozzle: reference angle diagnostics along the production continuation
Y_p
$\partial Y_p/\partial\alpha$ per degree
Signed exit angle from axial, α (deg)
Signed exit angle from axial, α (deg)
s/c = 0.45
s/c = 0.65
s/c = 0.85
s/c = 1.05
New analytical fit
Aungier