

Blue: production angle continuation below 10 deg; beige: outside chart. References follow the fixed positive-design angle path. Tint: angle extrapolation. Spacings 0, 2 and 3 have no chart data.