

Blue: production angle continuation below 10 deg; beige: outside chart. References follow the fixed positive-design angle path.