What remains as blade speed approaches zero?

$\Omega_s = 1.05$ · all samples retained down to $U/c_0 = 10^{-5}$ · shared coordinate (0.30 limit)