Complete trailing-edge loss versus thickness/opening



Outlet Mach = 0.7; gamma = 1.4. Nozzle/impulse references, z interpolation and equation (18) are all included.
Beige: thickness/opening beyond the chart range. Zero thickness gives exactly zero loss with a finite derivative.