

Blue: production angle continuation below 10 deg. Beige: outside chart angle coverage; some spacings also exceed coverage.
References follow the fixed positive-design production angle path; the signed physical angle is not reflected.