Production thickness factor: smooth values, slopes and curvature



Blue: numerical onset, 0 < z < 0.05. Beige: z outside [0, 1]. Dashed: thickness/chord outside 0.15 to 0.25.
Factor value, slope and curvature match at both joins. The full AM reference blend is only C1 at z = 0.