



AM reference angle slices: chart spacings, signed angle extension









Blue: production angle continuation below 10 deg; beige/dashes: outside chart coverage.
Unsigned reference families follow the fixed positive-design production angle path; no nozzle reset or angle reflection.