

AR = 2; zero incidence; M1 = M2 = 0. Left: complete loss. Right: loading Z.
Solid: production result. Dashed: original angle expressions, only through 89 deg (may leave panel).
Beige: negative outlet trials (top) and tangent continuation beyond 80 deg. Dotted: zero/90 deg and Z = 32.