Reynolds correction: C2 transitions and a nonzero high-Re limit
Blue: original blending bands. Beige: continuation above ten million; lower limit = 0.457305.