

stm protimer
/ mobj->p_time = 0;
STAT
entry / disp_time(mobj->p_time),
disp_msg("productive_time")
exit / disp_clr();
INC_TIME / mobj->p_time = 0
DEC_TIME / mobj->p_time = 0
IDLE
entry / mobj->c_time = 0;mobj->etime = 0;
disp_time(0);disp_msg("Set time");
exit / disp_clr();
TIME_TICK(ss) [ss == 5] / do_beep();
TIME_SET
entry / disp_time(mobj->c_time);
exit / disp_clr();
INC_TIME / mobj->c_time+=60
DEC_TIME [mobj->c_time >= 60] / mobj->c_time-=60
INC_TIME / mobj->c_time+=60
ABRT
TIME_TICK [e->ss == 10]
START_PAUSE
[mobj->c_time == 0]
[ELSE]
ABRT
ABRT
START_PAUSE [mobj->c_time >= 60]
DEC_TIME [mobj->c_time >= 60] / mobj->c_time-=60;
INC_TIME / mobj->c_time+=60;
TIME_TICK [e->ss == 10] / --mobj->c_time;
++mobj->e-time;
disp_time(mobj->c_time);
COUNTDOWN
exit / mobj->p_time += mobj->e_time;
mobj->e_timer = 0;
PAUSE
entry / disp_msg("paused");
exit / disp_clr();
START_PAUSE
START_PAUSE