DISTRICT BRIDGE REPAIR WORK ORDER

DATE: 1/8/2016 9:20 AM

FROM: LARRY HARGIST

TO: 551602

| BRIDGE INFORMATION | The second secon | |
|--|--|--|
| Bridge Number: 8\$23.61035 | FHWA Number: 49360 | |
| Facility Intersection: LONG DICK CREEK | | |
| Facility Carried: SB I-35 | | |
| Location: 0.5 MILES N OF SR E18 | | |

| REPAIR NEEDED | | |
|--|--------------------|------------------|
| Description: 531 - Guardrail - Repair guardrail - Far approach | Function: 670 | Repair Code: 531 |
| Repair Type: Corrective | Due Date: 9/8/2016 | |

Inspection Recommendation: The guardrail at the far end of the bridge is in need of repair. Two broken blockouts are present on the far left and 1 broken post on the far right. Both anchor cables are loose.

REPAIR INSTRUCTIONS

The guardrail at the far end of the bridge is in need of repair. Two broken blockouts are present on the far left and 1 broken post on the far right. Both anchor cables are loose.

EQUIPMENT AND MATERIALS NEEDED

RESOLUTION Complete Date: ___ Name:

Bridge No: 8523.6L035 Repair Code: 531 Date: 1/8/2016 9:20 AM Recommendation ID: 518394

