

Function Specification (FncS)

(In Vehicle Software Update Vehicle FIS)

Document Type	Function Specification (FncS)	
Document ID	547918	
Document Location	VSEM Rich Client, VSEM Active Workspace	lgX5oHybx3NrTD
Document Owner	Tummepalli, Amareswar (atummepa)	
Document Version	F	
Document Status	Released	
Date Issued	09-Apr-2020 10:26	
Date Revised	24-Jul-2020 11:32	
Document	GIS1 Item Number:	
Classification	GIS2 Classification:	

Document Approval			
Person	Role	Email Confirmation	Date

This document contains Ford Motor Company Confidential information. Disclosure of the information contained in any portion of this document is not permitted without the expressed, written consent of a duly authorized representative of Ford Motor Company, Dearborn, Michigan, U.S.A.

Copyright © 2016 - 2020, Ford Motor Company

Printed Copies are Uncontrolled



Content

,		di adian	_
1		duction	
	1.1	Purpose	
	1.2	Scope	
	1.3	Audience	
	1.3.1	Stakeholder List	8
	1.4	Document Organization	9
	1.4.1	Document Context	9
	1.4.2		
	1.5	References	
	1.5.1		
	1.5.2		
	1.6	Terminology	
	1.6.1		
_	1.6.2		
2		ure Implementation Description	
	2.1	Overview	
	2.2	Input Requirements	11
	2.2.1	FRD-REQ-308047/B-###R_CMP_IVSU_V_00002### DIDs for OTA Command Signing Key	ys
	and A	Application Signing Keys	11
	2.2.2	FRD-REQ-308048/C-###R_CMP_IVSU_V_00003### Differential Updater	11
	2.2.3		12
	2.2.4		
		ware Files	12
	2.2.5		12
	2.2.6		
	2.2.7	'	
	2.2.8		
	2.2.9		13
	2.2.1		13
	2.2.1		13
	2.2.1		
	have	local wake up/stay awake	14
	2.2.1		
	igniti	on_status <> Off	14
	2.2.1	FRD-REQ-308062/B-OTA Client shall NOT start any OTA Activity if it receives a load	
		lding signal	14
	2.2.1		
		ery is in critical condition	14
	2.2.1		'-
		rammingSession	11
	2.2.1		
	2.2.1	, ,	
	2.2.1	o i	3
		15	
	2.2.2		
		ule PART II spec to be up to date in VSEM	
	2.3	Assumptions & Constraints	
3	Fund	ctional Architecture	17
	3.1	Function List	
	3.2	Signal List	19
4	Fund	ction Deployment	
	4.1	E/E Architecture Variant 1	
	4.1.1	E/E Components	



		RD-REQ-308756/C-###R_CMP_IVSU_V_00025### Capacitance Requirement n case of Power OFF While OTA Update	24
	•	onnections	
	4.1.3 Functi	on Allocation	24
_	•	/ Parameter Mapping	
5		mentation Modelingent Interaction Diagrams	
		rio: "ECG updating itself via USB"	
	5.1.2 Scena	rio: "Sync updating itself via USB"	52
		rio: "Update of TCU, Sync and ECG via USB"	
		ırio: "Update of Sync via OTA" ırio: "Update Sync via TCU On Ignition On Engine Running"	
		rio: "Update SYNC via External WIFI On Key Off"	
		rio: "Update SYNC via TCU on Key Off"	
	5.1.8 Scena 5.1.9 Scena	ırio: "Update ECG via TCU on Key Off" ırio: "Update ECG via SYNC on Key Off"	66
		enario "On Demand Charging" Request	
	5.1.11 Sce	nario: "Update Target ECU with one Micro Via OVTP"	74
	5.1.11.1	Read OTA Data by Identifier	
	5.1.11.2	Authorize Erase Memory	
	5.1.11.3	Erase Memory	
	5.1.11.4	Authorize Download	
	5.1.11.5	Initiate Download	77
	5.1.11.6	Transfer Download Data	
	5.1.11.7	Complete Download Data	
	5.1.11.8	Validate Logical Block	
	5.1.11.9	Initiate Force Sync Counter	
	5.1.11.10	Prepare for Activation	
	5.1.11.11	Authorize Activation	81
	5.1.11.12	Initiate Activation	82
	5.1.11.13	Initiate Rollback of in-active Flash Memory	83
	5.1.12 Sce 5.1.12.1	enario: "Updating Target ECU which has two Micro Via OVTP" Read OTA Data by Identifier for Two Micros	
	5.1.12.2	Authorization for Erase Memory for Two Micros	85
	5.1.12.3	Erase Memory for both Micros of Target ECU Over Can/CanFD:	87
	5.1.12.4	Erase Memory Target ECU Micro 1 over Can/Can Fd and Micro 2 Over Ethernet	t:88
	5.1.12.5	Authorize Download for Both Micros of Target ECU:	89
	5.1.12.6	Initiate Download for Both Micros of Target ECU:	92
	5.1.12.7	Transfer OTA Update Download to Both Micros of Target ECU	93
	5.1.12.8	Complete Download for both Micros	94
	5.1.12.9	Validate Logical Block for both Micros through CAN/CANFD	95
	5.1.12.10	Validation of Logical Block for Micro1 Via Can/CanFd and Micro2 Over Ethernet	96
	5.1.12.11	Initiate Force Sync Counter for Both Micros	97
	5.1.12.12	Prepare for Activation for Both Micros	98



	5.1.12.1	3 Au	uthorize Activation for both Micros	100
	5.1.12.1	4 In	tiate Activation for both Micros	101
	5.1.12.1	5 In	tiate RollBack for both Micros	103
	5.1.13	DC Co	nfiguration Scenario: "Change Parameter Over The Air"	104
	5.1.14	REQ-3	65946/B-OTA Update during vehicle in transport mode	105
			Interface Behavior Diagrams	
6			ntation Requirementsts Derivation Diagram	
			ts	
	6.2.1 Re	equirem	ents on Electrical Components	108
	6.2.1.1	Hard	ware Variants	108
	6.2.1.	.1.1 F	FRD-REQ-308073/A-###R_CMP_IVSU_V_00035### Hardware Variant Revie	w 108
	6.2.1.	1.2	OTA Architecture Type 1 – Hardware Facilitated Address Remapping	108
	6.2.1.	1.3	OTA Architecture Type 2 –Memory Caching Option 1	108
	6.2.1.	1.4	OTA Architecture Type 3 – Memory Caching Option 2	109
	6.2.1.	1.5	OTA Architecture Type 4 – Execute from RAM	110
	6.2.1.2	Com	ponent	110
	6.2.2 Re		ents on Electrical Distribution System (EDS)	
	6.2.2.1	FRD	-REQ-308067/B-###R_CMP_IVSU_V_00055### Electrical Load Architecture	110
	6.2.2.2 ECU on		-REQ-308070/B-###R_CMP_IVSU_V_00058### Programming NON A/B PAA FF State with Run/Start bus Active	
	6.2.2.3 from clo		-REQ-308072/B-###R_CMP_IVSU_V_00060### ECU Capable of Downloadir I be awake for certain time period as per ECG request	
	6.2.2.4	FRD	-REQ-328062/B-###R_CMP_IVSU_V_00062### ECU that requires learning secific process or action after an update	
	6.2.2.5	•	-REQ-362586/B-TCU shall track SOC in vehicle transport mode	
	6.2.2.6		-REQ-362587/B-TCU to handle OTA SMS in vehicle transport mode	
	6.2.2.7		-REQ-362589/B-TCU to wake up ECG when there is a wake SMS from cloud	
	•		rt mode	
	6.2.2.8 regardle		-REQ-365739/B-TCU/ECG shall send vehicle mode change information to clonition state	
	6.2.2.9	•	-365775/B-TCU shall sync SOC from BCM periodically to get accurate SOC	
	6.2.2.10		RD-REQ-394957/A-Routine to Cancel an Active OTA Update	
	6.2.2.11		RD-REQ-394958/A-Reading DIDs in Application Default and Diagnostic sessio	
	6.2.2.12	2 FF	RD-REQ-394960/A-Update\Flash All ECUs regardless of Vehcile Mode	113
			ents on DTC and DIDs	
7				
8	Verificatio	n Revie	w	116
9		•		
10			's	
			onary	
			Signals	
			Parameters	
	10.2.3	Techni	cal Signals	126



10.2.4	Technical Parameters	
10.2.5	Data Types	126
FRD-REQ	૧-308047	126
DIDs for (OTA Command Signing Keys and Application Signing Keys	126
X		126
FRD-REQ	૧-308048	126
	tial Updater	
)-308049	
	of Software Updates	
	EQ-308050	_
Tempo	orary Vehicle Storage for Software Files	127
X		127
V		127
	08052	
	ECU Activation Time	
	00052	
	08053t Hardware Reviewt	
	t Hardware Review	
	08054	
	ng in background	
	iig iii backgi ouriu	
	08055	
	igning	
	0 0	
x		127
FRD-REQ-30	08056	127
Vehicle Inhi	ibit	127
x		127
X		127



FRD-REQ-308057	127
Preserve Data	127
Х	
Х	
X	
X	
X	
X	
x	
X	
FRD-REQ-308058	
Configuration Data	
FRD-REQ-308060	
ECUs that can download files from Cloud/USB shall be capable to have local wake up/stay awake	
X	
x	
FRD-REQ-308061	
OTA Client shall not request the OTA Run/Start active if ignition_status <> Off	
X	
FRD-REQ-308062	
OTA Client shall NOT start any OTA Activity if it receives a load shedding signal	
X	
FRD-REQ-308065	
OTA Client shall NOT initiate or process any OTA activity when Battery is in critical condition	
X	
FRD-REQ-324142	
DID for Entering in to OTA ProgrammingSession	
Х	
X	
X	
X	
X	
X	
X	
X	
FRD-REQ-348263	
Self Install ECU during Load shed	
x	
x	
X	
FRD-REQ-308756	127
Capacitance Requirement Availability in case of Power Off While OTA Update	127
X	127
FRD-REQ-308073	127
Hardware Variant Review	127
FRD-REQ-308067	127
Electrical Load Architecture	127



	x	
	X	127
	FRD-REQ-308070	127
	Programming NON A/B PAAT ECU on Key OFF State with Run/Start Bus Active	127
	x	
	FRD-REQ-308072	
	·	
	ECU Capable of Downloading from cloud shall be awake for certain timer period as per ECG request	
	x	
	x	
	FRD-REQ-328062	127
	ECU that requires learning algorithm for specific process or action after an update	127
	X	
	x	
	X	121
Lict	of Figures	
LISU	t of Figures	17
	e 2: E/E Architecture, Variant 1	
	e 3: Flowchart of ECG Updating TCU via USB	
	e 34: Authorize Download for Both Micros of Target ECU	
	e 46: DC Configuration Scenario: "Change Parameter Over The Air"	
_	6: OTA Undate during vehicle in transport mode	



1 Introduction

1.1 Purpose

The Feature Implementation Specification (FIS) specifies the deployment of the logical functions of a feature to an electrical architecture. The FIS specifies all interactions between the ECUs of the electrical architecture required for the feature including the technical signals and the interfaces. It also gives interface and integration requirements, which are specific to the feature for the electrical architecture. To get more information about the concept of feature, function and component level abstraction refer to the Ford RE Wiki.

1.2 Scope

This FIS describes the deployment of the IN VEHICLE SOFTWARE UPDATE feature to the following electrical architecture(s):

Electrical Architecture Name	Owner	Reference
FNV2 – Fully Network Vehicle	Gwen Ald	<add link="" vsem=""></add>
CGEA1.3C	Gwen Ald	

Table 1: Electrical Architecture(s) referenced in this document

The following functions from the Global Feature & Function List are referenced in this Feature Implementation Specification:

Function ID	Function (Group) Name	Owner	Reference
<add id="" vsem=""></add>	CAVC Function Specification	Vijay Jayaraman	<add link="" vsem=""></add>
	OVTP OTA Function Definition	Mohamad Nasser	

Table 2: Functions referenced in this document

1.3 Audience

The FIS is authored by CVS IVSU Team. All Stakeholders, i.e., all people who have a valid interest in the feature implementation should read and, if possible, review the FIS. It needs to be guaranteed, that all stakeholders have access to the currently valid version of the FIS.

1.3.1 Stakeholder List

For the latest list of the function stakeholders and their roles & responsibilities refer to <Put VSEM Link here>.

Name	CDSID	Responsibilities
Jim Weinfurther		Body Control Technical
		Specialist
Jeremy Rusell		PCM Technical Specialist
Gwen Ald		EE Architecture System Lead
Jason Miller		OVTP and Diagnostic Technical
		Specialist
Jennifer Shaw		ECG Supervisor
Aldi Caushi		Cyber Security Functional
		Owner
Bill Waldeck		NetCom Technical Specialist

GIS2 Classification:



Name	CDSID	Responsibilities
Scott Watkins		Cluster Technical Specialist

Table 3: Stackholder List

1.4 Document Organization

1.4.1 Document Context

Refer to the Specification Structure page in the Ford RE Wiki to understand how the FIS relates to other Ford Requirements Documents and Specifications.

1.4.2 Document Structure

The structure of this document is explained below:

- Section 1 Introduction Giving an explanation how to use this document including responsibilities and the scope of the document. Additionally, it contains the revision history and a list of unsettled but known issues that have to be consolidated in future versions. It explains the terminology and gives a clarification of the definitions, concepts and abbreviations used in the document.
- **Section 2** Platform Description Giving an overview of the platform and listing assumptions, constraints or dependencies
- **Section 3** Functional Architecture Showing the logical architecture of functions
- **Section 4** Function Deployment Presenting the allocation of logical functions and signals to their electrical counter parts
- **Section 5** Deployment Specific Modeling –Modeling techniques providing additional detail on e.g. interface behavior
- **Section 6** Deployment Specific Requirements Deployment specific requirements for ECUs, Network Communication, and Process
- **Section 7** List of Open Concerns
- Section 8 Traceability Matrix
- Section 9 Revision History
- Section 10 Appendix Presenting additional data mainly in a tabular form, e.g., a data dictionary

1.5 References

1.5.1 Ford Documents

Lst here all Ford internal documents, which are directly related.

Reference	Title	Doc. ID	Revision	
1	OVTP OTA Function Definition			
2	OVTP Protocol Specification			
3	OTA Signed Commands			
4	Application Signing Requirements			
5	ESN Specification			
6	SWDL			
7	IVSU Feature Document			
8	IVSU_Vehicle_Function_Bare Metal Diff Updater			
9	IVSU FNV2 DFMEA	Please refer to LFMA documentId: 66689		
10	IVSU Functional safety requirements			
11	IVSU_Vehicle_Function_Diff Generator		·	



1.5.2 External Documents and Publications

The list of external documents could include books, reports and online sources.

Reference	Document / Publication

Table 5: External documents and publications

1.6 Terminology

1.6.1 Definitions

Definition	Description

Table 6: Definitions used in this document

1.6.2 Abbreviations

Abbr.	Stands for	Description
FS	Function Specification	
E/E	Electrical and Electronics	
FIS	Feature Implementation Specification	
IVSU	In Vehicle Software Update	
FESN	Ford Electronic Serial Number	Ford-specific ECU serial number used for OTA and security purposes
OTA	Over The Air	
DID	Diagnostic Data Identifier	

Table 7: Abbreviations used in this document.



Feature Implementation Description

Overview 2.1

Software updates for all vehicle's component is a way to reduce the warranty cost and improve the vehicle's functionality.

In Vehicle Software Updates feature provides the ability to re-flash the vehicle without the customer being required to go to a Ford dealer and service her car. There are two methods that the software gets to the vehicle: via OTA or via USB.

Ford owner's website or Ford Customer Service site are the only locations where the software can be downloaded into a USB.

OTA (Over the Air) will use the vehicle connectivity to download the software directly in the vehicle. The highest priority is Home Wi-Fi, then AppLink, then Cellular which is paid by Ford. However, the priorities can be modified based on Ford's requirement per each software update.

Once the software is present in the vehicle, the ECG module shall use Ethernet or CAN/CAN FD to distribute the software to the other entire vehicle ECUs.

To reduce the possibilities of permanent failure each component shall have double memory to keep the previous software in addition to the new software that is re-flashed with. The double memory is needed so that modules can revert back to the previous software in case of failures.

2.2 Input Requirements

2.2.1 FRD-REQ-308047/B-###R CMP IVSU V 00002### DIDs for OTA Command Signing Keys and Application Signing Keys

The hash of the OTA command signing key and the hash of the in-use application signing key shall be verified at Ford EOL by reading DID 0xD03E and 0xD03F.

FRD-REQ-308048/C-###R CMP IVSU V 00003### Differential Updater

OTA supported ECUs shall support differential file updates If total programmable software size is larger than 1MB. (Ref 8, Ref 11)


Note: If an ECU supports differential files, the compiler settings shall be investigated to optimize the effectiveness of the differential generation.

Page 11 of 127

Document ID: 547918 Date Issued: 09-Apr-2020 10:26 Date Revised: 24-Jul-2020 11:32

GIS2 Classification:





In addition to the steps of a regular OVTP update, a Diff is programmed into a reserved region of memory. Then an additional step of installing the Diff is performed. Once the Diff installation is complete, the new software is present in the inactive memory and is ready to be remapped as described in OTA Function Definition Reference 1.

High Level Requirements:

- Hardware assisted memory remapping
- 2x internal flash to support storage of both A & B memory
- Additional reserved internal flash Diff Memory, which at least 30% of the size of A.
- Read-while-write capability to internal flash

2.2.3 FRD-REQ-308049/A-###R_CMP_IVSU_V_00004### Number of Software Updates

ECU shall support software update capability over the life of the vehicle (10yr/150K miles), assuming 5 re-flashes per year (50 total).

2.2.4 FRD-REQ-308050/B-###R_CMP_IVSU_V_00005### Temporary Vehicle Storage for Software Files

OTA client module shall support storage of 1 GB of OTA files for download.

2.2.5 FRD-REQ-308052/C-###R_CMP_IVSU_V_00007### Maximum ECU Activation Time

For OVTP OTA modules, the worst case allowed activationTime (Ref 1) for the initiateActivation command is 90s. For OVTP OTA modules, the worst case allowed rollbackTime (Ref 1) for the initiateRollback command is 90s. This is the worst cast time based upon nominal operating conditions and not the worst case time based upon extreme operating conditions, etc.

GIS2 Classification:



2.2.6 FRD-REQ-308053/B-###R_CMP_IVSU_V_00008### Component Hardware Review

Every OVTP OTA ECUs that requires an activationTime or rollbackTime (Ref 1) greater than 70s shall complete a deep dive review with the CVPP IVSU team. These components shall strive for technology improvements in their hardware to reduce the activation and rollback time.

2.2.7 FRD-REQ-308054/B-###R CMP IVSU V 00009### Downloading in background

An ECU must be capable of downloading and storing a completely new set of all application software while the existing application software is running as normal. This background download shall not impact the ECU's normal application functionality performance requirements.

2.2.8 FRD-REQ-358773/A-Pause and Resume OTA Progress for OVTP OTA Modules

Every OVTP OTA ECU which supports an individual OVTP OTA function which cannot complete the request/response transaction within 5 minutes shall be capable of pausing the functionality when the network goes to sleep (if a sleep/wake ECU) or when the customer keys off (if a switched ECU). Furthermore, the OVTP OTA ECU shall be capable of resuming the functionality from where it was paused when the same OVTP OTA function is re-requested by the OTA client. For example, if the prepareActivation function for an ECU were to take 7 minutes as the worst case, this functionality must be capable of being paused as describe and resumed from that point (e.g., at the next key cycle). The intent of this is to ensure that progress toward completion of OTA will be made for customers who typically have short drive times of 5 minutes, Exceptions to this are possible but require review and explicit approval of the details of the design by the core IVSU OTA team.

2.2.9 FRD-REQ-308055/A-###R_CMP_IVSU_V_00010### Software Signing

All software downloaded via OTA shall be signed either by application signing, traditional signing or any other signing that is defined by Ford Security Team.

2.2.10 FRD-REQ-308056/B-###R CMP IVSU V 00011### Vehicle Inhibit

The vehicle shall be inhibited for a maximum time of 30 minutes for any combination of non-interruptible OTA activity.

Note:

- 1. The vehicle shall be inhibited for a maximum time of 2 minutes for OTA over OVTP or Ethernet based SOA SFTP OTA activation.
- 2. The vehicle shall be inhibited for a maximum time of 4 minutes for DC Configuration.
- 3. The vehicle shall be inhibited for a maximum time of 15 minutes for SWDL OTA (E/R) Programming.

If Rollback, the timing may be double of mentioned above.

2.2.11 FRD-REQ-308057/B-###R_CMP_IVSU_V_00012### Preserve Data

Each ECU that is re-flashed via OTA or USB shall preserve all the direct ECU Configuration data, or previously learned data, adaptive factors, or other long-term adjustments, etc. Examples of information



that must not be lost after a reset include clock value, radio presets, correct fault gauge level, Bluetooth Pairing info. Seat settings etc

.

2.2.12 FRD-REQ-308060/B-ECUs that can download files from Cloud/USB shall be capable to have local wake up/stay awake

The ECUs (Sync/ECG) capable of downloading files from Cloud/USB on its own, shall have download capability with the location of files to download with the allowed time for the download activity even during Key Off, by keeping itself awake.

2.2.13 FRD-REQ-308061/B-OTA Client shall not request the OTA Run/Start active if ignition_status <> Off

The OTA client shall not request control of the Run/Start bus (e.g., VehOn_D_RqCld <> NoControl) when Ignition_Status <> Off or when VehOnSrc2_D_Stat <> Off.

2.2.14 FRD-REQ-308062/B-OTA Client shall NOT start any OTA Activity if it receives a load shedding signal.

OTA client shall not start any OTA activity if load shedding is active. In the case there is an OTA activity and load shedding transitions to active, the OTA client shall obey the following depending on the OTA activity stage:

- 1. If performing background download, it shall pause the download until load shedding is no longer active
- 2. If the vehicle is inhibited due to an OTA activity, the non-interruptible OTA activity shall complete.

2.2.15 FRD-REQ-308065/B-OTA Client shall NOT initiate or process any OTA activity when Battery is in critical condition

The OTA client shall NOT initiate any OTA activity if the battery is in critical condition (KeyOffMde_D_Actl = Critical Battery). If the vehicle is already inhibited due to an OTA activity, the non-interruptible OTA activity shall complete.

2.2.16 FRD-REQ-324142/C-###R_CMP_IVSU_V_00022### DID for Entering in to OTA ProgrammingSession

DID \$D04F shall be supported for all ECUs supporting diagnostics. If an ECU can always enter programmingSession upon request (and therefore has no preconditions), only bit 31 "No ProgrammingSession Preconditions Supported" shall be supported. If an ECU has any preconditions for entering programmingSession due to an OTA initiated event, then bit 31 shall not be supported and bits for each precondition which prevent the transition shall be supported. A reported DID value of all 0s shall always be used to indicate the ECU is able to transition into ProgrammingSession due to an OTA initiated request if asked at the present time. Conversely, a reported DID value with at least one bit not equal to zero requires the ECU to reject a request to transition to programmingSession due to an OTA initiated request.

Support of bits within DID \$D04F (i.e., additional entry conditions for programmingSession and OTA activation) shall be kept to a minimum. Support of bits other than bit 31 requires explicit approval from CVPP core IVSU team. If a parameter is defined in the DID (e.g., hazards on) does NOT mean that an



ECU must use that as a precondition. Its presence is because at least one ECU presented a use case to CVPP demonstrating why their particular ECU needs to validate this condition. In other words, because an ECU can determine the state of a parameter in the DID does not mean it needs to implement that as a precondition to prevent OTA activation or programming Session entry.

When a diagnostic programmingSession entry request is received, it can be recognized as an OTA initiated request by checking if VehOnSrc D Stat == OverTheAir OR VehOnSrc2 D Stat == OverTheAir. DID \$D04F shall always report the correct state of all supported bits each time the DID is read independent of the signal value of VehOnSrc D Stat and VehOnSrc2 D Stat.

2.2.17 FRD-REQ-348263/A-Self Install ECU during Load shed

For ECUs with self-installation if they started the installation process and load shed transitioned to active, they shall complete the installation. For ECUs with self-installation if load shedding is active before starting the installation, they shall not start the installation and they shall install the next time the conditions are met (Next ignition cycle or when requested by the OTA client).

2.2.18 FRD-REQ-355940/A-Error Recovery During OVTP OTA Activation and Rollback

This requirement only applies to OTA OVTP ECUs which implement a hardware architecture in which the software is executed out of internal flash, and during OTA OVTP activation and rollback, the active software is temporarily erased and then programmed with new software (e.g., see hardware variants OTA Architecture Type 2 and Type 3).

When performing this activation and rollback, the application software jumps to the bootloader to initiate the erasure of the current software and the programming of the desired new software. This process shall be robust to resets and power interruption, so that if either occurs, the ECU shall be able to retry the erasing of internal flash and programming of the intended software. When performing a swap to different software initiated by the OTA OVTP client, if the ECU is unable to successfully fully program the intended software into internal flash, the ECU shall automatically erase the necessary areas of internal flash and attempt to program the original software stored in the appropriate backup in order to decrease the likelihood of the ECU from being stuck in the bootloader without a valid application.

2.2.19 FRD-REQ-358785/A-DID for Preventing OTA Update of Target ECU but Not Other ECUs

As described in requirement FRD-REQ-324142/C-###R CMP IVSU V 00022###, DID \$D04F is a standard DID that is implemented in all ECUs which prevents OTA SWDL programming of any ECU. DID \$D031 is a standard DID that is only implemented if an ECU has additional preconditions above and beyond DID \$D04F that must be checked in order to prevent the OTA programming of itself. To support DID \$D031, underlying rationale for each supported bit must receive explicit approval in writing from the core OTA team within Ford CVPP.

DID \$D04F will be read from all ECUs whenever an OTA SWDL event occurs on the vehicle. DID \$D031 will only be read from ECUs which are undergoing an actual OTA update. Examples:

DID \$D04F prevents any ECU from being OTA programmed via SWDL

DID \$D031 prevents the ECU reporting it from being OTA updated

DID \$D04F means your ECU can't be A/B swapped

DID \$D04F means your ECU can't go into programmingSession (which means no ECU can go into programmingSession).

DID \$D031 means your ECU can't be A/B swapped

DID \$D031 means your ECU can go into programmingSession but does not want to be programmed. Onus is on the ECG to not program it.



2.2.20 FRD-REQ-376027/A-All Modules or Target ECUs that supports OTA Shall have the module PART II spec to be up to date in VSEM

All Modules or Target ECUs that supports OTA Shall have the module PART II spec to be up to date in VSEM

2.3 Assumptions & Constraints

- The IVI components (ECG, SYNC and TCU) have more logical functions that are allocated to them. For easy of representation, the details between those modules are contained in its own FIS.
- As a design considerations to improve performance of Wifi medium based OTA update following factor shall be considered
 - a. Wifi Protocol supported (Say for example: 802.11a aZ)
 - b. Signal strength (Say for example -65dBm) and Proximity (Say for example 5 meters to 250 meters) to WiFi Access Point.



3 Functional Architecture




Figure 1: Functional Architecture

Vehicle components that are communicating in CAN, shall be updatable via CAN using the OVTP protocol.

Vehicle components that are communicating in Ethernet, shall be updatable via Ethernet using the OVTP protocol.

Note: L_ECG2ECU_x is many logical signals grouped together for easy presentation in this diagram. Each signal is represented as L_ECG2ECU_001, L_ECG2ECU_002,..and so on. L_ECU2ECG_x is many logical signals grouped together for easy presentation in this diagram. Each signal is represented as L_ECU2ECG_001, L_ECU2ECG_002,..and so on. Please refer Signal List Section for comprehensive list of logical signals.

3.1 Function List



Function ID	Function Name	Function Description	
F1	IVSU_Vehicle_Function_OTAManager	Function in the ECG that is responsible for orchestrating the OTA update of the vehicle.	
F2	IVSU_Vehicle_Function_OTA_OVTP_CLIENT	The function lives in the ECG module which is responsible for updating other ECUs in the vehicle.	
F3	IVSU_Vehicle_Function_VILClient	The function lives in the ECG module and is responsible for doing all the diagnostic calls to read the part numbers or other DID information that are required to be reported to Ford's Cloud	
F4	IVSU_Vehicle_Function_SelfInstallManager	This function is responsible for controlling, verifying and integrity check while installation, verification, activation, rollback of an installation file to respective Micros as per the Manifest.	
F5	IVSU_Vehicle_Function_DownloadManager	This function is responsible for downloading binaries, control such as pause/resume of downloads, report Errors and reports Progress of downloads.	
F6	IVSU_Vehicle_Function_TriggerManager	This function is responsible for categorize different type of IVSU related triggers and suggests error-handling mechanism for IVSU triggers	
F7	IVSU_Vehicle_Function_StatusManager	Status Manager's responsibility is to periodically send logs to the IVSU cloud based on some configurable parameters, like every x days or when the log files gets to a certain size. Status Manager uses the Cloud Interface Manager to send the reports to the IVSU Cloud	
F8	IVSU_Vehicle_Function_CAVC_Control	The function is responsible for starting the vehicle	
F9	IVSU_Vehicle_Function_CAVC_Inhibit	The function that is responsible for inhibiting the start of the vehicle	
F10	IVSU_Vehicle_Function_CAVC_Display	The function is responsible for displaying the correct messages to the customer within the required time.	
F11	IVSU_Vehicle_Function_HMI	This function will define safer and reliable user experience with IVSU for OTA update.	
F12	IVSU_Cloud_Function_StatusManager	This function is for monitoring, correcting, analyzing IVSU process from beginning to end. Thus, it is important to retrieve and dispatch status from vehicle side to corresponding micro service in cloud side.	
F13	IVSU_Cloud_Function_SignedCommands	This function defines group of functions in IVSU feature which are Signed commands for OTA Program, Erase and DiffUpdate, Prepare, Activate, Rollback, Vehicle Inhibit and Vehicle De-inhibit	



F14	IVSU_Cloud_Function_LoggingMonitoring	This function group specifies high-level requirements to log and monitor cloud operations.
F15	IVSU_Cloud_Function_Consumer_and_Service_Website	This function specification is to provide all requirements and flows for consumer and dealer website.
F16	IVSU_APP_Function_FMC_Brand_HMI	The function specific will cover all the Phone HMI flows, default values, and requirements for consumer FMC Brand App
F17	IVSU_Interface_Function_USB_Software_Updates	The purpose of this interface function is to provide requirements for all the vehicles that are capable to update thru USB port
F18	IVSU_Interface_Spec_Applink	The purpose of this Interface is to provide a middleware between IVSU Application and Applink Interface to avoid any code change dependency between IVSU Application and Applink Interface.
F19	IVSU_Interface_Spec_Connectivity	The purpose of this Interface is to provide a middleware between IVSU Application and Wireless Router Interface to avoid any code change dependency between IVSU Application and Wireless Router Interface.
F20	OVTP OTA FUNCTION Defination	This Function describes the functional use case of OTA for OVTP and is the controlling document for OTA Function IDs
F21	OTA Cloud Interface Specification	This Function describes interface requirements between Client device module and Ford back end OTA cloud infrastructure

Table 8: List of Functions

3.2 Signal List

Signal ID	Signal Name	Description
LS_ECG2E CU_00001	OVTP OTA session number	
LS_ECG2E CU_00002	SUCounter	Software Update Counter. For detailed description please refer to OVTP OTA FID spec
LS_ECG2E CU_00003	Number of blocks to erase	Parameters associated with Authorize Erase and Erase commands.
LS_ECG2E CU_00004	Start address of each block to be erased	Parameters associated with Authorize Erase and Erase commands
LS_ECG2E CU_00005	Size of each block to be erased	Parameters associated with Authorize Erase and Erase commands
LS_ECG2E CU_00006	Erase Memory Authorize command Signature	Parameters associated with Authorize Erase and Erase commands
LS_ECG2E CU_00007	Force Sync Counter Authorize command Signature	Parameters associated with Authorize Force Sync Counter command
LS_ECG2E CU_00008	Force Sync Counter after Successful Erase	



LS_ECG2E	Number of blocks to	Parameters associated with Authorize Program and Initiate Program
CU_00009	program	commands
LS_ECG2E	Start address of each block	Parameters associated with Authorize Program and Program
CU_00010	to be programmed	commands
LS_ECG2E	Size of each block to be	Parameters associated with Authorize Program and Program
CU_00011	programmed	commands
LS_ECG2E	Program memory Authorize	Parameters associated with Authorize Program and Program
CU_00012	command signature	commands
LS_ECG2E	Block Sequence counter	
CU_00013		
LS_ECG2E	Force Sync Counter after	
CU_00014	Successful logic program	
	(0x16)	

Signal ID	Signal Name	Description
LS_ECU2E CG_00001	ESN	ECU Serial number. (DID – New DID to be defined)
LS_ECU2E CG_00002	ECU Core Assembly number	ECU Core Assembly number (DID – 0xF111)
LS_ECU2E CG_00003	ECU delivery Assembly number	ECU delivery Assembly number (DID – 0xF113)
LS_ECU2E CG_00004	SWDL specification version	SWDL specification version (DID – 0xF162)
LS_ECU2E CG_00005	Diagnostic specification version	Diagnostic specification version (DID – 0xF163)
LS_ECU2E CG_00006	Vehicle Manufacturer ECU SW number	Vehicle Manufacturer ECU SW number (DID – 0xF188)
LS_ECU2E CG_00007	DID Configuration DID DE00 - DEFF	DID Configuration DID DE00-DEFF
LS_ECU2E CG_00008	DID Configuration DID DE01	DID Configuration DID DE01
LS_ECU2E CG_00009	DID Configuration DID DE02	DID Configuration DID DE02
LS_ECU2E CG_00010	DID Configuration DID DE03	DID Configuration DID DE03
LS_ECU2E CG_00011	DID Configuration DID DE04	DID Configuration DID DE04
LS_ECU2E CG_00012	DID Configuration DID DE05	DID Configuration DID DE05
LS_ECU2E CG_00013	DID Configuration DID DE06	DID Configuration DID DE06
LS_ECU2E CG_00014	DID Configuration DID DE07	DID Configuration DID DE07
LS_ECU2E CG_00015	DID Configuration DID DE08	DID Configuration DID DE08
LS_ECU2E CG_00016	DID Configuration DID DE09	DID Configuration DID DE09
LS_ECU2E CG_00017	DID Configuration DID DE0A	DID Configuration DID DE0A
LS_ECU2E CG_00018	DID Configuration DID DE0B	DID Configuration DID DE0B
LS_ECU2E CG_00019	DID Configuration DID DE0C	DID Configuration DID DE0C



LS_ECU2E	DID Configuration DID DE0D	DID Configuration DID DE0D	
CG_00020	DID 0 (DID O (" (" DID DEOE	
LS_ECU2E	DID Configuration DID DE0E	DID Configuration DID DE0E	
CG_00021 LS_ECU2E	DID Configuration DID DE1B	DID Configuration DID DE1B	
CG_00022	DID Configuration DID DE 18	DID Configuration DID DE1B	
LS_ECU2E	ECU Cal-Config Part Number	ECU Cal-Config Part Number" didValue="F10A"	
CG_00023	200 car comig rant tramsor	200 car coming rank rambon and value 1 1071	
LS_ECU2E	On-line Diagnostic Database	On-line Diagnostic Database Reference Number didValue="F110"	
CG_00024	Reference Number		
LS_ECU2E	OTA session response	Positive Response/Negative response NRC(13/22/31)	
CG_00025	Tanast FOLLIntanasi OTA	DID ¢D000	
LS_ECU2E CG_00026	Target ECU Internal OTA State	DID \$D022 .	
CG_00026	State	Byte 1: One byte Hex:	
		■ Last FID received	
		Byte 2:	
		One byte SED (Internal OTA State)	
		 Maybe 2 bytes if we really think we could 	
		have more than 256 states for future	
		expansion	
		• Byte 3 - 6	
		 4 byte Hex: OTA Expected Address to Write and 	
		address to Erase	
		 Note this would only be valid if Internal OTA State was a set of values indicating that a 	
		download is in progress, etc.	
		Otherwise, would simply be reported as all	
		\$00s	
		Block sequence counter may be added in here as well???	
LS_ECU2E	Authorize Erase Memory	Positive Response/Negative response NRC(11/13/15/16/17/31)	
CG_00027	response	D '' D	
LS_ECU2E	Erase Memory response	Positive Response/Negative response NRC(11/13/33/31)	
LS ECU2E	Erase Successful Force Sync	Positive Response/Negative response NRC(11/13/17)	
CG_00029	Counter response	Toshive response/regalive response rire (11/16/17)	
LS_ECU2E	Authorize Program response	Positive Response/Negative response NRC(11/13/15/16/31/33)	
CG_00030	3	3 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2	
LS_ECU2E	maxNumberOfBlockLength	For Flash Write, Maximum block length accepted by Target ECU.	
CG_00031			
LS_ECU2E	Initiate download response	Positive Response/Negative response NRC(11/13/15/16/17/31/33)	
CG_00032	To select the late	For 33, Send Auth again.	
LS_ECU2E CG 00033	Transfer data reponse	Positive Response/Negative response NRC(11/13/24/31/73)	
06_0003		NRC Data bigger than requested block size(maxNumberOfBlockLength) – 0x31	
LS ECU2E	Block Sequence counter	Positive response (Transfer data reponse).	
CG_00034	echo		
LS_ECU2E	Calculated Hash of all logical		
CG_00035	blocks root hashes (Swash)		
LS_ECU2E	Complete data Transfer	Positive and negative response(11/13/22/24)	
CG_00036	response	·	
	L Fares Cure Counter offer	Desitive and negative response	
LS_ECU2E	Force Sync Counter after	Positive and negative response	
LS_ECU2E CG_00037	Successful logic program response	Positive and negative response	



LS ECU2E	
LO_LOOZL	
CG_00038	



Function Deployment

4.1 E/E Architecture Variant 1




Figure 2: E/E Architecture, Variant 1

The first variant is the full connected vehicle where:

- ECG is the OTA Master and a tester tool. It will download other ECUs files, will program modules in CAN or Ethernet and provide the Activation command to all ECUs in the vehicle. ECG is connected via Ethernet to TCU and SYNC therefore it will use any connectivity available to download software from the cloud.
- TCU provides cellular connectivity and WiFi connectivity during ignition ON and OFF. The 2. software files are first downloaded into the ECG then transferred to TCU.
- 3. SYNC4 provides WiFi connectivity during Ignition OFF that will be used for software file downloads requested from the ECG. The software files, are downloaded directly in the SYNC cache because if its size.
- BCM is the module that will arbitrate all the requests to start the vehicle, including the OTA 4. request
- 5. PCM is the module that will inhibit the vehicle when OTA requests it thru ECG
- Cluster is the module that will display all time critical messages such as vehicle inhibit 6.

4.1.1 **E/E Components**

All components that are OTA updatable shall utilize the CAN OVTP or Ethernet OVTP Server application. The exception is the SYNC4 and TCU module.

Copyright © 2020, Ford Motor Company



4.1.1.1 FRD-REQ-308756/C-###R_CMP_IVSU_V_00025### Capacitance Requirement Availability in case of Power OFF While OTA Update

For target ECUs which are powered at all times (or have the capability to latch power at key off), when the vehicle is shut down due to normal usage (e.g., customer keys off, remote start ends, etc.) the ECU must ensure that the OTA server component is correctly shut down and all information (e.g. DID \$D022) to ensure the OTA client can resume the OTA transfer from the point where it was interrupted is written prior to module sleep or power down. The ECU is not explicitly required to ensure OTA resumption due to unexpected power removal (e.g., customer fuse pull or disconnection of the battery).

For target ECUs which are not powered at all times but, for example, rely upon power from the switched run/start bus, the target ECU shall have enough capacitance to ensure the OTA server component can correctly shutdown and accurately store all information (e.g. DID \$D022) to ensure the OTA client can resume the OTA transfer from the point where it was interrupted. This is required even for unexpected removal of power. Exceptions to this are possible but require review and approval of the details of the design by the core IVSU OTA team.

4.1.2 E/E Connections

NA

4.1.3 Function Allocation

FunID	Function Name	Reference	VSEM ID	Allocated to (Element)
F1	OTA Manager	IVSU_Vehicle_Function_OTAManager	547911	ECG
F2	CAN OTA OVTP CLIENT	IVSU_Vehicle_Function_OTA_OVTP_C LIENT	547910	ECG
F3	VIL Manager	IVSU_Vehicle_Function_VILClient	547912	ECG
F4	Self-Install Manager	IVSU_Vehicle_Function_SelfInstallMana ger	547922	ECG, SYNC, TCU
F5	Download Manager	IVSU_Vehicle_Function_DownloadMana ger	547923	ECG, SYNC, TCU
F6	Trigger Manager	IVSU_Vehicle_Function_TriggerManager	547921	ECG
F7	Status Manager	IVSU_Vehicle_Function_StatusManager	548480	ECG
F8	Vehicle Control	IVSU_Vehicle_Function_CAVC_Control	546767	BCM
F9	Vehicle Inhibit	IVSU_Vehicle_Function_CAVC_Inhibit	546768	PCM
F10	Vehicle Display	IVSU_Vehicle_Function_CAVC_Display	527515	CLUSTER
F11	HMI Interface	IVSU_Vehicle_Function_HMI	548171	SYNC
F12	Cloud Status Manager	IVSU_Cloud_Function_StatusManager	547915	CLOUD
F13	Cloud Signed Commands	IVSU_Cloud_Function_SignedCommand s	547916	CLOUD
F14	Cloud Logging Monitoring	IVSU_Cloud_Function_LoggingMonitorin g	547917	CLOUD
F15	Cloud Consumer and Service Website	IVSU_Cloud_Function_Consumer_and_ Service_Website	545839	CLOUD
F16	IVSU_APP_Fun ction_FMC_Bra nd_HMI	IVSU_APP_Function_FMC_Brand_HMI	547920	Customer Mobile App

GIS2 Classification:



F17	IVSU_Interface_ Function_USB_ Software_Updat es	IVSU_Interface_Funcation_USB_Softwa re_Updates	547914	Module which has USB Interface and Ethernet interface with ECG
F18	IVSU_Interface_ Spec_Applink	IVSU_Interface_Spec_Applink	547927	SYNC
F19	IVSU_Interface_ Spec_Connectiv ity	IVSU_Interface_Spec_Connectivity	547925	ECG
F20	OVTP OTA FUNCTION Definition	OVTP OTA FUNCTION Definition	547919	Fast OTA ECUs
F21	OTA Cloud Interface Specification	OTA Cloud Interface Specification	546616	CLOUD, ECG
F22	Campaign Manager	IVSU_Cloud_Function_CampaignManag er	583938	CLOUD
F23	Diff Generator	IVSU_Cloud_Function_Diff_Generator	584144	CLOUD
F24	Diff Updater	IVSU_Vehicle_Function_Diff Updater	583758	Any module that can be updated via OTA

Table 9: Function Allocation

Architectural Component/Interface	Overall Component ASIL	Req IDs	Req ASIL	Function/Behaviour	Req IDs	Req ASIL
	C(D)	Req a	В	Function 1	Req d	
Component 1		Req b	QM		Req e	B(C)
Component		Req c	C(C)	Function 3	Req f	C(D)
				Function 4	Req g	B(D)
Component 2	B(C)	Req b	QM	Function 1	Req d	
Component 2		Req h	B(C)			

Proposed Allocation Table

4.1.4 Signal / Parameter Mapping

ID	Logical Signal Name	Logical Signal Values	Mapped to Physical Signal Name	Physical Signal Values	Description
1	LS_OTAM_Updat e_Percentage_Pr ogress_APP_x	Value {percentage}			Check for Update progress



2	LS_ASUHMI_AS U_ReoccuringSc hedule	Value{ 01 - FALSE; 02 - TRUE}		Input to OTA Manager
3	LS_ASUHMI_AS U_CheckUpdate	Value{ 01 - True 02 - False }		One time consent
4	LS_OTAM_Trigg erExpiration_Tim e	Values{ 01 - Not_expired 02 - Expire }		Software update expired clear all HMIs
5	LS_OTAM_Updat eReminder_Time	Values{ 01 - Bytes - date/time }		SW Activation Reminder
6	LS_OTAM_Updat eExpiration_Time	Value { date/time }		Max time shown in the schdeule screen, if expire time is 3days from now then HMI shall only show 3days to activation the software bacause 4th day SW is not available.
7	LS_ASUHMI_Ma nage_Notification	Value{TRUE, FALSE}		



		T		
8	LS_ASUHMI_AS U_FeatureStatus	Values{ 01 - Enable 02 - Disable }		HMI Automatic software updates enable or disable OTA After Master reset or default values change
9	LS_ASUHMI_AS U_Consent	Value{TRUE, FALSE}		CCS settings True or False
10	LS_OTAM_SW_ Update_Notify	Value { 01 - PII_UPDATE; 02 - Additional }		HMI to display additional/pii consent
11	LS_OTAM_ECU_ App_reside	Value { 01 - APP_ECU_Updating }		Customer check for update when App ECU is updating then HMI shall prompt the customer try later
12	LS_ASUHMI_AS U_Additional_Co nsent	Value{ 00 - NONE; 01 - ONE_TIME; 02 - PII_UPDATE; }		OTA: One time skip additional but may need PII
13	LS_ASUHMI_AS U_ScheduleTime	Values{ 00 – Null 01 – Bytes - date/time }		Signal identify scheduled time/day for activation



_	1			
14	LS_OTAM_Updat e_Time	Values{ Bytes - date/time }		OTA manager Last SW update time and date. Update HMI after every activation
15	LS_OTAHMI_Ma ster_Reset_Statu s*	Value{ 00 - NONE 01 - MasterReset 02 - NoMasterReset }		HMI shall notify OTA Manager for Master Reset
16	LS_ PARSERUSB_C onn_Status*	Values{ 01 - USB_Plug 02 - USB_unPlug (download) }		USB device status
17	LS_PARSER_US BSW_Update_De tected*	Values{ 01 - False 02 - True }		True: Processing Updatetransient message
18	LS_PARSER_US BSW_Update_U RL	Values { URLs/VIL Folder Location }		if LS_PARSER_USBSW_Up date_Detected = true, then Set IVSU trigger with content
19	LS_USBOTA_Sy stem_Updating*	Values{ 01 - Older_Software 02 - Valid Manifest 03 - Redownload Files 04 - Sys_to_update_date }		Determine if USB device is with vaild software



20	LS_USBOTA_S W_Update_Statu s*	Values{ 01 - Updating (Downloading/Installi ng/Resumed) 02 - Failed 03 - PENDING_Activatio n, 04 - SUCCESSFUL, 05 - Paused }		If updating (download/install) failed then use "Failed" for USB Software update Status
21	LS_ASUHMI_Acti vation_Consent	Value{ 01 - NOW; 02 - DATETIME; }		One time schedule and NOW
22	LS_OTAM_Updat e_Percentage_O verallProgress	Value {percentage}		OTA/USB overall progress bar
23	LS_OTAM_OTA USB_Number_of _Files	Value { 01 - file remaining 02 - total files }		Total number of files in the manifest
24	LS_OTAM_Activ ation_Schedule_ Type	Value { 01 - WEEKLY; 02 - DAY; }		Schedule weekly or daily share with OTA Manager
25	LS_OTAM_SW_ Activation_Fail_R eason	Values{ 00_ NONE 01 - SW CORRUPTED; 02 - PERMANENT_INHI BIT; 03 - USB_FAILURE; 04 - WARNING; 05 - PARTIAL }		IF USB software activation failed then Use "USB_Failure"
26	LS_OTAM_SW_ Update_Fail_Rea son	{ErrorCode; }		USB Software update failed reason
27	LS_OTAM_Relea se_Notes_Info	Value {text}		Release Notes



28	LS_OTAM_Activ ation_TypeSW_A B_ER	Value{ 01- AB 02- ER 03 - AB and ER }		OTA Manage sharing type of software update
29	LS_OTAM_Activ ation_Type	Value{ 01- NOIGNITIONCYCL E 02- IGNITIONCYCLE 03- INHIBIT }		Activation Type
30	LS_OTAM_Vehic le_Inhibit_Type	Value{ 00 - NONE 01 - ProgrammingSessio n 02 - ActivatingNOW }		Vehicle in Programming Mode or activating the software HMI Logic shall make decision if LS_OTAM_Activation_Typ eSW_AB_ER = AB-ER then show LS_OTAM_Vehicle_Inhibit _Type = ProgrammingSession if LS_OTAM_Activation_Typ eSW_AB_ER = AB then show LS_OTAM_Vehicle_Inhibit _Type = ActivatingNow if LS_OTAM_Vehicle_Inhibit _Type = Activation_Typ eSW_AB_ER = ER then show LS_OTAM_Activation_Typ eSW_AB_ER = ER then show LS_OTAM_Vehicle_Inhibit _Type = ProgrammingSession



31	LS_OTAM_Activ ation_Time	Domain: 2 bytes (In seconds).		Activation for both E/R and/or AB Time range (2min to 30mins)
32	LS_OTAM_HMI_ OTAUSB_Clear	Values{ 01 - Pending 02 - ConfigtimeExpire 03 - ClearHMIs }		USB update is paused and OTA Manager shall clear cache after 7days
33	LS_OTAM_SW_I nstalation_State	Values{ 01 - IN_PROGRESS 02 - PENDING, 03 - FAILED, 04 - PAUSED, 05 - SUCCESSFUL }		HMI shows if Check for update was requested
34	LS_OTAM_SW_ Download_State	Values{ 01 - IN_PROGRESS, 02 - PENDING, 03 - PAUSED, 04 - FAILED, 05 - SUCCESSFUL }		HMI shows if Check for update was requested
35	LS_OTAM_SW_ Update_Postpon e	Values{True or false}		
36	LS_OTAM_SW_ Update_State	Values{ 00 - Clear_HMI 01 - IN_PROGRESS 02 - PENDING 03 - FAILED, 04 - SUCCESSFUL; 05 - UP_TO_DATE; }		OTA Software update Status



37	LS_OTAM_No_P rogSession_Prec onditions_Suppor ted	Values{ 01 - Vehicle Speed Too High 02 - Voltage Out of Range 03 - Charging in Progress 04 - PRNDL Out of Range 05 - Hazards On 06 - After Run Active 07 - ESCL Lock Pending 08 - Alarm Actively Sounding 09 - Steering Pinsion Torque Out of 10 - Range 11 - Diagnostic Self- Test Active 12 - Engine RPM Too High (or 02 - Torque Available) 13 - Charging Fault 14 - Ignition Status Out of Range 15 - Liftgate Ajar 16 - Park Lamps On 17 - Limp Home Active 18 - Illuminated Exit Active 19 - Door Ajar 20 - Hot Reclamp Active 21 - Brake Pedal		If software activation is postponed then set a flag for HMI and next action
		20 - Hot Reclamp Active		



38	LS_OTAM_HMI_ Master_Reset	Values{ 01 - Cancel 02 - Pending, 03 - Pause, }	1. ASU = OFF Cancel the pre- download for only one-time 2. ASU = ON Pending for consent, with additional consent 3. ASU = ON Pause during master reset and resume after it's complete without additional consent	
39	LS_OTAM_Activ ation_Status	Values{ 01 - Expired 02 - Pending, 03 - Pause }	Software Activation status	
40	OVTP_REQ			
41	OVTP_RES			_



42	LS_OTAM_Displ ayMsg_Type		VehStrtInh bt_D_Dspl y: 200ms FP	Periodicity: 200ms FP Domain: 4 bits 0b0000 - NoMessage 0b0001 - DuringOtaActiva te 0b0010 - PostOtaActivate Warning 0b0011 - PostOtaActivate PermFail 0x4 to 0xF - Reserved. Description: ECG sets value to display different messages in IPC ASIL: QM Cloud signed: NO	
----	-----------------------------	--	---	--	--



43	LS_OTAM_Displ ayMsgInfo_Time	VehStrtInh bt_T_Dspl y: 100ms EP	Domain: 2 bytes Time16bit_ET in seconds. Description: ECG sets value to display time information Vehicle Inhibited display message. ASIL: QM Cloud signed: NO	
44	LS_OTAM_TO_V SC_VehInhbt_Re q	CloudVeh CtlData_T p_Rq - Event Only TP	Domain: 269 bytes Byte1: 0x01 (Vehicle Inhibit) Byte 2-269 bytes: FESN, Cccounter, Signature Description: Authorize to Vehicle Inhibit. ASIL: B (meets E2E req) Cloud signed: YES	



45	LS_OTAM_TO_V SC_RunStartCtrl	CloudVeh CtlData_T p_Rq - Event Only TP	Domain: 269 bytes Byte1: 0x00 (Vehicle De- Inhibit) Byte 2-269 bytes: FESN, Cccounter, Signature Description: Authorize to Vehicle De- Inhibit. ASIL: B (meets E2E req) Cloud signed: YES	
46	LS_VIC_TO_VS C_ISPR_Fdbk	VehOn_D _RqCld	Periodicity: 200ms FP Domain: 2 bits 0b00 – Null, 0b01 – Off, 0b10 – On, 0b11 – Not used ASIL: B Cloud signed: NO	



47	LS_VIC_TO_VS C_ISPR_Fdbk		OtaActv_ D_Stat	Periodicity: 200ms FP Domain: 4 bits (State encoded) 0x00 - NoInVehicleOta 0x01- Interruptible_AB 0x02 - NonInterruptible _AB 0x03 - NonInterruptible _ER 0x04 - NonInterruptible Config 0x05 - NonInterruptible _Pending 0x06 - NonInterruptible _KeyDist 0x07 to 0x0F - NotUsed Description: ECG sets appropriate state value based on OTA Manager state machine. ASIL: B Cloud signed: NO	
----	-----------------------------	--	--------------------	--	--



48	LS_VIC_TO_VS C_ISPR_Fdbk		VehOnRq str_D_Stat	Periodicity: 200ms FP Domain: 4 bits (State encoded) 0x00 - NoRequestor 0x01- OverTheAir 0x02 - StolenVehInhbt 0x03 - FleetVehInhbt 0x04 to 0x0F - NotUsed Description: ECG sets appropriate state value based on Feature requesting for RunStart Bus Control ASIL: B Cloud signed: NO Dependability Signals: VehOnDRqCld_ No_Crc VehOnDRqCld_ No_Cnt	
----	-----------------------------	--	-----------------------	---	--



49	LS_VSC_TO_OT AM_RunStartCtrl _Status		VehOnSrc 2_D_Stat	Domain: 4 bits 0x00 – Off 0x01 – Manual 0x02 – RemoteStart 0x03 – RemoteParkAssi st 0x04 – OverTheAir 0x05 – 0xF – NotUsed Description: BCM sets state based on feature for which RunStart Bus control was offered and being offered. ASIL: B Cloud signed: NO Dependability Signals: CrnkInhbt2_No_ Cnt CrnkInhbt_No_C rc	
----	--	--	----------------------	---	--



50	LS_VSC_TO_OT AM_RunStartCtrl _Status		VehOnCtl _D_Stat	Domain: 2 bits 0x00 – NULL 0x01 – Off 0x02 – On 0x03 – Not Used Description: BCM broadcasts commanded state of the Run/Start bus so ECG can verify it is being requested on. ASIL: B Cloud signed: NO Dependability Signals: CrnkInhbt2_No_ Cnt CrnkInhbt_No_C rc	
----	--	--	---------------------	--	--



LS_OTAM_TO_V SC_VehInhbt_Re q CloudVeh CtlData_T p_Rq Event Only TP	Domain: 270 bytes Byte1: 0x01 (Vehicle Inhibit) Byte 2-269 bytes: FESN, Cccounter, Signature Description: Authorize to Vehicle Inhibit. ASIL: B (meets E2E req) Cloud signed: YES
--	--



52	LS_OTAM_TO_V SC_VehDeInhbt_ Req	CloudVeh CtlData_T p_Rq Event Only TP	Domain: 270 bytes Byte1: 0x00 (Vehicle De- Inhibit) Byte 2-269 bytes: FESN, Cccounter, Signature Description: Authorize to Vehicle De- Inhibit. ASIL: B (meets E2E req) Cloud signed: YES	
53	LS_VSC_TO_OT AM_VehInhbt_Re s	CloudVeh CtlData_T p_Res - Event Only TP	Postive response (3 bytes): 0x81,echo CP & Requestor Negative reponse (2 bytes): 0x7F, NRC ASIL: QM Cloud signed: NO	



54	LS_VSC_TO_OT AM_VehInhbt_Re s	VehStrtInh bt_D_Stat - 200ms FP	Domain: 1 bit (0b0 – No Inhibit,0b1 – Inhibit) Description: Value set to 0b1- Inhibit – Vehicle Inhibited due to CAVC ASIL: B Cloud signed: NO Counter:VehOn DRqCld_No_Cnt CRC: VehOnDRqCld_ No_Crc	
55	LS_VSC_TO_OT AM_VehDeInhbt_ Res	CloudVeh CtlData_T p_Res - Event Only TP	Postive response (3 bytes): 0x80,echo CP & Requestor Negative reponse(2 bytes): 0x7F, NRC ASIL: QM Cloud signed: NO	



56	LS_VSC_TO_OT AM_VehDeInhbt_ Res		VehStrtInh bt_D_Stat – 200ms FP	Domain: 1 bit (0b0 – No Inhibit,0b1 – Inhibit) Description: Value set to 0b0 - No Inhibit – "Vehicle NOT Inhibited due to CAVC" ASIL: B Cloud signed: NO Counter:VehOn DRqCld_No_Cnt CRC: VehOnDRqCld_ No_Crc	
----	---------------------------------------	--	--	---	--



57	LS_VSC_TO_VI C_CrankInhibit	CrnkInhbt _B_Stat - - 60ms FP	Domain: 1 bit 0b0 – No Inhibit 0b1 – Inhibit Description: No Inhibit – No Crank Inhibit due to ESCL OR OTA. Inhibit – Crank Inhibit due to ESCL OR OTA. ASIL: B Cloud signed: NO	
58	LS_VIC_TO_VS C_ISPR_Fdbk	PtlgnSwtc h_D_Stat 100ms EP	Domain: 2 bits Off, On, No data exists and Faulty ASIL: B Cloud signed: NO Counter: PtlgnSwtch_No_ Cnt CRC/CS: PtlgnSwtch_No_ Cs	



59	LS_OTAM_TO_V SC_GlblClk_Actl	1000ms EP GlblClkYr _No_Actl GlblClkHr _No_Actl GlblClkDa y_No_Actl GlblClkMn te_No_Act I GlblClkSc nd_No_Ac tl	Description: BCM broadcasts global clock	
60	LS_OTAM_TO_V SC_InhbtGlblClk _Req	1000ms EP InhbtGlbIC IkYr_No_ Rq InhbtGlbIC IkHr_No_ Rq InhbtGlbIC IkDay_No _Rq InhbtGlbIC IkMnte_N o_Rq InhbtGlbIC IkScnd_N o_Rq InhbtGlbIC IkScnd_B _Rq	Description: ECG requests to set global clock	
61	LS_ECG_TO_BC M_OnDemandRe quest	BattULoC hrg_D_Rq Ota	0x0 No request (don't initiate on account OTA request - default) 0x1 Request for charging	



					1
62	LS_BCM_TO_EC G_Energy_Transf er_Request		BattULoC hrgHyb_B _Rq	0x0 No_Request 0x1 Request_Energy _Transfer	
63	LS_HPCM_TO_E CG_Energy_Tran sfer_Status		ULoBattTr ansfer_D_ Stat	0x0 No_Transfer 0x1 Transfer_in_Pro gress 0x2 Insufficient_Ener gy_To_Transfer 0x3 Transfer_Throug h_Grid_Energy 0x4 Transfer_Compl ete 0x5 Transfer_Error	
64	LS_OTAM_APP_ Update_DOWN	Value{ 01 – App_Name}			APP name, such as Navigation
65	LS_OTAM_APP_ UPDATE_Timer	Value{xx Minutes}			APP shut down time
66	LS_ASUHMI_AP P_DOWN	Value {0- False 1-True}			APP Shut down Consent



67	LS_SVS_OTAM_ Active	Value{ True or false}		Stolen vehicle service
68	LS_OTAM_Preco ndition_unknown _Error	Value { True False }		"Unknown reason" when it is not in \$ D04F
69	LS_OTAM_HMI_ Remote_Consent	Value{ 00 - ASU Setting On/OFF 01 - One-time Consent 02 - Additional Consent 03 - PII Consent }		OTAM shall set this flag when it receives remote consent changes and notify HMI.
70	LS_OTAM_HMI_ Remote_Notificati on	Value{ 00 – Default 01 – Notification On/Off}		OTAM shall set this flag when it receives remote notification settings change and notify HMI.
71	LS_OTAM_HMI_ Schedule_Chang es	Value{ 00 – Clear the schedule 01 – Update day/time }		OTAM shall set this flag when it receives remote schedule and notify HMI.



72	LS_OTAM_HMI_ ClearHMIsPromp ts	Value { 00 – Service tool 01 – OTA cancel trigger 02 – Clear failures ICONs by service tool }		Update is cancelled
73	LS_OTAM_Cone nctionType_WiFi	Value{ 00 - True 01 - False}		
74	LS_OTAM_SW_ Download_Pause _Reason	Values{ 01 – USB Update, 02 – Master Reset, 03 - eCall, 04 – Loadshed, 05 – no connectivity 06 – unknown, 07 – none }		If LS_OTAM_SW_Download _State = pause, send reason
75	LS_OTAM_downl oad_progress_pe rcentage	Value {percentage}		Software is downloading over Wi-Fi

Table 10: Signal / Parameter Mapping



5 Feature Implementation Modeling

All interaction/sequence diagrams in this section are for illustration purpose only. They are not requirements. Purpose of these diagrams are meant to be used as example.

5.1 Component Interaction Diagrams

Scenario: "ECG updating TCU via USB"




Figure 3: Flowchart of ECG Updating TCU via USB



5.1.1 Scenario: "ECG updating itself via USB"




Figure 4: Flowchart of ECG Updating itself via USB

STEP1: VehicleState = INHIBIT | NO_INHIBIT

STEP2: ActivationType= LOCAL, AUTH_CMD,NOAUTH_CMD

LOCAL = On the power up of the ECU, the new software will be activated

Or, we can say on successful completion of the installation the activation will occur

AUTH_CMD = ECG will provide an authorized command based on the OTA Signed Cmds

NOAUTH_CMD = ECG will provide a command for activation ubut it is not authorized from the cloud (TCU or SYNC)



5.1.2 Scenario: "Sync updating itself via USB"





Figure 5: Flowchart of Sync Updating itself via USB



5.1.3 Scenario: "Update of TCU, Sync and ECG via USB"



The Activation process shall follow the manifestns. The activation for all the three ECUs could happen during the next ignition cycle.

Figure 6: Flowchart of Sync, TCU and ECG update via USB



5.1.4 Scenario: "Update of Sync via OTA"









Figure 7: Flowchart of Sync Updating itself via OTA



5.1.5 Scenario: "Update Sync via TCU On Ignition On Engine Running"





Document Owner: Tummepalli, Amareswar (atummepa) GIS1 Item Number:

GIS2 Classification:

Page 58 of 127

Date Issued: 09-Apr-2020 10:26 Date Revised: 24-Jul-2020 11:32

Copyright © 2020, Ford Motor Company



Figure 8: Update Sync Via TCU On Ignition On Engine Running



5.1.6 Scenario: "Update SYNC via External WIFI On Key Off"








Figure 9: Update SYNC via External WIFI on Key Off



5.1.7 Scenario: "Update SYNC via TCU on Key Off"









Figure 11: Update SYNC via TCU on Key Off



5.1.8 Scenario: "Update ECG via TCU on Key Off"





GIS2 Classification:




Figure 12: Update ECG via TCU on Key Off



5.1.9 Scenario: "Update ECG via SYNC on Key Off"





GIS1 Item Number: GIS2 Classification:

Date Issued: 09-Apr-2020 10:26 Date Revised: 24-Jul-2020 11:32



Figure 13: Update ECG via SYNC on Key Off







Figure 14: OVTP A/B Activation Flowchart (ECG is not part of the update)





Document Owner: Tummepalli, Amareswar (atummepa)

GIS1 Item Number: GIS2 Classification: Page 73 of 127

Date Issued: 09-Apr-2020 10:26 Date Revised: 24-Jul-2020 11:32



Figure 15: ECG Activation Flowchart

5.1.10 Scenario "On Demand Charging" Request




Figure 16: "On Demand Charging" Request

5.1.11 Scenario: "Update Target ECU with one Micro Via OVTP"

5.1.11.1 Read OTA Data by Identifier




Figure 17: Read OTA Data by Identifier



5.1.11.2 Authorize Erase Memory



Figure 18: Authorize Erase Memory



5.1.11.3 Erase Memory




Figure 19: Erase Memory



5.1.11.4 Authorize Download




Figure 20: Authorize Download

5.1.11.5 Initiate Download




Figure 21: Initiate Download



5.1.11.6 Transfer Download Data




Figure 22: Transfer Download Data

5.1.11.7 Complete Download Data



Figure 23: Complete Download Data



5.1.11.8 Validate Logical Block




Figure 24: Validate Logical Block

5.1.11.9 Initiate Force Sync Counter



Figure 25: Initiate Force Sync Counter



5.1.11.10 Prepare for Activation




Figure 26: Prepare for Activation



5.1.11.11 Authorize Activation




Figure 27: Authorize Activation



5.1.11.12 Initiate Activation




Figure 28: Initiate Activation



5.1.11.13 Initiate Rollback of in-active Flash Memory




Figure 29: Initiate Rollback of in-active Flash Memory



5.1.12 Scenario: "Updating Target ECU which has two Micro Via OVTP"

5.1.12.1 Read OTA Data by Identifier for Two Micros





Figure 30: Read OTA Data by Identifier for Two Micros



5.1.12.2 Authorization for Erase Memory for Two Micros









Figure 31: Authorization for Erase Memory for Two Micros



5.1.12.3 Erase Memory for both Micros of Target ECU Over Can/CanFD:






Figure 32: Erase Memory for both Micros of Target ECU Over Can/CanFD



5.1.12.4 Erase Memory Target ECU Micro 1 over Can/Can Fd and Micro 2 Over Ethernet:






Figure 33: Erase Memory Target ECU Micro 1 over Can/Can Fd and Micro 2 Over Ethernet



5.1.12.5 Authorize Download for Both Micros of Target ECU:







Document Owner: Tummepalli, Amareswar (atummepa)

GIS1 Item Number: GIS2 Classification:

Page 90 of 127

Document ID: 547918
Date Issued: 09-Apr-2020 10:26
Date Revised: 24-Jul-2020 11:32



Figure 4: Authorize Download for Both Micros of Target ECU



5.1.12.6 Initiate Download for Both Micros of Target ECU:





Figure 35: Initiate Download for Both Micros of Target ECU



5.1.12.7 Transfer OTA Update Download to Both Micros of Target ECU






Figure 36: Transfer OTA Update Download to Both Micros of Target ECU



5.1.12.8 Complete Download for both Micros




Figure 37: Complete Download for both Micros



5.1.12.9 Validate Logical Block for both Micros through CAN/CANFD




Figure 38: Validate Logical Block for both Micros through CAN/CANFD



5.1.12.10 Validation of Logical Block for Micro1 Via Can/CanFd and Micro2 Over Ethernet




Figure 39: Validation of Logical Block for Micro1 Via Can/CanFd and Micro2 Over Ethernet



5.1.12.11 Initiate Force Sync Counter for Both Micros




Figure 40: Initiate Force Sync Counter for Both Micros



5.1.12.12 Prepare for Activation for Both Micros








Figure 41: Prepare for Activation for both Micros

5.1.12.13 Authorize Activation for both Micros





Figure 42: Authorize Activation for both Micros



5.1.12.14 Initiate Activation for both Micros





Document Owner: Tummepalli, Amareswar (atummepa)

GIS1 Item Number: GIS2 Classification:

Page 102 of 127

Decument D: 547918

Date Issued: 09-Apr-2020 10:26

Date Revised: 24-Jul-2020 11:32



Figure 43: Initiate Activation for both Micros

5.1.12.15 Initiate RollBack for both Micros




Figure 44: Initiate RollBack for both Micros



5.1.13 DC Configuration Scenario: "Change Parameter Over The Air"




Figure 5: DC Configuration Scenario: "Change Parameter Over The Air"



5.1.14 REQ-365946/B-OTA Update during vehicle in transport mode








Figure 6: OTA Update during vehicle in transport mode

5.2 Component Interface Behavior Diagrams



6 Feature Implementation Requirements

6.1 Requirements Derivation Diagram

6.2 Requirements

6.2.1 Requirements on Electrical Components


6.2.1.1 Hardware Variants

6.2.1.1.1 FRD-REQ-308073/A-###R_CMP_IVSU_V_00035### Hardware Variant Review

Each component can evaluate the hardware variants and choose the one that fits best in their overall system architecture. However, if a new variant is introduced than it shall be reviewed with CVS IVSU Team for approval and addition in the approved list.

6.2.1.1.2 OTA Architecture Type 1 - Hardware Facilitated Address Remapping

With this approach, activation of a partition involves remapping the active and inactive memory address spaces. This is normally achieved in hardware through the writing of a register or user configuration block.



High Level Requirements:

- Hardware assisted memory remapping
- 2x internal flash to support storage of both A & B memory
- · Read-while-write capability to internal flash


General flow comments

In initiateActivation, the ECU shall execute the necessary actions (example: writes register/UCB) to perform the memory remapping and resets. This assumes the SWash calculation provided in the authorizeActivation request already verified is still valid.

6.2.1.1.3 OTA Architecture Type 2 – Memory Caching Option 1

With this approach, the new software is downloaded in the background into an allocated external memory area. Prior to activation of the new software, the currently active application is backed up into external memory and the new software is then copied into the active internal memory by the bootloader.





High Level Requirements:


• 2x external flash to support storage of both A & B memory

General flow comments

- 1. Prepare for activation The ECU will erase external flash and copy active application into external flash (in case it is needed for rollback). In case of failure during activation, the ECU shall be able to rollback using the OTA Active Backup copy automatically without the need for rollback FID.
- 2. Perform activation and reset The ECU will erase internal flash and copy the new software from external flash into internal flash. This assumes the SWash calculations match both in the OTA Inactive Map prior to beginning the erase and copy, and also the SWash calculations match in the Active App after copying prior to activation.

6.2.1.1.4 OTA Architecture Type 3 - Memory Caching Option 2

With this approach, the new software is downloaded in the background into an allocated internal memory area. Prior to activation of the new software, the currently active application is backed up into a dedicated backup location in either internal or external memory and the new software is then copied from the inactive internal partition to the active internal partition by the bootloader. The position independent code issue is addressed since the software is always running from the same memory address.



High Level Requirements

- 3x memory to support storage of both A & B memory along with backup
- Read-while-write capability to internal flash
- down time required to copy the internal memory to internal




General flow comments

- 1. Prepare for activation The ECU will erase the backup memory area and copy active application into this area in case of rollback
- 2. Perform activation and reset The ECU will erase internal flash and copy the new software from the inactive partition of internal flash to the active partition of internal flash. This assumes the SWash calculations match both in the Inactive Partition prior to beginning the erase and copy.

6.2.1.1.5 OTA Architecture Type 4 - Execute from RAM

With this approach, the software is compiled to run from a fixed location in RAM. On startup, a lookup table is used to determine which partition is copied into RAM. The position independent code issue is addressed since the software is always running from the same memory address (in RAM).



High Level Requirements

- 2x memory to support storage of both A & B memory along with backup
- Sufficient RAM to execute the application
- on microcontrollers with sufficient RAM, but often only a viable option for system on a chip configurations

General flow comments

1. Perform activation and reset – The ECU will update the lookup table and resets. This assumes the SWash calculation provided in the activation request matches prior to updating lookup table and resetting.

6.2.1.2 Component

6.2.2 Requirements on Electrical Distribution System (EDS)

6.2.2.1 FRD-REQ-308067/B-###R CMP IVSU V 00055### Electrical Load Architecture

Current and future Vehicle architectures shall provide options to reduce current draw for various OTA activities

(For example: Background programming during Key Off, File download from cloud during Key off) For example: In FNV2 architecture, If ECG downloads file from cloud via TCU, only HS4 shall kept awake for this purpose.



6.2.2.2 FRD-REQ-308070/B-###R_CMP_IVSU_V_00058### Programming NON A/B PAAT ECU on Kev OFF State with Run/Start bus Active

To background download to a non-powered at all-time ECU during Key OFF, the OTA client shall request the Run/Start bus to be active (Conditions shall be met first for the Run/Start bus).

6.2.2.3 FRD-REQ-308072/B-###R_CMP_IVSU_V_00060### ECU Capable of Downloading from cloud shall be awake for certain time period as per ECG request

The ECU that can download from the cloud shall be able to stay awake local for a configurable time to perform the download activity. The OTA Manager shall request the ECU to download in that mode when needed.

6.2.2.4 FRD-REQ-328062/B-###R_CMP_IVSU_V_00062### ECU that requires learning algorithm for specific process or action after an update

Any ECU that requires a learning algorithm or a specific process or action after an OTA update, shall be able to do so without any customer intervention.

6.2.2.5 FRD-REQ-362586/B-TCU shall track SOC in vehicle transport mode

Power Manager to keep track of the Battery SOC when in transitioned and during Transport mode and log timestamp (to be used for wake up time cycle), TCU wake up timer will stop once vehicle mode exit from transport mode.

6.2.2.6 FRD-REQ-362587/B-TCU to handle OTA SMS in vehicle transport mode

TCU shall be able to listen to SMS and to handle SMS for OTA update in Transport Mode if the battery SoC allows

6.2.2.7 FRD-REQ-362589/B-TCU to wake up ECG when there is a wake SMS from cloud in vehicle transport mode

TCU shall wake up ECG (HS4) if there is a wake up SMS form cloud.

6.2.2.8 FRD-REQ-365739/B-TCU/ECG shall send vehicle mode change information to cloud regardless of ignition state

ECG shall send vehicle mode change information (enter Factory Mode/Transport Mode/Normal Mode etc.,) to cloud regardless of ignition state.

6.2.2.9 REQ-365775/B-TCU shall sync SOC from BCM periodically to get accurate SOC

Power Manager shall sync SOC from BCM periodically and the period to sync shall be a configurable parameter.

Copyright © 2020, Ford Motor Company



6.2.2.10 FRD-REQ-394957/A-Routine to Cancel an Active OTA Update

The purpose of this Routine is to cancel an active OTA update (triggered) that is not yet in progress (has not yet been activated on any ECU or has begun a SWDL update of any ECU).

Request Parameters:

Name	Туре	Size	Values	Repeatable
OTA Event	ASCII	36 bytes	Identifier of an OTA	Yes: 0N
Update ID			Event Update IDs	
			to cancel	

This a list of OTA Event Update IDs to cancel. If no OTA Event Update IDs are given, then all active OTA Event Update IDs will be cancelled.

Response Parameters:

Name	Packeted	Туре	Size	Values	Repeatable
OTA Cancel Result	Cancel Result	State Encoded	1 byte	00 = Success 01 = Invalid OTA Event Update ID 02 = Unable to Cancel 03 = No OTA Event IDs Active or In Progress	Yes: 1N
	OTA Event Update ID	ASCII	36 bytes	OTA Event Update ID	

This is a list of all OTA Event Update IDs that were requested to be cancelled and the result for each of them.

- If the request was to cancel all OTA Event Update IDs (no OTA Event Update IDs given in the request) then all Active or in-progress OTA Event Update IDs are listed with their corresponding cancel result.
- If the request was to cancel all OTA Event Update IDs and there were none active or are in progress, then there shall be only one OTA Cancel Result. The OTA Event Update ID shall be zero and the Cancel Result shall be: 03 = OTA Event Update ID Active or in progress.
- If a particular OTA Event Update ID is repeated in the Routine Request (normally should not be done) then there will only be one corresponding OTA Event Update ID in the OTA Cancel Result.

Examples

Scenario: OTA Event Update IDs 1, 2, 3, and 4. 1, 2, 3 and are active and 4 is in progress **Example 1**: Request to cancel all, with above scenario

- Request Parameters: <empty>
- Response parameters -- OTA Cancel Result List
 - OTA Event Update ID: 1
 - Cancel Result: 00 0
 - OTA Event Update ID: 2
 - Cancel Result: 00
 - OTA Event Update ID: 3
 - o Cancel Result: 00
 - OTA Event Update ID: 4
 - Cancel Result: 02

Example 2: Request to cancel a specified list with an invalid OTA Event Update, with above scenario

- Request Parameters: OTA Event Update IDs 1, 3, 4, 5
- Response parameters -- OTA Cancel Result List
 - OTA Event Update ID: 1
 - Cancel Result: 00 0
 - OTA Event Update ID: 3 0
 - Cancel Result: 00
 - OTA Event Update ID: 4
 - Cancel Result: 02



OTA Event Update ID: 5

Cancel Result: 01

Example 3: Request to cancel all, with no OTA Event Update IDs active or in progress

Request Parameters: <empty

Response parameters -- OTA Cancel Result List

o OTA Event Update ID: 0

o Cancel Result: 03

6.2.2.11 FRD-REQ-394958/A-Reading DIDs in Application Default and Diagnostic sessions

All the DIDs specified in this Spec shall able to read in Application Default and extended diagnostic sessions for MMOTA needs.

6.2.2.12 FRD-REQ-394960/A-Update\Flash All ECUs regardless of Vehcile Mode

All ECU shall be updateable\flash able regardless of the vehicle mode (Factory, Transport, In plant, Normal, etc.,).

6.2.3 Requirements on DTC and DIDs

Note: Following list provides consolidated list. For details, refer to OTA server and Client documents

Name	ID	Description	Number of Bytes	Sour
In Progress OTA				OVTP C
Download Address	D022	Address of next byte to program	5 Bytes	Server
OTA Activation				OVTP C
Preconditions	D026	Precondition Status/Ignition OFF Time	2 Bytes	Server
OTA Over OVTP		Allows OTA Client to verify OTA spec		OVTP C
Support Level	D029	version	2 Bytes	Server
OTA Software				OVTP C
Update Counter	D02B	OTA client to verify ECU's value	4 Bytes	Server
OTA Debug				OVTP C
Information	D03B	OTA Update debug information	24 Bytes	Server
OTA Partition Status	D039	The intent of this DID is to provide information on the ECU partition and status. A/B ECUs would not support bits in Byte 3 (as they don't have a 3rd partition). Therefore, a non-zero value in Byte 3 then always indicates this is an "A/B/A architecture", whereas a 0x00 value in byte 3 always indicates it is an "A/B architecture"	3 Bytes	OVTP C Server Applical AB or A memoric
In-Use Cloud Authorized Vehicle Control Public Key	D034	Used to report out the public key hash	32 Rytes	BCM
Hash	D034	used as part of CAVC	32 Bytes	BCI

Page 113 of 127

Document ID: 547918 Date Issued: 09-Apr-2020 10:26 Date Revised: 24-Jul-2020 11:32

GIS2 Classification:



ı	1		1	1
	DID 0xD042 Most			
	Recent OTA Event			
	Status			
	DID 0xD043 2nd Most			
	Recent OTA Event			
	Status			
	DID 0xD044 3rd Most	This is the most recent OTA Event		
	Recent OTA Event	Status. This DID provide statuses for		
	Status	the different OTA update steps and		
	DID 0xD045 4th Most	ECUs. The OTA update steps include		
	Recent OTA Event	trigger status, download status, Data		
	Status	Configuration status, file transfer		
	DID 0xD046 5th Most Recent OTA Event	status, activation status, Rollback		
Troublesheeting OTA	Status	status and the overall update status. This DID shall be used for trouble		OVTP C
Troubleshooting OTA update	Giaius			Client
υρυαισ		shooting and diagnostic purposes This DID provide statuses for the		Cilett
		different VIL steps statuses and		
		information. The VIL steps include		
		VIL creation, VIL pause and VIL post.		
		The VIL information includes VIL		
		reason and time VIL is created. This		
Vehicle Interrogator		DID shall be used for trouble shooting		OVTP C
Log Status	0xD047	and diagnostic purposes	18 Bytes	Client
		DID D032 provides reason on why		0
		the" most recent OTA event is stuck or		
		waiting for activation and never		
		activated. The DID specifies the		
		reason why a scheduled event for		
		activation did not happen. The		
		possible reason would be if the		
		activation was cancelled by the user,		
		vehicle was in use during the		
		scheduled time and/or certain		
		preconditions were not met. These		
		reasons and preconditions can be		
Reason for Most		vehicle and/or ECU specific. This DID		
Recent OTA Event		shall be used for trouble shooting and		OVTP O
Non-Activation	0xD032	diagnostic purposes.	86 Bytes	Client
		Incompatible Vehicle Software		
		DTC: 0xD02D57 when vehicle is not		
		inhibited but in Reduce functionality		
		due to Invalid/Incompatible Software		
		Component. DTC:0xD02D53 when Vehicle is		
		Inhibited as not in drivable conditions		
		due to Invalid/Incompatible Software	SAE_J2012-	OVTP C
DTC	U102D (0XD02D)	Component.	DA_DTCFormat_00	Client
טוט	01020 (070020)	сотронени.	DA_DTGF0IIIat_00	Client



7 Open Concerns

ID	Concern Description	e-Tracker Reference	Status	Solution

Table 15: Open Concerns



8 Verification Review



Completed	appropriately	Yes / No
Input from System Design, Item Definition / Feature Document, and Functional Safety Concept (GPDS: VNV0/UPV0, GTDS: <ar>)</ar>	External Interfaces	
	Constraints	
	Technical Block Diagram	
	Functional Overview of Components/Subsystems	
	Implementation Details of Internal Interfaces	
	System Level architecture (including redundancy)	
Technical Safety Requirements Specification Technical Safety Requirements Derivation	Derivation of Technical Safety Requirements (without V&V acceptance criteria) (GPDS: UNVO/UPV0, GTDS: <ar>)</ar>	
	Definitionof Technical Safety Requirements V&V acceptance criteria (GPDS: UNV1/UPV1)	
	Derivation of Fault Tolerant Time (GPDS: UNV0/UPV0, GTDS: <ar>)</ar>	
	Derivation of Reduced Functionality (interval) (GPDS: UNV0/UPV0, GTDS: <ar>)</ar>	
	Each Technical Safety Requirement • contains all required attributes (except "V&V acceptance criteria") (GPDS: UNV0/UPV0, GTDS: <ar>)</ar>	
	Each Technical Safety Requirement is simple, atomic, verifiable, necessary, achievable, and traceable (GPDS: UNVO/UPV0, GTDS: <ar>)</ar>	
	Each Technical Safety Requirement is accepted by the component/subsystem provider (GPDS: UNVO/UPV0, GTDS: <ar>)</ar>	
	Constraints are transformed into requirements (GPDS: UNV0/UPV0, GTDS: <ar>)</ar>	
	HW Metric Requirements - Derivation and Rationale • the metric values assigned to the components fulfil the Safety Goal metric requirements. (GPDS: UNVO/UPV0, GTDS: <ar>)</ar>	
	ASIL Decomposition (Optional) (GPDS: UNV0/UPV0, GTDS: <ar>)</ar>	
	Safety Related Parameters (GPDS: UNV0/UPV0, GTDS: <ar>)</ar>	
	Requirements concerning the ability to configure a system by calibration data are defined (GPDS: UNVO/UPV0, GTDS: <ar>)</ar>	



	Each Technical Safety Requirement	
	can be verified (GPDS: UNV0/UPV0, GTDS: <ar>)</ar>	
	The Technical Safety Requirements are consistent and complete regarding the System Design, including "Response to Stimuli". (GPDS: UNVO/UPV0, GTDS: <ar>)</ar>	
	For all categories (Safety Related Function, Internal Fault Handling, External Fault Handling, Latent Fault Handling, Reduced Functionality, User Information, Maintain Safe State / Recovery, General Requirement, Decomposition Requirement) Technical Safety Requirements are derived if relevant. (GPDS: UNVO/UPVO, GTDS: <ar>)</ar>	
	Technical Safety Requirements necessary for the achievement of the Functional Safety Requirement are generated and documented. (GPDS: UNVO/UPV0, GTDS: <ar>)</ar>	
Description of other functions of the system (GPDS: UNV0/UPV0, GTDS: <ar>)</ar>		
System Design (GPDS: UNV0/UPV0, GTDS: <ar>)</ar>	Technical Safety Requirements included in the system design specification(s). Aligned with Technical Safety Requirements System Design developed in accordance with requirements related to: • System architectural design constraints • Avoidance of systematic faults • Usage of well-trusted design principles • Measures for control of random hardware failures during operation • Allocation to hardware and software • Hardware-Software Interface Specification (see guideline for "FFSD 04 Safety Requirements Specification")	
Requirements for Operation, Service and Decommissioning (GPDS: UNV0/UPV0, GTDS: <ar>)</ar>	Requirements for Operation and Service completed	
Technical Safety Requirements on Components/Subsystems (GPDS: UNV0/UPV0, GTDS: <ar>)</ar>	V&V acceptance criteria	



9 Revision History

Rev. (revision)	Vers.	Description	Approved by	Responsible
9/15/17	1.0	Requirements. This is a draft version of the specification.		
11/15/1	1.1	1- Updated the numbering and few		
7		clarifications in the Input requirement section		
•		2- updated the logical function diagram to		
		show the functions for starting and inhibitnig		
		the start of the vehicle and the display		
12/14/2	1.2	1- Flowchart for update over USB and OTA		
017		2- Added fucntions tht are common between		
		ECG and SYNC related to OTA Manager		
04/13/2	2.0	1- Modified Requirement		
018		R_CMP_IVSU_V_00002 DIDs for OTA		
		Command Signing Keys and Application		
		Signing Keys		
		2- Modified R_CMP_IVSU_V_00003 to support		
		Differential Updater for A/B or ABA methods.		
		3- Added below input requirements for ECG to		
		perform OTA Activity and OTA Run/Start		
		request.		
		1. R CMP IVSU V 00015		
		2. R_CMP_IVSU_V_00016		
		3. R_CMP_IVSU_V_00017		
		4. R_CMP_IVSU_V_00018		
		5. R_CMP_IVSU_V_00019		
		6. R_CMP_IVSU_V_00020		
		7. R_CMP_IVSU_V_00021		
		4- Added Below Electrical Distribution System		
		Requirements for Target ECU's to perform		
		OTA Activity.		
		1. R_CMP_IVSU_V_00056		
		2. R_CMP_IVSU_V_00057		
		3. R_CMP_IVSU_V_00058		
		4. R_CMP_IVSU_V_00060		
		5- Added R_CMP_IVSU_V_00059 for		
		Network Availability for OTA Activity		
		6- Updated Figure 1 Functional Architecture to		
		match with latest OTA Architecture.		
		7- Updated Figure 2: E/E Architecture, to		
		match with latest OTA Architecture		
		8- Updated the Function List Section 3.1 as per		
		new Functional Architecture.		
		9- Updated the Section 4.1.1.3 Function		
		Allocation to respective Modules		
		10- Added Section 4.1.1.4 Signal / Parameter		
		Mapping table.		
		11- Added Section 5.1.5 to 5.1.11 various		
		Scenarios for OTA update procedure for Sync,		
		TCU, ECG and all Target ECU's with single		
		micro or two micros.		
		12- Added Section 11.1 ECG DID's	1	1



Rev. (revision)	Vers.	Description	Approved by	Responsible
		13- Added 11.2.5 Implementation Guide Report. 14- updated Section 1.5 References 15- Updated Section 1.3.1 with Stack Holder list. 16- Updated Section 7 Open Concerns: deleted the earlier concerns which are not valid anymore.		
07/31/2 018	2.1.0	Updated 1.6.2 Abbrivations: Updated FESN description and added DID. Added R_CMP_IVSU_V_00022 DID for Entering in to OTA ProgrammingSession Added R_CMP_IVSU_V_00061 User start Vehicle during OTA Vehicle Inhibit Added R_CMP_IVSU_V_00062 ECU that requires learning algorithm for specific process or action after an update Modified R_CMP_IVSU_V_00025 for Capacitance Requirement Availability in case of Power OFF While OTA Update		
8/30/20 18	2.2.0	 Updated the sequences 5.1.11 5.1.12 all the scenarios as per latest reference to latest PCM sequences. Added DC configuration sequences 5.1.13 to 5.1.16 Updated section 4.1.1.4 Signal/Parameter Mapping table as per new CAVC signals. 		
8/31/20 18	2.2.1	 Updated section 4.1.1.4 Signal/Parameter Mapping table with ECG <> BCM signals. Added 5.1.11 OTA OTA On Demand Request Updated 3. Functional Architecture Updated 4.1 E/E Architecture Variant 1 		
9/4/201 8	2.2.2	Updated section 4.1.1.4 Signal/Parameter with HMI and USB signals. Updated Reference Documents		
9/11/20 18	2.2.3	1. Updated 4.1.3 Function Allocation		
1/7/201 9	2.2.4	1 Updated section 4.1.1.4 Signal/Parameter with HMI signals.		
1/8/201	3.0	Released v1.7 in the VSEM plus removed the all reference to RE template and unused sections		
4/8/201 9	4.0	Deleted R_CMP_IVSU_V_00019 Deleted R_CMP_IVSU_V_0001, R_CMP_IVSU_V_00014, R_CMP_IVSU_V_00015, R_CMP_IVSU_V_00024, R_CMP_IVSU_V_00056, R_CMP_IVSU_V_00057, R_CMP_IVSU_V_00059, R_CMP_IVSU_V_00061		



Rev. (revision)	Vers.	Description	Approved by	Responsible
		Deleted: DC Configuration Scenarios "Add New Feature Content Over The Air", "Perform Initial Configuration Over The Air", "Restore And Replace Electronic Module". Updated DC Configuration Scenario: "Change Parameter Over The Air" Updated: R_CMP_IVSU_V_00002 to R_CMP_IVSU_V_00013, FRD-REQ-308060, FRD-REQ-308061, FRD-REQ-308062, FRD-REQ-308065, FRD-REQ-324142, FRD-REQ-348263, FRD-REQ-308756, FRD-REQ-308073, FRD-REQ-308067, FRD-REQ-308070, FRD-REQ-308072, FRD-REQ-328062 Updated All the Scenarios from 5.1.1 to 5.1.10. Updated section 4.1.1.4 Signal/Parameter with HMI signals.		
8/28/20 19	4.1	Added TCU Requirement: FRD-REQ- 362586/A, FRD-REQ-362587/A, FRD-REQ- 362588/A, FRD-REQ-362589/A, FRD-REQ- 362590/A, FRD-REQ-362591/A		
3/9/202 0	4.2	Updated the DO39 and D034 DIDs in the Req 533276 Requirements on DTC and DIDs		
7/21/20 20	5.0	Added the requirements FRD-REQ-394957/A, FRD-REQ-394958/A, FRD-REQ-394960/A Updated 6.2.3 with DIDs D042 to D046, D047, D032 and DTC U102D. Added new signals from OTAM to HMI LS_OTAM_Precondition_unknown_Error LS_OTAM_HMI_Remote_Consent LS_OTAM_HMI_Remote_Notification LS_OTAM_HMI_Schedule_Changes LS_OTAM_HMI_ClearHMIsPrompts LS_OTAM_ConenctionType_WiFi		



10 Appendix

10.1 ECG DID's

DID Number (Hex)	Parameter Number	Parameter Name	Size (Bits)	State (Hex)	State Name
D03B	11	4th Most Recent OTA FID Response Type	8	000000	positiveResponse
D03B	11	4th Most Recent OTA FID Response Type	8	000010	generalReject
D03B	11	4th Most Recent OTA FID Response Type	8	000011	functionNotSupported
D03B	11	4th Most Recent OTA FID Response Type	8	000013	incorrectMessageLengthOrInvalidFormat
D03B	11	4th Most Recent OTA FID Response Type	8	000014	responseTooLong
D03B	11	4th Most Recent OTA FID Response Type	8	000015	endToEndSignatureInvalid
D03B	11	4th Most Recent OTA FID Response Type	8	000016	ESNInvalid
D03B	11	4th Most Recent OTA FID Response Type	8	000017	softwareUpdateCounterInvalid
D03B	11	4th Most Recent OTA FID Response Type	8	000021	busyRepeatRequest
D03B	11	4th Most Recent OTA FID Response Type	8	000022	conditionsNotCorrect
D03B	11	4th Most Recent OTA FID Response Type	8	000024	requestSequenceError
D03B	11	4th Most Recent OTA FID Response Type	8	000031	requestOutOfRange
D03B	11	4th Most Recent OTA FID Response Type	8	000033	securityRequired
D03B	11	4th Most Recent OTA FID Response Type	8	000070	downloadNotAccepted
D03B	11	4th Most Recent OTA FID Response Type	8	000071	transferDataSuspended
D03B	11	4th Most Recent OTA FID Response Type	8	000072	generalProgrammingFailure
D03B	11	4th Most Recent OTA FID Response Type	8	000073	wrongSequenceCounter
D03B	11	4th Most Recent OTA FID Response Type	8	000078	requestCorrectlyReceived- ResponsePending



D03B	11	4th Most Recent OTA FID Response Type	8	000079	validationFailed
D03B	11	4th Most Recent OTA FID Response Type	8	00007D	sessionMismatch
D03B	11	4th Most Recent OTA FID Response Type	8	00007F	noActiveSession
D03B	2	Most Recent OTA FID Response Type	8	000000	positiveResponse
D03B	2	Most Recent OTA FID Response Type	8	000010	generalReject
D03B	2	Most Recent OTA FID Response Type	8	000011	functionNotSupported
D03B	2	Most Recent OTA FID Response Type	8	000013	incorrectMessageLengthOrInvalidFormat
D03B	2	Most Recent OTA FID Response Type	8	000014	responseTooLong
D03B	2	Most Recent OTA FID Response Type	8	000015	endToEndSignatureInvalid
D03B	2	Most Recent OTA FID Response Type	8	000016	ESNInvalid
D03B	2	Most Recent OTA FID Response Type	8	000017	softwareUpdateCounterInvalid
D03B	2	Most Recent OTA FID Response Type	8	000021	busyRepeatRequest
D03B	2	Most Recent OTA FID Response Type	8	000022	conditionsNotCorrect
D03B	2	Most Recent OTA FID Response Type	8	000024	requestSequenceError
D03B	2	Most Recent OTA FID Response Type	8	000031	requestOutOfRange
D03B	2	Most Recent OTA FID Response Type	8	000033	securityRequired
D03B	2	Most Recent OTA FID Response Type	8	000070	downloadNotAccepted
D03B	2	Most Recent OTA FID Response Type	8	000071	transferDataSuspended
D03B	2	Most Recent OTA FID Response Type	8	000072	generalProgrammingFailure
D03B	2	Most Recent OTA FID Response Type	8	000073	wrongSequenceCounter
D03B	2	Most Recent OTA FID Response Type	8	000078	requestCorrectlyReceived- ResponsePending
D03B	2	Most Recent OTA FID Response Type	8	000079	validationFailed
D03B	2	Most Recent OTA FID Response Type	8	00007D	sessionMismatch
D03B	2	Most Recent OTA FID Response Type	8	00007F	noActiveSession
D03B	5	2nd Most Recent OTA FID Response Type	8	000000	positiveResponse
D03B	5	2nd Most Recent OTA FID Response Type	8	000010	generalReject
D03B	5	2nd Most Recent OTA FID Response Type	8	000011	functionNotSupported



D03B	5	2nd Most Recent OTA FID Response Type	8	000013	incorrectMessageLengthOrInvalidFormat
D03B	5	2nd Most Recent OTA FID Response Type	8	000014	responseTooLong
D03B	5	2nd Most Recent OTA FID Response Type	8	000015	endToEndSignatureInvalid
D03B	5	2nd Most Recent OTA FID Response Type	8	000016	ESNInvalid
D03B	5	2nd Most Recent OTA FID Response Type	8	000017	softwareUpdateCounterInvalid
D03B	5	2nd Most Recent OTA FID Response Type	8	000021	busyRepeatRequest
D03B	5	2nd Most Recent OTA FID Response Type	8	000022	conditionsNotCorrect
D03B	5	2nd Most Recent OTA FID Response Type	8	000024	requestSequenceError
D03B	5	2nd Most Recent OTA FID Response Type	8	000031	requestOutOfRange
D03B	5	2nd Most Recent OTA FID Response Type	8	000033	securityRequired
D03B	5	2nd Most Recent OTA FID Response Type	8	000070	downloadNotAccepted
D03B	5	2nd Most Recent OTA FID Response Type	8	000071	transferDataSuspended
D03B	5	2nd Most Recent OTA FID Response Type	8	000072	generalProgrammingFailure
D03B	5	2nd Most Recent OTA FID Response Type	8	000073	wrongSequenceCounter
D03B	5	2nd Most Recent OTA FID Response Type	8	000078	requestCorrectlyReceived- ResponsePending
D03B	5	2nd Most Recent OTA FID Response Type	8	000079	validationFailed
D03B	5	2nd Most Recent OTA FID Response Type	8	00007D	sessionMismatch
D03B	5	2nd Most Recent OTA FID Response Type	8	00007F	noActiveSession
D03B	8	3rd Most Recent OTA FID Response Type	8	000000	positiveResponse
D03B	8	3rd Most Recent OTA FID Response Type	8	000010	generalReject
D03B	8	3rd Most Recent OTA FID Response Type	8	000011	functionNotSupported



D03B	8	3rd Most Recent OTA FID Response Type	8	000013	incorrectMessageLengthOrInvalidFormat
D03B	8	3rd Most Recent OTA FID Response Type	8	000014	responseTooLong
D03B	8	3rd Most Recent OTA FID Response Type	8	000015	endToEndSignatureInvalid
D03B	8	3rd Most Recent OTA FID Response Type	8	000016	ESNInvalid
D03B	8	3rd Most Recent OTA FID Response Type	8	000017	softwareUpdateCounterInvalid
D03B	8	3rd Most Recent OTA FID Response Type	8	000021	busyRepeatRequest
D03B	8	3rd Most Recent OTA FID Response Type	8	000022	conditionsNotCorrect
D03B	8	3rd Most Recent OTA FID Response Type	8	000024	requestSequenceError
D03B	8	3rd Most Recent OTA FID Response Type	8	000031	requestOutOfRange
D03B	8	3rd Most Recent OTA FID Response Type	8	000033	securityRequired
D03B	8	3rd Most Recent OTA FID Response Type	8	000070	downloadNotAccepted
D03B	8	3rd Most Recent OTA FID Response Type	8	000071	transferDataSuspended
D03B	8	3rd Most Recent OTA FID Response Type	8	000072	generalProgrammingFailure
D03B	8	3rd Most Recent OTA FID Response Type	8	000073	wrongSequenceCounter
D03B	8	3rd Most Recent OTA FID Response Type	8	000078	requestCorrectlyReceived- ResponsePending
D03B	8	3rd Most Recent OTA FID Response Type	8	000079	validationFailed
D03B	8	3rd Most Recent OTA FID Response Type	8	00007D	sessionMismatch
D03B	8	3rd Most Recent OTA FID Response Type	8	00007F	noActiveSession
D03C	1	Campaign #1 Source	8	000000000000000000000000000000000000000	OTA
D03C	1	Campaign #1 Source	8	00000000000000001	USB
D03C	1	Campaign #1 Source	8	000000000000000000000000000000000000000	Vehicle
D03C	4	Campaign #2 Source	8	00000000000000000	OTA
D03C	4	Campaign #2 Source	8	00000000000000001	USB
D03C	4	Campaign #2 Source	8	000000000000000000000000000000000000000	Vehicle



D03C	7	Campaign #3 Source	8	000000000000000000000000000000000000000	ОТА
D03C	7	Campaign #3 Source	8	00000000000000001	USB
D03C	7	Campaign #3 Source	8	000000000000000000002	Vehicle
D03C	10	Campaign #4 Source	8	00000000000000000	ОТА
D03C	10	Campaign #4 Source	8	00000000000000001	USB
D03C	10	Campaign #4 Source	8	000000000000000000002	Vehicle

10.2 Data Dictionary

10.2.1 Logical Signals

#Macro: Add Ins -> Add Requirement macro (select "Logical Signal" as type)

10.2.2 Logical Parameters

#Macro: Add Ins -> Add Requirement macro (select "Logical Parameter" as type)

10.2.3 Technical Signals

#Macro: Add Ins -> Add Requirement macro (select "Technical Signal" as type) #Hint:This section lists all GSDB + GDT + SW signals relevant for the feature deployment. Additionally to the he basic attributes, it shall capture the detailed requirements of a signal, such as:

10.2.4 Technical Parameters

#Macro: Add Ins -> Add Requirement macro (select "Technical Parameter" as type) **#Hint:**This section lists all Method 2, Method 3 and calibration parameters relevant for the feature deployment.

10.2.5 Data Types

Implementation Guide Report					SYNC	тси	Replace Ecus	ВСМ	PCM	Cluster
Requirement ID	Feature/Function/Requirment/Use Case	Comments	OVTP	ECG	SY)_	Erase & Re	B(Ğ	Clu
FRD-REQ- 308047	DIDs for OTA Command Signing Keys and Application Signing Keys		х							
FRD-REQ- 308048	Differential Updater		х	х	х	Х				
FRD-REQ- 308049	Number of Software Updates		х	х	х	х	х			



FRD-REQ-	Temporary Vehicle Storage for Software		x	x					
308050	Files		<u> </u>	—	<u> </u>		<u> </u>	—	<u> </u>
FRD-REQ-		x	х	х	х				
308052	Maximum ECU Activation Time		<u> </u>	↓	 	-	<u> </u>	↓	<u> </u>
FRD-REQ-		x	х	x	х				
308053	Component Hardware Review		<u> </u>	<u> </u>	<u> </u>		<u> </u>	<u> </u>	<u> </u>
FRD-REQ-		x	х	x	х				
308054	Downloading in background		<u> </u>	—	<u> </u>	-	<u> </u>	↓	<u> </u>
FRD-REQ-		x	х	x	х	x			
308055	Software Signing		<u> </u>	<u> </u>	<u> </u>	<u> </u>	<u> </u>	<u> </u>	<u> </u>
FRD-REQ-			x				x	x	х
308056	Vehicle Inhibit			<u> </u>				<u> </u>	
FRD-REQ-		x	x	x	x	x	x	x	х
308057	Preserve Data			ļ.,		<u> </u>		<u> ^` </u>	
FRD-REQ-									
308058	Configuration Data								<u> </u>
ı	ECUs that can download files from								
FRD-REQ-	Cloud/USB shall be capable to have local		х	Х					
308060	wake up/stay awake								
FRD-REQ-	OTA Client shall not request the OTA								
308061	Run/Start active if ignition_status <> Off		Х						
- <u>-</u> -	OTA Client shall NOT start any OTA			†					
FRD-REQ-	Activity if it receives a load shedding		х						
308062	signal.								
	OTA Client shall NOT initiate or process			†	†			†	
FRD-REQ-	any OTA activity when Battery is in		х						
308065	critical condition								
FRD-REQ-	DID for Entering in to OTA				†				
324142	ProgrammingSession	Х	Х	Х	Х	Х	Х	Х	Х
FRD-REQ-	1 1 2 3 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2			 					
348263	Self Install ECU during Load shed		Х	Х	Х				
FRD-REQ-				 					
308756	Capacitance Requirement Availability in case of Power Off While OTA Update	Х	Х	Х	Х				
FRD-REQ-	Case of Fower off write of A opuate		 	+-			1	\vdash	
308073	Hardware Variant Review								
FRD-REQ-	Taluwale valialit neview		+	+-	 	T	┼	 	
308067	Electrical Load Architecture	х	х	х	х				х
			-	\vdash	+	-	 	┼	
FRD-REQ-	Programming NON A/B PAAT ECU on Key	х							
308070	OFF State with Run/Start Bus Active		<u> </u>	<u> </u>			<u> </u>	↓	<u> </u>
1	ECU Capable of Downloading from cloud								
FRD-REQ-	shall be awake for certain timer period		х	Х					
308072	as per ECG request								
FRD-REQ-	ECU that requires learning algorithm for	х	х	Х	х	x	x	x	х
328062	specific process or action after an update	^	^	^	^	^	^	_^_	

Table 16: Implementation Guide Report