U554_收音机

交互设计文档

版本:

v1.3

修订日期:

2020.2.3

设计师:

黄锐豪

	Image wasn't loaded		Image wasn't loaded		Image wasn't loaded	Image wasn't loaded			Image wasn't loaded			Image wasn't loaded	Image wasn't loaded	Image wasn't loaded	Image wasn't loaded					
)=:)-:):)=:]=:)-:):)-:)-:	je:)÷)÷	
	7																4			
Image wasn't loaded		Image wasn't loaded		Image wasn't loaded	Image wasn't loaded			Image wasn't loaded			Image wasn't loaded	Image wasn't loaded	Image wasn't loaded	Image wasn't loaded						
):):):):):)-:):)-:)-:)-:)-:)=)÷	
																		1		
																	,	-		

1	版本更新	01
2	FM收音机	02
3	AM收音机.	 03

版本更新

时间	版本	需求作者	交互设计	更新记录
2020.1.16	v1.0	福特HMI	黄锐豪	follow_P702横屏功能适配到林肯车型
2020.1.17	v1.1	福特HMI	黄锐豪	优化布局_follow_P702横屏收音机
2020.2.1	v1.2	福特HMI	黄锐豪	收藏列表里列表项增加可点击的收藏按钮
2020.2.3	v1.3	福特HMI	黄锐豪	增加AM模块的完整交互

无效频率时toast提示,3秒消失,界面仍停留在手动输入界面。

无效的频率

02

是否有效频率

无效的频率

→返回收音机主页并播放当前有效频率

无效频率时toast提示,3秒消失,界面仍停留在手动输入界面。

03

