1. Since chip DRV8835 is temporarily out-of-stock, we used chip TB6612 of the same quality. Therefore, in the following course, you will need to select the programs corresponding to different chips depending on the type of driver chip on the specific board.



As you can see in the picture above, it is chip TB6612 (or may be chip DRV8835), we need to choose one of the two options in the program folder to use according to different chip types:

