## Curvature sensor test object



Figure 1 - Test object for 3D printing.




Figure 2 - Test object dimensions (mm).




Figure 3 - 3D printing orientation.