

Parts Substitution Approval Request

Required for any drive, motor, gearbox, controller, or safety device not listed on the Approved Parts List for the applicable baseline revision.

Read before completing. Clause 3.2 qualifies a substitute component only where Cobalt Ridge Engineering issued written qualification **before the component was placed in service**. A supplier calling a component “equivalent” or “form-fit-function” does not make it an approved part. A form submitted after installation records the substitution for review; it does not qualify the component retroactively.

SECTION A · REQUEST AND ASSET

REQUEST NUMBER PSR-2026-0338	DATE OF THIS REQUEST 20 April 2026	RELATED WARRANTY CASE WR-2026-0417
CUSTOMER Northstar Retail Distribution	SITE Joliet DC · Line 3 / Induct	ASSET SERIAL CRA-SR440-2113-0087
EQUIPMENT Sortation Line SR-440	CONFIGURATION BASELINE CR-SR440-3.2 (controls set 2025.11)	REQUESTED BY T. Okafor, Maintenance Supervisor
SUBMITTING PARTY Customer · on behalf of Meridian Industrial Services (third party)		CONTACT t.okafor@northstar-rd.example · +1 815 555 0147

SECTION B · COMPONENT SUBSTITUTED

Position	Approved component	Component installed
Main sort drive	CR-DRV-4410-B (Rev B) s/n 4410B-22781 · on Approved Parts List CR-SR440-3.2	Altek AD-5500-HD s/n AD55-91043 · not listed
DATE PLACED IN SERVICE 6 April 2026	INSTALLED BY Meridian Industrial Services, W/O MIS-44182	COMPONENT COST \$11,480.00
REASON SUBSTITUTION WAS MADE OEM unit quoted at three weeks; customer unable to hold the line down through peak season.		PRIOR WRITTEN QUALIFICATION ON FILE None

SECTION C · BASIS OF EQUIVALENCE CLAIMED

☒ Same rated horsepower	☒ Same supply voltage and phase
☐ Same frame and mounting pattern	☐ Same thermal derating curve
☐ Same control interface and firmware profile	☐ Same safety certification and category
☐ Supplier equivalence certificate attached	☐ OEM test fixture used for commissioning
SUPPORTING DOCUMENTS ATTACHED Meridian work order MIS-44182. Altek datasheet not supplied.	SUPPLIER EQUIVALENCE STATEMENT Verbal, per Meridian lead technician. Not provided in writing.

SECTION D · INSTALLATION IMPACT

Mechanical. Frame and mounting pattern differ from the approved component. A 6 mm adapter plate was fabricated on site to seat the unit. The assembly fits within the existing guard envelope. The unit is not a drop-in replacement.

Controls. The substitute drive would not hold the released acceleration profile. The following parameters were changed from the baseline to keep the line running:

Parameter	Baseline	Set to	Reason given
ACCEL_RAMP_MS	420	610	Reduce inrush on start
CURRENT_LIM_PCT	115	135	Prevent nuisance trip at divert
THERM_CUTBACK_C	68	82	Substitute unit runs warmer by spec

Run-in performed at operating speed for 90 minutes. Full OEM commissioning test sequence was not performed; the OEM test fixture and the current baseline document were not available to the installing party.

SECTION E · REQUESTER DECLARATION

I confirm the information above is complete and accurate, that the component described was placed in service on the date stated, and that no written qualification for it was held at that time.

SIGNATURE · REQUESTER

DATE

PRINT NAME AND TITLE

COMPANY

SECTION F · COBALT RIDGE ENGINEERING DETERMINATION — DO NOT COMPLETE

☐ Qualified as equivalent

☐ Qualified with conditions

☐ Not qualified

DETERMINATION DATE

EFFECTIVE FROM

BASELINE REVISION ISSUED

CONDITIONS, REQUIRED TESTING, OR REASON FOR REFUSAL

SIGNATURE · COBALT RIDGE ENGINEERING

DATE

Route the completed form to warranty.engineering@cobaltridge.example. A determination under Section F does not of itself reinstate coverage on a claim already open; coverage is assessed against clauses 3.1, 3.2, and 3.3 as at the date the component was placed in service.