

# Typhoon OpenDSS 0.5.1

## Release Notes

Compatible with Typhoon HIL Control Center 2025.2

- Improvements/bugfixes:
  - Generator stability improvements and fixes to the incorrect power and voltage units in the mask description of the Generator Controller.
  - Load mask bugfixes in transition between load types.
  - Fixed Vsource container.
  - Updated handling of time series inputs on the SimDSS component.
  - Added property to change meter's snubbers on the Monitor component.
  - Co-simulation Widget Library Improvements.
  - PVSystem mask issue fixed.
  - Improvements on Examples documentation.
  - Temporary workaround on internal variable types of the VSource (due to the new numpy version used on THCC 2025.2)
- Added Examples:
  - EPC Power CHIL Interface using container component.