


The sample or the laser beam path probably moved yesterday. This morning the slit wasn't hit perfectly.

Today, the system was very stable: Elastic line at 0 after each measurement, Stokes frequency (solid lines) = anti-Stokes frequency (dashed lines)






We cannot reproduce the strong effect we saw yesterday. It may have been due to an incorrect temperature calculation due to a shifted frequency axis



We cannot reproduce the strong effect we saw yesterday. It may have been due to an incorrect temperature calculation due to a shifted frequency axis



Backgrounds at different currents, it looks like there is no change in this Raman shift range

