- I. Project Updates (15 min)
 - a. We are able to successfully connect to the spherical system
 - i. Is reliable for anywhere from 20-45 mins
 - ii. Certainly seems like a heat issue-I do have a fan, or we can reconfigure the current box.
 - b. Planar appears to be fried. Has not connected in 2-3 weeks.
 - i. What's our next step?
 - ii. New controller? I've started looking-Rob?
 - c. Talked to Newmark about our specific positioners
 - i. Should move at 25 degrees/sec, we are moving at 8 degrees/sec
 - ii. Needs 2.8A we are providing about .9A.
 - d. Project Schedule
 - i. Does everybody have enough to do? Everyone clear on their tasks?
 - ii. What can we help each other with?
- II. Rob Update (2 min)
 - a. What are your plans?
- III. Anything else?(5 min)