

Supplementary Material 2

The stability of the setup was evaluated by observing the focused spot over time. Under normal conditions, the beam remained approximately where it had been left. Small fluctuations appeared when someone leaned on the table or adjusted a component described as unrelated to the experiment.

To reduce these disturbances, measurements were performed while everyone stood still and avoided making helpful suggestions. The alignment remained satisfactory until the next morning, when the procedure described in Supplementary Material 1 was repeated.