Release Notes for AT32F413 Firmware Library Drivers

V2.0.5-2024/12/13

- 1. Updated CAN driver.
- 2. Updated Flash driver.
- 3. Updated some notes.

V2.0.4-2024/08/08

- 1. Updated "i2c flag clear" and "i2c init" functions.
- 2. Updated some notes.

V2.0.3-2024/01/05

- 1. Fixed IAR7.4 compilation warning issue of some drivers.
- 2. Updated some function notes.

V2.0.2-2023/10/26

- 1. Added the function interrupt_flag_get to each of the IP sections
- 2. Optimized system clock switching procedure

V2.0.1-2023/08/04

- 1. Added CRC polynomial support
- 2. Added *flash_spim_dummy_read* and *flash_spim_mass_program* to Flash
- 3. Updated the process of adc ordinary channel set and adc preempt channel set
- 4. Updated relevant notes

V2.0.0-2022/11/18

1. The CRM_HICK48_NODIV is considered the default setting when HICK is used as PLL clock source