

A mechanic is applying torque to a bolt using a d m wrench. The mechanic is applying F N at Degrees from the wrench. What is the magnitude of the moment on the bolt?

Moments M=(Fsin0)(1) F, to M