


Warehouse gate-course flight



1 ROS · 50 Hz passes G1 (2.0s)







2 ROS · 50 Hz crashes (9.0s)




3 XPU-RT · 100 Hz at G3 (7.3s)



4 XPU-RT · 100 Hz reaches G4 (10.2s)



(b) Control-command rate — why the flight completes or crashes



The schedule's worst-case control response sets the command rate; below the ~65 Hz cliff (Fig. 3 companion) the course is unflyable. Established co-design numbers (4.89 / 12.40 ms).