

Plot 7 — why adaptation failed: under every protective rung the risk signal is flat across  $B = 1..4$ , so the selector cannot tell 65% load from 131%

