




## 7. Pet Robot



## Pet Robot



1




X 1



X 1



X 1




2



X 1




X 1



3



X 2



4




X 2




DC Shaft X 2



X 2



5




Note the position of motor cables.

6



(S) X 2



7




X 1




X 1



8




9



10




(S) X 2



11




(S) X 1




12



(L) X 1




13




**Check again the position of bolts.**

14



15



(L) X



X




16



X 1




18



17




X 2




19



X 1




20




21

Screw (S) X 1




22




23

IR-PTR X 3



Finish





## Part List

