

Fleet Maintenance Report

Company: Gulf Coast Logistics Services **Report Date:** June 27, 2025
Fleet ID: GCLS-HOU-FLT-01 **Prepared By:** Fleet Maintenance Department

Vehicle Information

Field	Details
Vehicle ID	TRK-2134
License Plate	TX-1BF-5569
Make / Model	International LT Series
Year	2021
VIN	3HSDJAPR6MN789012
Engine Type	Cummins X15
Odometer Reading	163,880 miles
Assigned Route	Gulf Coast Long Haul
Primary Driver	F. Wilson

Maintenance Summary

Service Type: Preventive Maintenance (PM-B) – 160,000 Mile Interval
Service Location: Houston Fleet Maintenance Facility
Work Order #: WO-2025-06-2134
Service Date: June 25, 2025
Technician: M. Davis (ASE Certified)

Inspection Checklist

Engine & Powertrain

- ✓ Engine oil level checked – within spec
- Engine oil & filter replaced
- Fuel filters replaced (primary & secondary)
- ✓ Coolant level inspected – topped off 0.2 gal
- Accessory belt showing cracking – replace within 20,000 miles

Transmission

- ✓ Fluid level checked – normal
- ✓ No abnormal noise or vibration

Braking System

- Front brake pads at 40% remaining – schedule replacement within 20,000 miles
- ✓ Rear brake pads at 58% remaining
- ✓ Air brake system pressure test – passed

Suspension & Steering

- ✓ Steering linkage inspected – no play
- ✓ Shock absorbers within spec
- Left rear leaf spring bushing worn – replace at next service

Tires

Position	Tread Depth	Condition
Steer Axle L	7/32"	Even wear
Steer Axle R	6/32"	Minor center wear
Drive Axles	9/32" avg	Good

Tire pressure adjusted to manufacturer specification (110 PSI steer, 100 PSI drive)

Electrical System

- ✓ Battery voltage: 12.7V (resting)
- ✓ Alternator output within range
- Replaced faulty turn signal relay

Safety & Compliance

- ✓ DOT inspection completed
- ✓ Fire extinguisher certified
- ✓ Emergency triangles present
- ✓ ELD system operational

Diagnostic Scan Results

- No active engine fault codes
- Historical fault code: Boost pressure fault (resolved)
- Emissions system functioning normally

Parts Replaced

Part	Part Number	Qty
Engine Oil Filter	CUM-X15-FLT	1
Fuel Filter Kit	FF-CX15-KIT	1
15W-40 Synthetic Oil (gal)	OIL-1540-SYN	12
Turn Signal Relay	TSR-INT-STD	1

Labor Summary

Task	Hours
Preventive Maintenance Service	4.0
Brake Inspection	1.0
Electrical Repair	0.5
Diagnostic Scan	0.5
Total Labor Hours	6.0 hrs

Cost Summary

Category	Cost
Parts	\$892.00
Labor	\$690.00
Shop Supplies	\$55.00
Total Service Cost	\$1,637.00

Upcoming Recommended Maintenance

Item	Recommended At
Accessory Belt Replacement	180,000 miles
Front Brake Pad Replacement	180,000 miles
Leaf Spring Bushing (LR)	175,000 miles
Annual DOT Inspection	June 2026

Vehicle Status

Current Condition:	Roadworthy
Released to Service:	June 26, 2025
Next Scheduled Maintenance:	175,000 miles or 90 days (whichever occurs first)