

Fleet Maintenance Report

Company: Gulf Coast Logistics Services
Fleet ID: GCLS-HOU-FLT-01
Report Date: March 3, 2026
Prepared By: Fleet Maintenance Department

Vehicle Information

Field	Details
Vehicle ID	TRK-2147
License Plate	TX-8FJ-3921
Make / Model	Freightliner Cascadia 126
Year	2021
VIN	3AKJGLDR5MSMG1234
Engine Type	Detroit DD15
Odometer Reading	187,452 miles
Assigned Route	Houston Regional Distribution
Primary Driver	J. Martinez

Maintenance Summary

Service Type: Preventive Maintenance (PM-B) – 180,000 Mile Interval
Service Location: Houston Fleet Maintenance Facility
Work Order #: WO-2026-03-2147
Service Date: March 1, 2026
Technician: R. Thompson (ASE Certified)

Inspection Checklist

Engine & Powertrain

-  Engine oil level checked – within spec

-  Engine oil & filter replaced
-  Fuel filters replaced (primary & secondary)
-  Coolant level inspected – topped off 0.5 gal
-  Minor oil seepage detected at valve cover gasket (monitor next interval)

Transmission

-  Fluid level checked – normal
-  No abnormal noise or vibration

Braking System

-  Front brake pads at 35% remaining – schedule replacement within 15,000 miles
-  Rear brake pads at 60% remaining
-  Air brake system pressure test – passed

Suspension & Steering

-  Steering linkage inspected – no play
-  Right front shock absorber showing wear – recommend replacement within 10,000 miles
-  Leaf springs and bushings intact

Tires

Position	Tread Depth	Condition
Steer Axle L	7/32"	Even wear
Steer Axle R	6/32"	Slight outer edge wear
Drive Axles	10/32" avg	Good

- Tire pressure adjusted to manufacturer specification (110 PSI steer, 100 PSI drive)

Electrical System

-  Battery voltage: 12.7V (resting)
-  Alternator output within range
-  Replaced marker light (rear left)

Safety & Compliance

-  DOT inspection completed
-  Fire extinguisher certified
-  Emergency triangles present
-  ELD system operational

Diagnostic Scan Results

- No active engine fault codes
- Historical fault code: Low DEF level (resolved)
- Emissions system functioning normally

Parts Replaced

Part	Part Number	Qty
Engine Oil Filter	FL-8892	1
Fuel Filter Kit	FF-DET15-KIT	1
15W-40 Synthetic Oil (gal)	OIL-1540-SYN	10
Marker Light Assembly	ML-RED-TRK	1

Labor Summary

Task	Hours
Preventive Maintenance Service	4.0
Brake Inspection	1.0
Electrical Repair	0.5
Diagnostic Scan	0.5
Total Labor Hours	6.0 hrs

Cost Summary

Category	Cost
Parts	\$842.50
Labor	\$690.00
Shop Supplies	\$55.00
Total Service Cost	\$1,587.50

Upcoming Recommended Maintenance

Item	Recommended At
Front Brake Pad Replacement	200,000 miles
Shock Absorber Replacement (RF)	195,000 miles
PM-C Service (Major)	240,000 miles
Annual DOT Inspection	February 2027

Vehicle Status

Current Condition: Roadworthy

Released to Service: March 2, 2026

Next Scheduled Maintenance: 195,000 miles or 90 days (whichever occurs first)

If you'd like, I can also generate:

- A **more technical version** (with telematics data and predictive analytics indicators),
- A **simplified executive summary version** for management,
- Or a **JSON version** suitable for ingestion into a fleet analytics system.