

Fleet Maintenance Report

Company: Gulf Coast Logistics Services **Report Date:** October 3, 2025
Fleet ID: GCLS-HOU-FLT-01 **Prepared By:** Fleet Maintenance Department

Vehicle Information

Field	Details
Vehicle ID	TRK-2112
License Plate	TX-8NP-7756
Make / Model	Freightliner Cascadia 126
Year	2020
VIN	3AKJGLDR4LSMG5678
Engine Type	Detroit DD15
Odometer Reading	254,990 miles
Assigned Route	Houston Regional Distribution
Primary Driver	I. Gonzalez

Maintenance Summary

Service Type: Preventive Maintenance (PM-C) – 250,000 Mile Interval
Service Location: Houston Fleet Maintenance Facility
Work Order #: WO-2025-10-2112
Service Date: October 1, 2025
Technician: M. Davis (ASE Certified)

Inspection Checklist

Engine & Powertrain

- ✓ Engine oil level checked – within spec
- Engine oil & filter replaced
- Fuel filters replaced (primary & secondary)
- ✓ Coolant level inspected – topped off 0.4 gal
- Minor carbon buildup on EGR – cleaning performed

Transmission

- Transmission fluid replaced
- ✓ No abnormal noise or vibration

Braking System

- Front brake pads at 38% remaining – schedule replacement within 15,000 miles
- ✓ Rear brake pads at 55% remaining
- ✓ Air brake system pressure test – passed

Suspension & Steering

- ✓ Steering linkage inspected – no play
- Right rear shock absorber worn – replacement recommended within 15,000 miles
- ✓ Leaf springs intact

Tires

Position	Tread Depth	Condition
Steer Axle L	6/32"	Even wear
Steer Axle R	6/32"	Even wear
Drive Axles	8/32" avg	Good

Tire pressure adjusted to manufacturer specification (110 PSI steer, 100 PSI drive)

Electrical System

- ✓ Battery voltage: 12.7V (resting)
- ✓ Alternator output within range

Safety & Compliance

- ✓ DOT inspection completed
- ✓ Fire extinguisher certified
- ✓ Emergency triangles present
- ✓ ELD system operational

Diagnostic Scan Results

- No active engine fault codes
- Historical codes: DPF regen required, EGR fault (both resolved)
- Emissions system functioning normally

Parts Replaced

Part	Part Number	Qty
Engine Oil Filter	FL-8892	1
Fuel Filter Kit	FF-DET15-KIT	1
15W-40 Synthetic Oil (gal)	OIL-1540-SYN	10
Transmission Fluid (qt)	TF-FRT-DT12	8

Labor Summary

Task	Hours
Preventive Maintenance Service	4.5
Brake Inspection	1.0
Transmission Service	1.0
Diagnostic Scan	0.5
Total Labor Hours	7.0 hrs

Cost Summary

Category	Cost
Parts	\$1,023.00
Labor	\$805.00
Shop Supplies	\$65.00
Total Service Cost	\$1,893.00

Upcoming Recommended Maintenance

Item	Recommended At
Front Brake Pad Replacement	267,000 miles
Right Rear Shock Absorber	268,000 miles
PM-D Service	300,000 miles
Annual DOT Inspection	October 2026

Vehicle Status

Current Condition:	Roadworthy
Released to Service:	October 2, 2025
Next Scheduled Maintenance:	265,000 miles or 90 days (whichever occurs first)