

# Fleet Maintenance Report

**Company:** Gulf Coast Logistics Services    **Report Date:** May 16, 2025  
**Fleet ID:** GCLS-HOU-FLT-01    **Prepared By:** Fleet Maintenance Department

## Vehicle Information

| Field            | Details                       |
|------------------|-------------------------------|
| Vehicle ID       | TRK-2198                      |
| License Plate    | TX-7TW-9031                   |
| Make / Model     | Freightliner Cascadia 126     |
| Year             | 2024                          |
| VIN              | 3AKJGLDR8RSMG7890             |
| Engine Type      | Detroit DD15                  |
| Odometer Reading | 41,220 miles                  |
| Assigned Route   | Houston Regional Distribution |
| Primary Driver   | E. Lopez                      |

## Maintenance Summary

**Service Type:** Preventive Maintenance (PM-A) – 40,000 Mile Interval  
**Service Location:** Houston Fleet Maintenance Facility  
**Work Order #:** WO-2025-05-2198  
**Service Date:** May 14, 2025  
**Technician:** S. Patel (ASE Certified)

## Inspection Checklist

### Engine & Powertrain

- ✓ Engine oil level checked – within spec
- Engine oil & filter replaced
- ✓ Fuel filters inspected – no replacement needed
- ✓ Coolant level inspected – OK

### Transmission

- ✓ Fluid level checked – normal
- ✓ No abnormal noise or vibration

### Braking System

- ✓ Front brake pads at 88% remaining
- ✓ Rear brake pads at 90% remaining
- ✓ Air brake system pressure test – passed

### Suspension & Steering

- ✓ Steering linkage inspected – no play

- ✓ Shock absorbers like new
- ✓ Leaf springs and bushings intact

Tires

| Position     | Tread Depth | Condition |
|--------------|-------------|-----------|
| Steer Axle L | 13/32"      | Like new  |
| Steer Axle R | 13/32"      | Like new  |
| Drive Axles  | 14/32" avg  | Like new  |

Tire pressure adjusted to manufacturer specification (110 PSI steer, 100 PSI drive)

Electrical System

- ✓ Battery voltage: 12.9V (resting)
- ✓ Alternator output within range

Safety & Compliance

- ✓ DOT inspection completed
- ✓ Fire extinguisher certified
- ✓ Emergency triangles present
- ✓ ELD system operational

Diagnostic Scan Results

- No active engine fault codes
- Emissions system functioning normally

Parts Replaced

| Part                       | Part Number  | Qty |
|----------------------------|--------------|-----|
| Engine Oil Filter          | FL-8892      | 1   |
| 15W-40 Synthetic Oil (gal) | OIL-1540-SYN | 10  |

Labor Summary

| Task                           | Hours   |
|--------------------------------|---------|
| Preventive Maintenance Service | 2.5     |
| Diagnostic Scan                | 0.5     |
| Total Labor Hours              | 3.0 hrs |

Cost Summary

| Category      | Cost     |
|---------------|----------|
| Parts         | \$398.00 |
| Labor         | \$345.00 |
| Shop Supplies | \$30.00  |

|                           |                 |
|---------------------------|-----------------|
| <b>Total Service Cost</b> | <b>\$773.00</b> |
|---------------------------|-----------------|

Upcoming Recommended Maintenance

| Item                    | Recommended At |
|-------------------------|----------------|
| Fuel Filter Replacement | 60,000 miles   |
| PM-B Service            | 75,000 miles   |
| Annual DOT Inspection   | May 2026       |

Vehicle Status

|                                    |                                                  |
|------------------------------------|--------------------------------------------------|
| <b>Current Condition:</b>          | Roadworthy                                       |
| <b>Released to Service:</b>        | May 15, 2025                                     |
| <b>Next Scheduled Maintenance:</b> | 55,000 miles or 90 days (whichever occurs first) |