

SOURCE COORDINATE TEST - PAGE 1

Section HM-8.1 - Fan inspection

1. Stop the equipment before inspection.
2. Inspect the fan belt.

SOURCE COORDINATE TEST - PAGE 2

Section HM-8.1 - Pump inspection

1. Verify the isolation procedure.
2. Inspect the pump seal.