

INFORMATION

UNCLASSIFIED

PRIORITY

1009

25 MAR 67 1321z

24 Mar 67

Belt, Montana

FTD-

PTTU JAW RUWTFHA6257 0841255-UUUU--RUEDFIA.

ZNR UUUUU ZFH-1 RUWTFHA

DE RUCSBB 165 0841225

ZNR UUUUU

P 251224Z MAR 67

FM 341SNW MALMSTROM

TO RUWRNLS/ADC ENT

RUWMBQA/28 AD MALMSTROM

RUEDFIA/FTD WRIGHT PATTERSON

RUEDHQA/CSAF WASHINGTON

RUEDHQA/OSAF WASHINGTON

BT

UNCLAS ZIPPO 2414 MAR 67/SUBJ: PRELIMINARY UFO REPORT.

FTD FOR TDETR, CSAF FOR AFREC, OSAF FOR SAF-OI.

BETWEEN THE HOURS 2100 AND 0400 MST NUMEROUS REPORTS

WERE RECEIVED BY MALMSTROM AFB AGENCIES OF UFO SIGHTINGS

IN THE GREAT FALLS, MONTANA AREA.

REPORTS OF A UFO LANDING NEAR BELT, MONTANA WERE RECEIVED

FROM SEVERAL SOURCES INCLUDING DEPUTIES OF CASCADE COUNTY

SHERIFF'S OFFICE. INVESTIGATION IS BEING CONDUCTED BY

LT COL LEWIS CHASE PHONE: DUTY EXT 2215, HOME 452-1135

3-ETR

056

UNCLASSIFIED

PRIORITY

UNCLASSIFIED

PRIORITY

BASE OPERATIONS OFFICER. THE ALLEGED LANDING SITE IS
UNDER SURVEILLANCE, HOWEVER DAYLIGHT IS REQUIRED FOR
FURTHER SEARCH

056

PAGE 2 RUCSBS 165 UNCLAS

SHERIFF'S OFFICE WILL CONDUCT A LAND SEARCH AND A HELICOPTER
FROM MALNSTRON AFB WILL CONDUCT THE AIR SEARCH. FOLLOW-UP
REPORT WILL BE SUBMITTED AS DETAILS BECOME AVAILABLE.

BT

NNNN#

UNCLASSIFIED

PRIORITY

15 JAN RUCSAAAG196: 070015-SSSS--RUWNBOA.

NY SSSSS

P 172250Z MAR 67

FM SAC

TO RUWNBOA/OOAMA HILL. AFB IFAH

INFO RUWBNNA/15AF

RUWNBOA/3415MW MALMSTROM AFB, NEB

RUWNBOA/AFFRO BOEING CO, SEATTLE WASH

RUWJABA/BSD WORTON AFB CALIF

BT

SECRET DM 02752 MAR 67.

ACTION: OOAMA (COMNET, OONE-COL, DAVENPORT). INFO: 15AF (DM4C), 3415MW (DCND, BOEING AFFRO (D.J. DOWNEY, MINUTEMAN ENGINEERING) BSD (LSS, BSOR)

SUBJECT: LOSS OF STRATEGIC ALERT, ECNC FLIGHT, MALSTROM AFB. (U)

REF: MY SECRET MESSAGE DM72 02751, 17 MAR 67, SAME SUBJECT.

ALL TEN MISSILES IN ECNC FLIGHT AT MALMSTROM LOST STRAT ALERT WITHIN TEN SECONDS OF EACH OTHER. THIS INCIDENT OCCURRED AT 0845L ON 16 MARCH 67. AS OF THIS DATE, ASS MISSILES HAVE BEEN RETURNED TO STRAT

PAGE 2 RUCSAAAG196 SECRET

ALERT WITH NO APPARENT DIFFICULTY. INVESTIGATION AS TO THE CAUSE OF THE INCIDENT IS BEING CONDUCTED BY MALMSTROM TEST. TWO FITTS HAVE BEEN RUN THROUGH TWO MISSILES THUS FAR. NO CONCLUSIONS HAVE BEEN DRAWN. THERE ARE INDICATIONS THAT BOTH COMPUTERS IN BOTH G&C'S WERE UPSET MOMENTARILY. CAUSE OF THE UPSET IS NOT KNOWN AT THIS TIME. ALL OTHER SIGNIFICANT INFORMATION AT THIS TIME IS CONTAINED IN ABOVE REFERENCED MESSAGE.

FOR OOAMA: THE FACT THAT NO APPARENT REASON FOR THE LOSS OF TEN MISSILES CAN BE READILY IDENTIFIED IS CAUSE FOR GRAVE CONCERN TO THIS HEADQUARTERS. WE MUST HAVE AN IN-DEPTH ANALYSIS TO DETERMINE CAUSE AND CORRECTIVE ACTION AND WE MUST KNOW AS QUICKLY AS POSSIBLE WHAT THE IMPACT IS TO THE FLEET, IF ANY. REQUEST YOUR RESPONSE BE IN KEEPING WITH THE URGENCY OF THE PROBLEM. WE IN TURN WILL PROVIDE OUR FULL COOPERATION AND SUPPORT.

FOR OOAMA AND 15AF WE HAVE CONCURRED IN A BOEING REQUEST TO SEND TWO ENGINEERS, MR. R.E. RIGERT AND MR. W. M. DUTTON TO MALMSTROM TO COLLECT FIRST HAND KNOWLEDGE OF THE PROBLEM FOR POSSIBLE ASSISTANCE IN LATER ANALYSIS. REQUEST COOPERATION OF ALL CONCERNED TO PROVIDE THEM ACCESS TO AVAILABLE INFORMATION, I.E., CREW COMMANDERS LOG ENTRIES, MAINTENANCE FORMS, INTERROGATION OF KNOWLEDGEABLE PEOPLE, ETC.

PAGE 3 RUCSAAAG196 SECRET

SECURITY CLEARANCES AND DATE AND TIME OF ARRIVAL WILL BE SENT FROM THE AFFRO BY SEPARATE MESSAGE.

FOR 15AF. OOAMA HAS INDICATED BY TELECON THAT THEY ARE SENDING ADDITIONAL ENGINEERING SUPPORT. REQUEST YOUR COOPERATION TO INSURE MAXIMUM RESULTS ARE OBTAINED FROM THIS EFFORT. GP74. BCASMC-67-437

BT

DECLASSIFIED

IAW EO 12958 BY EORT

Date: 16 JAN 1996

Reviewer: [signature]

~~SECRET~~

GROUP-4

DOWNGRADED AT 3 YEAR INTERVALS:
DECLASSIFIED AFTER 12 YEARS

THIS DOCUMENT RETAINS IT ORIGINAL
CLASSIFICATION. THE ONLY PORTION
OF THIS DOCUMENT CONSIDERED
DECLASSIFIED ~~ON 10-15-2010 BY 6032~~
PAGES: ~~10~~ *this* **REF**

DECLASSIFIED

ED 11652

RUCCSAAAG196
1113 JAN 11KSDHAR196 070515-0000-10000000

ANY SSSSS

P 17225Z MAR 67

FM SAC

TO RUWMBBA/COAMA HOLL. AFB DEAR

INFO RUWMBBA/15AF

RUWMBBA/3415NW MALMSTRON AFB. ROM

RUWMBBA/AFPRO DOWNING DOOR AT THE WASH

RUWJABA/BSO WATSON AFB GLEAF

BT

S E C R E T DT 02752-0000 070

ACTION: COAMA (DENCY/0000-001. DANEM 0000. INFO: 15AF

(DNAC), 3415NW (DND), BOEING AFPRO (D.C. DOWNING, MINUTEMAN

ENGINEERING) REF 1655, 1655

SUBJECT: LOSS OF STRATEGIC ALERT, ECHO FLIGHT, MALMSTRON
AFB. (U)

? → ALL TEN MISSILES IN ECHO FLIGHT AT MALMSTRON LOST STRAT ALERT WITHIN
TEN SECONDS OF EACH OTHER. THIS INCIDENT OCCURRED AT 0845L ON
16 MARCH 67. AS OF THIS DATE, ASS MISSILES HAVE BEEN RETURNED TO STRAT

PAGE 2 RUCCSAAAG196 S E C R E T
ALERT WITH NO APPARENT DIFFICULTY. INVESTIGATION AS TO THE CAUSE OF THE
INCIDENT IS BEING CONDUCTED BY MALMSTRON TEST. TWO FITTS HAVE
BEEN RUN THROUGH TWO MISSILES THIS FAR. NO CONCLUSIONS HAVE BEEN
DRAWN. THERE ARE INDICATIONS THAT BOTH COMPUTERS IN BOTH G&C'S
WERE UPSET MOMENTARILY. CAUSE OF THE UPSET IS NOT KNOWN AT THIS
TIME. ALL OTHER SIGNIFICANT INFORMATION AT THIS TIME IS CONTAINED IN
ABOVE REFERENCED MESSAGE.

FOR COAMA. THE FACT THAT NO APPARENT REASON FOR THE LOSS OF TEN
MISSILES CAN BE READILY IDENTIFIED IS CAUSE FOR GRAVE CONCERN TO THIS
HEADQUARTERS. WE MUST HAVE AN IN-DEPTH ANALYSIS TO DETERMINE CAUSE
AND CORRECTIVE ACTION AND WE MUST KNOW AS QUICKLY AS POSSIBLE WHAT
THE IMPACT IS TO THE FLEET, IF ANY. REQUEST YOUR RESPONSE BE IN KEEP-
ING WITH THE URGENCY OF THE PROBLEM. WE IN TURN WILL PROVIDE OUR
FULL COOPERATION AND SUPPORT.

FOR COAMA AND 15AF WE HAVE CONCURRED IN A BOEING REQUEST TO SEND
TWO ENGINEERS. MR. R.E. RYCKERT AND MR. W. M. DUTTON TO MALMSTRON
TO COLLECT FIRST HAND KNOWLEDGE OF THE PROBLEM FOR POSSIBLE ASSISTANCE
IN LATER ANALYSIS. REQUEST COOPERATION OF ALL CONCERNED TO PROVIDE
THEM ACCESS TO AVAILABLE INFORMATION, I.E., CREW COMMANDERS LOG
ENTRIES, MAINTENANCE FORMS, INTERVIEW OF KNOWLEDGEABLE PEOPLE, ETC.

PAGE 3 RUCCSAAAG196 S E C R E T
SECURITY CLEARANCES AND DATE AND TIME OF ARRIVAL WILL BE SENT FROM
THE AFPRO BY SEPARATE MESSAGE.

FOR 15AF. COAMA HAS INDICATED BY TELECON THAT THEY ARE SENDING
ADDITIONAL ENGINEERING SUPPORT. REQUEST YOUR COOPERATION TO INSURE
MAXIMUM RESULTS ARE OBTAINED FROM THIS EFFORT. 0714, 1100-0000-67-4/8
BT

DECLASSIFIED

ED 11652