

INDEX

|       |                                                                 |
|-------|-----------------------------------------------------------------|
| Tab 1 | Index                                                           |
| Tab 2 | Chronology of Events                                            |
| Tab 3 | Transcription                                                   |
| Tab 4 | Flight Path Chart                                               |
| Tab 5 | Personnel Statements                                            |
| Tab 6 | Daily Record of Facility Operations,<br>FAA Form 7230-4         |
| Tab 7 | Position Logs, FAA Form 7230-10                                 |
| Tab 8 | ZAN EARTS Continuous Data Recordings,<br>(radar tracking data). |

**DRAFT**

The following is a chronological summary of the alleged aircraft sightings by Japan Airlines Flight 1628, on November 18, 1986:

All times listed are approximate UTC unless otherwise specified.

- 0219 - The pilot of JLL1628 requested traffic information from the ZAN Sector 15 controller. When the controller advised there was no traffic in the vicinity, JLL1628 responded that they had same direction traffic, approximately 1 mile in front, and it appeared to be at their altitude. When queried about any identifiable markings, the pilot responded that they could only see white and yellow strobes.
- 0225 - JLL1628 informed ZAN that the traffic was now visible on their radar, in their 11 o'clock position at 8 miles.
- \* 0226 - ZAN contacted the Military Regional Operations Control Center, (ROCC), and asked if they were receiving any radar returns near the position of JLL1628. The ZAN controller advised that he had a primary target in the aircraft's 11 o'clock position eight miles. The ROCC advised that they were receiving a primary radar return in JLL1628's 10 o'clock position same range (eight miles).
- 0227 - The ROCC contacted ZAN to advise they were no longer receiving any radar returns in the vicinity of JLL1628.
- 0231 - JLL1628 advised that the "plane" was "quite big", at which time the ZAN controller approved any course deviations needed to avoid the traffic.
- 0232 - JLL1628 requested and received a descent from FL350 to FL310. When asked if the traffic was descending also, the pilot stated it was descending "in formation".
- 0235 - JLL1628 requested and received a heading change to two one zero. The aircraft was now in the vicinity of Fairbanks and ZAN contacted Fairbanks Approach Control asking if they had any radar returns near JLL1628's position. The Fairbanks Controller advised they did not.
- 0236 - JLL1628 was issued a 360 degree turn and asked to inform ZAN if the traffic stayed with them.
- 0238 - The ROCC called ZAN advising they had confirmed a "flight of two" in JLL1628's position. They advised they had some "other equipment watching this", and one was a primary target only.
- 0239 - JLL1628 told ZAN they no longer had the traffic in sight.
- \* 0242 - The ROCC advised it looked as though the traffic had dropped back and to the left of JLL1628, however, they were no longer tracking it.
- 0244 - JLL1628 advised the traffic was now at 9 o'clock
- 0245 - ZAN issued a 10 degree turn to a northbound United Airlines flight, after pilot concurrence, in an attempt to confirm the traffic.
- 0248 - JLL1628 told ZAN the traffic was now at 7 o'clock, 8 miles.

0250 - The northbound United Flight advised they had the Japan Airlines flight in sight, against a light background, and could not see any other traffic.

0253 - JL1628 advised they no longer had contact with the traffic.

A subsequent review of ANC ARTCC's radar tracking data failed to confirm any targets in close proximity to JL1628.

\* These portions were revised from the original summary, following further review of the voice recordings.

**DRAFT**

# FLIGHT PATH CHART

## JAPAN AIRLINES FLIGHT 1628

November 18, 1986

R-2205

### LEGEND

 NORMAL RETURNS

 UNPLOTTED NORMAL RETURNS FOR CLARITY

 PRIMARY/SECONDARY SPLIT RETURNS

 SECONDARY SPLIT RETURNS

 PRIMARY SPLIT RETURNS

 NORTHBOUND UNITED AIRLINE FLIGHT

 MURPHY DOME RADAR SITE

CHART PREPARED BY

MANFRED F. KELLER

46 AUTOMATION SPECIAL

AND

ANTHONY M. WYLIE

QUALITY ASSURANCE

ANCHORAGE ARTCC

DELTA JUNCTION

AT DJN

REMININGTON (P-V)

1250-18

1262

DELTA AIRMOTIVE

1190-24

Joins Anchorage

R-2202 A & D  
R-2202 G


146°

FSS  
ALLEN AAF  
1277 L75

30'

(P-V)


DELTA AIRMOTIVE



DRAFT









pg. 4


51

56

47







DRAFT

