$\mathbf{x}_0^{\mathcal{C}} = [0.000, 0.000, 0.000, 0.000, 0.000, 0.000, 1.000]$ and $\mathbf{x}_1^{\mathcal{C}} = [0.600, 0.600, 0.050, -0.183, -0.183, 0.000, 0.966]$

