MAE 6245 (Spring 2020)

Robotic Systems

Assignment #3 Solutions

32 Points


- 1) State True or False for the following:
 - a) Configuration space for any manipulator is unique.
 - b) There are 12 basic parameters characterizing a link (also called link parameters).
 - c) Parallel robots are the way to go for high reachability.
 - d) Each joint can physically have only one joint variable associated with it.
 - e) Joint variables are always angles.

[5 points]

Solution

	a)	Falses Y drods delay substant		
	6)	False		
	c)	False	* ,	
1	d)	Fahe		
	e)	False		
	,			

2) For the manipulator shown here, do the following:




- a) Derive the link parameters (to find the transformation from wrist to base frame).
- b) In MATLAB, First create a function to determine the transformation matrix (T_i^{i-1}) based on the values of the 4 link parameters. First create a function to determine the

- transformation matrix (T_i^{i-1}) based on the values of the 4 link parameters (you can use the same function developed in class for the simple manipulator).
- c) Use this function to calculate all matrices required to go from tool frame to base frame. [Try to do this in a recursive fashion by writing a script that calls the function automatically multiple times, for different values of link parameters.] [Assume L1 = 10m, L2 = 10m, L3 = 0m, and $\theta_1 = 45^\circ$, $\theta_2 = 30^\circ$, $\theta_3 = -30^\circ$, or any arbitrary values for angles are also acceptable].
- d) Use this further to create a function to find the end effector position for given joint angles [Hint: End effector position is only the translational part of the homogeneous matrix].
- e) Plot the workspace for the robot, for $\theta_1 \in [0^\circ, 90^\circ]$, $\theta_2 \in [0^\circ, 90^\circ]$, $\theta_3 \in [-45^\circ, 45^\circ]$.
- f) For a particular configuration, $\theta_1=45^\circ$, $\theta_2=30^\circ$, $\theta_3=-30^\circ$ plot the robot links. [Hint: It doesn't have to be a fancy plot. Just find the end points of each link and join them with lines. You can use "plot3" command in MATLAB, and use the option "LineWidth" to control the thickness of the line. Or use the "quiver" command used before, or use anything of choice]

[15 points]

Solution

	1916	INTO ICE		.000		00	1 1		
							= T.	R	¥3
		0		0		0 1		· · · · · · · · · · · · · · · · · · ·	11/2
	Attach	ham	ei v	a di	Z. 1	SIL!	7	6/10/	3/ L2 3
	Attach	rately	and	7	ZI 1	10	a la company		2 Militar
	and	linh	parame	ten	The	3	> Li	Meak	Z.
		en Ends	olinae II	gar Ta	F OT	。 _ X	6 9 _	18	
	. bb	i	« Xi	a,	di	0:		2	1.3 .4
الماد	Baca	(Q + 6.5	80	100	0	0.			
de d	gomes.	9	90°	L	0	02	-	10 m	Toppot-
		3	0	L3	0	02			71
	0.000	1-010	Corner of		12.7	H we be		n.	lain.
	3, 2	21 2 ₁	00,	-50,	- ()	0		
	(0 T =	50.	c0,	int a	OUTAL	0	Ge	/ a
		1	0	0	V	1	0		
			0	0	i San	0	N I A	an)	6
	×	. 20	1			3	_		
	Ti di	1 Duris	C 0,	-50	. Ato	09	and h	7	16
		T=	0	0	81 12	1	0		
	2		50,	co,		0 ~	0		
		, , , , , , , , , , , , , , , , , , ,	0	0	F :	O	8 1 2		
				1				7	



The code could be as follows:

c) The results are:

T =

T =


T =

d) The final homogeneous matrix is:

End Effector Position:


$$x = 13.19$$
, $y = 13.19$, $z = 5$

e) The plot looks like the following:




3) Imagine an arm like the PUMA 560, except that joint 3 is replaced with a prismatic joint (Note that PUMA 560 is discussed in one of the examples in the textbook). Assume the prismatic joint slides along the direction of X_1 in the figure. However, there is still an offset equivalent to d_3 to be accounted for. Make any additional assumptions needed. Derive the kinematic equations.

[10 points]



Solution



		i.	2	di.	ai	- 3.6	di	46	turp	0;	1219	1/1	
		Ì	T	0	0	a E	0		1	9,		1	
		2		- 90°	0		dz			02			v
i o		0 3		900	100	9)	and 3	11	- 1	80°	helder!	2	
U	À	4		0	az	- 8	di		الهنزر	Dy	w JE		
,QJ	as.	5	N	900	0	den to	0	Ŷ	19	95	atarih		,
V		6		-90°	0	, AT	0	31	WS.	06	as to		
1	10	2 an	35	nod K	Migh	10)	w .	7	- 1	N	Nu 2		
				00,	-50,	0	0	0	9 5/1	144	ιθ ₂ -	502	0 0
10		OT		50,	c0,	0	0	1	1.	T = 1	0	0	1 d2
17				0	0	1	0	1	1 4	48.)	-502	C O2	0 0
hi	A	an I	Q	1400	0	6	1		13/	o logali	0	0	0 1
			V DA	w Salmer A	lo-a	èla	0-0	i A	- 1	l po	s te		<u> </u>
1	2	Car	-	1 0	O	0		3	120	coy	-50	0	az
	2	3 =	(0	-1	-d3	,		75	504	c0	4 0	0
4		1338	(0 -1	0	0		2	1/97	0	O	1	dy
				0 0	0	I		p.C		0	0	O	
		Fred	F		K	4	7		17				
	1.		ce	- 50	. 0	0	7	-	1 0	co6	-506	U	0
	4	T=	0	0	-1	0	15	5.	T=	0	0	1	0
-		25,	58	5 w	0	C	8			-506	006	0	0
			0	()	0	29	1			0	0	0	1

CULTANIA - II INDMINIATELY 91/42/40
1 1 1 2 2 1 2 Pa
: OT = ry wary man has I Py let have
Asial Ray Markage Proposition
0 0 0
- Forward Kinematics - & 15+5+5+
+ where + (0+(0)) = 10 = 10
$r_{11} = -c\theta_{1}c\theta_{2}c\theta_{3}c\theta_{6} + c\theta_{1}c\theta_{2}s\theta_{4}s\theta_{6} + s\theta_{1}s\theta_{3}c\theta_{5}c\theta_{6}$
+30, c0460, + c0, s0, s0, s0,
$x_{12} = c\theta_{1}c\theta_{2}c\theta_{4}c\theta_{5}s\theta_{6} + c\theta_{1}c\theta_{2}s\theta_{4}c\theta_{6} - s\theta_{1}s\theta_{2}c\theta_{5}s\theta_{6}$
+ 50, E04 C06 - 50, 50, 50, 50,
$h_{13} = c\theta_1 c\theta_2 c\theta_4 s\theta_5 - s\theta_1 s\theta_4 s\theta_5 + c\theta_1 s\theta_2 c\theta_5$
$h_{21} = -50, c\theta_{2}c\theta_{3}c\theta_{5}c\theta_{6} + 50, c\theta_{2}s\theta_{4}s\theta_{6} - c\theta_{1}s\theta_{4}c\theta_{5}c\theta_{6}$
-c0, e0, s0, + s0, s0, s0, c0,
22 = 50, cd, cd, cd, cd, s0, cd, s0, cd, t0, s0, cd, s0,
- c0, c0, c0, - s0, s0, s0, s0,
23 = 50,002004505 + 00,504505 + 50,502005
231 = 502 c 0y c 05 c 06 - 502 5 04 5 06 + c 02 505 € 06
$r_{32} = -50_{2}c0_{4}c0_{5}s0_{6} - 50_{2}s0_{4}c0_{6} - c0_{2}s0_{5}s0_{6}$
$233 = -5\theta_2 c\theta_1 c\theta_2 + c\theta_2 c\theta_5$
$P_{2} = -d_{2}s\theta_{1} + (d_{3}+d_{4})c\theta_{1}s\theta_{2} - a_{3}c\theta_{1}c\theta_{2}$
$P_{y} = d_{2}c\theta_{1} + (d_{3} + d_{4}) s\theta_{1} s\theta_{2} - a_{3} s\theta_{1}c\theta_{2}$
$P_{z}^{y} = \left(d_{3} + d_{4}\right) c \theta_{2} + a_{3} s \theta_{2}$
of while (do of a to of) to the series