

The Foliage Extracting Tele-Controlled Helicopter (F.E.T.C.H.): Hardware Errata

[4/30/2013]

Authors:
Kora Barnes
Elliot Dickison
Cable Johnson
Eric Johnston
Brian Lee
Theora Rice

University of Idaho Moscow, ID 83844-1010

Part	Specific Part	Description	Reason	Date Added	Added by
PIC32	PORTE, BIT_1	Shorted Pin	Overloaded the voltage	4/30/2013	Theora Rice
PIC32	PORTB, BIT_12	Shorted Pin	Manufacture Error	4/30/2013	Theora Rice