



# Naturally prepared failure modes — no bounded process map run

## PR pinchoff v1



## PR regularization damage v1



## surface coarsening only v1

