





'/OCT29/data_storage3/demount_2700V_x-12239_y-64239_board2.txt' (0.34 eff)









'/OCT29/data_storage3/demount_2700V_x-211717_y152689_board2.txt' (0.05 eff)







'/OCT29/data_storage3/demount_2700V_x-221277_y135269_board2.txt' (0.14 eff)




'/OCT29/data_storage3/demount_2700V_x-22386_y-135745_board2.txt' (0.32 eff)




'/OCT29/data_storage3/demount_2700V_x-225618_y127139_board2.txt' (0.08 eff)




'/OCT29/data_storage3/demount_2700V_x-22583_y-127020_board2.txt' (0.30 eff)




'/OCT29/data_storage3/demount_2700V_x-22794_y-117714_board2.txt' (0.33 eff)





'/OCT29/data_storage3/demount_2700V_x-22978_y-109572_board2.txt' (0.32 eff)







'/OCT29/data_storage3/demount_2700V_x-231769_y119015_board2.txt' (0.15 eff)










'/OCT29/data_storage3/demount_2700V_x-23702_y-77583_board2.txt' (0.24 eff)







'/OCT29/data_storage3/demount_2700V_x-23899_y-68858_board2.txt' (0.24 eff)







'/OCT29/data_storage3/demount_2700V_x-239731_y110896_board2.txt' (0.19 eff)












'/OCT29/data_storage3/demount_2700V_x-246800_y103356_board2.txt' (0.18 eff)




'/OCT29/data_storage3/demount_2700V_x-255679_y95821_board2.txt' (0.17 eff)




'/OCT29/data_storage3/demount_2700V_x-265477_y88871_board2.txt' (0.19 eff)




'/OCT29/data_storage3/demount_2700V_x-275300_y83083_board2.txt' (0.21 eff)




'/OCT29/data_storage3/demount_2700V_x-286029_y77299_board2.txt' (0.16 eff)




'/OCT29/data_storage3/demount_2700V_x-296758_y71514_board2.txt' (0.19 eff)








'/OCT29/data_storage3/demount_2700V_x-312123_y150654_board2.txt' (0.05 eff)




'/OCT29/data_storage3/demount_2700V_x-312805_y140769_board2.txt' (0.10 eff)









'/OCT29/data_storage3/demount_2700V_x-318692_y121013_board2.txt' (0.05 eff)




'/OCT29/data_storage3/demount_2700V_x-321197_y111715_board2.txt' (0.21 eff)





'/OCT29/data_storage3/demount_2700V_x-323751_y64614_board2.txt' (0.20 eff)




'/OCT29/data_storage3/demount_2700V_x-324593_y101837_board2.txt' (0.28 eff)










'/OCT29/data_storage3/demount_2700V_x-334068_y160605_board2.txt' (0.05 eff)







'/OCT29/data_storage3/demount_2700V_x-339137_y64658_board2.txt' (0.12 eff)












'/OCT29/data_storage3/demount_2700V_x102489_y-55268_board2.txt' (0.38 eff)





'/OCT29/data_storage3/demount_2700V_x104523_y-65161_board2.txt' (0.39 eff)




'/OCT29/data_storage3/demount_2700V_x105665_y-75632_board2.txt' (0.40 eff)













'/OCT29/data_storage3/demount_2700V_x107162_y-101808_board2.txt' (0.36 eff)










'/OCT29/data_storage3/demount_2700V_x107544_y-118675_board2.txt' (0.33 eff)





'/OCT29/data_storage3/demount_2700V_x107741_y-127399_board2.txt' (0.46 eff)





















All Files



All Files

